Portland Public Schools
Lead and Copper Water Sampling Results
A (Initial) and B (Follow-Up) Sample Data
Forest Park Elementary School

Sample Identification # and Location	Date/Time Collected	Date/Time Analyzed	Container ID	Analyte	Results	PPS Action Level*	Units
152-1997-A-002A Cafeteria	10/02/18 6:09 AM	10/08/18 4:15 PM	18024970	Copper	0.4	1.3	ppm
152-1997-A-002A Cafeteria	10/02/18 6:09 AM	10/05/18 6:37 PM	18024970	Lead	< 1	15	ppb
152-1997-A-002B Cafeteria	10/02/18 6:09 AM	10/08/18 4:18 PM	18024971	Copper	0.4	1.3	ppm
152-1997-A-002B Cafeteria	10/02/18 6:09 AM	10/05/18 6:41 PM	18024971	Lead	< 1	15	ppb
152-2035-A-002A Hallway 201	10/02/18 6:22 AM	10/08/18 4:21 PM	18024972	Copper	1.0	1.3	ppm
152-2035-A-002A Hallway 201	10/02/18 6:22 AM	10/05/18 6:45 PM	18024972	Lead	5	15	ppb
152-2035-A-002B Hallway 201	10/02/18 6:22 AM	10/08/18 4:24 PM	18024973	Copper	0.6	1.3	ppm
152-2035-A-002B Hallway 201	10/02/18 6:22 AM	10/05/18 6:49 PM	18024973	Lead	1	15	ppb
152-2036-A-002A Hallway 201	10/02/18 6:23 AM	10/08/18 4:27 PM	18024974	Copper	0.8	1.3	ppm
152-2036-A-002A Hallway 201	10/02/18 6:23 AM	10/05/18 6:53 PM	18024974	Lead	3	15	ppb
152-2036-A-002B Hallway 201	10/02/18 6:23 AM	10/08/18 4:49 PM	18024975	Copper	0.4	1.3	ppm
152-2036-A-002B Hallway 201	10/02/18 6:23 AM	10/05/18 7:23 PM	18024975	Lead	< 1	15	ppb
152-2031-A-002A Hallway 116	10/02/18 6:13 AM	10/08/18 4:52 PM	18024976	Copper	0.9	1.3	ppm
152-2031-A-002A Hallway 116	10/02/18 6:13 AM	10/05/18 7:27 PM	18024976	Lead	6	15	ppb
152-2031-A-002B Hallway 116	10/02/18 6:13 AM	10/08/18 4:55 PM	18024977	Copper	0.9	1.3	ppm
152-2031-A-002B Hallway 116	10/02/18 6:13 AM	10/05/18 7:31 PM	18024977	Lead	3	15	ppb
152-2033-A-002A Hallway 131	10/02/18 6:34 AM	10/08/18 7:33 PM	18024978	Copper	1.4	1.3	ppm
152-2033-A-002A Hallway 131	10/02/18 6:34 AM	10/08/18 7:33 PM	18024978	Lead	16	15	ppb
152-2033-A-002B Hallway 131	10/02/18 6:34 AM	10/08/18 4:58 PM	18024979	Copper	1.1	1.3	ppm
152-2033-A-002B Hallway 131	10/02/18 6:34 AM	10/05/18 7:35 PM	18024979	Lead	4	15	ppb
152-2034-A-002A Hallway 131	10/02/18 6:35 AM	10/08/18 5:01 PM	18024980	Copper	1.1	1.3	ppm
152-2034-A-002A Hallway 131	10/02/18 6:35 AM	10/05/18 7:39 PM	18024980	Lead	8	15	ppb
152-2034-A-002B Hallway 131	10/02/18 6:35 AM	10/08/18 5:04 PM	18024981	Copper	0.7	1.3	ppm
152-2034-A-002B Hallway 131	10/02/18 6:35 AM	10/05/18 7:43 PM	18024981	Lead	1	15	ppb
152-2029-A-002A Staff Cafeteria	10/02/18 6:05 AM	10/08/18 5:07 PM	18024982	Copper	0.2	1.3	ppm
152-2029-A-002A Staff Cafeteria	10/02/18 6:05 AM	10/05/18 7:47 PM	18024982	Lead	< 1	15	ppb
152-2029-A-002B Staff Cafeteria	10/02/18 6:05 AM	10/08/18 5:10 PM	18024983	Copper	0.1	1.3	ppm
152-2029-A-002B Staff Cafeteria	10/02/18 6:05 AM	10/05/18 7:52 PM	18024983	Lead	< 1	15	ppb
152-2037-A-002A Staff Room 123K	10/02/18 6:41 AM	10/08/18 5:13 PM	18024984	Copper	0.4	1.3	ppm
152-2037-A-002A Staff Room 123K	10/02/18 6:41 AM	10/05/18 7:56 PM	18024984	Lead	2	15	ppb
152-2037-A-002B Staff Room 123K	10/02/18 6:41 AM	10/08/18 5:16 PM	18024985	Copper	0.3	1.3	ppm
152-2037-A-002B Staff Room 123K	10/02/18 6:41 AM	10/05/18 8:00 PM	18024985	Lead	< 1	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.

Analyzed by: Pixis Labs

*EPA action level for lead is 20 ppb and 1.3 for copper

Reviewed by: TRC Environmental Corporation