

**Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
Jackson**

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
174-CH1865-A-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-01	Copper	0.0841	0.00200	1.3	ppm
174-CH1865-A-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-01	Lead	10.2	0.200	15	ppb
174-CH1865-A-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-02	Copper	0.0683	0.00200	1.3	ppm
174-CH1865-A-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-02	Lead	6.36	0.200	15	ppb
174-CH1865-B-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-03	Copper	0.0728	0.00200	1.3	ppm
174-CH1865-B-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-03	Lead	4.12	0.200	15	ppb
174-CH1865-B-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-04	Copper	0.0560	0.00200	1.3	ppm
174-CH1865-B-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-04	Lead	2.01	0.200	15	ppb
174-CH1866-A-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-09	Copper	0.0390	0.00200	1.3	ppm
174-CH1866-A-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-09	Lead	9.77	0.200	15	ppb
174-CH1866-A-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-10	Copper	0.00301	0.00200	1.3	ppm
174-CH1866-A-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-10	Lead	1.46	0.200	15	ppb
174-CH1866-B-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-11	Copper	0.0179	0.00200	1.3	ppm
174-CH1866-B-003-A	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-11	Lead	2.44	0.200	15	ppb
174-CH1866-B-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-12	Copper	0.00311	0.00200	1.3	ppm
174-CH1866-B-003-B	Hallway bubbler	11/8/2018	11/12/2018	A8K0286-12	Lead	1.09	0.200	15	ppb

Analyzed by:

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Reviewed by: PBS Engineering and Environmental

Page 1 of 2

174-CH2004-N/A-003-A	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-05	Copper	0.0208	0.00200	1.3	ppm
174-CH2004-N/A-003-A	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-05	Lead	16.2	0.200	15	ppb
174-CH2004-N/A-003-B	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-06	Copper	0.00315	0.00200	1.3	ppm
174-CH2004-N/A-003-B	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-06	Lead	5.12	0.200	15	ppb
174-CH2005-N/A-003-A	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-07	Copper	0.0308	0.00200	1.3	ppm
174-CH2005-N/A-003-A	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-07	Lead	5.11	0.200	15	ppb
174-CH2005-N/A-003-B	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-08	Copper	0.00271	0.00200	1.3	ppm
174-CH2005-N/A-003-B	Hallway Bubblers	11/8/2018	11/12/2018	A8K0286-08	Lead	5.57	0.200	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.

Analyzed by:

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Reviewed by: PBS Engineering and Environmental

Page 2 of 2