

**Portland Public Schools
Lead Water Sampling Results
Initial Flush Sample Data - No Follow Up Required
Jefferson - Test 3**

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
118-CH3651-N/A-003-A	Faculty Break Room	3/26/2019	4/10/2019	A9C1078-01	Lead	13.5	0.20	15	ppb
118-CH3624-A-003-A	Kitchen	3/26/2019	4/10/2019	A9C1078-03	Lead	1.24	0.20	15	ppb
118-CH3624-A-003-B	Kitchen	3/26/2019	4/10/2019	A9C1078-04	Lead	4.64	0.20	15	ppb
118-CH3624-A-003-C	Kitchen	3/26/2019	4/10/2019	A9C1078-05	Lead	0.268	0.20	15	ppb
118-CH3624-A-003-D	Kitchen	3/26/2019	4/10/2019	A9C1078-06	Lead	ND	0.20	15	ppb
118-CH3624-A-003-E	Kitchen	3/26/2019	4/10/2019	A9C1078-07	Lead	ND	0.20	15	ppb
118-CH3624-A-003-F	Kitchen	3/26/2019	4/10/2019	A9C1078-08	Lead	ND	0.20	15	ppb
118-CH3624-A-003-G	Kitchen	3/26/2019	4/10/2019	A9C1078-09	Lead	ND	0.20	15	ppb
118-CH3624-B-003-A	Kitchen	3/26/2019	4/10/2019	A9C1078-10	Lead	0.668	0.20	15	ppb
118-CH3624-B-003-B	Kitchen	3/26/2019	4/10/2019	A9C1078-11	Lead	ND	0.20	15	ppb
118-CH3624-B-003-C	Kitchen	3/26/2019	4/10/2019	A9C1078-12	Lead	0.512	0.20	15	ppb
118-CH3624-B-003-D	Kitchen	3/26/2019	4/10/2019	A9C1078-13	Lead	ND	0.20	15	ppb
118-CH3624-B-003-E	Kitchen	3/26/2019	4/10/2019	A9C1078-14	Lead	ND	0.20	15	ppb
118-CH3624-B-003-F	Kitchen	3/26/2019	4/10/2019	A9C1078-15	Lead	ND	0.20	15	ppb
118-CH3624-B-003-G	Kitchen	3/26/2019	4/10/2019	A9C1078-16	Lead	ND	0.20	15	ppb
118-CH3627-N/A-003-A	Kitchen	3/26/2019	4/10/2019	A9C1078-17	Lead	14.8	0.20	15	ppb
118-CH3627-N/A-003-B	Kitchen	3/26/2019	4/9/2019	A9C1078-18	Lead	0.211	0.20	15	ppb

Analyzed by: Apex Laboratories
Reviewed by: PSI-Intertek

*OHA Action Level = 15 ppb

118-CH3627-N/A-003-C	Kitchen	3/26/2019	4/9/2019	A9C1078-19	Lead	ND	0.20	15	ppb
118-CH3627-N/A-003-D	Kitchen	3/26/2019	4/9/2019	A9C1078-20	Lead	ND	0.20	15	ppb
118-CH3627-N/A-003-E	Kitchen	3/26/2019	4/9/2019	A9C1078-21	Lead	2.05	0.20	15	ppb
118-CH3627-N/A-003-F	Kitchen	3/26/2019	4/9/2019	A9C1078-22	Lead	ND	0.20	15	ppb
118-CH3627-N/A-003-G	Kitchen	3/26/2019	4/9/2019	A9C1078-23	Lead	ND	0.20	15	ppb
118-CH3621-N/A-003-A	Kitchen	3/26/2019	4/9/2019	A9C1078-24	Lead	0.613	0.20	15	ppb
118-CH3621-N/A-003-B	Kitchen	3/26/2019	4/9/2019	A9C1078-25	Lead	1.37	0.20	15	ppb
118-CH3621-N/A-003-C	Kitchen	3/26/2019	4/9/2019	A9C1078-26	Lead	ND	0.20	15	ppb
118-CH3621-N/A-003-D	Kitchen	3/26/2019	4/9/2019	A9C1078-27	Lead	ND	0.20	15	ppb
118-CH3621-N/A-003-E	Kitchen	3/26/2019	4/9/2019	A9C1078-28	Lead	ND	0.20	15	ppb
118-CH3621-N/A-003-F	Kitchen	3/26/2019	4/9/2019	A9C1078-29	Lead	ND	0.20	15	ppb
118-CH3621-N/A-003-G	Kitchen	3/26/2019	4/9/2019	A9C1078-30	Lead	ND	0.20	15	ppb
118-CH3657-N/A-003-A	Auditorium	3/26/2019	4/9/2019	A9C1078-31	Lead	4.19	0.20	15	ppb
118-CH3660-N/A-003-A	Hallway B-77	3/26/2019	4/9/2019	A9C1078-33	Lead	2.42	0.20	15	ppb
118-CH3664-N/A-003-A	Hallway Engineering Studio	3/26/2019	4/9/2019	A9C1078-35	Lead	21.30	0.20	15	ppb
118-CH3672-N/A-003-A	TV Studio B	3/26/2019	4/9/2019	A9C1078-37	Lead	7.18	0.20	15	ppb
118-CH3652-N/A-003-A	Hallway TV Studio A	3/26/2019	4/9/2019	A9C1078-39	Lead	115.00	0.20	15	ppb
118-CH3631-N/A-003-A	Cafeteria	3/26/2019	4/9/2019	A9C1078-41	Lead	6.05	0.20	15	ppb
118-CH3632-N/A-003-A	Dance Room South	3/26/2019	4/9/2019	A9C1078-43	Lead	9.26	0.20	15	ppb
118-CH3638-N/A-003-A	Locker Room	3/26/2019	4/9/2019	A9C1078-45	Lead	3.02	0.20	15	ppb
118-CH3641-N/A-003-A	Hallway (TV Wing/Boys Locker Room)	3/26/2019	4/9/2019	A9C1078-47	Lead	39.70	0.20	15	ppb
118-CH3667-N/A-003-A	Hallway C-4	3/26/2019	4/9/2019	A9C1078-49	Lead	3.51	0.20	15	ppb

Analyzed by: Apex Laboratories

Reviewed by: PSI-Intertek

*OHA Action Level = 15 ppb

118-CH3670-A-003-A	Hallway C21	3/26/2019	4/9/2019	A9C1078-51	Lead	4.48	0.20	15	ppb
118-CH3670-B-003-A	Hallway C21	3/26/2019	4/9/2019	A9C1078-53	Lead	4.48	0.20	15	ppb
118-CH3665-A-003-A	Hallway D-19	3/26/2019	4/9/2019	A9C1078-55	Lead	4.01	0.20	15	ppb
118-CH3665-B-003-A	Hallway D-19	3/26/2019	4/9/2019	A9C1078-57	Lead	2.71	0.20	15	ppb
118-CH3663-N/A-003-A	Hallway C-75	3/26/2019	4/9/2019	A9C1078-59	Lead	11.3	0.20	15	ppb
118-CH3666-N/A-003-A	Hallway D-78	3/26/2019	4/9/2019	A9C1078-61	Lead	12.5	0.20	15	ppb
118-CH3648-A-003-A	Transition Room (Track)	3/26/2019	4/9/2019	A9C1078-63	Lead	12.9	0.20	15	ppb
118-CH3648-B-003-A	Transition Room (Track)	3/26/2019	4/9/2019	A9C1078-65	Lead	34.10	0.20	15	ppb
118-CH3650-N/A-003-A	Gym	3/26/2019	4/10/2019	A9C1078-67	Lead	36.00	0.20	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.