

Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
Lincoln

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
120-CH1964-A-001-A	Hallway Bubblers	8/15/2018	8/20/2018	1808768-01A	Copper	1.21	0.000259	1.3	ppm
120-CH1964-A-001-A	Hallway Bubblers	8/15/2018	8/18/2018	1808768-01A	Lead	18.5	0.00523	15	ppb
120CH1964-A-001-B	Hallway Bubblers	8/15/2018	8/20/2018	1808768-02A	Copper	1.49	0.000259	1.3	ppm
120CH1964-A-001-B	Hallway Bubblers	8/15/2018	8/18/2018	1808768-02A	Lead	3.26	0.00523	15	ppb
120-CH1964-B-001-A	Hallway Bubblers	8/15/2018	8/20/2018	1808768-03A	Copper	1.33	0.000259	1.3	ppm
120-CH1964-B-001-A	Hallway Bubblers	8/15/2018	8/18/2018	1808768-03A	Lead	8.07	0.00523	15	ppb
120-CH1964-B-001-B	Hallway Bubblers	8/15/2018	8/20/2018	1808768-04A	Copper	1.46	0.000259	1.3	ppm
120-CH1964-B-001-B	Hallway Bubblers	8/15/2018	8/18/2018	1808768-04A	Lead	2.64	0.00523	15	ppb
120-CH1964-C-001-A	Hallway Bubblers	8/15/2018	8/20/2018	1808768-05A	Copper	1.60	0.000259	1.3	ppm
120-CH1964-C-001-A	Hallway Bubblers	8/15/2018	8/18/2018	1808768-05A	Lead	15.7	0.00523	15	ppb
120-CH1964-C-001-B	Hallway Bubblers	8/15/2018	8/20/2018	1808768-06A	Copper	1.48	0.000259	1.3	ppm
120-CH1964-C-001-B	Hallway Bubblers	8/15/2018	8/18/2018	1808768-06A	Lead	2.52	0.00523	15	ppb
120-CH1965-N/A-001-A	Hallway Bubblers	8/15/2018	8/20/2018	1808768-07A	Copper	0.909	0.000259	1.3	ppm
120-CH1965-N/A-001-A	Hallway Bubblers	8/15/2018	8/18/2018	1808768-07A	Lead	8.81	0.00523	15	ppb
120-CH1965-N/A-001-B	Hallway Bubblers	8/15/2018	8/20/2018	1808768-08A	Copper	0.912	0.000259	1.3	ppm
120-CH1965-N/A-001-B	Hallway Bubblers	8/15/2018	8/18/2018	1808768-08A	Lead	4.19	0.00523	15	ppb

Analyzed by:

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Reviewed by: PBS Engineering and Environmental

120-CH1963-A-001-A	Hallway Bubbler	8/15/2018	8/20/2018	1808768-09A	Copper	1.43	0.000259	1.3	ppm
120-CH1963-A-001-A	Hallway Bubbler	8/15/2018	8/18/2018	1808768-09A	Lead	5.6	0.00523	15	ppb
120-CH1963-A-001-B	Hallway Bubbler	8/15/2018	8/20/2018	1808768-10A	Copper	1.56	0.000259	1.3	ppm
120-CH1963-A-001-B	Hallway Bubbler	8/15/2018	8/18/2018	1808768-10A	Lead	1.39	0.00523	15	ppb
120-CH1963-B-001-A	Hallway Bubbler	8/15/2018	8/20/2018	1808768-11A	Copper	1.28	0.000259	1.3	ppm
120-CH1963-B-001-A	Hallway Bubbler	8/15/2018	8/18/2018	1808768-11A	Lead	8.93	0.00523	15	ppb
120-CH1963-B-001-B	Hallway Bubbler	8/15/2018	8/20/2018	1808768-12A	Copper	1.26	0.000259	1.3	ppm
120-CH1963-B-001-B	Hallway Bubbler	8/15/2018	8/18/2018	1808768-12A	Lead	1.22	0.00523	15	ppb
120-CH1963-C-001-A	Hallway Bubbler	8/15/2018	8/20/2018	1808768-13A	Copper	1.15	0.000259	1.3	ppm
120-CH1963-C-001-A	Hallway Bubbler	8/15/2018	8/18/2018	1808768-13A	Lead	4.11	0.00523	15	ppb
120-CH1963-C-001-B	Hallway Bubbler	8/15/2018	8/20/2018	1808768-14A	Copper	1.12	0.000259	1.3	ppm
120-CH1963-C-001-B	Hallway Bubbler	8/15/2018	8/18/2018	1808768-14A	Lead	1.22	0.00523	15	ppb
120-CH1962-A-001-A	Hallway Bubbler	8/15/2018	8/18/2018	1808768-15A	Copper	0.371	0.0000259	1.3	ppm
120-CH1962-A-001-A	Hallway Bubbler	8/15/2018	8/18/2018	1808768-15A	Lead	25	0.00523	15	ppb
120-CH1962-A-001-B	Hallway Bubbler	8/15/2018	8/18/2018	1808768-16A	Copper	0.217	0.0000259	1.3	ppm
120-CH1962-A-001-B	Hallway Bubbler	8/15/2018	8/18/2018	1808768-16A	Lead	5.16	0.00523	15	ppb
120-CH1962-B-001-A	Hallway Bubbler	8/15/2018	8/21/2018	1808768-17A	Copper	0.553	0.0000259	1.3	ppm
120-CH1962-B-001-A	Hallway Bubbler	8/15/2018	8/21/2018	1808768-17A	Lead	18.2	0.00523	15	ppb
120-CH1962-B-001-B	Hallway Bubbler	8/15/2018	8/21/2018	1808768-18A	Copper	0.139	0.0000259	1.3	ppm
120-CH1962-B-001-B	Hallway Bubbler	8/15/2018	8/21/2018	1808768-18A	Lead	2.27	0.00523	15	ppb

Analyzed by:

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Reviewed by: PBS Engineering and Environmental

Page 2 of 4

120-CH1955-N/A-001-A	Gym Bubbler	8/15/2018	8/21/2018	1808768-19A	Copper	1.81	0.000259	1.3	ppm
120-CH1955-N/A-001-A	Gym Bubbler	8/15/2018	8/21/2018	1808768-19A	Lead	6.27	0.00523	15	ppb
120-CH1955-N/A-001-B	Gym Bubbler	8/15/2018	8/21/2018	1808768-20A	Copper	0.191	0.0000259	1.3	ppm
120-CH1955-N/A-001-B	Gym Bubbler	8/15/2018	8/21/2018	1808768-20A	Lead	0.781	0.00523	15	ppb
120-CH1956-N/A-001-A	Gym Bubbler	8/15/2018	8/21/2018	1808768-21A	Copper	1.14	0.000259	1.3	ppm
120-CH1956-N/A-001-A	Gym Bubbler	8/15/2018	8/21/2018	1808768-21A	Lead	7.1	0.00523	15	ppb
120-CH1956-N/A-001-B	Gym Bubbler	8/15/2018	8/21/2018	1808768-22A	Copper	1.08	0.000259	1.3	ppm
120-CH1956-N/A-001-B	Gym Bubbler	8/15/2018	8/21/2018	1808768-22A	Lead	2.38	0.00523	15	ppb
120-CH1945-N/A-001-A	Kitchen Prep Sink	8/15/2018	8/21/2018	1808768-23A	Copper	0.133	0.0000259	1.3	ppm
120-CH1945-N/A-001-A	Kitchen Prep Sink	8/15/2018	8/21/2018	1808768-23A	Lead	9.33	0.00523	15	ppb
120-CH1945-N/A-001-B	Kitchen Prep Sink	8/15/2018	8/21/2018	1808768-24A	Copper	0.0140	0.0000259	1.3	ppm
120-CH1945-N/A-001-B	Kitchen Prep Sink	8/15/2018	8/21/2018	1808768-24A	Lead	0.803	0.00523	15	ppb
120-CH1942-N/A-001-A	Art Wing Bubbler	8/15/2018	8/21/2018	1808768-25A	Copper	0.422	0.0000259	1.3	ppm
120-CH1942-N/A-001-A	Art Wing Bubbler	8/15/2018	8/21/2018	1808768-25A	Lead	4.99	0.00523	15	ppb
120-CH1942-N/A-001-B	Art Wing Bubbler	8/15/2018	8/21/2018	1808768-26A	Copper	0.137	0.0000259	1.3	ppm
120-CH1942-N/A-001-B	Art Wing Bubbler	8/15/2018	8/21/2018	1808768-26A	Lead	0.51	0.00523	15	ppb
120-CH1957-A-001-A	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-27A	Copper	0.941	0.000259	1.3	ppm
120-CH1957-A-001-A	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-27A	Lead	6.56	0.00523	15	ppb
120-CH1957-A-001-B	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-28A	Copper	1.03	0.000259	1.3	ppm
120-CH1957-A-001-B	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-28A	Lead	0.53	0.00523	15	ppb

Analyzed by:

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Reviewed by: PBS Engineering and Environmental

Page 3 of 4

120-CH1957-B-001-A	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-29A	Copper	0.791	0.0000259	1.3	ppm
120-CH1957-B-001-A	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-29A	Lead	1.61	0.00523	15	ppb
120-CH1957-B-001-B	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-30A	Copper	0.289	0.0000259	1.3	ppm
120-CH1957-B-001-B	Boys Locker Bubbler	8/15/2018	8/21/2018	1808768-30A	Lead	0.3	0.00523	15	ppb
120-CH1951-N/A-001-A	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-31A	Copper	0.215	0.0000259	1.3	ppm
120-CH1951-N/A-001-A	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-31A	Lead	1.69	0.00523	15	ppb
120-CH1951-N/A-001-B	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-32A	Copper	2.03	0.000259	1.3	ppm
120-CH1951-N/A-001-B	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-32A	Lead	22.8	0.00523	15	ppb
120-CH1952-N/A-001-A	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-33A	Copper	1.19	0.000259	1.3	ppm
120-CH1952-N/A-001-A	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-33A	Lead	7.76	0.00523	15	ppb
120-CH1952-N/A-001-B	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-34A	Copper	1.12	0.000259	1.3	ppm
120-CH1952-N/A-001-B	Weight Room Bubbler	8/15/2018	8/21/2018	1808768-34A	Lead	2.17	0.00523	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.

Analyzed by: