

Portland Public Schools
Lead and Copper Water Sampling Results
A (Initial) and B (Follow-Up) Sample Data
Metropolitan Learning Center

Sample Identification # and Location	Date/Time Collected	Date/Time Analyzed	Container ID	Analyte	Results	PPS Action Level*	Units
154-1977-A-001A Hallway near Rm 113	08/03/18 9:37 AM	08/06/18 2:04 PM	18017590	Copper	0.2	1.3	ppm
154-1977-A-001A Hallway near Rm 113	08/03/18 9:37 AM	08/06/18 2:04 PM	18017590	Lead	6	15	ppb
154-1977-A-001B Hallway near Rm 113	08/03/18 9:37 AM	08/07/18 8:02 PM	18017596	Copper	0.6	1.3	ppm
154-1977-A-001B Hallway near Rm 113	08/03/18 9:37 AM	08/07/18 8:02 PM	18017596	Lead	17	15	ppb
154-1978-A-001A Hallway near Rm 113	08/03/18 9:37 AM	08/07/18 8:07 PM	18017593	Copper	0.5	1.3	ppm
154-1978-A-001A Hallway near Rm 113	08/03/18 9:37 AM	08/07/18 8:07 PM	18017593	Lead	14	15	ppb
154-1978-A-001B Hallway near Rm 113	08/03/18 9:37 AM	08/07/18 8:11 PM	18017595	Copper	0.2	1.3	ppm
154-1978-A-001B Hallway near Rm 113	08/03/18 9:37 AM	08/07/18 8:11 PM	18017595	Lead	14	15	ppb
154-1974-A-001A Kitchen	08/03/18 9:55 AM	08/06/18 2:06 PM	18017594	Copper	0.4	1.3	ppm
154-1974-A-001A Kitchen	08/03/18 9:55 AM	08/06/18 2:06 PM	18017594	Lead	5	15	ppb
154-1974-A-001B Kitchen	08/03/18 9:55 AM	08/06/18 2:08 PM	18017591	Copper	0.3	1.3	ppm
154-1974-A-001B Kitchen	08/03/18 9:55 AM	08/06/18 2:08 PM	18017591	Lead	1	15	ppb
154-1975-A-001A Kitchen	08/03/18 9:55 AM	08/06/18 2:09 PM	18017597	Copper	0.4	1.3	ppm
154-1975-A-001A Kitchen	08/03/18 9:55 AM	08/06/18 2:09 PM	18017597	Lead	4	15	ppb
154-1975-A-001B Kitchen	08/03/18 9:55 AM	08/06/18 2:11 PM	18017592	Copper	0.3	1.3	ppm
154-1975-A-001B Kitchen	08/03/18 9:55 AM	08/06/18 2:11 PM	18017592	Lead	1	15	ppb
154-1975-B-001A Kitchen	08/03/18 9:55 AM	08/06/18 2:13 PM	18017601	Copper	0.3	1.3	ppm
154-1975-B-001A Kitchen	08/03/18 9:55 AM	08/06/18 2:13 PM	18017601	Lead	6	15	ppb
154-1975-B-001B Kitchen	08/03/18 9:55 AM	08/06/18 2:15 PM	18017598	Copper	0.3	1.3	ppm
154-1975-B-001B Kitchen	08/03/18 9:55 AM	08/06/18 2:15 PM	18017598	Lead	1	15	ppb
154-1979-A-001A 2nd Fl near Rm 204	08/03/18 10:04 AM	08/06/18 2:17 PM	18017600	Copper	0.8	1.3	ppm
154-1979-A-001A 2nd Fl near Rm 204	08/03/18 10:04 AM	08/06/18 2:17 PM	18017600	Lead	19	15	ppb
154-1979-A-001B 2nd Fl near Rm 204	08/03/18 10:04 AM	08/06/18 2:19 PM	18017599	Copper	0.5	1.3	ppm
154-1979-A-001B 2nd Fl near Rm 204	08/03/18 10:04 AM	08/06/18 2:19 PM	18017599	Lead	1	15	ppb
154-1980-A-001A 3rd Fl near Rm 301	08/03/18 10:10 AM	08/06/18 2:31 PM	18017602	Copper	0.9	1.3	ppm
154-1980-A-001A 3rd Fl near Rm 301	08/03/18 10:10 AM	08/06/18 2:31 PM	18017602	Lead	1	15	ppb
154-1980-A-001B 3rd Fl near Rm 301	08/03/18 10:10 AM	08/06/18 2:33 PM	18017603	Copper	0.7	1.3	ppm
154-1980-A-001B 3rd Fl near Rm 301	08/03/18 10:10 AM	08/06/18 2:33 PM	18017603	Lead	1	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.