

**Portland Public Schools**  
**Lead and Copper Water Sampling Results**  
**Initial and Follow Up Flush Sample Data**  
**2nd Site Visit - Sabin Elementary**

| Sample Identification # | Location                               | Date Collected | Date Analyzed | Lab ID        | Analyte | Results | Detection Limit | PPS Action Level* | Units |
|-------------------------|----------------------------------------|----------------|---------------|---------------|---------|---------|-----------------|-------------------|-------|
| 279-2149-A-001-A        | Sink (Food Prep) - Staff 205           | 8/31/2018      | 9/7/2018      | A8H0905-01    | Copper  | 0.689   | 0.00400         | 1.3               | ppm   |
| 279-2149-A-001-A        | Sink (Food Prep) - Staff 205           | 8/31/2018      | 9/10/2018     | A8H0905-01RE1 | Lead    | 212     | 0.200           | 15                | ppb   |
| 279-2149-A-001-B        | Sink (Food Prep) - Staff 205           | 8/31/2018      | 9/13/2018     | A8H0905-02RE1 | Copper  | 0.00772 | 0.00200         | 1.3               | ppm   |
| 279-2149-A-001-B        | Sink (Food Prep) - Staff 205           | 8/31/2018      | 9/13/2018     | A8H0905-02RE1 | Lead    | 1.61    | 0.200           | 15                | ppb   |
| 279-2149-B-001-A        | Sink Bubbler - Staff 205               | 8/31/2018      | 9/13/2018     | A8H0905-03RE1 | Copper  | 0.0765  | 0.00200         | 1.3               | ppm   |
| 279-2149-B-001-A        | Sink Bubbler - Staff 205               | 8/31/2018      | 9/13/2018     | A8H0905-03RE1 | Lead    | 17.2    | 0.200           | 15                | ppb   |
| 279-2149-B-001-B        | Sink Bubbler - Staff 205               | 8/31/2018      | 9/13/2018     | A8H0905-04RE1 | Copper  | 0.00851 | 0.00200         | 1.3               | ppm   |
| 279-2149-B-001-B        | Sink Bubbler - Staff 205               | 8/31/2018      | 9/13/2018     | A8H0905-04RE1 | Lead    | 2.44    | 0.200           | 15                | ppb   |
| 279-2152-N/A-001-A      | Classroom Sink Bubbler - Classroom 221 | 8/31/2018      | 9/13/2018     | A8H0905-05RE1 | Copper  | 0.0104  | 0.00200         | 1.3               | ppm   |
| 279-2152-N/A-001-A      | Classroom Sink Bubbler - Classroom 221 | 8/31/2018      | 9/13/2018     | A8H0905-05RE1 | Lead    | 6.07    | 0.200           | 15                | ppb   |
| 279-2152-N/A-001-B      | Classroom Sink Bubbler - Classroom 221 | 8/31/2018      | 9/13/2018     | A8H0905-06RE1 | Copper  | 0.00470 | 0.00200         | 1.3               | ppm   |
| 279-2152-N/A-001-B      | Classroom Sink Bubbler - Classroom 221 | 8/31/2018      | 9/13/2018     | A8H0905-06RE1 | Lead    | 5.96    | 0.200           | 15                | ppb   |
| 279-2153-N/A-001-A      | Classroom Sink Bubbler - Classroom 222 | 8/31/2018      | 9/13/2018     | A8H0905-07RE1 | Copper  | 0.0160  | 0.00200         | 1.3               | ppm   |
| 279-2153-N/A-001-A      | Classroom Sink Bubbler - Classroom 222 | 8/31/2018      | 9/13/2018     | A8H0905-07RE1 | Lead    | 20.2    | 0.200           | 15                | ppb   |
| 279-2153-N/A-001-B      | Classroom Sink Bubbler - Classroom 222 | 8/31/2018      | 9/13/2018     | A8H0905-08RE1 | Copper  | 0.00590 | 0.00200         | 1.3               | ppm   |
| 279-2153-N/A-001-B      | Classroom Sink Bubbler - Classroom 222 | 8/31/2018      | 9/13/2018     | A8H0905-08RE1 | Lead    | 9.09    | 0.200           | 15                | ppb   |
| 279-2161-A-001-A        | Sink (Food Prep) - Staff 111           | 8/31/2018      | 9/13/2018     | A8H0905-09RE1 | Copper  | 0.152   | 0.00200         | 1.3               | ppm   |
| 279-2161-A-001-A        | Sink (Food Prep) - Staff 111           | 8/31/2018      | 9/13/2018     | A8H0905-09RE1 | Lead    | 14.0    | 0.200           | 15                | ppb   |
| 279-2161-A-001-B        | Sink (Food Prep) - Staff 111           | 8/31/2018      | 9/13/2018     | A8H0905-10RE1 | Copper  | 0.0136  | 0.00200         | 1.3               | ppm   |
| 279-2161-A-001-B        | Sink (Food Prep) - Staff 111           | 8/31/2018      | 9/13/2018     | A8H0905-10RE1 | Lead    | 1.17    | 0.200           | 15                | ppb   |
| 279-2161-B-001-A        | Sink Bubbler - Staff 111               | 8/31/2018      | 9/13/2018     | A8H0905-11RE1 | Copper  | 0.0348  | 0.00200         | 1.3               | ppm   |
| 279-2161-B-001-A        | Sink Bubbler - Staff 111               | 8/31/2018      | 9/13/2018     | A8H0905-11RE1 | Lead    | 4.89    | 0.200           | 15                | ppb   |
| 279-2161-B-001-B        | Sink Bubbler - Staff 111               | 8/31/2018      | 9/13/2018     | A8H0905-12RE1 | Copper  | 0.0133  | 0.00200         | 1.3               | ppm   |

|                    |                                        |           |           |               |        |         |         |     |     |
|--------------------|----------------------------------------|-----------|-----------|---------------|--------|---------|---------|-----|-----|
| 279-2161-B-001-B   | Sink Bubbler - Staff 111               | 8/31/2018 | 9/13/2018 | A8H0905-12RE1 | Lead   | 1.68    | 0.200   | 15  | ppb |
| 279-2163-N/A-001-A | Classroom Sink Bubbler - Classroom 105 | 8/31/2018 | 9/13/2018 | A8H0905-13RE1 | Copper | 0.00723 | 0.00200 | 1.3 | ppm |
| 279-2163-N/A-001-A | Classroom Sink Bubbler - Classroom 105 | 8/31/2018 | 9/13/2018 | A8H0905-13RE1 | Lead   | 3.74    | 0.200   | 15  | ppb |
| 279-2163-N/A-001-B | Classroom Sink Bubbler - Classroom 105 | 8/31/2018 | 9/13/2018 | A8H0905-14RE1 | Copper | 0.00552 | 0.00200 | 1.3 | ppm |
| 279-2163-N/A-001-B | Classroom Sink Bubbler - Classroom 105 | 8/31/2018 | 9/13/2018 | A8H0905-14RE1 | Lead   | 2.97    | 0.200   | 15  | ppb |
| 279-2154-N/A-001-A | Classroom Sink Bubbler - Classroom 113 | 8/31/2018 | 9/13/2018 | A8H0905-15RE1 | Copper | 0.0167  | 0.00200 | 1.3 | ppm |
| 279-2154-N/A-001-A | Classroom Sink Bubbler - Classroom 113 | 8/31/2018 | 9/13/2018 | A8H0905-15RE1 | Lead   | 21.2    | 0.200   | 15  | ppb |
| 279-2154-N/A-001-B | Classroom Sink Bubbler - Classroom 113 | 8/31/2018 | 9/13/2018 | A8H0905-16RE1 | Copper | 0.00852 | 0.00200 | 1.3 | ppm |
| 279-2154-N/A-001-B | Classroom Sink Bubbler - Classroom 113 | 8/31/2018 | 9/13/2018 | A8H0905-16RE1 | Lead   | 19.3    | 0.200   | 15  | ppb |
| 279-2148-N/A-001-A | Classroom Sink Bubbler - Classroom 20  | 8/31/2018 | 9/13/2018 | A8H0905-17RE1 | Copper | 0.0174  | 0.00200 | 1.3 | ppm |
| 279-2148-N/A-001-A | Classroom Sink Bubbler - Classroom 20  | 8/31/2018 | 9/13/2018 | A8H0905-17RE1 | Lead   | 3.73    | 0.200   | 15  | ppb |
| 279-2148-N/A-001-B | Classroom Sink Bubbler - Classroom 20  | 8/31/2018 | 9/13/2018 | A8H0905-18RE1 | Copper | 0.0585  | 0.00200 | 1.3 | ppm |
| 279-2148-N/A-001-B | Classroom Sink Bubbler - Classroom 20  | 8/31/2018 | 9/13/2018 | A8H0905-18RE1 | Lead   | 9.57    | 0.200   | 15  | ppb |
| 279-2171-N/A-001-A | Classroom Sink Bubbler - Classroom P5  | 8/31/2018 | 9/13/2018 | A8H0905-19RE1 | Copper | 0.443   | 0.00200 | 1.3 | ppm |
| 279-2171-N/A-001-A | Classroom Sink Bubbler - Classroom P5  | 8/31/2018 | 9/13/2018 | A8H0905-19RE1 | Lead   | 17.3    | 0.200   | 15  | ppb |
| 279-2171-N/A-001-B | Classroom Sink Bubbler - Classroom P5  | 8/31/2018 | 9/13/2018 | A8H0905-20RE1 | Copper | 0.511   | 0.00200 | 1.3 | ppm |
| 279-2171-N/A-001-B | Classroom Sink Bubbler - Classroom P5  | 8/31/2018 | 9/13/2018 | A8H0905-20RE1 | Lead   | 29.3    | 0.200   | 15  | ppb |
| 279-2170-N/A-001-A | Classroom Sink Bubbler - Classroom P4  | 8/31/2018 | 9/13/2018 | A8H0905-21RE1 | Copper | 0.689   | 0.00200 | 1.3 | ppm |
| 279-2170-N/A-001-A | Classroom Sink Bubbler - Classroom P4  | 8/31/2018 | 9/13/2018 | A8H0905-21RE1 | Lead   | 27.1    | 0.200   | 15  | ppb |
| 279-2170-N/A-001-B | Classroom Sink Bubbler - Classroom P4  | 8/31/2018 | 9/5/2018  | A8H0905-22    | Copper | 0.211   | 0.00200 | 1.3 | ppm |
| 279-2170-N/A-001-B | Classroom Sink Bubbler - Classroom P4  | 8/31/2018 | 9/5/2018  | A8H0905-22    | Lead   | 4.74    | 0.200   | 15  | ppb |

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.