

Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
Scott Elementary

Sample Identification #		Location	Date Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
282-2178-N/A-001-A	Bubbler - Near HDF 1.2		7/31/2018	8/2/2018	A8G0812-01	Copper	0.0357	0.00200	1.3	ppm
282-2178-N/A-001-A	Bubbler - Near HDF 1.2		7/31/2018	8/2/2018	A8G0812-01	Lead	6.13	0.200	15	ppb
282-2178-N/A-001-B	Bubbler - Near HDF 1.2		7/31/2018	8/2/2018	A8G0812-02	Copper	0.0139	0.00200	1.3	ppm
282-2178-N/A-001-B	Bubbler - Near HDF 1.2		7/31/2018	8/2/2018	A8G0812-02	Lead	1.26	0.200	15	ppb
282-2177-N/A-001-A	Bubbler - Gym South Wall		7/31/2018	8/2/2018	A8G0812-03	Copper	0.0148	0.00200	1.3	ppm
282-2177-N/A-001-A	Bubbler - Gym South Wall		7/31/2018	8/2/2018	A8G0812-03	Lead	46.1	0.200	15	ppb
282-2177-N/A-001-B	Bubbler - Gym South Wall		7/31/2018	8/2/2018	A8G0812-04	Copper	ND	0.00200	1.3	ppm
282-2177-N/A-001-B	Bubbler - Gym South Wall		7/31/2018	8/2/2018	A8G0812-04	Lead	3.96	0.200	15	ppb
282-2191-N/A-001-A	Bubbler - Near Office		7/31/2018	8/2/2018	A8G0812-05	Copper	0.0108	0.00200	1.3	ppm
282-2191-N/A-001-A	Bubbler - Near Office		7/31/2018	8/2/2018	A8G0812-05	Lead	6.69	0.200	15	ppb
282-2191-N/A-001-B	Bubbler - Near Office		7/31/2018	8/2/2018	A8G0812-06	Copper	0.00364	0.00200	1.3	ppm
282-2191-N/A-001-B	Bubbler - Near Office		7/31/2018	8/2/2018	A8G0812-06	Lead	0.646	0.200	15	ppb
282-2192-N/A-001-A	Drinking Fountain (Stainless) - Hallway around corner from 207		7/31/2018	8/2/2018	A8G0812-07	Copper	0.0555	0.00200	1.3	ppm
282-2192-N/A-001-A	Drinking Fountain (Stainless) - Hallway around corner from 207		7/31/2018	8/2/2018	A8G0812-07	Lead	2.21	0.200	15	ppb
282-2192-N/A-001-B	Drinking Fountain (Stainless) - Hallway around corner from 207		7/31/2018	8/2/2018	A8G0812-08	Copper	0.0242	0.00200	1.3	ppm
282-2192-N/A-001-B	Drinking Fountain (Stainless) - Hallway around corner from 207		7/31/2018	8/2/2018	A8G0812-08	Lead	0.799	0.200	15	ppb
282-2199-N/A-001-A	Bubbler - Near 201		7/31/2018	8/2/2018	A8G0812-09	Copper	0.0269	0.00200	1.3	ppm
282-2199-N/A-001-A	Bubbler - Near 201		7/31/2018	8/2/2018	A8G0812-09	Lead	10.9	0.200	15	ppb
282-2199-N/A-001-B	Bubbler - Near 201		7/31/2018	8/2/2018	A8G0812-10	Copper	0.0202	0.00200	1.3	ppm
282-2199-N/A-001-B	Bubbler - Near 201		7/31/2018	8/2/2018	A8G0812-10	Lead	3.27	0.200	15	ppb
282-2186-N/A-001-A	Bubbler - Near 305		7/31/2018	8/2/2018	A8G0812-11	Copper	0.0147	0.00200	1.3	ppm
282-2186-N/A-001-A	Bubbler - Near 305		7/31/2018	8/2/2018	A8G0812-11	Lead	16.2	0.200	15	ppb

282-2186-N/A-001-B	Bubbler - Near 305	7/31/2018	8/2/2018	A8G0812-12	Copper	0.00530	0.00200	1.3	ppm
282-2186-N/A-001-B	Bubbler - Near 305	7/31/2018	8/2/2018	A8G0812-12	Lead	1.53	0.200	15	ppb
282-2172-N/A-001-A	Drinking Fountain (Stainless) - Cafeteria left of Room 17	7/31/2018	8/2/2018	A8G0812-13	Copper	0.0163	0.00200	1.3	ppm
282-2172-N/A-001-A	Drinking Fountain (Stainless) - Cafeteria left of Room 17	7/31/2018	8/2/2018	A8G0812-13	Lead	10.7	0.200	15	ppb
282-2172-N/A-001-B	Drinking Fountain (Stainless) - Cafeteria left of Room 17	7/31/2018	8/2/2018	A8G0812-14	Copper	0.00504	0.00200	1.3	ppm
282-2172-N/A-001-B	Drinking Fountain (Stainless) - Cafeteria left of Room 17	7/31/2018	8/2/2018	A8G0812-14	Lead	4.51	0.200	15	ppb
282-2175-A-001-A	Food Prep Faucet - Kitchen	7/31/2018	8/2/2018	A8G0812-15	Copper	0.0641	0.00200	1.3	ppm
282-2175-A-001-A	Food Prep Faucet - Kitchen	7/31/2018	8/2/2018	A8G0812-15	Lead	2.62	0.200	15	ppb
282-2175-A-001-B	Food Prep Faucet - Kitchen	7/31/2018	8/2/2018	A8G0812-16	Copper	0.00512	0.00200	1.3	ppm
282-2175-A-001-B	Food Prep Faucet - Kitchen	7/31/2018	8/2/2018	A8G0812-16	Lead	ND	0.200	15	ppb
282-2175-B-001-A	Food Prep Sprayer - Kitchen	7/31/2018	8/2/2018	A8G0812-17	Copper	0.0396	0.00200	1.3	ppm
282-2175-B-001-A	Food Prep Sprayer - Kitchen	7/31/2018	8/2/2018	A8G0812-17	Lead	0.551	0.200	15	ppb
282-2175-B-001-B	Food Prep Sprayer - Kitchen	7/31/2018	8/2/2018	A8G0812-18	Copper	0.00517	0.00200	1.3	ppm
282-2175-B-001-B	Food Prep Sprayer - Kitchen	7/31/2018	8/2/2018	A8G0812-18	Lead	ND	0.200	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.