

**Portland Public Schools
Lead Water Sampling Results
Initial Flush Sample Data
Terwilliger School (Sunstone Montessori) - Test 1**

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
366-CH2223-A-001-A	Kitchen	4/24/2019	5/8/2019	A9D0962-01	Lead	ND	0.20	15	ppb
366-CH2223-A-001-B	Kitchen	4/24/2019	5/8/2019	A9D0962-02	Lead	0.232	0.20	15	ppb
366-CH2223-A-001-C	Kitchen	4/24/2019	5/8/2019	A9D0962-03	Lead	0.447	0.20	15	ppb
366-CH2223-A-001-D	Kitchen	4/24/2019	5/8/2019	A9D0962-04	Lead	ND	0.20	15	ppb
366-CH2223-A-001-E	Kitchen	4/24/2019	5/8/2019	A9D0962-05	Lead	ND	0.20	15	ppb
366-CH2223-A-001-F	Kitchen	4/24/2019	5/8/2019	A9D0962-06	Lead	ND	0.20	15	ppb
366-CH2223-A-001-G	Kitchen	4/24/2019	5/8/2019	A9D0962-07	Lead	ND	0.20	15	ppb
366-CH2223-B-001-A	Kitchen	4/24/2019	5/8/2019	A9D0962-08	Lead	ND	0.20	15	ppb
366-CH2223-B-001-B	Kitchen	4/24/2019	5/8/2019	A9D0962-09	Lead	ND	0.20	15	ppb
366-CH2223-B-001-C	Kitchen	4/24/2019	5/8/2019	A9D0962-10	Lead	ND	0.20	15	ppb
366-CH2223-B-001-D	Kitchen	4/24/2019	5/8/2019	A9D0962-11	Lead	ND	0.20	15	ppb
366-CH2223-B-001-E	Kitchen	4/24/2019	5/8/2019	A9D0962-12	Lead	ND	0.20	15	ppb
366-CH2223-B-001-F	Kitchen	4/24/2019	5/8/2019	A9D0962-13	Lead	ND	0.20	15	ppb
366-CH2223-B-001-G	Kitchen	4/24/2019	5/8/2019	A9D0962-14	Lead	ND	0.20	15	ppb
366-CH2224-A-001-A	Hallway (6)	4/24/2019	5/8/2019	A9D0962-15	Lead	1.48	0.20	15	ppb
366-CH2224-B-001-A	Hallway (6)	4/24/2019	5/8/2019	A9D0962-16	Lead	0.96	0.20	15	ppb
366-CH2224-C-001-A	Hallway (6)	4/24/2019	5/8/2019	A9D0962-17	Lead	0.63	0.20	15	ppb

Analyzed by: Apex Laboratories
Reviewed by: PSI-Intertek

*OHA Action Level = 15ppb

366-CH2221-A-001-A	Hallway (1)	4/24/2019	5/8/2019	A9D0962-18	Lead	23.50	0.20	15	ppb
366-CH2221-B-001-A	Hallway (1)	4/24/2019	5/8/2019	A9D0962-19	Lead	4.3	0.20	15	ppb
366-CH2221-C-001-A	Hallway (1)	4/24/2019	5/8/2019	A9D0962-20	Lead	3.94	0.20	15	ppb
366-CH2221-D-001-A	Hallway (1)	4/24/2019	5/8/2019	A9D0962-21	Lead	2.18	0.20	15	ppb

Results highlighted indicate a value at or above PPS Action Level and the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.