

Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
Wilson 1

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
126-CH1894-NA-002-A	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-45	Copper	0.0448	0.00200	1.3	ppm
126-CH1894-NA-002-A	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-45	Lead	19.1	0.200	15	ppb
126-CH1894-NA-002-B	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-46	Copper	0.0186	0.00200	1.3	ppm
126-CH1894-NA-002-B	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-46	Lead	1.99	0.200	15	ppb
126-CH1895-NA-002-A	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-47	Copper	0.0615	0.00200	1.3	ppm
126-CH1895-NA-002-A	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-47	Lead	4.09	0.200	15	ppb
126-CH1895-NA-002-B	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-48	Copper	0.198	0.00200	1.3	ppm
126-CH1895-NA-002-B	Gym Apparatus	10/4/2018	10/9/2018	A8J0166-48	Lead	13.6	0.200	15	ppb
126-CH1896-NA-002-A	Gym Wrestling	10/4/2018	10/9/2018	A8J0166-43	Copper	0.315	0.00200	1.3	ppm
126-CH1896-NA-002-A	Gym Wrestling	10/4/2018	10/9/2018	A8J0166-43	Lead	456	0.200	15	ppb
126-CH1896-NA-002-B	Gym Wrestling	10/4/2018	10/9/2018	A8J0166-44	Copper	0.185	0.00200	1.3	ppm
126-CH1896-NA-002-B	Gym Wrestling	10/4/2018	10/9/2018	A8J0166-44	Lead	295	0.200	15	ppb
126-CH1899-A-002-A	Hallway 21	10/4/2018	10/9/2018	A8J0166-33	Copper	0.134	0.00200	1.3	ppm
126-CH1899-A-002-A	Hallway 21	10/4/2018	10/9/2018	A8J0166-33	Lead	3.09	0.200	15	ppb
126-CH1899-A-002-B	Hallway 21	10/4/2018	10/9/2018	A8J0166-34	Copper	0.233	0.00200	1.3	ppm
126-CH1899-A-002-B	Hallway 21	10/4/2018	10/9/2018	A8J0166-34	Lead	0.786	0.200	15	ppb

Analyzed by: Apex Laboratories

Reviewed by: PBS Engineering and Environmental

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

126-CH1899-B-002-A	Hallway 21	10/4/2018	10/9/2018	A8J0166-35	Copper	0.207	0.00200	1.3	ppm
126-CH1899-B-002-A	Hallway 21	10/4/2018	10/9/2018	A8J0166-35	Lead	0.405	0.200	15	ppb
126-CH1899-B-002-B	Hallway 21	10/4/2018	10/9/2018	A8J0166-36	Copper	0.258	0.00200	1.3	ppm
126-CH1899-B-002-B	Hallway 21	10/4/2018	10/9/2018	A8J0166-36	Lead	0.318	0.200	15	ppb
126-CH1900-A-002-A	Hallway 30A	10/4/2018	10/9/2018	A8J0166-37	Copper	0.0128	0.00200	1.3	ppm
126-CH1900-A-002-A	Hallway 30A	10/4/2018	10/9/2018	A8J0166-37	Lead	10.8	0.200	15	ppb
126-CH1900-A-002-B	Hallway 30A	10/4/2018	10/9/2018	A8J0166-38	Copper	0.0693	0.00200	1.3	ppm
126-CH1900-A-002-B	Hallway 30A	10/4/2018	10/9/2018	A8J0166-38	Lead	10.2	0.200	15	ppb
126-CH1900-B-002-A	Hallway 30A	10/4/2018	10/9/2018	A8J0166-39	Copper	0.0274	0.00200	1.3	ppm
126-CH1900-B-002-A	Hallway 30A	10/4/2018	10/9/2018	A8J0166-39	Lead	10.1	0.200	15	ppb
126-CH1900-B-002-B	Hallway 30A	10/4/2018	10/9/2018	A8J0166-40	Copper	0.0170	0.00200	1.3	ppm
126-CH1900-B-002-B	Hallway 30A	10/4/2018	10/9/2018	A8J0166-40	Lead	8.42	0.200	15	ppb
126-CH1900-C-002-A	Hallway 30A	10/4/2018	10/9/2018	A8J0166-41	Copper	0.0563	0.00200	1.3	ppm
126-CH1900-C-002-A	Hallway 30A	10/4/2018	10/9/2018	A8J0166-41	Lead	35.0	0.200	15	ppb
126-CH1900-C-002-B	Hallway 30A	10/4/2018	10/9/2018	A8J0166-42	Copper	0.0314	0.00200	1.3	ppm
126-CH1900-C-002-B	Hallway 30A	10/4/2018	10/9/2018	A8J0166-42	Lead	15.8	0.200	15	ppb
126-CH1913-NA-002-A	Hallway 11	10/4/2018	10/9/2018	A8J0166-31	Copper	0.0178	0.00200	1.3	ppm
126-CH1913-NA-002-A	Hallway 11	10/4/2018	10/9/2018	A8J0166-31	Lead	13.4	0.200	15	ppb
126-CH1913-NA-002-B	Hallway 11	10/4/2018	10/9/2018	A8J0166-32	Copper	0.0172	0.00200	1.3	ppm
126-CH1913-NA-002-B	Hallway 11	10/4/2018	10/9/2018	A8J0166-32	Lead	8.98	0.200	15	ppb

Analyzed by: Apex Laboratories

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Reviewed by: PBS Engineering and Environmental

126-CH1915-NA-002-A	Hall	10/4/2018	10/9/2018	A8J0166-01	Copper	0.588	0.00200	1.3	ppm
126-CH1915-NA-002-A	Hall	10/4/2018	10/9/2018	A8J0166-01	Lead	68.6	0.200	15	ppb
126-CH1915-NA-002-B	Hall	10/4/2018	10/9/2018	A8J0166-02	Copper	0.731	0.00200	1.3	ppm
126-CH1915-NA-002-B	Hall	10/4/2018	10/9/2018	A8J0166-02	Lead	18.9	0.200	15	ppb
126-CH1916-NA-002-A	Hall	10/4/2018	10/9/2018	A8J0166-03	Copper	0.333	0.00200	1.3	ppm
126-CH1916-NA-002-A	Hall	10/4/2018	10/9/2018	A8J0166-03	Lead	38.3	0.200	15	ppb
126-CH1916-NA-002-B	Hall	10/4/2018	10/9/2018	A8J0166-04	Copper	0.969	0.00200	1.3	ppm
126-CH1916-NA-002-B	Hall	10/4/2018	10/9/2018	A8J0166-04	Lead	64.3	0.200	15	ppb
126-CH1922-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-29	Copper	0.0247	0.00200	1.3	ppm
126-CH1922-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-29	Lead	8.46	0.200	15	ppb
126-CH1922-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-30	Copper	0.00992	0.00200	1.3	ppm
126-CH1922-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-30	Lead	0.387	0.200	15	ppb
126-CH1923-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-23	Copper	0.0157	0.00200	1.3	ppm
126-CH1923-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-23	Lead	0.264	0.200	15	ppb
126-CH1923-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-24	Copper	0.00888	0.00200	1.3	ppm
126-CH1923-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-24	Lead	ND	0.200	15	ppb
126-CH1924-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-25	Copper	0.0257	0.00200	1.3	ppm
126-CH1924-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-25	Lead	2.07	0.200	15	ppb
126-CH1924-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-26	Copper	0.0129	0.00200	1.3	ppm
126-CH1924-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-26	Lead	ND	0.200	15	ppb

Analyzed by: Apex Laboratories

Reviewed by: PBS Engineering and Environmental

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Page 3 of 5

126-CH1925-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-27	Copper	0.0268	0.00200	1.3	ppm
126-CH1925-NA-002-A	Gym	10/4/2018	10/9/2018	A8J0166-27	Lead	5.45	0.200	15	ppb
126-CH1925-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-28RE1	Copper	0.0166	0.00200	1.3	ppm
126-CH1925-NA-002-B	Gym	10/4/2018	10/9/2018	A8J0166-28RE1	Lead	1.41	0.200	15	ppb
126-CH1927-A-002-A	Hallway 132	10/4/2018	10/9/2018	A8J0166-17	Copper	0.468	0.00200	1.3	ppm
126-CH1927-A-002-A	Hallway 132	10/4/2018	10/9/2018	A8J0166-17	Lead	9.27	0.200	15	ppb
126-CH1927-A-002-B	Hallway 132	10/4/2018	10/9/2018	A8J0166-18	Copper	0.341	0.00200	1.3	ppm
126-CH1927-A-002-B	Hallway 132	10/4/2018	10/9/2018	A8J0166-18	Lead	7.00	0.200	15	ppb
126-CH1927-B-002-A	Hallway 132	10/4/2018	10/9/2018	A8J0166-19	Copper	0.0325	0.00200	1.3	ppm
126-CH1927-B-002-A	Hallway 132	10/4/2018	10/9/2018	A8J0166-19	Lead	5.76	0.200	15	ppb
126-CH1927-B-002-B	Hallway 132	10/4/2018	10/9/2018	A8J0166-20	Copper	0.0367	0.00200	1.3	ppm
126-CH1927-B-002-B	Hallway 132	10/4/2018	10/9/2018	A8J0166-20	Lead	4.56	0.200	15	ppb
126-CH1927-C-002-A	Hallway 132	10/4/2018	10/9/2018	A8J0166-21	Copper	0.0312	0.00200	1.3	ppm
126-CH1927-C-002-A	Hallway 132	10/4/2018	10/9/2018	A8J0166-21	Lead	9.40	0.200	15	ppb
126-CH1927-C-002-B	Hallway 132	10/4/2018	10/9/2018	A8J0166-22	Copper	0.0189	0.00200	1.3	ppm
126-CH1927-C-002-B	Hallway 132	10/4/2018	10/9/2018	A8J0166-22	Lead	3.78	0.200	15	ppb
126-CH1928-NA-002-A	Hall	10/4/2018	10/9/2018	A8J0166-05	Copper	0.248	0.00200	1.3	ppm
126-CH1928-NA-002-A	Hall	10/4/2018	10/9/2018	A8J0166-05	Lead	36.7	0.200	15	ppb
126-CH1928-NA-002-B	Hall	10/4/2018	10/9/2018	A8J0166-06	Copper	0.229	0.00200	1.3	ppm
126-CH1928-NA-002-B	Hall	10/4/2018	10/9/2018	A8J0166-06	Lead	25.1	0.200	15	ppb

Analyzed by: Apex Laboratories

Reviewed by: PBS Engineering and Environmental

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

126-CH1933-A-002-A	Hallway 216	10/4/2018	10/9/2018	A8J0166-07	Copper	0.147	0.00200	1.3	ppm
126-CH1933-A-002-A	Hallway 216	10/4/2018	10/9/2018	A8J0166-07	Lead	5.72	0.200	15	ppb
126-CH1933-A-002-B	Hallway 216	10/4/2018	10/9/2018	A8J0166-08	Copper	0.196	0.00200	1.3	ppm
126-CH1933-A-002-B	Hallway 216	10/4/2018	10/9/2018	A8J0166-08	Lead	5.95	0.200	15	ppb
126-CH1933-B-002-A	Hallway 216	10/4/2018	10/9/2018	A8J0166-09	Copper	0.127	0.00200	1.3	ppm
126-CH1933-B-002-A	Hallway 216	10/4/2018	10/9/2018	A8J0166-09	Lead	2.76	0.200	15	ppb
126-CH1933-B-002-B	Hallway 216	10/4/2018	10/9/2018	A8J0166-10	Copper	0.151	0.00200	1.3	ppm
126-CH1933-B-002-B	Hallway 216	10/4/2018	10/9/2018	A8J0166-10	Lead	0.921	0.200	15	ppb
126-CH1936-A-002-A	Hallway 236	10/4/2018	10/9/2018	A8J0166-11	Copper	0.0163	0.00200	1.3	ppm
126-CH1936-A-002-A	Hallway 236	10/4/2018	10/9/2018	A8J0166-11	Lead	5.21	0.200	15	ppb
126-CH1936-A-002-B	Hallway 236	10/4/2018	10/9/2018	A8J0166-12	Copper	0.0133	0.00200	1.3	ppm
126-CH1936-A-002-B	Hallway 236	10/4/2018	10/9/2018	A8J0166-12	Lead	7.21	0.200	15	ppb
126-CH1936-B-002-A	Hallway 236	10/4/2018	10/9/2018	A8J0166-13	Copper	0.0217	0.00200	1.3	ppm
126-CH1936-B-002-A	Hallway 236	10/4/2018	10/9/2018	A8J0166-13	Lead	9.38	0.200	15	ppb
126-CH1936-B-002-B	Hallway 236	10/4/2018	10/9/2018	A8J0166-14	Copper	0.0125	0.00200	1.3	ppm
126-CH1936-B-002-B	Hallway 236	10/4/2018	10/9/2018	A8J0166-14	Lead	7.85	0.200	15	ppb
126-CH1936-C-002-A	Hallway 236	10/4/2018	10/9/2018	A8J0166-15	Copper	0.0217	0.00200	1.3	ppm
126-CH1936-C-002-A	Hallway 236	10/4/2018	10/9/2018	A8J0166-15	Lead	11.9	0.200	15	ppb
126-CH1936-C-002-B	Hallway 236	10/4/2018	10/9/2018	A8J0166-16	Copper	0.00891	0.00200	1.3	ppm
126-CH1936-C-002-B	Hallway 236	10/4/2018	10/9/2018	A8J0166-16	Lead	5.71	0.200	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.