

**Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
Woodlawn**

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
294-CH3037-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-01	Copper	0.282	0.00100	1.3	ppm
294-CH3037-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-01	Lead	0.297	0.200	15	ppb
294-CH3037-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-02	Copper	0.310	0.00100	1.3	ppm
294-CH3037-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-02	Lead	ND	0.200	15	ppb
294-CH3040-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-03RE1	Copper	0.791	0.00500	1.3	ppm
294-CH3040-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-03	Lead	4.77	0.200	15	ppb
294-CH3040-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-04RE1	Copper	0.530	0.00500	1.3	ppm
294-CH3040-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-04	Lead	0.359	0.200	15	ppb
294-CH3043-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-05	Copper	0.472	0.00100	1.3	ppm
294-CH3043-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-05	Lead	46.6	0.200	15	ppb
294-CH3043-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-06	Copper	0.178	0.00100	1.3	ppm
294-CH3043-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-06	Lead	2.36	0.200	15	ppb
294-CH3046-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-07	Copper	0.298	0.00100	1.3	ppm
294-CH3046-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-07	Lead	8.28	0.200	15	ppb
294-CH3046-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-08	Copper	0.189	0.00100	1.3	ppm
294-CH3046-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-08	Lead	0.882	0.200	15	ppb

Analyzed by: Apex Laboratories

Reviewed by: PBS Engineering and Environmental

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Page 1 of 2

294-CH3047-N/A-001-A	all Water Bottle Fill	3/10/2018	3/22/2018	A8C0442-13	Copper	0.153	0.00100	1.3	ppm
294-CH3047-N/A-001-A	all Water Bottle Fill	3/10/2018	3/22/2018	A8C0442-13	Lead	1.18	0.200	15	ppb
294-CH3047-N/A-001-B	all Water Bottle Fill	3/10/2018	3/22/2018	A8C0442-14	Copper	0.124	0.00100	1.3	ppm
294-CH3047-N/A-001-B	all Water Bottle Fill	3/10/2018	3/22/2018	A8C0442-14	Lead	ND	0.200	15	ppb
294-CH3048-N/A-001-A	Cafeteria Bubbler	3/10/2018	3/22/2018	A8C0442-09RE1	Copper	0.673	0.00500	1.3	ppm
294-CH3048-N/A-001-A	Cafeteria Bubbler	3/10/2018	3/22/2018	A8C0442-09	Lead	54.6	0.200	15	ppb
294-CH3048-N/A-001-B	Cafeteria Bubbler	3/10/2018	3/22/2018	A8C0442-10RE1	Copper	1.86	0.00500	1.3	ppm
294-CH3048-N/A-001-B	Cafeteria Bubbler	3/10/2018	3/22/2018	A8C0442-10	Lead	6.08	0.200	15	ppb
294-CH3050-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-11	Copper	0.180	0.00100	1.3	ppm
294-CH3050-N/A-001-A	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-11	Lead	1.47	0.200	15	ppb
294-CH3050-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-12	Copper	0.115	0.00100	1.3	ppm
294-CH3050-N/A-001-B	Hall Bubbler	3/10/2018	3/22/2018	A8C0442-12	Lead	ND	0.200	15	ppb

Results highlighted yellow indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.