



**VENTURA UNIFIED SCHOOL DISTRICT
ROOFING REPLACEMENT AT ELMHURST ELEMENTARY SCHOOL**

BID # E18-24

April 1st , 2024

ADDENDUM #02

NOTICE TO BIDDERS:

The following revisions and/or clarifications shall be made to the bidding requirements and contract documents. Revise and amend the documents for the above-named project in accordance with this addendum. The bid shall reflect these addendum changes and each bidder shall refer in their bid to this addendum.

All bidding requirements and contract documents shall apply to this addendum as originally indicated in the applicable portions of the contract documents, unless otherwise modified by this addendum.

Contractors shall acknowledge this addendum at the space provided on the Bid Proposal.

REVISIONS, CLARIFICATIONS, & RESPONSES TO PRE-BID RFI'S:

1. Review attached findings regarding the roofing at Elmhurst Elementary School, confirming penetration mastic contains asbestos (Final report not yet received and will be provided to awarded contractor). Contractor is responsible to provide all required removal and abatement of asbestos-containing material in bid, following all applicable codes, regulations, and safety standards. A certified hazardous-material removal firm will be required for proper reporting, removal and disposal of hazardous material.
2. Prequalification in Quality Bidders is not required for this project.

REVISIONS TO THE PLANS: Not Applicable

REVISIONS TO THE SPECIFICATIONS: Not Applicable

REVISED DOCUMENTS ATTACHED AT END OF ADDENDUM #02

Addendum: 2 Pages

ENCLOSURES: 4 Pages

Total Number of Pages: 6 Pages



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322408012

Customer ID: 32ETAS62

Customer PO:

Project ID:

Attention: Kevin Riley

Environmental Testing Associates

850 Hampshire Rd

Suite G

Westlake Village, CA 91361

Project: ELMHURST ELEMENTARY SCHOOL Roofing Project - VENTURA UNIFIED SCHOOL DISTRICT/ 5080
Elmhurst Street Ventura, CA 93003

Phone: (805) 497-7499

Fax: (805) 497-7477

Received Date: 03/29/2024 8:00 AM

Analysis Date: 03/29/2024

Collected Date: 03/28/2024

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A1-Felt/Tar 1 322408012-0001	Roofing Materials	Brown/Black Fibrous Heterogeneous	15% Cellulose	85% Non-fibrous (Other)	None Detected
A1-Felt/Tar 2 322408012-0001A	Roofing Materials	Brown/Black Fibrous Heterogeneous	15% Glass	85% Non-fibrous (Other)	None Detected
A1-Tar 322408012-0001B	Roofing Materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A2-Felt 322408012-0002	Roofing Materials	Brown/Black Fibrous Heterogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
A2-Tar 322408012-0002A	Roofing Materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A3-Felt/Tar 1 322408012-0003	Roofing Materials	Brown/Black Fibrous Heterogeneous	15% Cellulose	85% Non-fibrous (Other)	None Detected
A3-Felt/Tar 2 322408012-0003A Unable to separate	Roofing Materials	Brown/Black Fibrous Heterogeneous	15% Glass	85% Non-fibrous (Other)	None Detected
A4-Felt 322408012-0004	Roofing Materials	Black Non-Fibrous Homogeneous	20% Glass	80% Non-fibrous (Other)	None Detected
A4-Tar 322408012-0004A	Roofing Materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A5-Felt 322408012-0005	Roofing Materials	Black Fibrous Homogeneous	20% Glass	80% Non-fibrous (Other)	None Detected
A5-Tar 322408012-0005A	Roofing Materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A6-Felt/Tar 1 322408012-0006 Unable to separate	Roofing Materials	Brown/Black Fibrous Heterogeneous	15% Cellulose	85% Non-fibrous (Other)	None Detected
A6-Felt/Tar 2 322408012-0006A Unable to separate	Roofing Materials	Brown/Black Fibrous Heterogeneous	15% Glass	85% Non-fibrous (Other)	None Detected
A7-Felt 322408012-0007	Roofing Materials	Brown/Black Fibrous Heterogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
A7-Tar 322408012-0007A	Roofing Materials	Black Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 03/29/2024 16:33:15



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@lateesting.com

LA Testing Order: 322408012

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A8-Felt 322408012-0008	Roofing Materials	Brown/Black Fibrous Heterogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
A8-Tar 322408012-0008A	Roofing Materials	Black Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
A9-Felt 322408012-0009	Roofing Materials	Black Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
A9-Tar 322408012-0009A	Roofing Materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A10 322408012-0010	Penetration Mastic	Black Fibrous Heterogeneous	45% Cellulose	55% Non-fibrous (Other)	None Detected
A11 322408012-0011	Penetration Mastic	Black/Silver Fibrous Heterogeneous	40% Cellulose	58% Non-fibrous (Other)	2% Chrysotile
A12 322408012-0012	Penetration Mastic				Positive Stop (Not Analyzed)
A13 322408012-0013	Penetration Mastic				Positive Stop (Not Analyzed)
A14 322408012-0014	Penetration Mastic				Positive Stop (Not Analyzed)
A15 322408012-0015	Penetration Mastic				Positive Stop (Not Analyzed)
A16 322408012-0016	Penetration Mastic				Positive Stop (Not Analyzed)
A17 322408012-0017	Penetration Mastic				Positive Stop (Not Analyzed)
A18 322408012-0018	Penetration Mastic				Positive Stop (Not Analyzed)

Analyst(s)

Caleb Elquezabal (6)

Alexis Payan (15)

Jerry Drapala Ph.D, Laboratory Manager
or Other Approved Signatory

LA Testing maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by LA Testing. LA Testing bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore LA Testing recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by LA Testing South Pasadena, CA NVLAP Lab Code 200232-0, CA ELAP 2283

Initial report from: 03/29/2024 16:33:15

#322408012



CHAIN OF CUSTODY

L.A. TESTING

520 Mission Street, South Pasadena, CA

Phone: 800.303.0047

Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ELMHURST ELEMENTARY SCHOOL Roofing Project- VENTURA UNIFIED SCHOOL DISTRICT Inspector: Kevin Riley Date: 03/28/2024Project Address: 5080 Elmhurst Street Ventura, CA 93003Client Name: VENTURA UNIFIED SCHOOL DISTRICTContact # Ryan Hughes 805.901.9620Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	H/T
A1	ROOFING MATERIALS	G/D/SD	510.21 17	PLM	See map	NK
A2		G/D/SD		PLM		
A3		G/D/SD		PLM		
A4		G/D/SD		PLM		
A5		G/D/SD		PLM		
A6		G/D/SD		PLM		
A7		G/D/SD		PLM		
A8		G/D/SD		PLM		
A9		G/D/SD		PLM		

Relinquished by: Kevin Riley

Kevin Riley CAC-17-5871

DATE: 3-28-24 TIME: 7:11 ☐ Sent Via FedEx ☒ Hand Delivered to LabReceived by: Rachel Rangel (DB)

Name (please print)

Signature

DATE: 3/29/24 TIME: 8:00

Requested Analysis Circle one:

6 Hour

Page 1 of 2



#322408012

CHAIN OF CUSTODY

L.A. TESTING

520 Mission Street, South Pasadena, CA

Phone: 800.303.0047

Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ELMHURST ELEMENTARY SCHOOL Roofing Project- VENTURA UNIFIED SCHOOL DISTRICT Inspector: Kevin Riley Date: 03/28/2024Project Address: 5080 Elmhurst Street Ventura, CA 93003Client Name: VENTURA UNIFIED SCHOOL DISTRICTContact # Ryan Hughes 805.901.9620Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	H/T
510 A10	PENETRATION MASTIC	G/D/SD	2 K14	PLM	SSE amp	NK
A11		G/D/SD		PLM		
A12		G/D/SD		PLM		
A13		G/D/SD		PLM		
A14		G/D/SD		PLM		
A15		G/D/SD		PLM		
A16		G/D/SD		PLM		
A17		G/D/SD		PLM		
A18		G/D/SD		PLM		

Relinquished by: [Signature]DATE: 3/29/24 TIME: 7:00☐ Sent Via FedEx ☒ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Rachel Kangel (DB)[Signature]
SignatureDATE: 3/29/24 TIME: 8:00

Name (please print)

Requested Analysis Circle one:

6 Hour

Page 2 of 2