

LAKE VIEW ELEMENTARY

16401 SE 318TH ST, AUBURN



SAFETY, SECURITY & FACILITY PLANNED IMPROVEMENTS: **\$7,718,813**

-  Install secure badge access systems at all exterior primary access doors
-  Install secure vestibule entry
-  Replace/expand fencing
-  Upgrade door lock hardware
-  Replace fire sprinkler piping
-  Replace flooring
-  Replace heating coils
-  Add air conditioning to building

SCHOOL SITE INFORMATION:



Year Built - 1980



Site Size - 16.48 acres



Building Capacity - 419



Portable Classrooms - 0

TECHNOLOGY REPLACEMENT LEVY

-  Student 1:1 classroom devices
-  Teacher computer devices & training
-  Classroom technology
-  Educational software licensing
-  Digital citizenship
-  Cyber security protection
-  Assistive technology for students with disabilities
-  Installation of safety cameras in hallways

KEY:

- | | |
|---|---|
|  Major Maintenance |  Enhancement/Maintenance |
|  Safety/Security |  ADA Requirement |
|  Energy Sustainability |  Technology |