January 16th, 2024

Dear Parents and Guardians,

We are writing to let you know that the Timberland High School recently completed testing for lead in drinking water. This is part of an ongoing effort related to New Hampshire's House Bill 1421, which requires school and child care facilities to test for lead in drinking water and to act when lead is found at levels at or above 5 parts per billion (ppb).

Lead is a toxic heavy metal that has a range of adverse health effects if inhaled or swallowed. Lead typically enters drinking water due to the wearing away of piping, faucets, fixtures and other plumbing materials. Lead rarely occurs naturally in New Hampshire's drinking water sources (groundwater or surface water).

Because lead is tasteless, odorless and colorless in drinking water, testing is a way to learn whether lead is present. It is important to sample each faucet or water fountain that is used for drinking or food prep because test results can vary between locations.

During recent testing, we collected samples from **77** drinking water outlets (e.g., drinking fountains, classroom faucets, kitchen sinks), with **3** samples testing at or above 5 ppb, the level where action must be taken

We have removed access to these outlets until the problem can be corrected. The table below shows a list of all of the tested outlets, their locations, sample results and our planned remediation.

All sample results and additional resources from the New Hampshire Department of Environmental Services (NHDES) can be viewed at gettheleadoutnh.org.

Sincerely,

Sarah Draper
Certified Public Water Systems Operator
Secondwind Water Systems
735 East Industrial Park Drive
Manchester, NH 03109
603-641-5767

Outlet Number	Location	Sample Result (ppb)	Planned Remediation
275	300 Hallway Bottle Filler By Gym	<1	No Remediation Necessary
276	400 Girls RR Left	<1	No Remediation Necessary
277	400 Girls RR Right	1.4	No Remediation Necessary
278	400 Hallway Admin Kitchen	1.1	No Remediation Necessary
279	400 Hallway All Gender	<1	No Remediation Necessary
280	400 Hallway Bottle Filler By Custodian	<1	No Remediation Necessary
281	400 Hallway Bottle Filler By Restrooms	<1	No Remediation Necessary
282	400 Hallway Staff Bath	1.3	No Remediation Necessary
283	402 Sink 1	<1	No Remediation Necessary
284	402 Sink 2	<1	No Remediation Necessary
285	402 Sink 3	<1	No Remediation Necessary
286	402 Sink 4	<1	No Remediation Necessary
287	402 Sink 5	<1	No Remediation Necessary
288	503 Left	<1	No Remediation Necessary
289	504 Middle	<1	No Remediation Necessary
290	600 Hallway All Gender Left	2.4	No Remediation Necessary
291	600 Hallway All Gender Right	1.8	No Remediation Necessary
292	600 Hallway Battle Filler	<1	No Remediation Necessary
293	600 Hallway Boys Left	1.5	No Remediation Necessary
294	600 Hallway Boys Right	1.6	No Remediation Necessary
295	600 Hallway Custodian	15.7	Permanently Post Non Potable/ Hand Wash Only
296	700-1 PAC Bottle Filler	<1	No Remediation Necessary
297	900-1 PAC Bubbler	<1	No Remediation Necessary

Outlet Number	Location	Sample Result (ppb)	Planned Remediation
298	709-1	2.0	No Remediation Necessary
299	709-3	1.1	No Remediation Necessary
300	709-4	<1	No Remediation Necessary
301	709-5	11.7	Permanently Post Non Potable/ Hand Wash Only
302	711-1	<1	No Remediation Necessary
303	711-2	<1	No Remediation Necessary
304	711-3	4.3	No Remediation Necessary
305	711-4	3.3	No Remediation Necessary
306	713-1	<1	No Remediation Necessary
307	714-1	1.8	No Remediation Necessary
308	Boys Bath B9 Center	<1	No Remediation Necessary
309	Boys Bath B9 Left	<1	No Remediation Necessary
310	Boys Bath B9 Right	<1	No Remediation Necessary
311	Boys Locker Left By B12 Door	1.4	No Remediation Necessary
312	Boys Locker Right by B12 Door	1.5	No Remediation Necessary
313	Boys Locker Right Team	1.4	No Remediation Necessary
314	Boys PE Locker Left	<1	No Remediation Necessary
315	Boys PE Locker Right	1.4	No Remediation Necessary
316	Boys Room Across 305	<1	No Remediation Necessary
317	Boys Sink Center By Door 17	<1	No Remediation Necessary
318	Boys Sink Left By Door 17	<1	No Remediation Necessary
319	Boys Sink Right By Door 17	<1	No Remediation Necessary
320	Bottle Filler By Door 17	<1	No Remediation Necessary
321	Bubbler Across Room 305	<1	No Remediation Necessary

Outlet Number	Location	Sample Result (ppb)	Planned Remediation
322	Bubbler Hallway by Door 17	<1	No Remediation Necessary
323	Girls Bath Across 305 Right	<1	No Remediation Necessary
324	Girls Bath Across 305 Left	5.0	Permanently Post Non Potable/ Hand Wash Only
325	Girls Bath B9 1	<1	No Remediation Necessary
326	Girls Bath B9 2	<1	No Remediation Necessary
327	Girls Bath B9 3	<1	No Remediation Necessary
328	Girls Bath B9 4	1.1	No Remediation Necessary
329	Girls Coaches Bath	<1	No Remediation Necessary
330	Girls Locker Left By B12 Door	<1	No Remediation Necessary
331	Girls Locker Right by B12 Door	<1	No Remediation Necessary
332	Girls PE Locker Sink Gym Side	1.0	No Remediation Necessary
333	Girls PE Locker Sink Hallway Side	3.8	No Remediation Necessary
334	Girls Sink Center by Door 17	<1	No Remediation Necessary
335	Girls Sink Left by Door 17	<1	No Remediation Necessary
336	Girls Sink Right by Door 17	<1	No Remediation Necessary
337	Gym Bottle Filler Adj B9 Door	<1	No Remediation Necessary
338	Kitchen 2 Bay	1.2	No Remediation Necessary
339	Kitchen 4 Bay Left	1.5	No Remediation Necessary
340	Kitchen 4 Bay Right	1.2	No Remediation Necessary
341	Kitchen Hand Wash	<1	No Remediation Necessary
342	Kitchen Pot Filler	<1	No Remediation Necessary
343	Kitchen Skillet Filler	3.3	No Remediation Necessary
344	Kitchen Wash Sink	<1	No Remediation Necessary
345	Men’s Faculty Bath Adj Library	1.2	No Remediation Necessary

Outlet Number	Location	Sample Result (ppb)	Planned Remediation
346	Nurse Left	2.2	No Remediation Necessary
347	Nurse Right	1.2	No Remediation Necessary
348	Room 324	1.4	No Remediation Necessary
349	Room 326	<1	No Remediation Necessary
350	Special Ed RR	4.6	No Remediation Necessary
351	Women's Faculty Bath Adj Library	<1	No Remediation Necessary