

ARAM Environmental Testing

PO Box 114
Manville RI. 02838
401-256-7446

Att: Gene Jones
135 Marion Rd.
Mattapoisett, MA 02739

Project No: OH 82724-02

Old Hammondtown School
20 Shaw St.
Mattapoisett MA

RESULTS SUMMARY

On September 08 and September 23, 2025, Environmental Consultant Daniel J. McGrath from ARAM Env. Testing performed Air-O-Cell air sampling with direct examination analysis as well as visuals for mold at the Old Hammondtown Elem. School. After one reclean, the highest Total Fungi Raw count collected indoor was 205 and was collected in the music room. All other areas tested fell well below that level. Most Current EPA guidelines state that any indoor Total Fungi Raw count that is 100 above the outdoor control level, constitutes a mold issue. The day of testing, the outside Total Fungi Raw count was 1,323. All other areas tested were substantially lower. At this time, in all areas tested, there are no areas which constitute an EPA guideline mold issue.

If you were to follow the American Industrial Hygiene Association's (AIHA) recommendation, a count equal to or over of 10,000 s/m³ is considered "probable contamination". The highest count indoor was below their guideline as a contaminated area. The total sample was 8,310 s/m³. At this time the music room is not considered as having a mold issue. The total outdoor sample result the day of testing was 54,070 s/3.

A total of thirteen (13) air-o-cell samples were collected. The areas tested include hallways, classrooms, and other common areas. The areas tested are considered a good overall representation of the building. Two (2) outdoor sample was collected for a control level comparison.

It is the opinion of ARAM Environmental Testing that the according to the lab results and visual inspection, the school is currently suitable for occupancy.

RECOMMENDATIONS

After reviewing the lab report from EMSL, as well as my visual inspection, my recommendations are as follows:

At this time, there are no issues that must be addressed.

Although mold is a naturally occurring event and there is no way to guarantee a mold-free environment without taking extraordinary housekeeping, mechanical, and HVAC related measures, the recommendations below, will guarantee a much safer environment.

ANY FUTURE WATER INTRUSION ISSUES MUST BE SOLVED IMMEDIATELY.

Any wetted or stained ceiling tiles, cardboard boxes or paperwork should be removed from the area immediately .

Any standing water should be vacuumed immediately.

All surfaces and remaining items should be HEPA-vacuumed, cleaned with a fungicide mold cleaner and HEPA-vacuumed again.

Any areas affected should be misted and encapsulated to eliminate airborne mold spores.

This should be done by a mold remediation contractor under negative pressure.

Relative humidity levels should be kept no higher than 45%.

Daniel J. McGrath
ARAM Environmental Testing