

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882352	Test Start :	12/02/2025 @ 05:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:21
Location :	1st FL = Main Office	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:43
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4881390	Test Start :	12/02/2025 @ 05:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:23
Location :	1st FL=Athletics-1	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:43
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881456	Test Start :	12/02/2025 @ 05:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:24
Location :	1st FL=Athletics-2	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 16:19
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4882436	Test Start :	12/02/2025 @ 05:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:22
Location :	1st FL = A-17	Received:	12/08/2025 @ 15:27
Radon Level :	1.9 pCi/L	Analyzed:	12/09/2025 @ 12:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881420	Test Start :	12/02/2025 @ 05:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL=Athletics-3	Received:	12/08/2025 @ 15:26
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 14:35
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881434	Test Start :	12/02/2025 @ 05:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:25
Location :	1st FL=Athletics-4	Received:	12/08/2025 @ 15:26
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 15:58
Error for Measurement is: $\pm$	0.4 pCi/L		



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882398	Test Start :	12/02/2025 @ 05:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:24
Location :	1st FL = A-15	Received:	12/08/2025 @ 15:27
Radon Level :	0.5 pCi/L	Analyzed:	12/09/2025 @ 13:45
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883906	Test Start :	12/02/2025 @ 05:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:24
Location :	1st FL = A-16	Received:	12/08/2025 @ 15:27
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 12:31
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881442	Test Start :	12/02/2025 @ 05:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:27
Location :	1st FL=Athletics-5	Received:	12/08/2025 @ 15:26
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 14:53
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883502	Test Start :	12/02/2025 @ 05:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:30
Location :	1st FL=Auditorium-1	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 13:47
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4882803	Test Start :	12/02/2025 @ 05:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:24
Location :	1st FL = H-01	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:25
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881336	Test Start :	12/02/2025 @ 05:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:24
Location :	1st FL=Student Svcs.	Received:	12/08/2025 @ 15:26
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 14:04
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883482	Test Start :	12/02/2025 @ 05:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:31
Location :	1st FL=Auditorium-2	Received:	12/08/2025 @ 15:27
Radon Level :	0.5 pCi/L	Analyzed:	12/09/2025 @ 12:22
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4882404	Test Start :	12/02/2025 @ 05:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:24
Location :	1st FL = A-13/BL	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 13:34
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882400	Test Start :	12/02/2025 @ 05:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:26
Location :	1st FL = A-13	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 11:43
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882346	Test Start :	12/02/2025 @ 05:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:26
Location :	1st FL = A-14	Received:	12/08/2025 @ 15:26
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 14:46
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4883566	Test Start :	12/02/2025 @ 05:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:32
Location :	1st FL=Auditorium-3	Received:	12/08/2025 @ 15:27
Radon Level :	1.4 pCi/L	Analyzed:	12/09/2025 @ 11:41
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882349	Test Start :	12/02/2025 @ 05:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:25
Location :	1st FL=Student Store	Received:	12/08/2025 @ 15:26
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4881423	Test Start :	12/02/2025 @ 05:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:27
Location :	1st FL=Athletics-6	Received:	12/08/2025 @ 15:26
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883543	Test Start :	12/02/2025 @ 05:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:33
Location :	1st FL=Auditorium-4	Received:	12/08/2025 @ 15:27
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 12:23
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881457	Test Start :	12/02/2025 @ 05:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:25
Location :	1st FL = A-12	Received:	12/08/2025 @ 15:27
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 13:00
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881391	Test Start :	12/02/2025 @ 05:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:26
Location :	1st FL = H-01/Office	Received:	12/08/2025 @ 15:27
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 13:23
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881454	Test Start :	12/02/2025 @ 05:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:28
Location :	1st FL=Athletics-7	Received:	12/08/2025 @ 15:26
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883530	Test Start :	12/02/2025 @ 05:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:34
Location :	1st FL = Stage	Received:	12/08/2025 @ 15:26
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 14:08
Error for Measurement is: ±	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882373	Test Start :	12/02/2025 @ 05:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:28
Location :	1st FL = A-11	Received:	12/08/2025 @ 15:27
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 12:48
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881435	Test Start :	12/02/2025 @ 05:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL=Athletics-8/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 14:45
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882383	Test Start :	12/02/2025 @ 05:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL=Athletics-8/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.4 pCi/L	Analyzed:	12/09/2025 @ 15:14

Average of Side by Side Canisters 1.3 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4883549	Test Start :	12/02/2025 @ 05:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:36
Location :	1st FL = Stage/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 16:00
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883561	Test Start :	12/02/2025 @ 05:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:36
Location :	1st FL = Stage/DP	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 14:25

Average of Side by Side Canisters 1.0 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882473	Test Start :	12/02/2025 @ 05:36
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:28
Location :	1st FL = A-10	Received:	12/08/2025 @ 15:27
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 13:55
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881337	Test Start :	12/02/2025 @ 05:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL = A-08	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 11:41
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882456	Test Start :	12/02/2025 @ 05:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL = A-09	Received:	12/08/2025 @ 15:27
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 12:21
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881370	Test Start :	12/02/2025 @ 05:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL = H-02/DP	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 14:04
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882783	Test Start :	12/02/2025 @ 05:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL = H-02/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 12:39

Average of Side by Side Canisters 0.6 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881509	Test Start :	12/02/2025 @ 05:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:29
Location :	1st FL=Athletics/BL	Received:	12/08/2025 @ 15:26
Radon Level :	0.1 pCi/L	Analyzed:	12/09/2025 @ 14:45

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4882386
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = FA-01
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 05:37
Test Stop : 12/04/2025 @ 06:37
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:10

Canister ID# : 4882468
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = A-07
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 05:38
Test Stop : 12/04/2025 @ 06:31
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:48

Canister ID# : 4883904
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = FA-09
Radon Level : 40.0 pCi/L
Error for Measurement is: $\pm$ 1.0 pCi/L

Test Start : 12/02/2025 @ 05:39
Test Stop : 12/04/2025 @ 06:39
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:43

Canister ID# : 4881400
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = FA-03/DP
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 05:39
Test Stop : 12/04/2025 @ 06:40
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:01

Canister ID# : 4883528
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = FA-03/DP
Radon Level : 0.3 pCi/L

Test Start : 12/02/2025 @ 05:39
Test Stop : 12/04/2025 @ 06:40
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:25

Average of Side by Side Canisters 0.6 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882379	Test Start :	12/02/2025 @ 05:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:31
Location :	1st FL = A-20	Received:	12/08/2025 @ 15:27
Radon Level :	1.7 pCi/L	Analyzed:	12/09/2025 @ 12:22
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4882421	Test Start :	12/02/2025 @ 05:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:40
Location :	1st FL = FA-10	Received:	12/08/2025 @ 15:27
Radon Level :	42.2 pCi/L	Analyzed:	12/09/2025 @ 12:23
Error for Measurement is: ±	1.0 pCi/L		

Canister ID# :	4883534	Test Start :	12/02/2025 @ 05:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:41
Location :	1st FL = Office-A	Received:	12/08/2025 @ 15:26
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4882351	Test Start :	12/02/2025 @ 05:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:30
Location :	1st FL = H-03	Received:	12/08/2025 @ 15:27
Radon Level :	0.2 pCi/L	Analyzed:	12/09/2025 @ 13:56
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4882347	Test Start :	12/02/2025 @ 05:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:32
Location :	1st FL=Off.Outside H-03	Received:	12/08/2025 @ 15:27
Radon Level :	0.3 pCi/L	Analyzed:	12/09/2025 @ 13:25
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881510	Test Start :	12/02/2025 @ 05:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:35
Location :	1st FL = A-19/DP	Received:	12/08/2025 @ 15:27
Radon Level :	1.5 pCi/L	Analyzed:	12/09/2025 @ 13:45
Error for Measurement is: ±	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882348	Test Start :	12/02/2025 @ 05:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:35
Location :	1st FL = A-19/DP	Received:	12/08/2025 @ 15:27
Radon Level :	1.7 pCi/L	Analyzed:	12/09/2025 @ 12:43

Average of Side by Side Canisters 1.6 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	4881460	Test Start :	12/02/2025 @ 05:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:42
Location :	1st FL = Office-B	Received:	12/08/2025 @ 15:26
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 14:43

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881406	Test Start :	12/02/2025 @ 05:43
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:53
Location :	1st FL = Office-C	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:22

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	4881421	Test Start :	12/02/2025 @ 05:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:33
Location :	1st FL = A-22/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 14:08

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	4881450	Test Start :	12/02/2025 @ 05:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:33
Location :	1st FL = A-22/DP	Received:	12/08/2025 @ 15:27
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 12:22

Average of Side by Side Canisters 1.2 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882414	Test Start :	12/02/2025 @ 05:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:34
Location :	1st FL = A-21	Received:	12/08/2025 @ 15:27
Radon Level :	1.4 pCi/L	Analyzed:	12/09/2025 @ 13:15
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883533	Test Start :	12/02/2025 @ 05:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:44
Location :	1st FL = FA-04#1	Received:	12/08/2025 @ 15:26
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	4881405	Test Start :	12/02/2025 @ 05:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:45
Location :	1st FL = FA-04#2	Received:	12/08/2025 @ 15:27
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 13:27
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4881451	Test Start :	12/02/2025 @ 05:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:33
Location :	1st FL = H-04	Received:	12/08/2025 @ 15:27
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 12:43
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4882360	Test Start :	12/02/2025 @ 05:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:36
Location :	1st FL = A-23	Received:	12/08/2025 @ 15:27
Radon Level :	1.6 pCi/L	Analyzed:	12/09/2025 @ 13:07
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4882314	Test Start :	12/02/2025 @ 05:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:36
Location :	1st FL = Lobby	Received:	12/08/2025 @ 15:26
Radon Level :	1.6 pCi/L	Analyzed:	12/09/2025 @ 15:15
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883603	Test Start :	12/02/2025 @ 05:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:46
Location :	1st FL = FA-05	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 15:06
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881379	Test Start :	12/02/2025 @ 05:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:56
Location :	1st FL=Commons-1	Received:	12/08/2025 @ 15:26
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 14:45
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881403	Test Start :	12/02/2025 @ 05:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:37
Location :	1st FL = A-24	Received:	12/08/2025 @ 15:27
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 13:15
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883509	Test Start :	12/02/2025 @ 05:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:47
Location :	1st FL = FA-06	Received:	12/08/2025 @ 15:26
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 14:47
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4881357	Test Start :	12/02/2025 @ 05:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:56
Location :	1st FL=Commons-2	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:27
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4882315	Test Start :	12/02/2025 @ 05:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:35
Location :	1st FL = H-05	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:56
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882411	Test Start :	12/02/2025 @ 05:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:37
Location :	1st FL = A-26	Received:	12/08/2025 @ 15:27
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 12:43
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883523	Test Start :	12/02/2025 @ 05:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:48
Location :	1st FL = FA-06/BL	Received:	12/08/2025 @ 15:26
Radon Level :	0.3 pCi/L	Analyzed:	12/09/2025 @ 14:14
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881404	Test Start :	12/02/2025 @ 05:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:56
Location :	1st FL=Commons-3	Received:	12/08/2025 @ 15:26
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 14:27
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882378	Test Start :	12/02/2025 @ 05:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:38
Location :	1st FL = A-27	Received:	12/08/2025 @ 15:27
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 12:00
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883582	Test Start :	12/02/2025 @ 05:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:49
Location :	1st FL = FA-07	Received:	12/08/2025 @ 15:26
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 16:08
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881438	Test Start :	12/02/2025 @ 05:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:40
Location :	1st FL = A-25	Received:	12/08/2025 @ 15:27
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 12:43
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882392	Test Start :	12/02/2025 @ 05:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:40
Location :	1st FL = A-25.1	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883546	Test Start :	12/02/2025 @ 05:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:50
Location :	1st FL = FA-08	Received:	12/08/2025 @ 15:26
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 16:19
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882376	Test Start :	12/02/2025 @ 05:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:59
Location :	1st FL = Media Ctr.-1	Received:	12/08/2025 @ 15:26
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 16:19
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4881384	Test Start :	12/02/2025 @ 05:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:59
Location :	1st FL = Media Ctr.-2	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 16:20
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4881368	Test Start :	12/02/2025 @ 05:51
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:36
Location :	1st FL = H-06	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 13:45
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881364	Test Start :	12/02/2025 @ 05:51
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:40
Location :	1st FL = A-28/DP	Received:	12/08/2025 @ 15:27
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 13:23
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882422	Test Start :	12/02/2025 @ 05:51
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:40
Location :	1st FL = A-28/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 13:45

Average of Side by Side Canisters 1.0 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	4881459	Test Start :	12/02/2025 @ 05:51
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:59
Location :	1st FL = Media Ctr.-3	Received:	12/08/2025 @ 15:26
Radon Level :	1.6 pCi/L	Analyzed:	12/09/2025 @ 15:58

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881440	Test Start :	12/02/2025 @ 05:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:37
Location :	1st FL = H-07	Received:	12/08/2025 @ 15:26
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 14:05

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882475	Test Start :	12/02/2025 @ 05:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:41
Location :	1st FL = A-29	Received:	12/08/2025 @ 15:27
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 12:00

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881428	Test Start :	12/02/2025 @ 05:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:59
Location :	1st FL = Media Ctr.-4	Received:	12/08/2025 @ 15:26
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 13:47

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881407	Test Start :	12/02/2025 @ 05:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:03
Location :	1st FL = M-01/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.5 pCi/L	Analyzed:	12/09/2025 @ 14:43

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882367	Test Start :	12/02/2025 @ 05:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:03
Location :	1st FL = M-01/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 14:53

Average of Side by Side Canisters 1.3 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881374	Test Start :	12/02/2025 @ 05:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:39
Location :	1st FL = H-08	Received:	12/08/2025 @ 15:27
Radon Level :	0.1 pCi/L	Analyzed:	12/09/2025 @ 13:45

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881444	Test Start :	12/02/2025 @ 05:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:41
Location :	1st FL = A-31	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:40

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881387	Test Start :	12/02/2025 @ 05:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:01
Location :	1st FL=Media Ctr/Comp. Rm	Received:	12/08/2025 @ 15:26
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 15:58

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881433	Test Start :	12/02/2025 @ 05:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:04
Location :	1st FL = M-03/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 16:19

Error for Measurement is: $\pm$ 0.5 pCi/L

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882369	Test Start :	12/02/2025 @ 05:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:04
Location :	1st FL = M-03/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.4 pCi/L	Analyzed:	12/09/2025 @ 16:00

Average of Side by Side Canisters 1.3 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881360	Test Start :	12/02/2025 @ 05:54
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:42
Location :	1st FL = H-09/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:01

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	4882888	Test Start :	12/02/2025 @ 05:54
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:42
Location :	1st FL = H-09/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.3 pCi/L	Analyzed:	12/09/2025 @ 13:07

Average of Side by Side Canisters 0.6 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882368	Test Start :	12/02/2025 @ 05:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:41
Location :	1st FL = A-30	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:02

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882428	Test Start :	12/02/2025 @ 05:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:43
Location :	1st FL = A-32	Received:	12/08/2025 @ 15:27
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 13:07

Error for Measurement is: $\pm$ 0.4 pCi/L*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882361	Test Start :	12/02/2025 @ 05:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:04
Location :	1st FL = M-02	Received:	12/08/2025 @ 15:26
Radon Level :	0.2 pCi/L	Analyzed:	12/09/2025 @ 14:45
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881429	Test Start :	12/02/2025 @ 05:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:04
Location :	1st FL = M-02/BL	Received:	12/08/2025 @ 15:26
Radon Level :	1.4 pCi/L	Analyzed:	12/09/2025 @ 16:20
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4881396	Test Start :	12/02/2025 @ 05:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:45
Location :	1st FL = H-10A	Received:	12/08/2025 @ 15:26
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 15:04
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4882355	Test Start :	12/02/2025 @ 06:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:42
Location :	1st FL = A-04	Received:	12/08/2025 @ 15:26
Radon Level :	0.3 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4881401	Test Start :	12/02/2025 @ 06:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:42
Location :	1st FL = A-04/BL	Received:	12/08/2025 @ 15:27
Radon Level :	0.1 pCi/L	Analyzed:	12/09/2025 @ 12:01
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4882350	Test Start :	12/02/2025 @ 06:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:47
Location :	1st FL = H-10B	Received:	12/08/2025 @ 15:27
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 13:15
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4881449	Test Start :	12/02/2025 @ 06:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:42
Location :	1st FL = TA-11	Received:	12/08/2025 @ 15:26
Radon Level :	0.1 pCi/L	Analyzed:	12/09/2025 @ 14:35
Error for Measurement is: $\pm$	0.1 pCi/L		

Canister ID# :	4882474	Test Start :	12/02/2025 @ 06:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:49
Location :	1st FL = A-05	Received:	12/08/2025 @ 15:27
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 11:41
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882377	Test Start :	12/02/2025 @ 06:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:42
Location :	1st FL = TA-11/BL	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:25
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883888	Test Start :	12/02/2025 @ 06:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:47
Location :	1st FL = H-10C	Received:	12/08/2025 @ 15:26
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 14:14
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881399	Test Start :	12/02/2025 @ 06:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:49
Location :	1st FL = A-06	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:23
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882381	Test Start :	12/02/2025 @ 06:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:49
Location :	1st FL = A-06.1	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:07
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882345	Test Start :	12/02/2025 @ 06:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:43
Location :	1st FL = TA-12/DP	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 16:08
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4882370	Test Start :	12/02/2025 @ 06:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:43
Location :	1st FL = TA-12/DP	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 16:00

Average of Side by Side Canisters 0.8 pCi/L

Error for Measurement is: ± 0.4 pCi/L

Canister ID# :	4882434	Test Start :	12/02/2025 @ 06:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:48
Location :	1st FL = H-10D	Received:	12/08/2025 @ 15:26
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 14:07
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4881409	Test Start :	12/02/2025 @ 06:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:44
Location :	1st FL=Custodial Off.	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 16:20
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4882382	Test Start :	12/02/2025 @ 06:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:45
Location :	1st FL=Wood Shop-1	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 15:26
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4883893	Test Start :	12/02/2025 @ 06:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:49
Location :	1st FL = A-03	Received:	12/08/2025 @ 15:27
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 13:25

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4881354
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Wood Shop-2
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:06
Test Stop : 12/04/2025 @ 06:45
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 16:08

Canister ID# : 4881430
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Wood Shop-3
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:06
Test Stop : 12/04/2025 @ 06:45
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:35

Canister ID# : 4881415
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = A-02/DP
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:06
Test Stop : 12/04/2025 @ 06:50
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 15:04

Canister ID# : 4882330
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = A-02/DP
Radon Level : 0.5 pCi/L

Test Start : 12/02/2025 @ 06:06
Test Stop : 12/04/2025 @ 06:50
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:26

Average of Side by Side Canisters 0.7 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4882467
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-11
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:06
Test Stop : 12/04/2025 @ 06:51
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:10

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4881427	Test Start :	12/02/2025 @ 06:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:46
Location :	1st FL=Wood Shop/Off.	Received:	12/08/2025 @ 15:26
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882374	Test Start :	12/02/2025 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:47
Location :	1st FL=Auto Shop-1	Received:	12/08/2025 @ 15:26
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 15:06
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881361	Test Start :	12/02/2025 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:53
Location :	1st FL = A-01	Received:	12/08/2025 @ 15:27
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 13:05
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882459	Test Start :	12/02/2025 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:53
Location :	1st FL = H-12/DP	Received:	12/08/2025 @ 15:27
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 13:27
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4882848	Test Start :	12/02/2025 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:53
Location :	1st FL = H-12/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 13:26

Average of Side by Side Canisters 1.0 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881508	Test Start :	12/02/2025 @ 06:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:47
Location :	1st FL=Auto Shop-2	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 15:06

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4881458
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = HC-01/DP
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:10
Test Stop : 12/04/2025 @ 06:46
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:05

Canister ID# : 4883606
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = HC-01/DP
Radon Level : 0.7 pCi/L

Test Start : 12/02/2025 @ 06:10
Test Stop : 12/04/2025 @ 06:46
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:25

Average of Side by Side Canisters 0.8 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 4881385
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Auto Shop/Off.
Radon Level : 1.1 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:10
Test Stop : 12/04/2025 @ 06:46
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:27

Canister ID# : 4881431
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Auto Shop/Class Rm
Radon Level : 0.2 pCi/L
BLANK

Test Start : 12/02/2025 @ 06:10
Test Stop : 12/04/2025 @ 06:48
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:27

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 4882358
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Auto Shop/Class Rm
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 12/02/2025 @ 06:10
Test Stop : 12/04/2025 @ 06:48
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:53

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4881418	Test Start :	12/02/2025 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:55
Location :	1st FL = H-13	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:39
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881452	Test Start :	12/02/2025 @ 06:12
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:47
Location :	1st FL=HC-01/Off.-A	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:14
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883537	Test Start :	12/02/2025 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:48
Location :	1st FL=HC-01/Off.-B	Received:	12/08/2025 @ 15:26
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 14:47
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4881447	Test Start :	12/02/2025 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:49
Location :	1st FL = CTE-Shop	Received:	12/08/2025 @ 15:26
Radon Level :	0.5 pCi/L	Analyzed:	12/09/2025 @ 15:06
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881417	Test Start :	12/02/2025 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:57
Location :	1st FL = H-14	Received:	12/08/2025 @ 15:27
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 13:33
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883558	Test Start :	12/02/2025 @ 06:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:49
Location :	1st FL = HC-02	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:05
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4881411	Test Start :	12/02/2025 @ 06:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:50
Location :	1st FL = TA-08	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:35
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881446	Test Start :	12/02/2025 @ 06:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:58
Location :	1st FL = H-15	Received:	12/08/2025 @ 15:27
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 12:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883574	Test Start :	12/02/2025 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:50
Location :	1st FL = HC-03	Received:	12/08/2025 @ 15:27
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 12:23
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881402	Test Start :	12/02/2025 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:50
Location :	1st FL = TA-07	Received:	12/08/2025 @ 15:26
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 16:20
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	4882477	Test Start :	12/02/2025 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:57
Location :	1st FL=Cafeteria-1	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:39
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883551	Test Start :	12/02/2025 @ 06:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:51
Location :	1st FL = HC-04	Received:	12/08/2025 @ 15:26
Radon Level :	0.3 pCi/L	Analyzed:	12/09/2025 @ 14:07
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883583	Test Start :	12/02/2025 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:52
Location :	1st FL = HC-05	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 13:47
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881432	Test Start :	12/02/2025 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:58
Location :	1st FL=Cafeteria-2	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:21
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881455	Test Start :	12/02/2025 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:52
Location :	1st FL = TA-02	Received:	12/08/2025 @ 15:26
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 14:27
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883570	Test Start :	12/02/2025 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:53
Location :	1st FL = HC-05/BL	Received:	12/08/2025 @ 15:26
Radon Level :	0.2 pCi/L	Analyzed:	12/09/2025 @ 15:04
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	4881439	Test Start :	12/02/2025 @ 06:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:51
Location :	1st FL = TA-01/DP	Received:	12/08/2025 @ 15:26
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 14:43
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4881507	Test Start :	12/02/2025 @ 06:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:51
Location :	1st FL = TA-01/DP	Received:	12/08/2025 @ 15:26
Radon Level :	1.2 pCi/L	Analyzed:	12/09/2025 @ 15:58

Average of Side by Side Canisters 1.1 pCi/L

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4883541
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = HC-08
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:19
Test Stop : 12/04/2025 @ 06:54
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:43

Canister ID# : 4881453
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = TA-03
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 12/02/2025 @ 06:20
Test Stop : 12/04/2025 @ 06:52
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:47

Canister ID# : 4883568
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=CDC/Pre-School
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:20
Test Stop : 12/04/2025 @ 06:55
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:04

Canister ID# : 4881426
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-17
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:20
Test Stop : 12/04/2025 @ 07:00
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 11:51

Canister ID# : 4881383
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-17/BL
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:20
Test Stop : 12/04/2025 @ 07:00
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:47

Canister ID# : 4881334
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=CDC/Off.-C/DP
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:21
Test Stop : 12/04/2025 @ 06:57
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:06

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883486	Test Start :	12/02/2025 @ 06:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:57
Location :	1st FL=CDC/Off.-C/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:45

Average of Side by Side Canisters 0.6 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882325	Test Start :	12/02/2025 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:52
Location :	1st FL = TA-04	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:53

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882403	Test Start :	12/02/2025 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:57
Location :	1st FL=Cafeteria-3	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:10

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882817	Test Start :	12/02/2025 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:02
Location :	1st FL = H-18	Received:	12/08/2025 @ 15:27
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 11:51

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881437	Test Start :	12/02/2025 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:53
Location :	1st FL = TA-05	Received:	12/08/2025 @ 15:26
Radon Level :	1.3 pCi/L	Analyzed:	12/09/2025 @ 16:08

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4881412	Test Start :	12/02/2025 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:58
Location :	1st FL=CDC/Infant Rm	Received:	12/08/2025 @ 15:27
Radon Level :	0.5 pCi/L	Analyzed:	12/09/2025 @ 13:00

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4882409
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-19
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:23
Test Stop : 12/04/2025 @ 07:04
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:00

Canister ID# : 4881511
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = TA-06/DP
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:24
Test Stop : 12/04/2025 @ 06:54
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:46

Canister ID# : 4881513
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = TA-06/DP
Radon Level : 0.9 pCi/L

Test Start : 12/02/2025 @ 06:24
Test Stop : 12/04/2025 @ 06:54
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:25

Average of Side by Side Canisters 1.0 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4882328
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Cafeteria-4
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:24
Test Stop : 12/04/2025 @ 06:59
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:40

Canister ID# : 4881416
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=CDC/Off.-D
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:24
Test Stop : 12/04/2025 @ 06:59
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:56

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883507	Test Start :	12/02/2025 @ 06:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:04
Location :	1st FL = H-20	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:00
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883508	Test Start :	12/02/2025 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:00
Location :	1st FL=CDC/Off.-D/BL	Received:	12/08/2025 @ 15:27
Radon Level :	0.2 pCi/L	Analyzed:	12/09/2025 @ 13:33
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883547	Test Start :	12/02/2025 @ 06:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:01
Location :	1st FL=CDC/Infant Rm-E	Received:	12/08/2025 @ 15:26
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 14:04
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882327	Test Start :	12/02/2025 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:59
Location :	1st FL = C-01/DP	Received:	12/08/2025 @ 15:27
Radon Level :	1.4 pCi/L	Analyzed:	12/09/2025 @ 11:51
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882396	Test Start :	12/02/2025 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 06:59
Location :	1st FL = C-01/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:00

Average of Side by Side Canisters 1.2 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882393	Test Start :	12/02/2025 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:02
Location :	1st FL=North Office-A	Received:	12/08/2025 @ 15:27
Radon Level :	1.1 pCi/L	Analyzed:	12/09/2025 @ 12:22

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 4881397
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-21/DP
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:27
Test Stop : 12/04/2025 @ 07:06
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:40

Canister ID# : 4883616
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-21/DP
Radon Level : 0.6 pCi/L

Test Start : 12/02/2025 @ 06:27
Test Stop : 12/04/2025 @ 07:06
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:31

Average of Side by Side Canisters 0.7 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4881443
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=South Office-B
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:30
Test Stop : 12/04/2025 @ 07:03
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:05

Canister ID# : 4882354
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=South Office-B
Radon Level : 0.1 pCi/L
BLANK

Test Start : 12/02/2025 @ 06:30
Test Stop : 12/04/2025 @ 07:03
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:21

Error for Measurement is: $\pm$ 0.3 pCi/L

Canister ID# : 4883483
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Planetarium
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:30
Test Stop : 12/04/2025 @ 07:05
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:43

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4882471	Test Start :	12/02/2025 @ 06:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:04
Location :	1st FL=Office-C	Received:	12/08/2025 @ 15:27
Radon Level :	45.6 pCi/L	Analyzed:	12/09/2025 @ 12:31
Error for Measurement is: $\pm$	1.1 pCi/L		

Canister ID# :	4883535	Test Start :	12/02/2025 @ 06:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:06
Location :	1st FL=Planetarium Off.	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:31
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883909	Test Start :	12/02/2025 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:05
Location :	1st FL=Office-D	Received:	12/08/2025 @ 15:27
Radon Level :	40.4 pCi/L	Analyzed:	12/09/2025 @ 13:00
Error for Measurement is: $\pm$	1.1 pCi/L		

Canister ID# :	4883525	Test Start :	12/02/2025 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:08
Location :	1st FL = S-07/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:40
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883563	Test Start :	12/02/2025 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:08
Location :	1st FL = S-07/DP	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:46

Average of Side by Side Canisters 0.9 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4883503	Test Start :	12/02/2025 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:08
Location :	1st FL = H-22	Received:	12/08/2025 @ 15:27
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 13:45

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4883540
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = S-09
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:34
Test Stop : 12/04/2025 @ 07:09
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:45

Canister ID# : 4883596
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-41
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:35
Test Stop : 12/04/2025 @ 07:09
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:01

Canister ID# : 4883538
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = S-08
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:35
Test Stop : 12/04/2025 @ 07:10
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:07

Canister ID# : 4883584
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-42
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:35
Test Stop : 12/04/2025 @ 07:11
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 11:41

Canister ID# : 4883604
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-43
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:35
Test Stop : 12/04/2025 @ 07:11
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 11:43

Canister ID# : 4881359
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-44
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:35
Test Stop : 12/04/2025 @ 07:12
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:01

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883565	Test Start :	12/02/2025 @ 06:36
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:11
Location :	1st FL = S-06	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:45
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4883567	Test Start :	12/02/2025 @ 06:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:12
Location :	1st FL = S-04	Received:	12/08/2025 @ 15:26
Radon Level :	1.7 pCi/L	Analyzed:	12/09/2025 @ 15:15
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4881514	Test Start :	12/02/2025 @ 06:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:13
Location :	1st FL = H-25	Received:	12/08/2025 @ 15:27
Radon Level :	0.6 pCi/L	Analyzed:	12/09/2025 @ 13:45
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883552	Test Start :	12/02/2025 @ 06:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:13
Location :	1st FL = S-03	Received:	12/08/2025 @ 15:26
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 15:04
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883529	Test Start :	12/02/2025 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:14
Location :	1st FL = S-03/BL	Received:	12/08/2025 @ 15:26
Radon Level :	0.1 pCi/L	Analyzed:	12/09/2025 @ 14:46
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4881413	Test Start :	12/02/2025 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:15
Location :	1st FL = H-23	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:27
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883522	Test Start :	12/02/2025 @ 06:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:15
Location :	1st FL = S-02	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:39
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883559	Test Start :	12/02/2025 @ 06:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:16
Location :	1st FL = H-26	Received:	12/08/2025 @ 15:27
Radon Level :	0.5 pCi/L	Analyzed:	12/09/2025 @ 13:45
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883517	Test Start :	12/02/2025 @ 06:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:16
Location :	1st FL = S-05	Received:	12/08/2025 @ 15:26
Radon Level :	0.5 pCi/L	Analyzed:	12/09/2025 @ 14:08
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4881445	Test Start :	12/02/2025 @ 06:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:17
Location :	1st FL = S-01	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 13:26
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4881371	Test Start :	12/02/2025 @ 06:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:18
Location :	1st FL = H-24	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:25
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882801	Test Start :	12/02/2025 @ 06:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:18
Location :	1st FL = H-24/BL	Received:	12/08/2025 @ 15:27
Radon Level :	0.1 pCi/L	Analyzed:	12/09/2025 @ 13:05
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4881422	Test Start :	12/02/2025 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:17
Location :	1st FL = H-27	Received:	12/08/2025 @ 15:26
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 14:08
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4882457	Test Start :	12/02/2025 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:17
Location :	1st FL = H-28	Received:	12/08/2025 @ 15:27
Radon Level :	0.5 pCi/L	Analyzed:	12/09/2025 @ 13:15
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883539	Test Start :	12/02/2025 @ 06:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:18
Location :	1st FL = H-31/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 13:07
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	4883926	Test Start :	12/02/2025 @ 06:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:18
Location :	1st FL = H-31/DP	Received:	12/08/2025 @ 15:27
Radon Level :	0.7 pCi/L	Analyzed:	12/09/2025 @ 12:48

Average of Side by Side Canisters 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	4882790	Test Start :	12/02/2025 @ 06:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:22
Location :	1st FL = H-29	Received:	12/08/2025 @ 15:27
Radon Level :	0.4 pCi/L	Analyzed:	12/09/2025 @ 13:45
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4882885	Test Start :	12/02/2025 @ 06:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:23
Location :	1st FL = H-30	Received:	12/08/2025 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	12/09/2025 @ 12:23

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 4882884
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-32
Radon Level : 1.1 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 12/02/2025 @ 06:51
Test Stop : 12/04/2025 @ 07:24
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:22

Canister ID# : 4882889
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-33
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:55
Test Stop : 12/04/2025 @ 07:25
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 13:33

Canister ID# : 4881377
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-34
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:57
Test Stop : 12/04/2025 @ 07:26
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 15:14

Canister ID# : 4881448
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-34/BL
Radon Level : 0.1 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 12/02/2025 @ 06:57
Test Stop : 12/04/2025 @ 07:26
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:21

Canister ID# : 4882887
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-38
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:58
Test Stop : 12/04/2025 @ 07:28
Received: 12/08/2025 @ 15:26
Analyzed: 12/09/2025 @ 14:14

Canister ID# : 4882890
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = H-39
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 12/02/2025 @ 06:59
Test Stop : 12/04/2025 @ 07:29
Received: 12/08/2025 @ 15:27
Analyzed: 12/09/2025 @ 12:10

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

Canister ID# :	4883900	Test Start :	12/02/2025 @ 07:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:30
Location :	1st FL = H-40	Received:	12/08/2025 @ 15:26
Radon Level :	0.2 pCi/L	Analyzed:	12/09/2025 @ 13:47
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883527	Test Start :	12/02/2025 @ 07:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:31
Location :	1st FL = H-35	Received:	12/08/2025 @ 15:27
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 13:05
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883485	Test Start :	12/02/2025 @ 07:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:32
Location :	1st FL = H-37	Received:	12/08/2025 @ 15:27
Radon Level :	1.0 pCi/L	Analyzed:	12/09/2025 @ 13:23
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4883572	Test Start :	12/02/2025 @ 07:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:33
Location :	1st FL = H-36	Received:	12/08/2025 @ 15:27
Radon Level :	0.9 pCi/L	Analyzed:	12/09/2025 @ 12:48
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4882419	Test Start :	12/02/2025 @ 07:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:53
Location :	1st FL = H-45	Received:	12/08/2025 @ 15:27
Radon Level :	39.5 pCi/L	Analyzed:	12/09/2025 @ 13:26
Error for Measurement is: ±	1.0 pCi/L		

Canister ID# :	4882390	Test Start :	12/02/2025 @ 07:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	12/04/2025 @ 07:54
Location :	1st FL = H-46	Received:	12/08/2025 @ 15:27
Radon Level :	43.7 pCi/L	Analyzed:	12/09/2025 @ 11:51
Error for Measurement is: ±	1.0 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 12/08/2025

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: North High School
Test Location: 1900 North Keeneway Drive
Medford, OR 97504-

Individual Canister Results

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201