


Lead in Drinking Water Testing Churchville-Chili Middle School

Location:

Churchville-Chili Middle School
139 Fairbanks Road
Churchville, New York 14428



LaBella Project No.

2254751

December 19, 2025



Sample #	Location	Outlet Type	Notes	Date	Time	Concentration (ug/L)
MSN-GYMCH-01	Hallway by Gym C	Drinking Fountain	Left	10/21/2025	0550	<1.0
MSN-GYMCH-02	Hallway by Gym C	Drinking Fountain	Right	10/21/2025	0551	<1.0
MSN-GYMCH-03	Hallway by Gym C	Bottle Filler	---	10/21/2025	0552	<1.0
MSN-GYMDH-01	Hallway by Gym D	Drinking Fountain	---	10/21/2025	0720	<1.0
MSN-GYMDH-02	Hallway by Gym D	Bottle Filler	---	10/21/2025	0721	<1.0
MSN-3408H-01	Hallway by Room 3408	Drinking Fountain	---	10/21/2025	0546	<1.0
MSN-3408H-02	Hallway by Room 3408	Bottle Filler	---	10/21/2025	0547	<1.0
MSN-3201H-01	Hallway by Room 3201	Drinking Fountain	---	10/21/2025	0555	<1.0
MSN-3201H-02	Hallway by Room 3201	Bottle Filler	---	10/21/2025	0556	<1.0
MSN-KIT-01	Kitchen	Tap	B-Wall	10/21/2025	0601	34.5
MSN-KIT-02	Kitchen	Tap	C-Wall, By Windows	10/21/2025	0602	<1.0
MSN-KIT-03	Kitchen	Tap	C-Wall, By Dishwashing Area	10/21/2025	0603	6.5
MSN-KIT-04	Kitchen	Ice Machine	D-Wall	10/21/2025	0604	<1.0
MSN-KIT-05	Kitchen	Sprayer	D-Wall	10/21/2025	0607	5.0
MSN-KIT-06	Kitchen	Tap	A-Wall, Left	10/21/2025	0608	<1.0
MSN-KIT-07	Kitchen	Tap	A-Wall, Right	10/21/2025	0609	<1.0
MSN-KIT-08	Kitchen	Tap	Island by A-Wall	10/21/2025	0611	1.3
MSN-KIT-09	Kitchen	Tap	Island by C-Wall	10/21/2025	0612	<1.0
MSN-KITS-01	Kitchen Serving Line	Tap	---	10/21/2025	0613	3.1
MSN-CAFEC-01	Cafeteria C	Drinking Fountain	---	10/21/2025	0615	<1.0
MSN-CAFEC-02	Cafeteria C	Bottle Filler	---	10/21/2025	0616	<1.0
MSN-3520H-01	Hallway by Room 3520	Drinking Fountain	Not Installed	NT	X	X
MSN-3520H-02	Hallway by Room 3520	Bottle Filler	Not Installed	NT	X	X
MSN-3520-01	FACS Room 3520	Tap	---	10/21/2025	0618	<1.0
MSN-3522-01	FACS Room 3522	Tap	---	10/21/2025	0619	<1.0
MSN-3524-01	FACS Room 3524	Tap	Island by Windows	10/21/2025	0620	<1.0
MSN-3524-02	FACS Room 3524	Tap	2nd Island to Windows	10/21/2025	0621	<1.0
MSN-3524-03	FACS Room 3524	Tap	2nd Island to Hallway	10/21/2025	0622	<1.0

NW = Not Working, NT= Not Tested

Sample #	Location	Outlet Type	Notes	Date	Time	Concentration (ug/L)
MSN-3524-04	FACS Room 3524	Tap	Island by Hallway	10/21/2025	0623	<1.0
MSN-3524-05	FACS Room 3524	Tap	Far Wall (D-Wall), Left	10/21/2025	0624	<1.0
MSN-3524-06	FACS Room 3524	Tap	Far Wall (D-Wall), Center	10/21/2025	0625	<1.0
MSN-3524-07	FACS Room 3524	Tap	Far Wall (D-Wall), Right	10/21/2025	0626	<1.0
MSN-BOARD-01	Board Room (CO)	Tap	---	10/21/2025	0714	<1.0
MSN-3915H-01	Hallway by Room 3915	Drinking Fountain	---	10/21/2025	0712	<1.0
MSN-3915H-02	Hallway by Room 3915	Bottle Filler	---	10/21/2025	0713	<1.0
MSN-3308H-01	Hallway by Room 3308	Drinking Fountain	Not Working	NW	X	X
MSN-3308H-02	Hallway by Room 3308	Bottle Filler	Not Working	NW	X	X
MSN-3327-01	Teacher's Lounge 3327	Tap	---	10/21/2025	0708	1.4
MSN-3318H-01	Hallway by Room 3318	Drinking Fountain	---	10/21/2025	0706	<1.0
MSN-3318H-02	Hallway by Room 3318	Bottle Filler	---	10/21/2025	0707	<1.0
MSN-3326H-01	Hallway by Room 3326	Drinking Fountain	Left	10/21/2025	0641	<1.0
MSN-3326H-02	Hallway by Room 3326	Drinking Fountain	Right	10/21/2025	0642	<1.0
MSN-3326H-03	Hallway by Room 3326	Bottle Filler	---	10/21/2025	0643	<1.0
MSN-RS-01	Related Services	Tap	---	10/21/2025	0704	<1.0
MSN-MO-01	Main Office	Tap	---	10/21/2025	0645	1.1
MSN-NHO-01	Nurse's Office	Tap	---	10/21/2025	0650	1.3
MSN-NHO-01S	Nurse's Office	Sprayer	---	10/21/2025	0651	<1.0
MSN-3131H-01	Hallway by Room 3131	Drinking Fountain	Not Installed	NT	X	X
MSN-3131H-02	Hallway by Room 3131	Bottle Filler	Not Installed	NT	X	X
MSN-3125H-01	Hallway by Room 3125	Drinking Fountain	---	10/21/2025	0656	<1.0
MSN-3125H-02	Hallway by Room 3125	Bottle Filler	---	10/21/2025	0657	<1.0
MSN-LIB-01	Library Break Room	Tap	---	10/21/2025	0658	2.2
MSN-LIB-01S	Library Break Room	Sprayer	---	10/21/2025	0659	<1.0
MSN-3108H-01	Hallway by Room 3108	Drinking Fountain	Not Installed	NT	X	X
MSN-3108H-02	Hallway by Room 3108	Bottle Filler	Not Installed	NT	X	X

NW = Not Working, NT= Not Tested

Sample #	Location	Outlet Type	Notes	Date	Time	Concentration (ug/L)
MSS-ANX-01	Kitchen Annex	Ice Machine	---	10/21/2025	0510	<1.0
MSS-KIT-01	Kitchen	Tap	B-Wall	10/21/2025	0511	2.9
MSS-KIT-01S	Kitchen	Overhead Sprayer	On Tap 01	10/21/2025	0512	<1.0
MSS-KIT-02	Kitchen	Ice Machine	C-Wall	10/21/2025	0513	<1.0
MSS-KIT-03	Kitchen	Tap	D-Wall, Left	10/21/2025	0514	6.1
MSS-KIT-04	Kitchen	Tap	D-Wall, Right	10/21/2025	0515	30.8
MSS-KIT-04S	Kitchen	Tap	On Tap 04	10/21/2025	0516	1.4
MSS-KIT-05	Kitchen	Tap	Island	10/21/2025	0517	3.1
MSS-CAFÉB-01	Cafeteria B	Drinking Fountain	---	10/21/2025	0525	<1.0
MSS-CAFÉB-02	Cafeteria B	Bottle Filler	---	10/21/2025	0526	<1.0
MSS-2102H-01	Hallway by Room 2102	Drinking Fountain	---	10/21/2025	0530	<1.0
MSS-2102H-02	Hallway by Room 2102	Bottle Filler	---	10/21/2025	0531	<1.0
MSS-2206H-01	Hallway by Room 2206	Drinking Fountain	---	10/21/2025	0535	<1.0
MSS-2206H-02	Hallway by Room 2206	Bottle Filler	---	10/21/2025	0536	<1.0
MSS-NUR-1	Nurse's Office	Tap	---	10/21/2025	0727	4.2
MSS-EX12H-01	Hallway by Exit 12	Drinking Fountain	---	10/21/2025	0532	<1.0
MSS-EX12H-02	Hallway by Exit 12	Bottle Filler	---	10/21/2025	0533	<1.0
MSS-2134H-01	Hallway by Room 2134	Drinking Fountain	---	10/21/2025	0542	<1.0
MSS-2134H-02	Hallway by Room 2134	Bottle Filler	---	10/21/2025	0543	<1.0
MSS-2606H-01	Hallway by Room 2606	Drinking Fountain	---	10/21/2025	0539	<1.0
MSS-2606H-02	Hallway by Room 2606	Bottle Filler	---	10/21/2025	0540	<1.0

NW = Not Working, NT= Not Tested