

[Back](#)

MHSCPC Student Survey Results Overview

Respondents: 368 displayed, 368 total

Status: Closed

Launched Date: N/A

Closed Date: 11/01/2023

Display: Display all pages and questions ▼

Active Report Filters: None Active.

Manage Filters: 0 filters

Share Results: Disabled

[More](#)

1. Classroom

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Classroom Appearance (aesthetics)	4.35% (16)	31.52% (116)	51.36% (189)	6.52% (24)	6.25% (23)	368
Classroom Size (dimensions)	2.45% (9)	15.76% (58)	69.02% (254)	7.61% (28)	5.16% (19)	368
Classroom Furniture (student/teacher desks/chairs/shelving)	7.34% (27)	42.12% (155)	41.3% (152)	5.16% (19)	4.08% (15)	368
Classroom Functionality (layout or design serves instructional purpose)	4.08% (15)	20.38% (75)	61.68% (227)	8.42% (31)	5.43% (20)	368
Classroom Climate (air conditioning/heat/noise)	32.07% (118)	47.55% (175)	13.32% (49)	2.99% (11)	4.08% (15)	368
					Total Respondents	368

2. Library

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Library Appearance (aesthetics)	2.99% (11)	8.97% (33)	45.65% (168)	29.35% (108)	13.04% (48)	368
Library Size (dimensions)	2.72% (10)	9.24% (34)	44.02% (162)	30.98% (114)	13.04% (48)	368
Library Furniture (student/teacher desks/chairs/shelving)	3.26% (12)	10.05% (37)	38.32% (141)	35.05% (129)	13.32% (49)	368
Library Functionality (layout or design serves instructional purpose)	2.72% (10)	6.25% (23)	47.28% (174)	27.99% (103)	15.76% (58)	368
Library Climate (air conditioning/heat/noise)	6.79% (25)	13.32% (49)	48.37% (178)	14.13% (52)	17.39% (64)	368
					Total Respondents	368

3. Science Lab

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Science Lab Appearance (aesthetics)	4.62% (17)	19.02% (70)	51.09% (188)	8.7% (32)	16.58% (61)	368
Science Lab Size (dimensions)	5.16% (19)	19.02% (70)	47.55% (175)	11.41% (42)	16.85% (62)	368
Science Lab Functionality (layout or design serves instructional purpose)	6.25% (23)	13.32% (49)	51.9% (191)	10.87% (40)	17.66% (65)	368
Science Lab Furniture (student/teacher desks/chairs/shelving)	7.07% (26)	24.46% (90)	44.02% (162)	7.88% (29)	16.58% (61)	368
Science Lab Equipment	7.34% (27)	18.21% (67)	47.28% (174)	9.78% (36)	17.39% (64)	368
Science Lab Climate (air conditioning/heat/noise)	10.87% (40)	27.99% (103)	36.96% (136)	5.16% (19)	19.02% (70)	368
					Total Respondents	368

4. Technology Education Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Technology Education Room Appearance (aesthetics)	3.8% (14)	9.24% (34)	27.72% (102)	4.89% (18)	54.35% (200)	368
Technology Education Room Size (dimensions)	2.99% (11)	9.24% (34)	27.99% (103)	5.16% (19)	54.62% (201)	368

Technology Education Room						
Functionality (layout or design serves instructional purpose)	3.26% (12)	9.24% (34)	27.17% (100)	5.98% (22)	54.35% (200)	368
Technology Education Room Furniture (student/teacher desks/chairs/shelving)	3.26% (12)	9.24% (34)	27.45% (101)	5.71% (21)	54.35% (200)	368
Technology Education Room Equipment	3.8% (14)	10.6% (39)	25% (92)	6.52% (24)	54.08% (199)	368
Technology Education Room Climate (air conditioning/heat/noise)	6.52% (24)	13.59% (50)	20.65% (76)	4.89% (18)	54.35% (200)	368
					Total Respondents	368

5. Family Consumer Science Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Family Consumer Science Room Appearance (aesthetics)	5.16% (19)	9.24% (34)	26.36% (97)	6.79% (25)	52.45% (193)	368
Family Consumer Science Room Size (dimensions)	5.98% (22)	10.33% (38)	25.82% (95)	5.43% (20)	52.45% (193)	368
Family Consumer Science Room Functionality (layout or design serves instructional purpose)	5.98% (22)	7.61% (28)	27.45% (101)	6.79% (25)	52.17% (192)	368
Family Consumer Science Room Furniture (student/teacher desks/chairs/shelving)	5.71% (21)	10.05% (37)	22.01% (81)	9.51% (35)	52.72% (194)	368
Family Consumer Science Room Equipment	5.71% (21)	10.87% (40)	24.73% (91)	5.43% (20)	53.26% (196)	368
Family Consumer Science Room Climate (air conditioning/heat/noise)	6.79% (25)	11.68% (43)	23.37% (86)	4.62% (17)	53.53% (197)	368
					Total Respondents	368

6. Life Skills Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Life Skills Room Appearance (aesthetics)	3.53% (13)	7.07% (26)	22.01% (81)	4.08% (15)	63.32% (233)	368
Life Skills Room Size (dimensions)	4.35% (16)	5.71% (21)	22.55% (83)	4.08% (15)	63.32% (233)	368
Life Skills Room Functionality (layout or design serves instructional purpose)	3.8% (14)	7.07% (26)	22.01% (81)	3.8% (14)	63.32% (233)	368
Life Skills Room Furniture (student/teacher desks/chairs/shelving)	4.35% (16)	7.61% (28)	20.65% (76)	3.8% (14)	63.59% (234)	368
Life Skills Room Equipment	3.8% (14)	7.61% (28)	21.47% (79)	3.8% (14)	63.32% (233)	368
Life Skills Room Climate (air conditioning/heat/noise)	4.62% (17)	10.33% (38)	18.48% (68)	3.53% (13)	63.04% (232)	368
					Total Respondents	368

7. Hallway Appearance

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Hallway Appearance (aesthetics)	19.02% (70)	33.97% (125)	37.5% (138)	5.43% (20)	4.08% (15)	368
Hallway Size (dimensions)	33.7% (124)	36.68% (135)	22.01% (81)	4.35% (16)	3.26% (12)	368
Hallway Climate (air conditioning/heat/noise)	16.03% (59)	27.45% (101)	46.2% (170)	5.43% (20)	4.89% (18)	368
					Total Respondents	368

8. Main Gymnasium

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Main Gymnasium Appearance (aesthetics)	4.08% (15)	14.95% (55)	50% (184)	20.65% (76)	10.33% (38)	368
Main Gymnasium Size (dimensions)	3.8% (14)	13.59% (50)	52.17% (192)	20.11% (74)	10.33% (38)	368
Main Gymnasium Functionality (layout or design serves purpose)	3.53% (13)	8.97% (33)	60.05% (221)	16.3% (60)	11.14% (41)	368
Main Gymnasium Spectator Seating	6.25% (23)	19.57% (72)	47.83% (176)	14.13% (52)	12.23% (45)	368
Main Gymnasium Equipment	5.43% (20)	17.39% (64)	48.1% (177)	11.68% (43)	17.39% (64)	368
Main Gymnasium Storage (location for equipment)	4.35% (16)	13.04% (48)	47.01% (173)	11.14% (41)	24.46% (90)	368
Main Gymnasium Climate (air conditioning/heat/noise)	9.51% (35)	24.46% (90)	44.02% (162)	7.88% (29)	14.13% (52)	368
					Total Respondents	368

9. Gymnasiums

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Main Gymnasium Appearance (aesthetics)	5.43% (20)	16.58% (61)	50.27% (185)	15.22% (56)	12.5% (46)	368
Main Gymnasium Size (dimensions)	4.08% (15)	15.22% (56)	54.89% (202)	13.04% (48)	12.77% (47)	368

Main Gymnasium Functionality (layout or design serves purpose)	3.53% (13)	12.23% (45)	60.33% (222)	10.33% (38)	13.59% (50)	368
Main Gymnasium Spectator Seating	5.71% (21)	21.47% (79)	48.37% (178)	10.05% (37)	14.4% (53)	368
Main Gymnasium Equipment	4.89% (18)	17.93% (66)	49.46% (182)	9.24% (34)	18.48% (68)	368
Main Gymnasium Storage (location for equipment)	4.89% (18)	15.49% (57)	47.28% (174)	7.07% (26)	25.27% (93)	368
Main Gymnasium Climate (air conditioning/heat/noise)	8.42% (31)	24.73% (91)	45.92% (169)	6.25% (23)	14.67% (54)	368
Aux Gymnasium (boys/girls gym) Appearance (aesthetics)	11.68% (43)	28.53% (105)	39.67% (146)	5.43% (20)	14.67% (54)	368
Aux Gymnasium (boys/girls gym) Size (dimensions)	9.51% (35)	26.9% (99)	43.48% (160)	5.71% (21)	14.4% (53)	368
Aux Gymnasium (boys/girls gym) Functionality (layout or design serves purpose)	8.42% (31)	21.47% (79)	48.91% (180)	5.71% (21)	15.49% (57)	368
Aux Gymnasium (boys/girls gym) Spectator Seating	19.57% (72)	27.17% (100)	32.34% (119)	5.16% (19)	15.76% (58)	368
Aux Gymnasium (boys/girls gym) Equipment	7.88% (29)	26.09% (96)	38.59% (142)	6.52% (24)	20.92% (77)	368
Aux Gymnasium Storage (location for equipment)	8.15% (30)	18.48% (68)	40.76% (150)	5.98% (22)	26.63% (98)	368
Aux Gymnasium Climate (boys/girls gym) (air conditioning/heat/noise)	13.04% (48)	27.72% (102)	38.59% (142)	6.25% (23)	14.4% (53)	368
Total Respondents						368

10. Cafeteria

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Cafeteria Appearance (aesthetics)	13.86% (51)	33.97% (125)	41.03% (151)	7.07% (26)	4.08% (15)	368
Cafeteria Size (dimensions)	15.22% (56)	33.42% (123)	42.12% (155)	5.43% (20)	3.8% (14)	368
Cafeteria Functionality (layout or design serves purpose)	13.32% (49)	26.36% (97)	49.46% (182)	7.07% (26)	3.8% (14)	368
Cafeteria Furniture (student tables/chairs/counters)	14.95% (55)	38.59% (142)	37.5% (138)	4.89% (18)	4.08% (15)	368
Cafeteria Appliances (student use)	10.87% (40)	27.72% (102)	47.01% (173)	5.98% (22)	8.42% (31)	368
Cafeteria Climate (air conditioning/heat/noise)	14.4% (53)	28.8% (106)	45.65% (168)	5.98% (22)	5.16% (19)	368
Total Respondents						368

11. WiFi and Cellular Reception

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
District provided WiFi reception	36.96% (136)	35.33% (130)	19.29% (71)	2.99% (11)	5.43% (20)	368
Personal Cellular WiFi reception	48.91% (180)	27.45% (101)	14.67% (54)	1.36% (5)	7.61% (28)	368
Personal Cellular Phone reception	50.54% (186)	28.26% (104)	12.5% (46)	2.17% (8)	6.52% (24)	368
Total Respondents						368

12. Locker Rooms

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Physical Education locker room Appearance (aesthetics)	14.67% (54)	34.51% (127)	35.33% (130)	3.53% (13)	11.96% (44)	368
Physical Education locker room Size (dimensions)	12.23% (45)	25.27% (93)	46.74% (172)	4.08% (15)	11.68% (43)	368
Physical Education locker room Functionality (layout or design serves purpose)	10.05% (37)	26.63% (98)	47.01% (173)	2.72% (10)	13.59% (50)	368
Physical Education locker room Furniture (student benches, lockers, showers)	16.58% (61)	32.34% (119)	35.6% (131)	2.72% (10)	12.77% (47)	368
Physical Education locker room Climate (air conditioning/heat/noise)	17.66% (65)	32.07% (118)	33.97% (125)	3.53% (13)	12.77% (47)	368
Athletic Team locker room Appearance (aesthetics)	10.05% (37)	22.83% (84)	30.16% (111)	3.26% (12)	33.7% (124)	368
Athletic Team locker room Size (dimensions)	10.6% (39)	21.47% (79)	30.16% (111)	3.53% (13)	34.24% (126)	368
Athletic Team locker room Functionality (layout or design serves purpose)	8.42% (31)	17.93% (66)	34.51% (127)	3.26% (12)	35.87% (132)	368
Athletic Team locker room Furniture (student benches, lockers, showers)	11.14% (41)	20.38% (75)	30.16% (111)	2.99% (11)	35.33% (130)	368
Athletic Team locker room Climate (air conditioning/heat/noise)	13.32% (49)	20.65% (76)	27.45% (101)	2.45% (9)	36.14% (133)	368
Student Locker Appearance (aesthetics)	10.87% (40)	22.83% (84)	37.5% (138)	3.53% (13)	25.27% (93)	368
Student Locker Size (dimensions)	11.68% (43)	25% (92)	35.87% (132)	2.45% (9)	25% (92)	368
Student Locker Location (places in building)	10.6% (39)	18.21% (67)	39.13% (144)	3.26% (12)	28.8% (106)	368
Student Locker Functionality (layout or design serves purpose)	11.41% (42)	18.75% (69)	39.4% (145)	2.99% (11)	27.45% (101)	368
Total Respondents						368

13. Restrooms

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Student Restroom Appearance (aesthetics)	20.92% (77)	39.67% (146)	27.72% (102)	3.8% (14)	7.88% (29)	368
Student Restroom Size (dimensions)	16.3% (60)	28.53% (105)	42.66% (157)	4.35% (16)	8.15% (30)	368
Student Restroom Location (position(s) in building)	14.13% (52)	23.91% (88)	49.18% (181)	4.62% (17)	8.15% (30)	368
Student Restroom Functionality (layout or design serves purpose)	13.04% (48)	25.82% (95)	48.64% (179)	3.8% (14)	8.7% (32)	368
Student Restroom Furniture (stalls, urinals, sinks, mirrors, towel dispensers)	23.1% (85)	34.51% (127)	30.16% (111)	3.53% (13)	8.7% (32)	368
Student Restroom Climate (air conditioning/heat/noise)	16.3% (60)	25.27% (93)	42.66% (157)	3.53% (13)	12.23% (45)	368
					Total Respondents	368

14. Weight Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Weight Room Appearance (aesthetics)	16.58% (61)	16.03% (59)	21.47% (79)	3.8% (14)	42.12% (155)	368
Weight Room Size (dimensions)	20.92% (77)	18.21% (67)	17.66% (65)	2.72% (10)	40.49% (149)	368
Weight Room Functionality (layout or design serves purpose)	15.76% (58)	16.3% (60)	22.01% (81)	4.62% (17)	41.3% (152)	368
Weight Room Equipment (weights/machines)	18.75% (69)	14.13% (52)	20.65% (76)	4.62% (17)	41.85% (154)	368
Weight Room Climate (air conditioning/heat/noise)	14.67% (54)	15.76% (58)	23.1% (85)	3.8% (14)	42.66% (157)	368
					Total Respondents	368

15. Storage

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Storage Location(s) (inside building)	5.71% (21)	8.7% (32)	19.02% (70)	2.99% (11)	63.59% (234)	368
Storage Location Size (internal) (dimensions)	5.43% (20)	10.05% (37)	18.75% (69)	2.45% (9)	63.32% (233)	368
Storage Location Functionality (inside building) (layout or design serves purpose)	5.71% (21)	7.88% (29)	20.65% (76)	2.17% (8)	63.59% (234)	368
Total Storage Space (inside building)	5.43% (20)	8.7% (32)	19.02% (70)	2.72% (10)	64.13% (236)	368
Storage Location(s) (outside building)	6.52% (24)	7.88% (29)	19.29% (71)	2.45% (9)	63.86% (235)	368
Storage Location Size (outside building)	5.98% (22)	7.61% (28)	19.57% (72)	2.45% (9)	64.4% (237)	368
Storage Location Functionality (outside building)	6.52% (24)	7.34% (27)	18.75% (69)	2.99% (11)	64.4% (237)	368
Total Storage Space (outside building)	5.98% (22)	7.07% (26)	19.57% (72)	2.99% (11)	64.4% (237)	368
					Total Respondents	368

16. Art Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Art Room Appearance (aesthetics)	3.26% (12)	8.7% (32)	30.43% (112)	11.68% (43)	45.92% (169)	368
Art Room Size (dimensions)	4.35% (16)	10.87% (40)	30.98% (114)	8.15% (30)	45.65% (168)	368
Art Room Furniture (student/teacher desks/chairs/shelving)	4.08% (15)	12.77% (47)	28.8% (106)	7.88% (29)	46.47% (171)	368
Art Room Functionality (layout or design serves instructional purpose)	3.53% (13)	8.42% (31)	32.88% (121)	8.97% (33)	46.2% (170)	368
Art Room Storage (space for supplies)	3.8% (14)	11.68% (43)	28.8% (106)	7.61% (28)	48.1% (177)	368
Art Room Climate (air conditioning/heat/noise)	4.89% (18)	12.77% (47)	28.53% (105)	6.79% (25)	47.01% (173)	368
					Total Respondents	368

17. Music Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Music Room Appearance (aesthetics)	3.8% (14)	8.42% (31)	22.83% (84)	7.61% (28)	57.34% (211)	368
Music Room Size (dimensions)	5.43% (20)	8.97% (33)	20.65% (76)	7.34% (27)	57.61% (212)	368
Music Room Furniture (student/teacher desks/chairs/shelving)	4.35% (16)	7.61% (28)	23.91% (88)	6.25% (23)	57.88% (213)	368
Music Room Functionality (layout or design serves instructional purpose)	3.53% (13)	6.79% (25)	24.46% (90)	7.07% (26)	58.15% (214)	368
Music Room Storage (space for supplies/instruments)	5.16% (19)	8.97% (33)	21.2% (78)	5.43% (20)	59.24% (218)	368
Music Room Climate (air conditioning/heat/noise)	5.16% (19)	10.6% (39)	21.47% (79)	4.35% (16)	58.42% (215)	368
					Total Respondents	368

18. Band Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Band Room Appearance (aesthetics)	3.26% (12)	5.98% (22)	20.65% (76)	5.71% (21)	64.4% (237)	368
Band Room Size (dimensions)	3.8% (14)	7.34% (27)	17.93% (66)	6.52% (24)	64.4% (237)	368
Band Room Functionality (layout or design serves instructional purpose)	4.08% (15)	6.79% (25)	19.84% (73)	4.62% (17)	64.67% (238)	368
Band Room Furniture (student/teacher desks/chairs/shelving)	4.35% (16)	7.34% (27)	19.57% (72)	3.8% (14)	64.95% (239)	368
Band Room Storage (space for supplies/instruments)	5.43% (20)	7.34% (27)	17.66% (65)	4.35% (16)	65.22% (240)	368
Band Room Climate (air conditioning/heat/noise)	5.71% (21)	9.78% (36)	17.12% (63)	3.26% (12)	64.13% (236)	368
					Total Respondents	368

19. Chorus/Vocal Room

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Chorus/Vocal Room Appearance (aesthetics)	3.53% (13)	6.52% (24)	20.11% (74)	5.98% (22)	63.86% (235)	368
Chorus/Vocal Room Size (dimensions)	5.43% (20)	10.33% (38)	16.85% (62)	3.53% (13)	63.86% (235)	368
Chorus/Vocal Room Functionality (layout or design serves instructional purpose)	4.35% (16)	7.07% (26)	20.11% (74)	4.08% (15)	64.4% (237)	368
Chorus/Vocal Room Furniture (student/teacher desks/chairs/shelving)	4.62% (17)	6.25% (23)	20.11% (74)	4.89% (18)	64.13% (236)	368
Chorus/Vocal Room Storage (space for supplies/instruments)	4.89% (18)	7.34% (27)	18.21% (67)	3.53% (13)	66.03% (243)	368
Chorus/Vocal Room Climate (air conditioning/heat/noise)	4.89% (18)	10.05% (37)	16.58% (61)	3.8% (14)	64.67% (238)	368
					Total Respondents	368

20. Nursing Office

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Nursing Office Appearance (aesthetics)	4.62% (17)	11.41% (42)	36.68% (135)	9.78% (36)	37.5% (138)	368
Nursing Office Location (position within building)	3.8% (14)	15.76% (58)	36.14% (133)	7.88% (29)	36.41% (134)	368
Nursing Office Size (dimensions)	5.71% (21)	18.75% (69)	33.15% (122)	5.98% (22)	36.41% (134)	368
Nursing Office Functionality (layout or design serves instructional purpose)	3.8% (14)	11.96% (44)	39.13% (144)	7.07% (26)	38.04% (140)	368
Nursing Office Furniture (tables/beds/desks/chairs/shelving/etc.)	5.43% (20)	14.13% (52)	33.15% (122)	8.42% (31)	38.86% (143)	368
Nursing Office Storage (space for supplies)	3.8% (14)	10.87% (40)	32.61% (120)	5.98% (22)	46.74% (172)	368
Nursing Office Climate (air conditioning/heat/noise)	5.43% (20)	13.04% (48)	33.42% (123)	6.25% (23)	41.85% (154)	368
					Total Respondents	368

21. Counseling Office

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Counseling Office Appearance (aesthetics)	3.8% (14)	14.4% (53)	35.05% (129)	9.51% (35)	37.23% (137)	368
Counseling Office Location (position within building)	3.8% (14)	13.32% (49)	38.59% (142)	7.61% (28)	36.68% (135)	368
Counseling Office Size (dimensions)	4.35% (16)	12.5% (46)	38.32% (141)	7.07% (26)	37.77% (139)	368
Counseling Office Functionality (layout or design serves purpose)	4.62% (17)	9.78% (36)	40.22% (148)	7.07% (26)	38.32% (141)	368
Counseling Office Furniture (tables/desks/chairs/shelving/etc.)	3.8% (14)	13.59% (50)	35.05% (129)	8.42% (31)	39.13% (144)	368
Counseling Office Storage (space for supplies)	3.8% (14)	10.05% (37)	34.78% (128)	6.52% (24)	44.84% (165)	368
Counseling Office Climate (air conditioning/heat/noise)	5.16% (19)	13.32% (49)	33.42% (123)	6.79% (25)	41.3% (152)	368
					Total Respondents	368

22. Accessibility

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Accessibility inside building for all including students with disabilities	7.61% (28)	18.21% (67)	30.98% (114)	4.35% (16)	38.86% (143)	368
Accessibility outside building for all including students with disabilities	7.07% (26)	17.93% (66)	30.16% (111)	4.35% (16)	40.49% (149)	368
					Total Respondents	368

23. General

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Overall External Campus Appearance	9.78% (36)	31.25% (115)	44.84% (165)	6.79% (25)	7.34% (27)	368
Overall External Building Appearance	11.68% (43)	34.51% (127)	41.58% (153)	5.16% (19)	7.07% (26)	368
Overall Internal Building Appearance	14.67% (54)	36.68% (135)	36.41% (134)	5.43% (20)	6.79% (25)	368
Overall Internal Building Functionality (layout or design serves instructional purpose)	17.39% (64)	33.42% (123)	37.23% (137)	4.62% (17)	7.34% (27)	368
Visibility of School Spirit inside building	12.23% (45)	32.07% (118)	39.4% (145)	6.52% (24)	9.78% (36)	368
Visibility of school Spirit outside building	18.75% (69)	32.88% (121)	32.61% (120)	5.43% (20)	10.33% (38)	368
Student gathering spaces (space in building students can collaborate/socialize)	21.2% (78)	29.62% (109)	34.51% (127)	5.71% (21)	8.97% (33)	368
Staff gathering spaces (space in building students can collaborate/socialize)	12.5% (46)	20.11% (74)	30.16% (111)	4.89% (18)	32.34% (119)	368
					Total Respondents	368

24. Auditorium

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Auditorium Stage Sound System (dependable/functional)	10.87% (40)	20.65% (76)	40.22% (148)	8.15% (30)	20.11% (74)	368
Auditorium Stage Lighting System (dependable/functional)	10.6% (39)	21.74% (80)	39.13% (144)	8.15% (30)	20.38% (75)	368
Auditorium Appearance (aesthetics)	14.4% (53)	26.63% (98)	35.6% (131)	7.61% (28)	15.76% (58)	368
Auditorium Size (dimensions)	19.02% (70)	26.09% (96)	33.7% (124)	6.79% (25)	14.4% (53)	368
Auditorium Functionality (layout or design serves performance purpose)	12.77% (47)	19.29% (71)	44.29% (163)	6.52% (24)	17.12% (63)	368
Auditorium Furniture (seating)	14.4% (53)	20.65% (76)	41.03% (151)	8.7% (32)	15.22% (56)	368
Auditorium Climate (air conditioning/heat/noise)	14.4% (53)	21.47% (79)	39.95% (147)	5.98% (22)	18.21% (67)	368
					Total Respondents	368

25. Natatorium (room that contains pool)

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Natatorium (room that contains pool) Appearance (aesthetics)	11.68% (43)	20.92% (77)	35.87% (132)	5.71% (21)	25.82% (95)	368
Natatorium (room that contains pool) Accessibility (student access)	10.33% (38)	16.58% (61)	39.95% (147)	5.16% (19)	27.99% (103)	368
Natatorium (room that contains pool) Size (dimensions)	10.6% (39)	14.13% (52)	41.3% (152)	7.61% (28)	26.36% (97)	368
Natatorium (room that contains pool) Functionality (layout or design serves performance purpose)	9.78% (36)	14.95% (55)	43.75% (161)	4.89% (18)	26.63% (98)	368
Natatorium (room that contains pool) Furniture (student benches, platforms)	13.04% (48)	22.28% (82)	32.61% (120)	4.89% (18)	27.17% (100)	368
Natatorium (room that contains pool) Storage	10.33% (38)	17.12% (63)	33.7% (124)	4.08% (15)	34.78% (128)	368
Natatorium (room that contains pool) Climate (air conditioning/heat/noise)	16.3% (60)	22.01% (81)	28.53% (105)	5.16% (19)	27.99% (103)	368
					Total Respondents	368

26. Pool

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Pool Appearance (aesthetics)	10.87% (40)	20.11% (74)	39.67% (146)	7.07% (26)	22.28% (82)	368
Pool Accessibility (student access to pool)	8.97% (33)	14.95% (55)	44.02% (162)	5.98% (22)	26.09% (96)	368
Pool Size (dimensions)	10.05% (37)	12.23% (45)	43.21% (159)	9.78% (36)	24.73% (91)	368
Pool Functionality (layout or design serves performance purpose)	9.51% (35)	11.96% (44)	47.83% (176)	6.52% (24)	24.18% (89)	368
Pool Climate (air conditioning/heat/noise)	16.03% (59)	20.38% (75)	32.07% (118)	6.52% (24)	25% (92)	368
Pool Locker Room Appearance (aesthetics)	25.27% (93)	20.92% (77)	27.45% (101)	3.8% (14)	22.55% (83)	368
Pool Locker Room Accessibility (student access)	15.76% (58)	19.02% (70)	34.24% (126)	4.62% (17)	26.36% (97)	368
Pool Locker Room Size (dimensions)	17.93% (66)	18.75% (69)	34.78% (128)	4.35% (16)	24.18% (89)	368
Pool Locker Room Functionality (layout or design serves performance purpose)	18.48% (68)	17.66% (65)	35.33% (130)	4.35% (16)	24.18% (89)	368
Pool Locker Room Climate (air conditioning/heat/noise)	20.65% (76)	23.64% (87)	26.9% (99)	4.35% (16)	24.46% (90)	368
					Total Respondents	368

27. Water Bottle filler stations

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Water Bottle filler stations locations	8.15% (30)	17.12% (63)	46.47% (171)	7.07% (26)	21.2% (78)	368
Water Bottle filler stations Functionality	7.88% (29)	11.96% (44)	49.46% (182)	8.97% (33)	21.74% (80)	368
Water Bottle filler stations quantity	11.14% (41)	17.39% (64)	42.93% (158)	6.52% (24)	22.01% (81)	368
Total Respondents						368

28. Large Group Instruction

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Large Group Instruction Room Appearance (aesthetics)	4.89% (18)	11.68% (43)	40.49% (149)	5.71% (21)	37.23% (137)	368
Large Group Instruction Room Size (dimensions)	5.98% (22)	12.23% (45)	40.22% (148)	4.35% (16)	37.23% (137)	368
Large Group Instruction Room Furniture (student/teacher desks/chairs/shelving)	5.43% (20)	14.4% (53)	37.77% (139)	4.89% (18)	37.5% (138)	368
Large Group Instruction Room Climate (air conditioning/heat/noise)	7.88% (29)	13.59% (50)	36.14% (133)	3.26% (12)	39.13% (144)	368
Total Respondents						368

29. Entrance/Parking/Traffic

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Front Entrance Appearance (aesthetics)	13.59% (50)	25.54% (94)	33.97% (125)	3.53% (13)	23.37% (86)	368
Car drop off location (student)	16.85% (62)	24.46% (90)	30.16% (111)	3.26% (12)	25.27% (93)	368
Student parking location	17.12% (63)	22.28% (82)	29.08% (107)	3.8% (14)	27.72% (102)	368
Student parking quantity of spots	22.28% (82)	22.28% (82)	25% (92)	2.99% (11)	27.45% (101)	368
Staff parking locations	11.68% (43)	13.32% (49)	23.64% (87)	3.8% (14)	47.55% (175)	368
Staff parking quantity of spots	10.87% (40)	16.3% (60)	22.01% (81)	3.53% (13)	47.28% (174)	368
Campus Traffic Flow morning	28.53% (105)	26.63% (98)	18.75% (69)	3.8% (14)	22.28% (82)	368
Campus Traffic Flow afternoon	27.17% (100)	25.82% (95)	17.93% (66)	3.26% (12)	25.82% (95)	368
Total Respondents						368

30. Athletic Fields

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Overall condition of Stadium Field	4.35% (16)	11.41% (42)	39.13% (144)	13.86% (51)	31.25% (115)	368
Overall condition of Auxiliary Field	4.62% (17)	10.87% (40)	36.41% (134)	11.14% (41)	36.96% (136)	368
Overall condition of Softball - Varsity Field	4.62% (17)	9.51% (35)	26.63% (98)	6.25% (23)	52.99% (195)	368
Overall condition of Softball - Junior Varsity Field	4.62% (17)	10.05% (37)	26.09% (96)	5.71% (21)	53.53% (197)	368
Overall condition of Baseball – Varsity Field	4.35% (16)	8.7% (32)	28.53% (105)	7.88% (29)	50.54% (186)	368
Overall condition of Baseball – Junior Varsity Field	6.25% (23)	8.97% (33)	26.9% (99)	5.71% (21)	52.17% (192)	368
Overall condition of Tennis Courts	7.34% (27)	10.6% (39)	26.36% (97)	7.61% (28)	48.1% (177)	368
Overall condition of the Courtyard	6.25% (23)	13.86% (51)	30.98% (114)	8.7% (32)	40.22% (148)	368
Total Respondents						368

31. Lighting

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Lighting (interior) hallways	7.34% (27)	22.55% (83)	48.64% (179)	4.89% (18)	16.58% (61)	368
Lighting (interior) classrooms	7.61% (28)	19.29% (71)	52.17% (192)	4.35% (16)	16.58% (61)	368
Lighting (interior) cafeteria	7.07% (26)	16.85% (62)	54.89% (202)	4.62% (17)	16.58% (61)	368
Lighting (exterior) parking lots	7.07% (26)	18.21% (67)	45.38% (167)	4.62% (17)	24.73% (91)	368
Lighting (exterior) entrances	7.07% (26)	16.85% (62)	48.64% (179)	4.08% (15)	23.37% (86)	368
Lighting (exterior) sidewalks	7.88% (29)	17.12% (63)	44.84% (165)	4.62% (17)	25.54% (94)	368
Total Respondents						368

32. Signage

	Inadequate	Needs Improvement	Meets Expectations	Exceeds Expectations	No Opinion	Response Total
Exterior Directional Signage	6.25% (23)	18.75% (69)	30.71% (113)	2.45% (9)	41.85% (154)	368
Interior Directional Signage	6.25% (23)	18.75% (69)	30.71% (113)	2.99% (11)	41.3% (152)	368
Total Respondents						368

33. Do you feel safe in the school during the day?

Response Total	Response Percent
331	90%
37	10%
Total Respondents	368



34. Do you feel safe in the school after school hours?

Response Total	Response Percent
343	93%
25	7%
Total Respondents	368

