Indoor Air Quality Actions

(Short term IAQ interventions until replacement of HVAC system-as recommended in the FY26 IAQ Report)

Recommendation	Cost Estimate	Funding Source
Service RTU-2 Supply Fan	$500 (Diagnostic)	25-26 School District Funds
Service RTU-3 Supply Fan	$500 (Diagnostic)	25-26 School District Funds
Rebalance Nurse Office AC-3	$500	25-26 School District Funds
Filter Improvements	$1,550	25-26 School District Funds
Service & Repair Exhaust Fans	$4,800	FY27 School District Funds
Variable Air Volume (VAV) Recalibration	$8,200	FY28 Major Alteration Project
Rebalance Air Handler Outside Airflows and Reprogram Demand Control Ventilation	$13,100	FY28 Major Alteration Project
Replace CO2 Sensors	$23,885	FY28 Major Alteration Project
Spaces Without Mechanical Ventilation - Rooms 202, 212, 218, 303, 335	$68,000	FY28 Major Alteration Project
Replace Existing Unit Ventilators	TBD	FY28 Major Alteration Project