

Description

Media/Commons: Modified/installed new duct work




Description

Media/Commons: Set steel for operable partition



Description

Corridor 1000: COntinued fire caulking above ceiling



Description

Media/Commons: Set and framed around IS-03



Description

Media/Commons: Drywall installed



Description

Student/IT Help: Drywall installed



Description

Commons 1007: Framing complete, Drywall installed




Description

Corridor 1000: Insulation installed and inspected



Description

Field South: Field Goal installed



Description

Field North: Field goal post installed



Description

Field: Conduit installed for play clocks and score board