

Student Grade	Chromebook Model	Part Description	Cost
3rd, 4th, 5th, 6th, 7th, 8th	Acer Spin 511	Full System Replacement	\$ 479.00
3rd, 4th, 5th, 6th, 7th, 8th	Acer Spin 511	Display	\$ 89.95
3rd, 4th, 5th, 6th, 7th, 8th	Acer Spin 511	Keyboard	\$ 28.95
3rd, 4th, 5th, 6th, 7th, 8th	Acer Spin 511	Trackpad	\$ 14.95
3rd, 4th, 5th, 6th, 7th, 8th	Acer Spin 511	AC Adapter	\$ 36.95

0

Student Grade	Chromebook Model	Part Description	Cost
TK,K,1st,2nd	Dell 3100	Full System Replacement	\$ 349.99
TK,K,1st,2nd	Dell 3100	Display	\$ 89.99
TK,K,1st,2nd	Dell 3100	Keyboard	\$ 19.99
TK,K,1st,2nd	Dell 3100	Trackpad	\$ 19.99
TK,K,1st,2nd	Dell 3100	AC Adapter	\$ 36.95

All Chromebooks	Any physical damage not listed.	Technology Troubleshooting	\$25/hr + Part replacement cost
-----------------	---------------------------------	----------------------------	---------------------------------

Rev. 7/29/2026