

Holidays, Breaks, Instructor In-Services: No School	
Welding Foundation: October 26, 2026 - November 5, 2026 Veterans Day: November 11, 2026 Thermal Cutting: November 5, 2026 - December 2, 2026 Thanksgiving holiday: November 23, 2026 to November 26, 2026 Shield Metal Arc Welding (SMAW) Plate: December 2, 2026 - March 3, 2027 Winter Break: December 21, 2026 - January 1, 2027 <i>Instructor In-Service: January 4, 2027</i> Classes Resume: January 5, 2027 Martin Luther King Jr. Day: January 18, 2027 President's Day: February 15, 2027 Gas Metal Arc Welding (GMAW) Plate: March 4, 2027 - April 6, 2027 <i>Instructor In-Service: March 15, 2027</i> Spring Break: March 15 - 18, 2027 Classes Resume: March 22, 2027 Flux-Cored Arc Welding (FCAW) Plate: April 7, 2027 - May 3, 2027 Gas Tungsten Arc Welding (GTAW) Plate: May 4, 2027 - August 4, 2027 Memorial Day: May 31, 2027	Summer Break: June 21, 2027 - July 1, 2027 Independence Day (observed): July 5, 2027 <i>Instructor In-Service: July 6, 2027</i> Classes Resume: July 7, 2027 Fabrication Fundamentals: August 4, 2027 - September 7, 2027 Labor Day: September 6, 2027 Shield Metal Arc Welding (SMAW) Pipe: September 8, 2027 - November 2, 2027 Indigenous Peoples Day: October 11, 2027 <i>Instructor In-Service: October 18, 2027</i> Gas Metal Arc & Flux-Cored Arc Combo Welding Pipe: November 3, 2027 - December 7, 2027 Veterans Day: November 11, 2027 Thanksgiving holiday: November 22, 2027 to November 25, 2027 Gas Tungsten Arc & Shield Metal Arc Combo Welding Pipe: December 8, 2027 - February 15, 2028 Winter Break: December 20, 2027 - December 30, 2027 <i>Instructor In-Service: January 3, 2028</i> Classes Resume: January 4, 2028 Martin Luther King Jr. Day: January 17, 2028

Note: Dates are subject to change.