




Lebanon Community School District
Pursuing Excellence for Every Student, Every Day

SEVEN OAK MIDDLE SCHOOL

School Facility Profile

Facility Condition Summary



90 - 100	Excellent
70 - 90	Satisfactory
50 - 70	Minor Modernization Needed
30 - 50	Modernization Needed
0 - 30	Major Modernization Needed

* Older school buildings may contain materials such as asbestos or lead that were commonly used when they were built. Required inspections help ensure these materials remain properly sealed or encapsulated and can safely remain in place. If construction would disturb them, testing and appropriate abatement are required.

HIGH PRIORITY

The most pressing need at Seven Oak is exterior envelope renovations, including roofing, siding, and windows.

STAFF FEEDBACK

Staff recognize an urgent need for HVAC updates, roof repair to stop water damage due to leaks, and improved bathroom functionality.

