
Lebanon Community School District
Pursuing Excellence for Every Student, Every Day

HAMILTON CREEK K-8 SCHOOL

School Facility Profile

Facility Condition Summary



	90 - 100	Excellent
	70 - 90	Satisfactory
	50 - 70	Minor Modernization Needed
	30 - 50	Modernization Needed
	0 - 30	Major Modernization Needed

** Older school buildings may contain materials such as asbestos or lead that were commonly used when they were built. Required inspections help ensure these materials remain properly sealed or encapsulated and can safely remain in place. If construction would disturb them, testing and appropriate abatement are required.*

HIGH PRIORITY

In the oldest wing of the school, electrical systems need updating to support current technology needs.

STAFF FEEDBACK

Staff feedback shows needs focused on building condition, safety, HVAC/air quality, and staff restroom access.

