OVERVIEW

FACILITY CONDITION ASSESSMENT

CONCEPTUAL MASTER PLAN **EXISTING CAMPUS PLAN**



4001 Burnett Ave. Morgan Hill, Ca 95037 sobrato.mhusd.org

Year Built: 2004 Year Modernized: N/A Student Population (2016 - 2017): 1,476 Number of Classrooms: 74 Number of Portables: 2 Site Acreage: 120 acres Building Area: 189,360 square feet Academic Focus:

PRINCIPAL'S TOP 3 'WANTS'

- Fields 1.
- 2. Dirt spaces between classrooms
- Drop-off/Pick-up areas 3.

Desired Program Support Improvements/Additions

- Grouped science labs for the opportunity to share material.
- Additional private offices, conference room(s).
- Storage.
- Dedicated faculty lounge.

Functionality of Space

- Wayfinding is a challenge with the way rooms/ • classroom wings are numbered.
- Break-out rooms were designed for small group collaboration but are not well utilized and are difficult to supervise.
- Approximately 8 classrooms have operable partitions between rooms. These rarely get used and allow noise pollution from the adjacent room.

ASSESSMENT RA	TING LEGEND:
CATEGORY [0]	No Work
CATEGORY [1]	Minor Work
CATEGORY [2]	Minor Modernization
CATEGORY [3]	Standard Modernization
CATEGORY [4]	Major Modernization /
	Reconfiguration
CATEGORY [5]	Complete Replacement

COST SUMMARY

GENERAL

ADA Compliance

Category [0]

No issues were observed or reported. •

Parking

Category [2]

- Parking is ample, however ingress/egress circulation from Burnett Avenue is challenging.
- Parking and drop-off near Administration creates • circulation challenges.

Concrete Paving

Category [0]

No issues were observed or reported. •

AC paving

Category [1]

• AC paving is in fair condition and could use resurfacing.

Ramps & Stairs

Category [0]

This condition does not exist.





OVERVIEW

EXISTING CAMPUS PLAN FACILITY CONDITION ASSESSMENT

CONCEPTUAL MASTER PLAN

COST SUMMARY

ASSESSMENT RATING LEGEND:

CATEGORY [0]	No Work
CATEGORY [1]	Minor Work
CATEGORY [2]	Minor Modernization
CATEGORY [3]	Standard Modernization
CATEGORY [4]	Major Modernization /
	Reconfiguration
CATEGORY [5]	Complete Replacement

SITE AMENITIES **Drinking Fountains**

Category [-]

Drinking fountains are desired at the sports fields. •

Shade Shelter

Category [0]

• No issues were observed or reported.

Bike Area

Category [0]

No issues were observed or reported. •

Covered Walkways

Category [0]

• No issues were observed or reported.

Play Structures

Category [0]

This condition does not exist. •

Athletic Fields & Facilities Category [3]

- Synthetic turf is desired at the playfields.
- Permanent bleachers/spectator seating is desired at • the tennis courts.
- . Additional lockers are desired in the Girls locker room.
- . Roof leaks were reported throughout the Gymnasium, weight room, locker rooms, etc., which has caused water damage throughout. This may be due to the copper piping issue described in the Plumbing section of this document.

Landscape

Category [4]

 Landscaped areas between classroom wings have large areas of decomposed granite, which regularly gets tracked into classrooms and produces ponding in wet seasons.

Irrigation

Category [4]

- Sensors were not installed on the irrigation system, so leaks aren't identified in a timely fashion.
- Replacement of the irrigation system is desired.
- Replacement of the well is desired. .

Fencing & Gates

Category [0]

No issues were observed or reported at existing fencing.

ASSESSMENT OF BUILDINGS Exterior Overall Rating: Category [-]

Paint

Category [3]

 Exterior paint is extremely dirty and needs to be pressure-washed and/or repainted.

Door / Frames / Locks

- Category [0]
- No issues were observed or reported.

Windows

Category [0]

No issues were observed or reported.

Roof

Category [0]

No issues were observed or reported.

ADA Compliance

- Category [0]
- No issues were observed or reported.

Interior

Category [0]

No issues were observed or reported.

Food Service

Category [4]

- The central kitchen needs upgrades in order to be fully operational for all food type storage.
- Satellite food service window is in a poor location, • not central to student gathering areas and serves approximately 60-80 meals per service.



EXISTING CAMPUS PLAN OVERVIEW FACILITY CONDITION ASSESSMENT

CONCEPTUAL MASTER PLAN

COST SUMMARY

ASSESSMENT RATING LEGEND:

CATEGORY [0]	No Work
CATEGORY [1]	Minor Work
CATEGORY [2]	Minor Modernization
CATEGORY [3]	Standard Modernization
CATEGORY [4]	Major Modernization /
	Reconfiguration
CATEGORY [5]	Complete Replacement

Restrooms

Category [1]

• Water is not heated.

ASSESSMENT OF SYSTEMS

Site Utilities

Domestic Water

Category [0]

No issues were observed or reported. •

Fire Protection

Category [0]

No issues were observed or reported. •

Gas

Category [0]

No issues were observed or reported. •

Sewer

Category [0]

No issues were observed or reported.

Storm Drain / Drainage

Category [1]

Minor, occasional clogs in storm drain. •

Mechanical

Overall Rating: Category [5]

- Classroom wings receive HVAC from cooling towers behind the Kitchen/Gym, which are difficult to predict/control.
- Administration, Gym, and Media Center have package units.

Plumbing

Category [4]

- Copper piping at the locker rooms is eroding and • needs to be replaced.
- Pool mechanical room piping needs to be replaced.
- The acid pit for the pool produces a bad odor by the . end of the school year and could benefit from better drainage.

Electrical

Power

Category [0]

No issues were observed or reported.

Fire Alarm

Category [0]

• No issues were observed or reported.

Technology

Category [0]

No issues were observed or reported.

Intercom / Clock / Bell

Category [0]

No issues were observed or reported.

Security

Category [-]

- Intrusion alarms frequently malfunction.
- Additional security cameras are desired. .
- Perimeter fencing is desired.

Lighting

Category [4]

Exterior lighting is desired at the farm. •



FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



Drop-Off Lane



Covered Walkway



Playfields / Athletics







Outdoor Dining



Hardcourts



Typical Concrete Paving



Administration Office



Media Center



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



Windows



Staff Work Room / Lounge



Gymnasium



Exterior Door Hardware



Fitness Room



Pool



Counseling Office



Training Room





OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



Drinking Fountain



Music Room



Art



Typical Classroom



Drama / Theater



Teacher Prep Room



Science Lab



Career and Technical Education



Special Feature: Farm



FACILITY CONDITION ASSESSMENT 513 FACILITY CONDITION ASSESSIVIENT AND SOBRATO HIGH SCHOOL

OVERVIEW


FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







FACILITY CONDITION ASSESSMENT 5.13 FACILITY CONDITION ASSESSIVIENT AND SOBRATO HIGH SCHOOL


OVERVIEW


FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







FACILITY CONDITION ASSESSMENT 513 FACILITY CONDITION ASSESSIMIENT HIGH SCHOOL

OVERVIEW


FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY





Morgan Hill Unified School District



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN CON

CONCEPTUAL MASTER PLAN

COST SUMMARY





Morgan Hill Unified School District



	OVERVIEW	FACILITY CONDITION ASSESSMENT	EXISTING CAMPUS PLAN		CONCEPTL	JAL MASTER PLAN COST SUMMARY	
so	SCOPE OF WORK CATEGORIES		MASTER PLAN COST (2017\$)				
1.	Modernize / Reconfigure Exist	ing Classrooms		\$	6,611,000		
2.	Existing Building Systems, Toi		\$	4,625,000			
3.	Site Utilities		\$	1,360,000			
4.	New Construction (Classroom		\$	-			
5.	5. Science, Arts, CTE & Electives Programs			\$	6,565,000		
6.	Performing Arts Improvements	3		\$	-		
7.	MPR, Student Union & Food S	Service Improvements		\$	9,616,000		
8.	Physical Education Improvem	ents		\$	2,199,000		
9.	Staff & Parent Support			\$	2,180,000		
10.	. Media Center & Student Supp	ort Services		\$	841,000		
11.	. Safety & Security			\$	3,280,000		
12.	. Parking & Drop-Off			\$	3,204,000		
13.	. Outdoor Learning Courts, Qua	ads & Landscape		\$	3,074,000		
14.	. Exterior Play Spaces, Playfield	ls & Hardcourts		\$	13,963,000		
15.	. Instructional Design Furniture			\$	1,632,000		
16.	. Technology Infrastructure and	Equipment		\$	783,000	 The following items are excluded from this budget: Utility hook-up fees & City connection fees Off-site work and traffic signals 	
		Total Construction / Pr	oject Cost (2017\$)	\$	59,933,000	 Land acquisition costs Hazardous material surveys, abatement and disposa Escalation (costs are in 2017\$) 	al