OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



895 Barrett Ave. Morgan Hill, Ca 95037 barrett.mhusd.org

Year Built: 2001 Year Modernized: none Student Population (2016 - 2017): 443 Number of Classrooms: 25 Number of Portables: 0 Site Acreage: 9.64 acres Building Area: 47,845 square feet Academic Focus: None

PRINCIPAL'S TOP 3 'WANTS'

- 1. Update playground structures
- Technology 2.
- Audio/Visual improvements 3.

Desired Program Support Improvements/Additions

- Special Education: .
 - Sensory space/furniture
 - Lockable cabinets
 - Changing table
- Integration with peers
- Computer lab or 1:1 devices campus-wide
- Counseling: •

.

Additional, confidential offices within the

Administration building

- Small group rooms
- Food Service:
 - Enclosed dining area
- May need facilities to support Next Generation Science Standards; site currently does not have a science lab.

Functionality of Space

- Two classrooms have been combined (operable partition opened between rooms 23 and 24) and the space is used as a Teacher Learning Lab for professional development.
- The Library furniture is uncomfortable, uninviting, and makes the space feel tight. The Principal would like furniture that encourages students to stay and is more conducive to reading.

ASSESSMENT RATING LEGEND:						
CATEGORY [0]	No Work					
CATEGORY [1]	Minor Work					
CATEGORY [2]	Minor Modernization					
CATEGORY [3]	Standard Modernization					
CATEGORY [4]	Major Modernization /					
	Reconfiguration					
CATEGORY [5]	Complete Replacement					

GENERAL ADA Compliance

Category [3]

ADA parking spaces do not meet current code compliance. Consider updating striping, signage, and tactile domes.

Parking

Category [0]

No issues were observed or reported.

Concrete Paving

Category [0]

No issues were observed or reported.

AC paving

Category [3]

 AC paving is experiencing normal wear and tear, cracking; need to be resurfaced and repainted in parking lots and hardcourts.

Ramps & Stairs

Category [0]

No issues were observed or reported.





OVERVIEW

EXISTING CAMPUS PLAN FACILITY CONDITION ASSESSMENT

CONCEPTUAL MASTER PLAN

COST SUMMARY

ASSESSMENT RATING LEGEND:

CATEGORY [0]	No Work
CATEGORY [1]	Minor Work
CATEGORY [2]	Minor Modernization
CATEGORY [3]	Standard Modernization
CATEGORY [4]	Major Modernization /
	Reconfiguration
CATEGORY [5]	Complete Replacement

SITE AMENITIES **Drinking Fountains**

Category [5]

Drinking fountains do not meet current code • compliance. Complete replacement is recommended.

Shade Shelter

Category [0]

- The shade structure at Kinder is new and in good condition, but the school site feels that due to its height, does not provide adequate protection.
- Shade at pick-up areas is desired.

Bike Area

Category [0]

No issues were observed or reported. •

Covered Walkways

Category [0]

No issues were observed or reported. •

Play Structures

Category [3]

• Play structures are damaged; may need partial or full replacement.

Athletic Fields & Facilities Category [0]

No issues were observed or reported.

Landscape

Category [1]

 Turf grass areas between classroom wings are in good condition and provide opportunity to add bench seating or other areas for student congregation.

Irrigation

Category [2]

• VFD provides water from well and is problematic during a power outage.

Fencing & Gates

Category [0]

- Tube steel fencing and chain link are used to secure the school.
- No issues were observed or reported.

ASSESSMENT OF BUILDINGS

Exterior

Overall Rating: Category [3]

Stucco shows cracking and chipping due to normal . wear and tear.

Paint

Category [3]

- Paint at exterior doors is new however is showing extreme weathering/fading.
- Buildings are due for a new coat of paint.

Door / Frames / Locks

Category [0]

Aside from the faded paint mentioned above, the condition of the doors, frames, and hardware are aood.

Windows Category [0]

No issues were observed or reported.

Roof

Category [0]

- Standing seam metal roof. •
- The paint is faded, but generally the roofs are in good condition.

ADA Compliance

Category [2]

Ramp at MPR needs a handrail extension.

Interior

Overall Rating: Category [5]

Carpet shows typical wear and tear and need to be replaced.

Food Service

Category [2]

- Needs a dedicated delivery bay separate from dropoff lane.
- Minor table repair is needed. .

Restrooms

Category [0]

No issues were observed or reported.

ASSESSMENT OF SYSTEMS

Site Utilities

Domestic Water

Category [0]

No issues were observed or reported.

Fire Protection

Category [0]

No issues were observed or reported.



FACILITY CONDITION ASSESSMENT

OVERVIEW

ASSESSMENT RATING LEGEND:

No Work

Minor Work

Reconfiguration

Complete Replacement

Electrical

Power

Category [0]

- All rooms have occupancy sensors. •
- No issues were observed or reported. .

Fire Alarm

Category [0]

No issues were observed or reported.

Technology

Category [3]

Smartboards are an estimated 8 years old and due for a refresh.

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

- MPR needs an improved sound/presentation system, enhanced WIFI, and abilities to support performances.
- Consider additional outlets/ways to charge devices within classrooms.
- The Library has very limited technology, consider • providing presentation technology, additional outlets, and tech stations.

Intercom / Clock / Bell

Category [0]

No issues were observed or reported.

No issues were observed or reported.

Lighting

Category [4]

- Consider providing additional exterior lighting at the hardcourts and parking lots.
- Exterior site lighting is poor. .

Security

Category [0]



COST SUMMARY

Category [1]

- Fixtures experience normal wear and tear. ٠
- Facilities clog due to misuse. •
- Water pressure is good.

Minor Modernization Standard Modernization Major Modernization /

Gas Category [0]

CATEGORY [0]

CATEGORY [1]

CATEGORY [2]

CATEGORY [3]

CATEGORY [4]

CATEGORY [5]

No issues were observed or reported.

Sewer

Category [0]

No issues were observed or reported. •

Storm Drain / Drainage

Category [0]

No issues were observed or reported. •

Mechanical

Overall Rating: Category [-]

- District would like to install Alerton energy management system at this site.
- Domestic cooling towers serve the mechanical • system and will need an overhaul in the next 10 vears.
- It was reported that ventilation does not provide ٠ adequate cooling/warming.

Plumbing




OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN CONCEPTUAL MASTER PLAN

COST SUMMARY



Drop-Off Lane



Covered Walkway



Hardcourts



Parking



Outdoor Dining



Play Structure



Security Fencing



Landscaping





OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



Windows



Staff Work Room / Lounge



Multipurpose Room



Exterior Door Hardware



Counseling Office



Kitchen



Administration Office



Conference Room



Food Serving Area



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN COST SUMMARY



Drinking Fountain



Media Center



Restroom



Typical Classroom



Health Office



Teacher Prep Room



OVERVIEW


FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY





Morgan Hill Unified School District FACILITIES MASTER PLAN



OVERVIEW


FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







	OVERVIEW	FACILITY CONDITION ASSESSMENT	EXISTING CAMPUS PLAN		CONCEPTUAL MASTER PLAN		COST SUMMARY
SCOPE OF WORK CATEGORIES					PLAN COST 017\$)		
1.	Modernize / Reconfigure Exis	ting Classrooms		\$	3,929,000		
2.	Existing Building Systems, To		\$	3,287,000			
3.	Site Utilities		\$	26,000			
4.	New Construction (Classroon		\$	-			
5.	Science, Arts, CTE & Elective		\$	862,000			
6.	Performing Arts Improvement		\$	-			
7.	MPR, Student Union & Food		\$	2,454,000			
8.	Physical Education Improven		\$	-			
9.	Staff & Parent Support			\$	1,941,000		
10.	Media Center & Student Sup	port Services		\$	812,000		
11.	Safety & Security			\$	302,000		
12.	Parking & Drop-Off			\$	1,088,000		
13.	Outdoor Learning Courts, Qu	ads & Landscape		\$	623,000		
14.	Exterior Play Spaces, Playfiel	ds & Hardcourts		\$	1,316,000		
15.	Instructional Design Furniture)		\$	732,000		
16.	Technology Infrastructure and	d Equipment		\$	351,000	Utility hook-up feeOff-site work and	
		Total Construction / Pro	oject Cost (2017\$)	\$	17,723,000	Land acquisitionHazardous materEscalation (costs)	ial surveys, abatement and disposal