OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



121 Avenida Grande, San Jose, Ca 95139 | lospaseos.mhusd.org

Year Built: 1974; MPR: ~2007

Year Modernized: Roof replacement (2014); building #4

was renovated in 2002.

Student Population (2016 - 2017): 520

Number of Classrooms: 26 Number of Portables: 5 Site Acreage: 7.65 acres

Building Area: 47,081 square feet

PRINCIPAL'S TOP 3 'WANTS'

- 1. TK/K restrooms and carpet
- Front parking lot pick-up and drop-off
- Field

Desired Program Support Improvements/Additions

- Flexible seating options in all spaces.
- Enhanced integration of technology in MPR for music, performances, and assemblies.
- Administration organization:
 - Community liaison, secretary, and administrative staff should be organized at the front of the Admin building.
 - Views from main Admin desk to outside the front

office/drop-off lane.

- Counselor offices.
- Conversion of resource/TOSA room into a maker space/lab.
- Special Education:
 - Moderate/severe
 - Therapeutic SDC
 - Emotionally disturbed
 - Blind

Functionality of Space

- The current gate configuration requires students to exit the front gate in order to access the TK restroom and nurse office.
- Center pods:
 - Second pod: Resource room/TOSA (Teacher on Special Assignment)
 - Third pod: ASEP (After School Enrichment Program)
 - Fourth pod: YMCA rents room 22 for before and after school programs. During the day, the space houses counseling, CPS, community solutions and is a pull-out/flex room.

- Counseling:
 - Daily counseling is provided to Therapeutic SDC students daily and use 2 small rooms for individual counseling and student safe space (in a padded room).

ASSESSMENT RATING LEGEND:

CATEGORY [0] No Work CATEGORY [1] Minor Work

Minor Modernization CATEGORY [2] CATEGORY [3] Standard Modernization

CATEGORY [4] Major Modernization /

Reconfiguration

CATEGORY [5] Complete Replacement

GENERAL ADA Compliance

Category [-]

Parking

Category [-]

Improvements are desired to the drop-off lane to incorporate a dedicated bus lane.

Concrete Paving

Category [3]

Concrete paving is cracked and in poor condition

AC paving

Category [0]

- Hardcourts were resurfaced in 2015.
- No issues were observed or reported.

Ramps & Stairs

Category [0]

This condition does not currently exist.

OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY

ASSESSMENT RATING LEGEND:

CATEGORY [0] No Work
CATEGORY [1] Minor Work

CATEGORY [2] Minor Modernization
CATEGORY [3] Standard Modernization
CATEGORY [4] Major Modernization /

Reconfiguration

CATEGORY [5] Complete Replacement

SITE AMENITIES

Drinking Fountains

Category [5]

 Drinking fountains do not meet current code requirements and are in poor condition.

Shade Shelter

Category [-]

 The shade structure is new but has been vandalized (fabric cut at corner).

Bike Area

Category [0]

No issues were observed or reported.

Covered Walkways

Category [0]

This condition does not currently exist.

Play Structures

Category [5]

- Play structures are damaged and need to be repaired/replaced at upper playground.
- Play structure is in good condition at Kinder play yard.

Athletic Fields & Facilities

Category [-]

- The fields are in poor condition due to weeds and gophers.
- A running track is desired.

Landscape

Category [0]

• No issues were observed or reported.

Irrigation

Category [5]

- New controller and water valves are needed.
- New backflow preventer is needed.

Fencing & Gates

Category [4]

- The site experiences trespassers regularly.
- Fencing does not provide secured access to Administration from campus.
- Fencing around Kinder playground does not encompass all Kinder and TK classrooms.

ASSESSMENT OF BUILDINGS

Exterior

Paint

Category [-]

Door / Frames / Locks

Category [-]

Windows

Category [-]

Roof

Category [-]

Roof leaks at Library.

ADA Compliance

Category [-]

Interior

Overall Rating: Category [-]

Wall paneling on building interiors are outdated.
 Some teachers have painted interior walls.

Food Service

Category [4]

- No issues were observed or reported in the food prep area.
- The serving area is undersized.

Restrooms

Category [3]

Restrooms need to be modernized.

ASSESSMENT OF SYSTEMS

Site Utilities

Domestic Water

Category [-]

Fire Protection

Category [-]

Gas

Category [-]

5.4 LOS PASEOS ELEMENTARY SCHOOL

OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY

ASSESSMENT RATING LEGEND:

CATEGORY [0] No Work
CATEGORY [1] Minor Work

CATEGORY [2] Minor Modernization
CATEGORY [3] Standard Modernization
CATEGORY [4] Major Modernization /

Reconfiguration

CATEGORY [5] Complete Replacement

Sewer

Category [-]

Storm Drain / Drainage

Category [4]

 Storm drain is clogged due to root intrusion, creating flooding at the basketball court near the portables.
 Pumping is required when area floods.

Mechanical

Overall Rating: Category [-]

No individual mechanical controls in most classrooms.

Plumbing

Category [4]

Pipes are damaged due to root intrusion.

Electrical

Power

Category [0]

No issues were observed or reported.

Fire Alarm

Category [0]

No issues were observed or reported.

Technology

Category [4]

- Technology is needed in the Library.
- Technology needs to be supplemented in the MPR for enhanced presentation/sound quality with a builtin projector screen.
- · WiFi is spotty due to carrier issues.

Intercom / Clock / Bell

Category [-]

- The campus is located in an area of poor reception with the service provider, making the phone and PA system problematic at times.
- PA system is broken at building #3.

Security

Category [5]

- Trespassers frequent the campus; graffiti is evident at portables, MPR roof, and Kinder play yard.
- · Security cameras are desired.

Lighting

Category [-]

No issues were observed or reported at the main buildings. Exterior site lighting is desired at the portables.

OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN







Parking



Typical Concrete Paving



Outdoor Dining



Security Fencing



Hardcourts



Play Structure



Landscaping

OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN



Windows



Exterior Door Hardware



Administration Office



Staff Work Room / Lounge



Counseling Office



Conference Room



Multipurpose Room



Kitchen



Food Serving Area

OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN



Drinking Fountain



Typical Classroom



Interior Hallway



Media Center



Health Office



Restroom



Special Feature: Community Room

OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN





OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN





EXISTING CAMPUS PLAN CONCEPTUAL MASTER PLAN **OVERVIEW FACILITY CONDITION ASSESSMENT MASTER PLAN COST SCOPE OF WORK CATEGORIES** (2017\$)1. Modernize / Reconfigure Existing Classrooms 1.849.000 \$ Existing Building Systems, Toilets & Improved Energy Efficiency \$ 1,428,000 Site Utilities \$ 787.000 New Construction (Classrooms) \$ 14,269,000 Science, Arts, CTE & Electives Programs \$ 2,172,000 Performing Arts Improvements \$ 630,000 MPR, Student Union & Food Service Improvements 2.594.000 Physical Education Improvements \$ Staff & Parent Support \$ 3,912,000 10. Media Center & Student Support Services \$ 5,435,000 11. Safety & Security \$ 1,239,000 12. Parking & Drop-Off \$ 1,029,000 13. Outdoor Learning Courts, Quads & Landscape \$ 312.000 Exterior Play Spaces, Playfields & Hardcourts \$ 1,864,000 Instructional Design Furniture \$ 900,000 16. Technology Infrastructure and Equipment \$ 162.000 **Total Construction / Project Cost (2017\$)** 38,582,000

The following items are excluded from this budget:

- Utility hook-up fees & City connection fees
- Off-site work and traffic signals
- Land acquisition costs
- Hazardous material surveys, abatement and disposal
- Escalation (costs are in 2017\$)