OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



141 Avenida Espana, San Jose, Ca 95139 | martinmurphy.mhusd.org

Year Built: 1978 Year Modernized:

- 2016 (paint and floors);
- Gym was modernized in 2016
- Student Population (2016 2017): 719 Number of Classrooms: 34 Number of Portables: 2 Site Acreage: 17.32 acres Building Area: 70,000 square feet Academic Focus:

PRINCIPAL'S TOP 3 'WANTS'

- 1. Renovation of restrooms / efficiency update
- 2. Locker room update
- 3. Finish electrical update (more outlets and increased capacity)

Desired Program Support Improvements/Additions

- Additional space for Band.
- Upgrades to science labs to meet NGSS. .

Functionality of Space

Improved wayfinding/signage is needed at the entry • to campus.

	TING LEGEND					
ASSESSMENT RATING LEGEND:						
CATEGORY [0]	No Work					
CATEGORY [1]	Minor Work					
CATEGORY [2]	Minor Modernization					
CATEGORY [3]	Standard Modernization					
CATEGORY [4]	Major Modernization /					
	Reconfiguration					
CATEGORY [5]	Complete Replacement					

GENERAL

ADA Compliance

Category [0]

• No issues were observed or reported.

Parking

Category [4]

The front parking lot is small. •

Concrete Paving

Category [0]

No issues were observed or reported. •

AC paving

Category [3]

 Hardcourts and parking areas are in poor condition and need a new slurry coat and paint.

Ramps & Stairs

Category [0]

This condition does not exist.



FACILITY CONDITION ASSESSMENT

OVERVIEW

ASSESSMENT RATING LEGEND:

Landscape

Category [1]

• Landscaping is lush at the expansive turf at the street frontage near the campus entry, but is minimal elsewhere.

EXISTING CAMPUS PLAN

Irrigation

Category [4]

Replacement of irrigation controllers is desired.

Fencing & Gates

Category [0]

 Recent fencing improvements were made, however large gaps in the fencing remain.

ASSESSMENT OF BUILDINGS

Exterior Overall Rating: Category [-]

Paint

Category [0] No issues were observed or reported.

Door / Frames / Locks

Category [0]

No issues were observed or reported.

Windows

Category [3]

Windows are original to the building.

Roof

Category [0]

- Roof was recently replaced. •
- No issues were observed or reported. .

ADA Compliance

Category [0]

No issues were observed or reported.

Interior

CONCEPTUAL MASTER PLAN

Overall Rating: Category [2]

Damaged flooring was observed in the band room at the Gvm.

COST SUMMARY

Food Service

- Category [0]
- No issues were observed or reported.

Restrooms

Category [4]

Toilets clog/overflow regularly.

ASSESSMENT OF SYSTEMS

Site Utilities **Domestic Water**

Category [0]

No issues were observed or reported.

Fire Protection

Category [0]

No issues were observed or reported.

Gas

Category [0]

No issues were observed or reported. •


Sewer

Category [4]

Toilets clog/overflow regularly.







SITE AMENITIES **Drinking Fountains**

Category [5]

Drinking fountains do not meet current code • requirements and are in poor condition.

Shade Shelter

Category [0]

No issues were observed or reported. •

Bike Area

Category [0]

No issues were observed or reported. •

Covered Walkways

Category [0]

This condition does not exist. •

Play Structures

Category [0]

This condition does not exist.

Athletic Fields & Facilities

Category [4]

- The field and track are in poor condition. ٠
- Locker rooms have not been modernized and are original to the building.

CONCEPTUAL MASTER PLAN EXISTING CAMPUS PLAN COST SUMMARY **OVERVIEW** FACILITY CONDITION ASSESSMENT

ASSESSMENT RATING LEGEND:

CATEGORY [0]	No Work				
CATEGORY [1]	Minor Work				
CATEGORY [2]	Minor Modernization				
CATEGORY [3]	Standard Modernization				
CATEGORY [4]	Major Modernization /				
	Reconfiguration				
CATEGORY [5]	Complete Replacement				

Storm Drain / Drainage

Category [0]

No issues were observed or reported.

Mechanical

Overall Rating: Category [0]

٠ Mechanical system was replaced in 2012.

Plumbing

Category [4]

Toilets clog/overflow regularly. ٠

Electrical

Power

Category [4]

Electrical capacity needs to be increased. ٠

Fire Alarm

Category [5]

Fire alarm needs to be upgraded. •

Technology

Category [0]

No issues were observed or reported.

Intercom / Clock / Bell

Category [2]

• PA and phone system are tied to the internet connection, which is problematic at times.

Security

Category [-]

Lighting

Category [0]

No issues were observed or reported.



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN


COST SUMMARY







Parking



Outdoor Dining



Hardcourts



Administration Office



Media Center





Playfields / Athletics

OVERVIEW




EXISTING CAMPUS PLAN CONCEPTUAL MASTER PLAN COST SUMMARY



Windows



Staff Work Room / Lounge



Gymnasium



Exterior Door Hardware





Food Serving Area



Counseling Office



Interior Hallway





OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



Drinking Fountain



Music Room







Drama / Theater



Teacher Prep Room



Science Lab



Career and Technical Education



OVERVIEW


FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY





Morgan Hill Unified School District FACILITIES MASTER PLAN



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







OVERVIEW


FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY





Morgan Hill Unified School District FACILITIES MASTER PLAN



	OVERVIEW	FACILITY CONDITION ASSESSMENT	EXISTING CAMF	US PLAN CONCEPTU		IAL MASTER PLAN	COST SUMMARY
SCOPE OF WORK CATEGORIES			MASTER PLAN COST (2017\$)				
1.	Modernize / Reconfigure Exist	ing Classrooms		\$	3,915,000		
2.	2. Existing Building Systems, Toilets & Improved Energy Efficiency			\$	3,557,000		
3.	Site Utilities			\$	1,043,000		
4.	New Construction (Classroom	s)		\$	-		
5.	Science, Arts, CTE & Electives	Programs		\$	1,265,000		
6.	Performing Arts Improvements	6		\$	2,146,000		
7.	7. MPR, Student Union & Food Service Improvements			\$	802,000		
8.	8. Physical Education Improvements			\$	1,752,000		
9.	9. Staff & Parent Support			\$	3,865,000		
10.	Media Center & Student Supp	ort Services		\$	1,676,000		
11.	Safety & Security			\$	1,618,000		
12.	Parking & Drop-Off			\$	1,112,000		
13.	Outdoor Learning Courts, Qua	ads & Landscape		\$	775,000		
14.	Exterior Play Spaces, Playfield	ls & Hardcourts		\$	3,236,000		
15.	Instructional Design Furniture			\$	872,000		
16.	Technology Infrastructure and	Equipment		\$	419,000	Utility hook-up feOff-site work and	
		Total Construction / Pro	oject Cost (2017\$)	\$	28,053,000	Land acquisitiorHazardous mateEscalation (cost	erial surveys, abatement and disposal

