OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

CATEGORY [0]

CATEGORY [1]

CATEGORY [2] CATEGORY [3]

CATEGORY [4]

COST SUMMARY



13745 Llagas Ave. San Martin, Ca 95046 | smg.mhusd.org

Year Built:

- San Martin: 1955
- Gwinn: 1964

Year Modernized: 2017 (Gwinn) Student Population (2016 - 2017): 575 Number of Classrooms: 36 Number of Portables: 2 Site Acreage: 18.73 acres Building Area: 54,487 square feet

PRINCIPAL'S TOP 3 'WANTS'

- 1. Bigger Multipurpose Room and tables for middle school
- Repair gutters and ceiling gutters 2.
- Paths from playground to bathroom outside Library 3.

Desired Program Support Improvements/Additions

 Additional classrooms as the campus grows to a full K-8 site.

Functionality of Space

- Motor skills / Occupational Therapy uses a portable . across the hardcourts on the San Martin side.
- Special Education
 - SDC
 - RSP
 - SH

Complete Replacement CATEGORY [5] GENERAL ADA Compliance

ASSESSMENT RATING LEGEND:

No Work

Minor Work

Minor Modernization

Major Modernization / Reconfiguration

Standard Modernization

Category [0]

• No issues were observed or reported.

Parking

Category [0]

- Parking and drop-off along Llagas Avenue has been newly replaced.
- No issues were observed or reported with the • parking lot off of North Street.

Concrete Paving

Category [0]

No issues were observed or reported.

AC paving

Category [3]

Hardcourts are in poor condition.

Ramps & Stairs

Category [0]

This condition does not exist.





FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY

ASSESSMENT RATING LEGEND:

CATEGORY [0]	No Work
CATEGORY [1]	Minor Work
CATEGORY [2]	Minor Modernization
CATEGORY [3]	Standard Modernization
CATEGORY [4]	Major Modernization /
	Reconfiguration
CATEGORY [5]	Complete Replacement

SITE AMENITIES **Drinking Fountains**

Category [3]

- New drinking fountains have been installed on the • Gwinn side.
- Drinking fountains on the San Martin side are in poor • condition.

Shade Shelter

Category [0]

Shade shelters at the outdoor environmental science • labs are in new condition.

Bike Area

Category [0]

• No issues were observed or reported.

Covered Walkways

Category [2]

Walkway covers are in good condition, however • there are gaps in the vertical plane where the walkway meets the building. These gaps allow rainfall onto the walkway.

Play Structures

Category [0]

No issues were observed or reported. •

Category [-] Playfields may need improvements to accommodate

the program for middle school.

Landscape

Category [0]

Landscaping has been recently replaced and is in good condition.

Irrigation

Category [4]

Irrigation wiring is new. .

Athletic Fields & Facilities

- Irrigation on the San Martin side is sourced from a tank that may be reaching its useful life expectancy.
- Irrigation on the Gwinn side is sourced from a well which needs a new compressor for adequate water pressure.

Fencing & Gates

Category [1]

There are gaps in the chainlink fence at the Gwinn . hardcourts.

ASSESSMENT OF BUILDINGS

Exterior

Paint Category [0]

No issues were observed or reported.

Door / Frames / Locks

Category [3]

- Doors and frames on San Martin side show mild • damage due to age including chipped paint, leaks in hydraulic door closures, and dents in the frames.
- Locks appear to have been recently replaced and are functional.

Windows Category [3]

- Windows appear to be original, single pane at the buildings on the San Martin side.
- Windows have been recently replaced on the Gwinn side.

Roof

Category [5]

Gutters are damaged and leak onto walkway. •

ADA Compliance

Category [3]

- Restrooms on San Martin side need to be modernized.
- Many exterior thresholds do not provide a smooth transition to the interior.

Interior

Overall Rating: Category [3]

- The interior of classrooms on the San Martin side have not had recent modernization and appear in fair to poor condition.
- Interiors on the Gwinn side have been recently modernized or reconfigured.

Food Service

Category [4]

Kitchen/MPR needs to be modernized and/or • expanded to serve a K-8 community.

Restrooms

Category [3]

Restrooms on San Martin side need to be modernized.



EXISTING CAMPUS PLAN

OVERVIEW

ASSESSMENT RATING LEGEND:

No Work

Minor Work

Minor Modernization

Reconfiguration

Backflow preventer needs to be replaced on San

No issues were observed or reported.

Standard Modernization

Complete Replacement

Major Modernization /

CATEGORY [0]

CATEGORY [1]

CATEGORY [2] CATEGORY [3]

CATEGORY [4]

CATEGORY [5]

Site Utilities

Category [5]

•

•

•

•

Gas

Sewer Category [0]

Domestic Water

Fire Protection Category [0]

Category [0]

Category [0]

Martin side.

ASSESSMENT OF SYSTEMS

Plumbing

FACILITY CONDITION ASSESSMENT

Category [0]

No issues were observed or reported.

Electrical

Power

Category [1]

• Additional outlets are desired at the reception desk of Administration.

Fire Alarm

Category [2]

- Site fire panels are broken into three locations (on San Martin side, on Gwinn side, and at new renovations on Gwinn side), requiring each panel to be accessed/reset individually.
- Consider replacing wiring to alleviate frequency of • false alarms.

Technology

Category [0]

No issues were observed or reported.

Intercom / Clock / Bell

Category [0]

No issues were observed or reported.

Security

Category [0]

Consider replacing wiring to alleviate frequency of • false alarms.

Lighting

Category [0]

Lighting is desired at the North Street parking lot.

Mechanical

Overall Rating: Category [5]

Storm Drain / Drainage

Mechanical units in classroom wings are problematic ٠ and in poor condition.

CONCEPTUAL MASTER PLAN




COST SUMMARY

OVERVIEW

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



Drop-Off Lane



Parking



Typical Concrete Paving



Covered Walkway



Hardcourts



Outdoor Dining



Play Structure



Security Fencing



Landscaping



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







Staff Work Room / Lounge



Counseling Office

Exterior Door Hardware



Multipurpose Room



Kitchen



Administration Office



Conference Room



Food Serving Area



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN CONCEPTUAL MASTER PLAN

COST SUMMARY



Drinking Fountain



Typical Classroom



Interior Hallway





Special Feature: Outdoor Science Station





Media Center



Restroom



Health Office



Teacher Prep Room



FACILITY CONDITION ASSESSMENT

5.8 **SAN MARTIN / GWINN ENVIRONMENTAL SCIENCE ACADEMY**


OVERVIEW

FACILITY CONDITION ASSESSMENT

CONCEPTUAL MASTER PLAN EXISTING CAMPUS PLAN

COST SUMMARY





Morgan Hill Unified School District FACILITIES MASTER PLAN



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY





Morgan Hill Unified School District FACILITIES MASTER PLAN



	OVERVIEW	FACILITY CONDITION ASSESSMENT	EXISTING CAMPUS PLAN		CONCEPTUAL MASTER PLAN	
SCOPE OF WORK CATEGORIES		MASTER PLAN COST (2017\$)				
1.	Modernize / Reconfigure Exis	ting Classrooms		\$	-	
2.	Existing Building Systems, To	ilets & Improved Energy Efficiency		\$	-	
3.	Site Utilities			\$	780,000	
4.	New Construction (Classroon	ns)		\$	10,812,000	
5.	Science, Arts, CTE & Elective	s Programs		\$	1,569,000	
6.	Performing Arts Improvement	S		\$	765,000	
7.	MPR, Student Union & Food	Service Improvements		\$	9,122,000	
8.	Physical Education Improvem	nents		\$	797,000	
9.	Staff & Parent Support			\$	-	
10.	Media Center & Student Supp	port Services		\$	760,000	
11.	Safety & Security			\$	1,848,000	
12.	Parking & Drop-Off			\$	240,000	
13.	Outdoor Learning Courts, Qu	ads & Landscape		\$	1,272,000	
14.	14. Exterior Play Spaces, Playfields & Hardcourts			\$	3,553,000	
15.	Instructional Design Furniture			\$	507,000	
16.	Technology Infrastructure and	l Equipment		\$	-	 The following item Utility hook-up fe Off-site work and
		Total Construction / Pr	oject Cost (2017\$)	\$	32,025,000	 Land acquisition Hazardous mate Escalation (costs)

The following items are excluded from this budget:

- Utility hook-up fees & City connection fees
- Off-site work and traffic signals
- Land acquisition costs
- Hazardous material surveys, abatement and disposal
- Escalation (costs are in 2017\$)





COST SUMMARY