

School Radon Testing Reporting Form

General Instructions

According to MS 123B.571, radon testing conducted in public school buildings eligible for health and safety (i.e., not charter schools) must be reported to the Minnesota Department of Health.

For the purpose of this form, a building is defined as an occupied facility that has a unique address, including administrative buildings. A building could be a single structure or a complex of structures. For reference, all district owned buildings entered on the Minnesota Department of Education "Facilities Age and Square Footage Report" should be utilized.

Please submit information about the most recent round or cycle of testing conducted for each building, unless this was already reported to MDH in the 4/4/11 survey. We do not need details of prior rounds of testing.

- 1. Submit summary information and raw data if either of the following apply:
 - a. Radon testing has been completed in a building since the MDH 'School Radon Testing Survey' dated April 4, 2011, or
 - b. Radon testing was completed at some time previously and your district did not report radon testing in the MDH 'School Radon Testing Survey' dated April 4, 2011.
- 2. Complete one survey for each building tested
- 3. Submit the survey, raw data (e.g., laboratory analysis report) and a building map to MDH by email, to health.indoorair@state.mn.us
- 4. If follow-up testing, mitigation, and/or post-mitigation testing is not yet completed, please submit a completed form and raw data when the work is completed.

Contact Person for this Form
Name: DAVID MOREDOCK
Phone: 651-258-6294
Email: dmoredoca Sowashco. K/2. MN. US
Mailing Address: 7362 E. Point Doglas & S.
COTTAGE GROVE, MN 55016
35016

Radon Results for Each School Building
1. District Name & Number: SOUTH WASHINFTON COUNTY ISD 833
2. School Building Name: COTTAGE GROVE ELEMENTARY
3. School Building Address: 744765#ST ST Sottable Grove, MN 55016
4. What type of test kit was used? Manufacturer: Accustage Device name: Lious Scintilla from
Comments WA
5. When were the test kits retrieved? (month/year) More than one date can be entered if parts of buildings were tested at different times
Comments NA
6. How long were the test kits deployed in the rooms?
Comments: V[A
7. Was testing conducted over: a. Weekends? Yes No b. Holidays or Breaks? Yes No
Comments:
8. Were all frequently-occupied rooms in contact with the ground tested? Yes No No This includes: 1) rooms on grade and; 2) rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.
Comments: RANDOM SAMPLE
9. How many frequently-occupied rooms were tested?
Comments:
10. How many frequently-occupied rooms were at or above four picocuries per liter (≥ 4 pCi/L)?
Comments: NA
11. Were test results reported at a school board meeting? Yes No No If results will be reported at the next meeting, note in comments the month and year of the scheduled meeting in the comments section.
Comments: 3-26-15

If one or more rooms ≥4 pCi/L, complete Questions 12-14.

12. How many of the rooms \geq 4 pC/L had follow-up to	testing results that were:
a. \geq 4 pCi/L b. < 4 pCi/L	
'Follow-up' testing means testing done, prior to any radon	mitigation, to confirm or verify initial test results in those
	on monitor (CRM) was used, indicate concentration during
occupied times. If no follow-up testing was done, write the	
done in the future, note in comments the planned month and	d year in the comments section
done in the fatare, note in comments the planned month and	
Commants	
Comments:	
13. How many of the rooms \geq 4 pCi/L:	
13. How many of the rooms ≥ 4 pC//L:	41
a. were mitigated? b. had o 'Mitigated' means building changes such as adjusting the e	other corrective measures?
'Mitigated' means building changes such as adjusting the e	xisting HVAC system, increasing tresh air ventilation rate,
	Other corrective measures' could include moving staff out of
a room and making a room unoccupied or trying to seal rad	on entry points. If mitigation or other corrective measure(s)
will be completed in the future, note in comments the plant	ned month and year in the comments section.
Comments:	/
14. How many rooms re-tested after mitigation were	
a. \geq 4 pCi/L b. < 4 pCi/L	c. not tested
If post-mitigation re-testing will be completed in the future	, note the planned month and year in the comments section.
,	
Comments:	
,	
• /	
λ /	
IN /	
. ,	
/ /	
/ <i>H</i>	
/ ' 1	
/	
/	
/	



NELAC NY 11769 NRPP 101193 AL NRSB ARL0017

EPA Method #402-R-92-004 Liquid Scintillation NRPP Device Code 8088 NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 15-02-01

South Washington County Schools 7362 East Point Douglas Road South Cottage Grove MN 55016

Cottage Grove Elementary 7447 65th Street South Cottage Grove MN 55016

Log Number	Device Number	Test Exposu	re Duration:	Area Tested	Result (pCi/L)
1753134	2881001	02/16/2015 9:23 am	02/19/2015 8:24 am	Bldg. CGE Unit B115 First Floor	1.3
1753135	2881002	02/16/2015 9:25 am	02/19/2015 8:25 am	Bldg. CGE Unit C101 First Floor	0.8
1753136	2881003	02/16/2015 9:27 am	02/19/2015 8:26 am	Bldg. CGE Unit C119 First Floor	0.6
1753137	2881004	02/16/2015 9:30 am	02/19/2015 8:27 am	Bldg. CGE Unit C108 First Floor	0.6
1753138	2881005	02/16/2015 9:31 am	02/19/2015 8:28 am	Bldg. CGE Unit C106 First Floor	0.6
1753139	2881006	02/16/2015 9:32 am	02/19/2015 8:29 am	Bldg. CGE Unit D108 First Floor	0.4
1753140	2881007	02/16/2015 9:32 am	02/19/2015 8:29 am	Bldg. CGE Unit D108 First Floor	0.6
1753141	2881008	02/16/2015 9:35 am	02/19/2015 8:32 am	Bldg. CGE Unit E107 First Floor	0.8
1753142	2881009	02/16/2015 9:40 am	02/19/2015 8:33 am	Bldg. CGE Unit E118 First Floor	0.4
1753143	2881010	02/16/2015 9:41 am	02/19/2015 8:34 am	Bldg. CGE Unit E109 First Floor	1.0

Comment: Confidential: Release results to client only South Washington County Schools was emailed a copy of this report.

Test Performed By: David Moredock

Distributed by: South Washington County Schools

Date Received: 02/24/2015 Date Logged: 02/24/2015 Date Analyzed: 02/25/2015 Date Reported: 02/25/2015

> Report Reviewed By: M. Shape Report Approved By: Carolyn K. Allen, President, AccuStar Labs

Disclaimer: The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.



NELAC NY 11769 NRPP 101193 AL NRSB ARL0017 EPA Method #402-R-92-004 Liquid Scintillation NRPP Device Code 8088 NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 15-02-01

South Washington County Schools 7362 East Point Douglas Road South Cottage Grove MN 55016 Cottage Grove Elementary 7447 65th Street South Cottage Grove MN 55016

Log Number	Device Number	Test Exposure Duration:		Area Tested	Result (pCi/L)
1753144	2881011	02/16/2015 9:41 am	02/19/2015 8:35 am	Bldg. CGE Unit E101 First Floor	0.4
1753145	2881012	02/16/2015 9:43 am	02/19/2015 8:36 am	Bldg. CGE Unit E116 First Floor	0.4

Comment: Confidential: Release results to client only South Washington County Schools was emailed a copy of this report.

Test Performed By: David Moredock

Distributed by: South Washington County Schools

Report Reviewed By: M. Shay Report Approved By: Carolyn K. Allen, President, AccuStar Labs

Disclaimer:

Ca

The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical y

The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.