

School Radon Testing Reporting Form

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

Instructions

1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
2. Include this form, raw data (e.g. laboratory report) and a building map.
3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
4. Email information to health.indoorair@state.mn.us.

Contact Information

Name: <i>Wendy German</i>	
Mailing Address: <i>7362 East Point Douglas Rd, Cottage Grove, MN 55016</i>	
Phone: <i>320-224-1908</i>	Email: <i>wgerman@sowashco.org</i>

Initial Radon Testing Information

School Building Name: <i>Pathways to Independence</i>	
School District & District Number: <i>South Washington County Schools - District 833</i>	
Building Address: <i>1750 Weir Dr, Woodbury MN 55125</i>	
Test Kit Manufacturer: <i>AirCheck</i>	Device Name: <i>Pro Check</i>
Date of Kit Retrieval (DD/MM/YY): <i>03/21/19</i>	Length of Test (days): <i>3</i>
How many rooms were tested? <i>5</i>	
Does the test period include weekends? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Does the test period include school breaks or holidays? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

SCHOOL RADON TESTING REPORTING FORM

Were all frequently-occupied ground contact rooms tested?¹ Yes No
 If no, did you attempt to test all frequently occupied ground contact rooms, meaning test kits were placed in all these rooms? Yes No

How many rooms had results ≥ 4 pCi/L?: 0

Were the results reported at a school board meeting? Yes No *Scheduled for upcoming meeting*

Follow-up Testing, Mitigation, & Post-Mitigation Testing

If one or more rooms tested ≥ 4 pCi/L, please answer the questions below:

How many rooms had follow-up testing?:

Number of rooms with follow-up results	≥ 4 pCi/L:	< 4 pCi/L:
--	-----------------	------------

Of the rooms that had test results ≥ 4 pCi/L, how many rooms were:

mitigated by HVAC balancing or operational changes? :

mitigated by installation of active soil depressurization?:

addressed through other corrective measures?²:

What was the cost of the installation and/or HVAC service work, to mitigate radon? \$

What is the known or anticipated annual operating cost of mitigation (estimate)? \$

After radon mitigation, how many rooms were retested?:

Post mitigation results (# of rooms)	≥ 4 pCi/L:	< 4 pCi/L:
--------------------------------------	-----------------	------------

¹ This includes classrooms, offices, break rooms, laboratories, cafeterias, libraries, auditoriums, gymnasiums, etc. It includes rooms on grade and rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.

² 'Other corrective measures' could include moving staff out of a room and making a room unoccupied or trying to seal radon entry points.

5rooms



Pathways to Learning	
Building Room Numbers and Names	
School Year 2018 / 2019	
09/14/2018	

March 26, 2019

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

PATHWAYS

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9197875	108	2019-03-18 @ 10:00 am	2019-03-21 @ 10:00 am	< 0.3	2019-03-25
9197876	109	2019-03-18 @ 10:00 am	2019-03-21 @ 10:00 am	0.8 ± 0.4	2019-03-25
9197871	110	2019-03-18 @ 10:00 am	2019-03-21 @ 10:00 am	0.6 ± 0.4	2019-03-25
9197872	111	2019-03-18 @ 10:00 am	2019-03-21 @ 10:00 am	1.1 ± 0.4	2019-03-25
9197868	COMMONS	2019-03-18 @ 10:00 am	2019-03-21 @ 10:00 am	0.6 ± 0.4	2019-03-25

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498