

Lead in Water Testing Results  
South Washington County Schools  
Woodbury Middle School

On October 4th, 2018 Woodbury Middle School's drinking water was tested for concentration of lead.

**All water sources tested less than 20 parts-per-billion. No action was taken at this time.**

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULTS (in ug/L)</b>
Hallway (Gym B, 1)	FOUNTAIN	1.7
Hallway (Gym B, 2)	FOUNTAIN	2.2
Hallway (Gym B, 3)	FOUNTAIN	.79
Hallway (Gym B, 4)	FOUNTAIN	1.0
Hallway (outside D122)	FOUNTAIN	0
Hallway (outside G106, left)	FOUNTAIN	0
Hallway (outside G106, right)	FOUNTAIN	0
Hallway (outside G106)	BOTTLE FILLER	0
Hallway (outside H106, left)	FOUNTAIN	0
Hallway (outside H106, right)	FOUNTAIN	0
Hallway (outside H106)	BOTTLE FILLER	0
Hallway (outside E206)	FOUNTAIN	7.7
Office	SINK	11.3
Nurse's Office	SINK	7.8
Nurse's Office	FOUNTAIN	9.3
Lobby	FOUNTAIN	.12
Lobby	BOTTLE FILLER	0
Room B110	SINK	3.2

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULTS (in ug/L)</b>
Hallway (outside B114)	FOUNTAIN	.49
Cafeteria	FOUNTAIN	.12
Cafeteria	BOTTLE FILLER	.11
Kitchen	SINK	1.6
Kitchen	SPRAYER	.53
Hallway (outside Gym A)	FOUNTAIN	.33
Hallway (outside F219)	FOUNTAIN	1.6
Hallway (outside F212)	FOUNTAIN	1.4
Media Center Workroom	SINK	5.3
Hallway (outside 202)	FOUNTAIN	.10