

Lead in Water Testing Results
South Washington County Schools
Woodbury Elementary School

On September 20th, 2018 Woodbury Elementary School's drinking water was tested for concentration of lead.

The following water sources tested less than 20 parts-per-billion.

No action was taken at this time.

LOCATION	SOURCE	RESULTS (in ug/L)
Nurse's Bathroom	SINK	8.7
Gym A	FOUNTAIN	0
Gym B	FOUNTAIN	6.2
Cafeteria	FOUNTAIN	0
Cafeteria	BOTTLE FILLER	0
Kitchen (1)	SINK	3.3
Kitchen (2)	SPRAYER	7.0
Kitchen (3)	SINK	8.5
Staff Room	SINK	5.6
Room 203	SINK	10.1
Room 203	FOUNTAIN	6.9
Room 205	SINK	19.6
Room 205	FOUNTAIN	4.7
Room 207	SINK	11.8
Room 207	FOUNTAIN	10.0
Room 209	SINK	11.6

LOCATION	SOURCE	RESULTS (in ug/L)
Room 209	FOUNTAIN	6.5
Room 211	SINK	9.6
Room 211	FOUNTAIN	7.9
Room 215	SINK	11.4
Room 221	SINK	9.2
Room 218	SINK	11.7
Room 216	SINK	13.9
Hallway (south)	SINK	1.8
Room 210	SINK	16.7
Room 210	FOUNTAIN	12.0
Room 208	SINK	5.3
Room 208	FOUNTAIN	15.9
Room 206	SINK	11.7
Room 206	FOUNTAIN	7.1
Room 204	SINK	14.1
Room 204	FOUNTAIN	12.4
Room 202	SINK	11.8
Room 202	FOUNTAIN	3.7
Media Center Work Room	SINK	6.2
Room 127	SINK	4.5
Room 127	FOUNTAIN	3.8
Room 128	SINK	2.9
Room 128	FOUNTAIN	1.3
Room 126	SINK	2.9

LOCATION	SOURCE	RESULTS (in ug/L)
Room 126	FOUNTAIN	1.6
Room 124	FOUNTAIN	2.2
Hallway (east, left)	FOUNTAIN	1.6
Hallway (east, right)	FOUNTAIN	1.1
Room 122	SINK	3.9
Room 122	FOUNTAIN	1.8
Room 120	SINK	3.0
Room 120	FOUNTAIN	3.6
Room 118	SINK	2.3
Room 118	FOUNTAIN	3.1
Room 116	SINK	4.1
Room 116	FOUNTAIN	4.4
Room 114	SINK	4.5
Room 114	FOUNTAIN	5.0
Room 112	SINK	11.8
Room 112	FOUNTAIN	10.2
Room 111	SINK	10.3
Room 111	FOUNTAIN	17.9
Room 110	FOUNTAIN	6.9
Room 109	SINK	3.8
Room 109	FOUNTAIN	7.1
Room 108	SINK	6.2
Room 108	FOUNTAIN	7.4
Room 107	SINK	6.0

LOCATION	SOURCE	RESULTS (in ug/L)
Room 107	FOUNTAIN	5.8
Room 106	SINK	4.9
Room 106	FOUNTAIN	9.9
Room 105	SINK	5.5
Room 105	FOUNTAIN	9.2
Room 104	SINK	5.9
Room 104	FOUNTAIN	8.5
Room 103	SINK	6.6
Room 103	FOUNTAIN	9.4
Hallway (north)	FOUNTAIN	7.8
Room 102	FOUNTAIN	15.7
Room 101	SINK	9.6
Room 101	FOUNTAIN	8.5

The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources have been replaced and a re-test was administered. Results of the initial test and retest are below. No water sources re-tested over 20 parts-per-billion, so no further action was taken at this time.

LOCATION	SOURCE	INITIAL RESULTS (in ug/L)	RE-TEST RESULTS
Nurse's Office	SINK	22.1	8.1
Room 102	SINK	61.7	3.7
Room 110	SINK	24.2	15.8
Room 212	SINK	24.5	8.2
Room 214C	SINK	46.5	3.0
Room 220	SINK	25.6	10.6
Room 219	SINK	20.3	7.8
Room 213	SINK	33.6	8.7