# 5.4 EXISTING SITE CONDITIONS YORBA 6-8 MIDDLE





# **EXISTING SITE INFORMATION**

Year Built: 1956

Year Modernized: 2013

Student Population (2019-2020): 517

Grade Levels: 6-8

Number of Permanent Classrooms: 34

Number of Relocatables: 0

Site Acreage: 18.23

Permanent Building Area: 64,702 sf Relocatable Classroom Area: 0

Other Relocatable Area: 0

Parking: 65 spaces + 5 accessible

# **OVERVIEW**

The Condition Assessment information outlined on the following pages was gathered in the following four ways:

- 1. Each Principal filled out a survey related to the current educational programs, the needs and goals of those programs, and the ways in which physical space is supporting or hindering the program goals.
- 2. The District provided a Facilities Assessment that was completed internally in 2018.
- 3. LPA met with and interviewed the various trades in the Maintenance & Operations Department to understand what work has been completed, where they have identified

- issues and what items generate the most work orders.
- 4. LPA team members met with each Principal to ask questions and walk each site with them to get a better understanding of the layout, areas of concern, and work completed to-date.

# RECENT DEFERRED/MAJOR MAINTENANCE & RENOVATION PROJECTS

- 2013 Campus-wide Modernization
  - Upgraded classroom technology, including student computer stations, a technology station at the teacher's desk, an LCD projector and a teaching wall
  - Upgraded lighting, cabling and power at classrooms
  - Upgraded HVAC at Buildings A-K
  - Replaced acoustic ceiling tiles at classrooms
  - Installed new VCT flooring; installed quarry tile at the kitchen
  - Installed new hollow metal exterior doors and door hardware
  - Installed new vinyl tackable wall surface on (3) walls at classrooms
  - Replaced single pane glass with dual-paned tempered glass
  - Installed new casework, including a built-in teacher's desk, bookcase and computer stations at classrooms
  - Installed VOIP telephone systems at classrooms
  - New fire alarm system at classrooms
  - Reconfigured area for SH students to provide a changing room and Living Skills Lab
  - Reconfigured the Administration area



# 5.4 EXISTING SITE CONDITIONS YORBA 6-8 MIDDLE



- Installed new casework in administrative areas
- Installed new fencing to secure the campus during school hours
- Upgraded the Multi-purpose building to enhance the arts program
- New Kitchen building addition
- Upgraded the Computer Lab HVAC, lighting, cabling, and power
- Upgraded HVAC, lighting, cabling and power plus an LCD projector screen at Drama, Art, Choral, Band and Science
- Modernized (3) science labs
- Added HVAC in the Multi-purpose Building G for the Auditorium, Stage and Faculty Lounge
- Added heating to the locker room area of Building L
- Upgraded all restrooms to meet ADA requirements
- Redesigned restrooms at the locker rooms to add capacity to the campus
- Added one lift and a ramp to the stage area meet ADA requirements
- Upgraded site ramps and site dropoffs to meet ADA requirements
- Addressed ongoing drainage issues
- 2013 New Kitchen Building
- 2013 Addition to Administration Building
- 2018 Security System/IP Cameras
- 2018 Solar Panels installed

#### PRINCIPAL COMMENTS

#### Site

- The drop-off and parking areas are very limited. Large professional development trainings require people to park on the playfields.
- Delivery access interferes with student drop-off and pick-up.
- An access gate between California

- Elementary and Yorba Middle School, along the northeast edge, is desired.
- Need better basketball courts.
- The solar panels located north of the track & field cause major concerns regarding curb appeal and takes up field space and hardcourt space.
- Would like safety circles painted on concrete to indicate door swings.
- Security Cameras installed in summer 2018 is not working as of November 2018.

#### Program

- Need a gymnasium so the physical education teachers can do indoor activities/sports, especially in inclement weather.
- Would like more sinks in the Science and STEM labs.
- A dedicated classroom for video and broadcasting is desired.
- A Dual Immersion program will begin in the 2020-2021 school year.
- An indoor space for students to eat is needed.
- Would like a nicer Staff Lounge.
- The Library needs to be renovated.
- The Multi-Purpose Room (MPR) needs a better sound system.
- The Locker Rooms are in need of an update. The old ones were converted into classroom space.

#### **Highest Priorities**

- 1. Gymnasium
- Better air conditioning and a better sound system at the Multi-Purpose Room (MPR) for events with large groups of people
- 3. A larger staff parking lot

#### **COMMUNITY USE**

- Crossway Church of Orange County uses some classrooms, restrooms, and the MPR on Sundays.
- OJSC Youth Soccer uses the fields for practice and games after school hours.

# **CONDITION ASSESSMENT**

Each category evaluated is ranked using a facilities condition category as follows:

- CATEGORY [0]: No Work.
- CATEGORY [1]: Minor Modernization.
- CATEGORY [2]: Standard Modernization.
- CATEGORY [3]: Major Modernization/ Reconfiguration/ Complete Replacement.

## **ASSESSMENT OF SITE**

# **Curb Appeal**

Category [3]

#### Parking

Category [1]

- Parking is limited. Need additional parking.
- Improved ingress/egress, traffic flow and drop-off and pick-up is needed.

#### Paving

Category [2]

#### **AC Paving**

Category [2]

 The asphalt under the lunch table area puddles and has standing water during the rainy season.

## **Ramps and Stairs**

Category [0]

#### **SITE AMENITIES**

**Shade Shelter - Lunch Canopy** Category [0]

#### **Lunch Tables and Benches**

Category [1]





## **Drinking Fountains**

Category [1]

## Landscape

Category [1]

 Potholes and uneven surfaces create trip hazards at the playfields.

# Irrigation

Category [1]

Draining and flooding issues around campus.

# Fencing/Gates

Category [1]

• The dumpsters need to be secured from the public.

# **ASSESSMENT OF BUILDINGS**

#### **EXTERIOR**

Overall Rating: Category [0]

## **Exterior Finish/Paint**

Category [1]

Exterior paint could use a refresh.

#### **Door & Frames**

Category [0]

#### Windows

Category [0]

#### Roof

Category [0]

Roofing is new.

## **ADA Compliance**

Category [1]

#### INTERIOR

Overall Rating: Category [1]

- The stained and sagging ceiling tiles in the 200 and 300 wings need to be addressed.
- The locker rooms are in need of modernization/renovation.
- Interior spaces underwent upgrades in 2013 modernization.

#### **RESTROOMS**

ADA Compliance: [0]

- The student restrooms in the 100 wing have a foul smell and need renovation.
- The floor tile and grout are dirty and stained in most restrooms throughout campus.
- All restrooms received ADA upgrades in 2013 modernization.

# **ASSESSMENT OF SYSTEMS**

#### SITE UTILITIES

Overall Rating: Category [0]

#### **MECHANICAL**

Overall Rating: Category [0]

- HVAC is new.
- The air conditioner tends to break down school-wide quite often.
- The air conditioner in the MPR does not work well when the room is at capacity.

# **PLUMBING**

Overall Rating: Category [1]

 There are pipe and plumbing issues in the 100 Building.

#### **ELECTRICAL**

Overall Rating: Category [1]



# 5.4 EXISTING SITE CONDITIONS YORBA 6-8 MIDDLE



Puddling and drainage issues on track.



Blocked off playfields due to solar panel field.



Flooding issues on hardcourts.



Threshold into locker rooms need attention.



Typical water fountain due for an update.



Typical door hardware due for an update.



Typical classroom furniture due for an update.



Exterior paint due for a refresh.



Drainage and flooding issues between buildings.



Front office.



MPR and stage.



Faculty lunch room.



Kitchen.




Lunch shelter.



Food serving area.



STEAM/CTE classroom.



Student workbench area.



Typical restroom condition.



# 5.4 EXISTING SITE CONDITIONS YORBA 6-8 MIDDLE





Locker room.



Band room.



Dance classroom.



Typical classroom.



Typical science lab.



Living skills classroom.



Library.



Computer lab.



Quad space.

	TOTAL PROJECT COST (2021\$)	
01. Modernize & Reconfigure Existing Classrooms	\$	838,000
02. Building Systems, Toilets & Improved Energy Efficiency	\$	362,000
03. Site Utilities	\$	818,000
04. Classroom New Construction	\$	-
05. Enrichment Programs & Electives	\$	3,208,000
06. Science Labs	\$	-
07. Assembly & Food Service Improvements	\$	574,000
08. Media Center	\$	2,406,000
09. Student Support / Counseling Services	\$	749,000
10. Administration & Staff Support	\$	168,000
11. Physical Education Improvements	\$	7,722,000
12. After School Support	\$	-
13. Safety & Security	\$	817,000
14. Campus Arrival: Parking, Drop-off & Entry Plaza	\$	1,551,000
15. Outdoor Learning Environments & Quads	\$	1,801,000
16. Exterior Play Spaces, Playfields & Hardcourts	\$	2,996,000
17. Flexible Furniture	\$	1,046,000
18. Technology Infrastructure & Equipment	\$	633,000
Total Project Cost (2021\$)	\$	25,689,000

PLAN














#### Classrooms, CR

ENG English HIST History MATH Math

RSP Resource Specialist Special Day Class SDC

Vacant

# Electives / Labs

Science Lab COMP Computer Lab

# **Shared Spaces**

Multi-Purpose Room MC Media Center Locker Room

# Admin / Faculty

FW Faculty Work FL Faculty Lounge WR Workroom Office 0 Nurse Psychologist

Speech

Occupational Therapy/Physical Therapy

CONF Conference Room COUN Counselor

PTA Parent Teacher Association

#### **Support Spaces**

CARES Expanded Learning Program ASES After School Education & Safety

Storage Toilet Utility Custodial Kitchen

# Portable Classroom

Main Entry

Drop Off

# Existing 2019/20 Enrollment: 552

Teaching Stations:

English, ENG 3 History, HIST 3 Math 4 Science, SCI 3 Electives, ELEC 6 Computer Lab, COMP RSP 4 SDC 3 Other (1-ELD, 5-ASES, 1-Parent Room)

34

**Grand Total:** 

1" = 120'

5.4

MODERNIZATION RECONFIGURE NEW CONSTRUCTION Classrooms, CR

Electives / Labs

**Shared Spaces** 

Admin / Faculty

**Support Spaces** 

Kinder Play

Play Apparatus

Outdoor Colab/

Quad/Playfield

Hardcourts

Entry Plaza

No Work

Required Portable

Classrooms

Main Entry

Site to include

support future digital marquee

Fence

cost for undergound utilities to

MQ









1" = 200'


QTY.











MODERNIZATION