



Liberty High

Measure U Site Report

May 4, 2022

- 
1. Downstairs Classroom Modernization, including:
    - Replace Walls
    - Replace Windows
    - Replace Doors & Hardware
    - Replace Floors
    - Replace Ceilings
    - Paint Interior
    - New Interior Lighting Controls
    - Upgrade Electrical Wiring & Increase Electrical Outlets
    - Remaining Asbestos Removal
    - New Stair
  2. Required Code Update Allowance
  3. Public Address/Emergency Communication System [completed]
  4. Restroom Modernization
  - ~~5. Safety Locks at Classroom Doors~~
  6. Fire Alarm System [completed] + Emergency Lighting
  7. Intrusion Alarms
  8. Elevator Repair & Cab Finishes
  9. Air Conditioning at MDF/IDF

