

Lead in Water Testing Results  
South Washington County Schools  
Woodbury Middle School

On December 29<sup>th</sup>, 2020 Woodbury Middle School's drinking water was tested for concentration of lead.

**All water sources tested less than 20 parts-per-billion. No action was taken at this time.**

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULTS (in ug/L)</b>
Lobby	FOUNTAIN	0
Lobby	BOTTLE FILLER	.67
Office Work Room	SINK	13.7
Nurse's Office	SINK	18.0
Room A109	SINK	2.5
Hallway (outside B114)	FOUNTAIN	0
Cafeteria	FOUNTAIN	1.2
Cafeteria	BOTTLE FILLER	.92
Hallway (by pool)	FOUNTAIN	.18
Hallway (by pool)	BOTTLE FILLER	.52
Kitchen	SINK	2.5
Kitchen	SPRAYER	2.5
Staff Dining	SINK	7.3
Hallway (by art)	FOUNTAIN	.62
Hallway (2 <sup>nd</sup> floor, NW)	FOUNTAIN	.85
Hallway (2 <sup>nd</sup> floor, NE)	FOUNTAIN	.10
Hallway (2 <sup>nd</sup> floor, SW)	FOUNTAIN	17.5
G Wing	BOTTLE FILLER	.15

G Wing (left)	FOUNTAIN	.40
G Wing (right)	FOUNTAIN	.33
H Wing (right)	FOUNTAIN	.12