

Lead in Water Testing Results
South Washington County Schools
Oltman Middle School

On December 31st, 2020 Oltman Middle School's drinking water was tested for concentration of lead.

All water sources tested less than 20 parts-per-billion.

No action was taken at this time.

| LOCATION | SOURCE | RESULTS (in ug/L) |
|----------------------------|---------------|--------------------------|
| Office Work Room | SINK | .39 |
| Hallway (1, left) | FOUNTAIN | 0 |
| Hallway (1, right) | FOUNTAIN | 0 |
| Hallway (1, bottle filler) | BOTTLE FILLER | 0 |
| Hallway (2, left) | FOUNTAIN | 0 |
| Hallway (2, right) | FOUNTAIN | 0 |
| Hallway (2, bottle filler) | BOTTLE FILLER | 0 |
| Hallway (3, left) | FOUNTAIN | 0 |
| Hallway (3, right) | FOUNTAIN | 0 |
| Hallway (3, bottle filler) | BOTTLE FILLER | 0 |
| Nurse's Office | SINK | 1.5 |
| Staff Dining | SINK | .45 |
| Hallway (4, left) | FOUNTAIN | 0 |
| Hallway (4, right) | FOUNTAIN | 0 |
| Hallway (4, bottle filler) | BOTTLE FILLER | 0 |
| Room 110B (left) | SINK | 1.0 |
| Room 110B (left) | SPRAYER | 1.3 |

| | | |
|----------------------------|---------------|-----|
| Room 110B (right) | SINK | 1.7 |
| Room 110B (right) | SPRAYER | .93 |
| Hallway (5, left) | FOUNTAIN | .28 |
| Hallway (5, right) | FOUNTAIN | .60 |
| Hallway (5, bottle filler) | BOTTLE FILLER | .67 |
| Kitchen | SINK | .23 |
| Kitchen | SPRAYER | 1.2 |
| Hallway (6, left) | FOUNTAIN | 0 |
| Hallway (6, right) | FOUNTAIN | 0 |
| Hallway (6, bottle filler) | BOTTLE FILLER | 0 |
| Pool (left) | FOUNTAIN | 0 |
| Pool (right) | FOUNTAIN | 0 |
| Pool | BOTTLE FILLER | 0 |
| Hallway (A, left) | FOUNTAIN | 0 |
| Hallway (A, right) | FOUNTAIN | 0 |
| Hallway (A, bottle filler) | FOUNTAIN | 0 |
| Hallway (B, left) | FOUNTAIN | 0 |
| Hallway (B, right) | FOUNTAIN | 0 |
| Hallway (B, bottle filler) | BOTTLE FILLER | 0 |