

Lead in Water Testing Results  
South Washington County Schools  
Crestview Elementary

On December 28<sup>th</sup>, 2021 Crestview Elementary School's drinking water was tested for concentration of lead.

**The following water sources tested less than 20 parts-per-billion.**

**No action was taken at this time.**

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULTS (in ug/L)</b>
Nurse's Office	SINK	6.5
Media Center Workroom	SINK	2.9
Staff Lounge	SINK	4.7
Hallway (outside gym)	FOUNTAIN	0
Hallway (outside gym)	BOTTLE FILLER	0
Cafeteria	FOUNTAIN	0
Cafeteria	BOTTLE FILLER	0
Kitchen	SINK	3.4
Kitchen	SPRAYER	4.1
Room 102	SINK	12.8
Room 104	SINK	7.9
Room 106	SINK	5.7
Hallway (outside 106)	FOUNTAIN	9.2
Room 108	SINK	3.3
Room 110	SINK	5.7
Room 112	SINK	13.6

Room 113	SINK	7.6
Room 114	SINK	9.1
Hallway (outside 116, left)	FOUNTAIN	1.2
Hallway (outside 116, right)	FOUNTAIN	1.3
Room 116	SINK	2.5
Room 118	SINK	5.4
Room 117	SINK	1.3
Room 115	SINK	1.5
Room 111	SINK	9.8
Room 109	SINK	4.7
Room 107	SINK	7.7
Room 105	SINK	5.3
Room 103	SINK	12.0
Room 101	SINK	7.3
Room 202	SINK	13.8
Room 204	SINK	11.5
Room 208	SINK	16.4
Hallway (outside 208)	FOUNTAIN	4.2
Room 210	SINK	9.0
Room 212	SINK	17.6
Room 214	SINK	9.1
Room 216	SINK	7.5
Room 215	SINK	8.6
Room 211	SINK	10.7
Room 209	SINK	8.7

Room 207	SINK	14.9
Room 205	SINK	9.8
Room 201	SINK	8.4

**The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources were heavily flushed and a re-test was administered. Results of the initial test and retest are below. No water sources re-tested over 20 parts-per-billion and no further action will be taken at this time.**

<b>LOCATION</b>	<b>SOURCE</b>	<b>INITIAL RESULTS (in ug/L)</b>	<b>RE-TEST RESULTS</b>
Room 206	SINK	23.1	1.0