

IR-7-1-E102-DWC-F-18	Drinking Fountain w/Cooler Room E102	01/04/2023	0.0068		mg/L	0.0010
IR-7-1-E102-DWC-P-19	Drinking Fountain w/Cooler Room E102	01/04/2023	0.0083		mg/L	0.0010
IR-7-1-E102-DWC-SS-19	Drinking Fountain w/Cooler Room E102	01/04/2023	0.0068		mg/L	0.0010
IR-7-1-E102-DWC-F-19	Drinking Fountain w/Cooler Room E102	01/04/2023	0.0069		mg/L	0.0010
IR-7-2-D214-DWC-P-20	Drinking Fountain w/Cooler Room D214	01/04/2023	0.0022		mg/L	0.0010
IR-7-2-D214-DWC-SS-20	Drinking Fountain w/Cooler Room D214	01/04/2023	0.0032		mg/L	0.0010
IR-7-2-D214-DWC-F-20	Drinking Fountain w/Cooler Room D214	01/04/2023	0.0038		mg/L	0.0010
IR-7-2-D214-DWC-P-21	Drinking Fountain w/Cooler Room D214	01/04/2023	0.0082		mg/L	0.0010
IR-7-2-D214-DWC-SS-21	Drinking Fountain w/Cooler Room D214	01/04/2023	0.0032		mg/L	0.0010
IR-7-2-D214-DWC-F-21	Drinking Fountain w/Cooler Room D214	01/04/2023	0.0028		mg/L	0.0010

NA
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample
NA
NA
NA
NA
NA
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample
NA
NA

NA
Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Replace Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
NA
NA
NA
NA
NA
Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Replace Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
NA
NA

Key - Sample Name	
P	Primary Sample
SS	Sequential Sample
F	Flush Sample

Key - Qualifier	
U	Not Detected in Laboratory Analysis
J	Result is Between Laboratory Detection Limit & Laboratory Reporting Limit