

School Radon Testing Reporting Form

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

Instructions

- 1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
- 2. Include this form, raw data (e.g. laboratory report) and a building map.
- 3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
- 4. Email information to health.indoorair@state.mn.us.

Contact Information

Name: Wendy German	
Mailing Address: 7362 East Point Douglas	Road S, Cottage Grove, MN 55016
Phone: 651-425-6277	Email: wgerman@sowashco.org

Initial Radon Testing Information

School Building Name: Nuevas Fronteras	Spanish Immersion School	
School District & District Number: South Was	shington County Schools - District 833	
Building Address: 1020 Third Stree	t, St Paul Park, MN 55071	
Test Kit Manufacturer: AirChek	Device Name: ProChek	
Date of Kit Retrieval (DD/MM/YY): 12/3/21	Length of Test (days): 3	
How many rooms were tested? 36		
Does the test period include weekends?	′es ✓ No	
Does the test period include school breaks or	nolidays? 🖊 Yes No	

SCHOOL RADON TESTING REPORTING FORM

Were all frequently-occupied ground contact ro If no, did you attempt to test all frequen test kits were placed in all these rooms?	tly occupied ground co	
How many rooms had results ≥ 4 pCi/L?: 0	<u> </u>	
Were the results reported at a school board me	eting? Yes N	0
Follow-up Testing, Mitigation, & If one or more rooms tested ≥ 4 pCi/L, please ans		_
How many rooms had follow-up testing?:		
Number of rooms with follow-up results	≥ 4 pCi/L:	< 4 pCi/L:
Of the rooms that had test results ≥ 4 pCi/L, ho	w many rooms were:	
mitigated by HVAC balancing or operational chamitigated by installation of active soil depressur addressed through other corrective measures? ²	ization?:	7
What was the cost of the installation and/or HV What is the known or anticipated annual operat		
After radon mitigation, how many rooms were r	retested?:	

≥ 4 pCi/L:

< 4 pCi/L:

Post mitigation results (# of rooms)

¹ This includes classrooms, offices, break rooms, laboratories, cafeterias, libraries, auditoriums, gymnasiums, etc. It includes rooms on grade and rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.

² 'Other corrective measures' could include moving staff out of a room and making a room unoccupied or trying to seal radon entry points.

Radon test result report for: SWC 833 NUEVAS FRONTERAS

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
7324457	140	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.0 ± 0.4	2021-03-16
7324450	141	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	0.7 ± 0.4	2021-03-16
7324442	144	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	0.6 ± 0.3	2021-03-16
7324460	145	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.8 ± 0.4	2021-03-16
7324441	148	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.4 ± 0.4	2021-03-16
7324434	149	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324468	151	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	0.7 ± 0.4	2021-03-16
7324467	153	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324459	154	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.8 ± 0.4	2021-03-16
7324452	155	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.2 ± 0.3	2021-03-16
7324451	157	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.0 ± 0.3	2021-03-16
7324444	162	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.2 ± 0.4	2021-03-16
7324471	163	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.5 ± 0.4	2021-03-16
7324470	164	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	0.9 ± 0.4	2021-03-16
7324469	165	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	0.9 ± 0.3	2021-03-16
7324464	166	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	1.1 ± 0.4	2021-03-16
7324463	167	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	0.9 ± 0.3	2021-03-16
7324462	168	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	1.0 ± 0.4	2021-03-16
7324461	169	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324455	170	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	1.1 ± 0.3	2021-03-16
7324456	171	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	0.9 ± 0.3	2021-03-16
7324448	173	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	0.9 ± 0.4	2021-03-16
7324454	174	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324447	175	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	1.4 ± 0.3	2021-03-16
7324440	183	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	2.1 ± 0.4	2021-03-16
7324443	187	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	1.5 ± 0.4	2021-03-16
7324466	AUDITORIUM	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	0.6 ± 0.3	2021-03-16
7324458	CAFERERIA N	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324465	CAFETERIA S	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324445	GYM A	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324446	GYM B	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324449	MEDIA CENTER	2021-03-09 @ 9:00 am	2021-03-12 @ 8:00 am	0.9 ± 0.4	2021-03-16
7324433	NURSES	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324438	NURSES 2	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324435	OFFICE	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324436	OFFICE 2	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	< 0.3	2021-03-16
7324437	PRINCIPALS	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	1.0 ± 0.3	2021-03-16

March 16, 2021

** LABORATORY ANALYSIS REPORT **

Radon test result report for: SWC 833 NUEVAS FRONTERAS

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
7324439	STAFF DINING	2021-03-09 @ 8:00 am	2021-03-12 @ 8:00 am	0.5 ± 0.3	2021-03-16

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498