

School Radon Testing Reporting Form

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

Instructions

Contact Information

- 1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
- 2. Include this form, raw data (e.g. laboratory report) and a building map.
- 3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
- 4. Email information to health.indoorair@state.mn.us.

(Submitting this report)
Name Wendy German
Mailing Address 7362 E Point Douglas Rd Cottage Grove, MN 55016
Phone 651-425-6277 Email wgerman & Sowash co. org
Person(s) Deploying or Retrieving Test Devices ¹
Name Wendy German Organization/Company Mendian, RMEA-00447
NameOrganization/Company
NameOrganization/Company
School Board Reporting
Were all the results reported at a school board meeting? XYes No

¹ List all individuals that deployed (placed) or retrieved (picked up) test devices including initial, follow-up, and post-mitigation testing. Additional names can be added to notes at end of this form.

SCHOOL RADON TESTING REPORTING FORM

Initial Radon Testing

School Building Name OHMAN Middle School
School District & District Number South Washington County - District 833
Building Address 6625 Goodview Ave S Cottage Grove, MN 55106
Test Kit Manufacturer Aly Chek Device name Pro Chek
Date of Kit Retrieval (MM/DD/YY) 03/24/22 Length of Test (days) 2
How many rooms were tested? H5
How many rooms were tested?
Does the test period include weekends? Yes No
Does the test period include school breaks or holidays?
Was HVAC operating under occupied conditions?
Were test devices deployed in all occupied and intended to be occupied rooms in contact with the ground, and, if applicable, 10% of upper floor rooms?
Were valid measurements obtained in all occupied and intended to be occupied rooms in contact with the ground, and, if applicable, 10% of upper floor rooms? ² Yes No
If no, were all results obtained under 2.0 pCi/L and were there sufficient valid measurements obtained that allowed for no further testing? ³ Yes No
How many rooms had results ≥ 4 pCi/L?

² This includes rooms, offices, classrooms, and other general use areas. Ground contact means: 1) rooms that have floors or walls in contact with the ground; and 2) rooms that are closest to the ground over untested ground-contact locations, such as a crawl space, utility tunnel, parking garage and other non-habitable space that is in contact with ground. Intended to be occupied rooms are locations where there are plans to occupy rooms even though they are unoccupied at the time of the testing. In addition, if the building has upper floors, at least 10% of these rooms must be tested.

³ Section 6.2 of the ANSI/AARST standard allows for a specific small number of invalid measurements (e.g., test kits missing, damaged, etc) if all the valid test results were under 2.0 pCi/L. Review this section of the standard and evaluate how many rooms needed testing and how many had valid results. If there were too many invalid results, this means additional testing was required in these locations and answer this question as 'no'.

SCHOOL RADON TESTING REPORTING FORM

Follow-up Testing, Mitigation, & Post-Mitigation Testing

If one or more rooms tested ≥ 4 pCi/L, please answer the questions below.
How many rooms had follow-up testing?
Number of rooms with follow-up results:
≥ 4 pCi/L< 4 pCi/L
Of the rooms that had test results ≥ 4 pCi/L, how many rooms were:
mitigated by diluting or pressurizing the soil or indoor air
(not active soil depressurization)?
mitigated by installing active soil depressurization system(s)?
reduced by adjusting the HVAC system?
Individual who installed mitigation
NameOrganization/Company
What was the cost of the installation and/or HVAC service work, to mitigate radon?
What is the known or anticipated annual operating cost of mitigation (estimate)?
After radon mitigation, how many rooms were re-tested? ⁴
Post-mitigation results (# of rooms):
≥ 4 pCi/L< 4 pCi/L
Notes

Minnesota Department of Health | Environmental Health | Indoor Air Unit health.indoorair@state.mn.us www.health.state.mn.us June 2021
To obtain this information in a different format, call: 651-201-4601.

⁴ The building must be tested, to verify reduction and ensure mitigation has not increased radon in rooms that used to be low.

** LABORATORY ANALYSIS REPORT **

Radon test result report for: 833 OMS

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
11152920	100	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	0.7 ± 0.5	2022-03-30
11152932	101	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152931	102	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152929	103	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152930	103	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	0.7 ± 0.5	2022-03-30
11152911	104A	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152912	104B	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152913	104C	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152914	104D	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152915	104E	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152916	104F	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152958	104F.1	2022-03-22 @ 4:00 pm	2022-03-25 @ 6:00 pm	0.6 ± 0.4	2022-03-30
11152917	104F.2	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152933	146	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152922	147	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	0.8 ± 0.5	2022-03-30
11152921	147	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152926	149	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	1.1 ± 0.5	2022-03-30
11152979	301B	2022-03-23 @ 1:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152972	302B	2022-03-23 @ 1:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152980	303B	2022-03-23 @ 1:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152949	A151	2022-03-22 @ 3:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152948	A152	2022-03-22 @ 3:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152947	A153	2022-03-22 @ 3:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152946	A155	2022-03-22 @ 3:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152945	A155	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152951	A156	2022-03-22 @ 3:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152952	A159	2022-03-22 @ 4:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152953	A167	2022-03-22 @ 4:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152957	A267	2022-03-22 @ 4:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152925	AUDITORIUM	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152943	B171	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152937	B172	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	1.1 ± 0.6	2022-03-30
11152940	B172	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152942	B173	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	0.7 ± 0.5	2022-03-30
11152939	B175	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152944	B176	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152927	C183	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30

March 30, 2022

** LABORATORY ANALYSIS REPORT **

Radon test result report for: 833 OMS

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
11152938	C191	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152941	C192	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152936	C193	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152935	C195	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152934	C196	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152928	C199	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	0.7 ± 0.5	2022-03-30
11152954	C296	2022-03-22 @ 4:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152923	CAFETERIA	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152924	GYM E	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152919	GYM WEST	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152918	HEALTH OFFICE	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30
11152955	MEDIA	2022-03-22 @ 4:00 pm	2022-03-25 @ 6:00 pm	0.8 ± 0.4	2022-03-30
11152956	MEDIA CENTET	2022-03-22 @ 4:00 pm	2022-03-25 @ 6:00 pm	< 0.3	2022-03-30
11152910	OFFICE	2022-03-22 @ 3:00 pm	2022-03-24 @ 3:00 pm	< 0.3	2022-03-30

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498