

School Radon Testing Reporting Form

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

Instructions

1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
2. Include this form, raw data (e.g. laboratory report) and a building map.
3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
4. Email information to health.indoorair@state.mn.us.

Contact Information

Name: <i>Wendy German</i>	
Mailing Address: <i>7362 East Point Douglas Rd S, Cottage Grove, MN 55016</i>	
Phone: <i>320-224-1908</i>	Email: <i>wgerman@sowashco.org</i>

Initial Radon Testing Information

School Building Name: <i>Liberty Ridge Elementary</i>	
School District & District Number: <i>South Washington County Schools- District 833</i>	
Building Address: <i>11395 Eagle View Blvd, Woodbury, MN 55129</i>	
Test Kit Manufacturer: <i>Air Check</i>	Device Name: <i>Pro Check</i>
Date of Kit Retrieval (DD/MM/YY): <i>03/22/19</i>	Length of Test (days): <i>3</i>
How many rooms were tested? <i>47</i>	
Does the test period include weekends? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Does the test period include school breaks or holidays? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

SCHOOL RADON TESTING REPORTING FORM

Were all frequently-occupied ground contact rooms tested?¹ Yes No
 If no, did you attempt to test all frequently occupied ground contact rooms, meaning test kits were placed in all these rooms? Yes No

How many rooms had results ≥ 4 pCi/L?: 0

Were the results reported at a school board meeting? Yes No *Scheduled for upcoming meeting*

Follow-up Testing, Mitigation, & Post-Mitigation Testing

If one or more rooms tested ≥ 4 pCi/L, please answer the questions below:

How many rooms had follow-up testing?:

Number of rooms with follow-up results	≥ 4 pCi/L:	< 4 pCi/L:
--	-----------------	------------

Of the rooms that had test results ≥ 4 pCi/L, how many rooms were:

mitigated by HVAC balancing or operational changes? :

mitigated by installation of active soil depressurization?:

addressed through other corrective measures?²:

What was the cost of the installation and/or HVAC service work, to mitigate radon? \$

What is the known or anticipated annual operating cost of mitigation (estimate)? \$

After radon mitigation, how many rooms were retested?:

Post mitigation results (# of rooms)	≥ 4 pCi/L:	< 4 pCi/L:
--------------------------------------	-----------------	------------

¹ This includes classrooms, offices, break rooms, laboratories, cafeterias, libraries, auditoriums, gymnasiums, etc. It includes rooms on grade and rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.

² 'Other corrective measures' could include moving staff out of a room and making a room unoccupied or trying to seal radon entry points.

Radon test result report for:

LIBERTY RIDGE ELEMENTAY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9197676	A003	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197677	A004	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197678	A006	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197679	A008	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197680	A010	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197681	A011	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197682	A014	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197683	A018	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197589	B111	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197590	B115	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197587	C101	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197584	C103	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197583	C104	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197574	C106	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197575	C107	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197582	C108	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197581	C109	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197578	C111	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197579	C112	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197580	C114	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197585	C115	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197586	C116	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197577	C118	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197576	C119	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197572	D103	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197699	D108	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197700	D116	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197573	D119	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197685	E101	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197698	E103	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197697	E104	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197569	E106	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197571	E107	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197694	E108	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197693	E109	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197692	E111	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197689	E112	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27

March 27, 2019

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

LIBERTY RIDGE ELEMENTAY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9197688	E114	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197687	E115	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197686	E116	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197691	E118	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197690	E119	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197675	GYM C	2019-03-19 @ 1:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197588	MEDIA CENTER	2019-03-19 @ 2:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197674	NURSE	2019-03-19 @ 1:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27
9197696	OFFICE 1	2019-03-19 @ 1:00 pm	2019-03-22 @ 12:00 pm	< 0.3	2019-03-27
9197695	OFFICE 2	2019-03-19 @ 1:00 pm	2019-03-22 @ 12:00 pm	< 0.3	2019-03-27
9197898	PRINCIPAL	2019-03-19 @ 1:00 pm	2019-03-22 @ 1:00 pm	< 0.3	2019-03-27

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498