

Holden R-III School District

Facilities Master Plan



Updated March 2020

Facilities Master Plan – Holden R-III

Table of Contents

01 Executive Summary (4 Pages)

02 Maps

- A) City of Holden Plat Map
- B) Holden R-III Campus Plat Map
- C) Holden R-III Plat Map Summary
- D) Central Office Plat Map
- E) Tennis Courts Plat Map
- F) Holden R-III District Google Picture
- G) Holden Elementary School Google Picture
- H) Holden Elementary Map with Room Numbers
- I) Holden Middle School Google Picture
- J) Holden Middle School Map with Room Numbers
- K) Holden High School Google Picture
- L) Holden High School Map with Room Numbers
- M) Central Office Google Picture
- N) Central Office Map with Room Labels
- O) Auxiliary Services Google Picture
- P) Auxiliary Services Map with Room Labels
- Q) Holden R-III Sports and Activities Facilities
 - a. Campus Facilities
 - b. Stub Roberts Memorial Baseball Complex (Softball Program)
 - c. Holden FFA Trap Shooting Facility
- R) Holden R-III Topographic Survey Link to Larger Copy

03 Facility Overview

- A) Holden Elementary School (2 Pages)
- B) Holden Middle School (2 Pages)
- C) Holden High School (3 Pages)
- D) Holden R-III Central Office (2 Pages)
- E) Holden R-III Auxiliary Services (2 Pages)
- F) Tennis Courts (2 Pages)
- G) Vehicle/Equipment List

Q4 Roofs – Update this w/Roof type, installer, warranty, life expectancy, condition

- A) Holden Elementary School (2 Pages)
- B) Holden Middle School and Auxiliary Services (2 Pages)
- C) Holden High School (2 Pages)
- D) Holden R-III Central Office (2 Pages)
- E) Dugouts and Press Boxes (2 Pages)
- F) Roof Replacement Schedule (3 Pages)

05 Parking Lots

- A) Holden Elementary School
- B) Holden Middle School
- C) Holden High School
- D) Holden R-III Central Office
- E) Holden R-III Auxiliary Services
- F) Parking Lot Maintenance Schedule (3 Pages)

06 HVAC

- A) Holden Elementary School (2 Pages)
- B) Holden Middle School (2 Pages)
- C) Holden High School (2 Pages)
- D) Holden R-III Central Office (2 Pages)
- E) Holden R-III Auxiliary Services (2 Pages)
- F) HVAC Equipment List Update list include size (tons) & refrigerant type (3 Pages)

07 Technology

- A) Holden Elementary School
- B) Holden Middle School
- C) Holden High School
- D) Holden R-III Central Office
- E) Holden R-III Auxiliary Services
- F) Fiber Optic District Map

08 Educational Capacity Analysis – And number of students in each area & sq ft.

- A) Holden Elementary School
- B) Holden Middle School
- C) Holden High School
- D) Grade Level and Course Enrollments
- E) Enrollment Projections

09 Custodial and Maintenance

- A) Custodial Scope of Services (3 Pages)
- B) Grounds Scope of Services
- C) Maintenance Scope of Services
- D) Cleaning Job Cards (5 Pages)
- E) Floor Maintenance Schedule (3 Pages)
 - a. Holden Elementary School Floor Map
 - b. Holden Middle School Floor Map
 - c. Holden High School Floor Map
 - d. Misc. Areas Floor Map
- F) Athletic Field Maintenance Summarize lists from Arlan manual
- G) Inspection Lists

10 Long-Term Project Plans — Currently Utilizing Bond List — Update for Long-Term

- A) Bond Project List
- B) Future Bonding Options

Appendices

A Facilities Survey (4 Pages)

B Facilities Survey Results (48 Pages)

C Facilities Survey Results sorted by Site (Pre & Post Site Meeting) (30 Pages)

Pacility Needs Walk-Through Lists (7 Pages)

Facility Meeting Agendas (3 Pages)

F District-Wide Project List (6 Pages)

G Project List and Cost Projections (2 Pages)

01 Executive Summary

Mission: The Facilities Master Plan will support proactive, long-term management, improvement, and maintenance of the Holden R-III School District which will benefit the students, staff, and the community for years to come.

Vision: The Facilities Master Plan will result in safe, comfortable, efficient, and inspiring spaces for student learning and spaces where staff members are empowered to engage every student in excellent academic opportunities.

Purpose: The Holden R-III School District has seven facilities that are utilized to transport and instruct approximately 1200 students. Those facilities include the Eagles Nest Preschool, Holden Elementary School, Holden Middle School, Holden High School, Holden Multipurpose and Locker Room facility, Holden R-III Central Office and the Holden Auxiliary Services Building. In addition, the district maintains buildings and grounds that include two press boxes, three outbuildings, greenhouse, football field, track, two football practice fields, baseball field, two tennis courts, and two elementary playgrounds. The grounds include three gravel parking lots, one gravel bus drive, one paved bus drive, two paved/concrete pick-up lanes, and six paved parking lots. All of these facilities are located on approximately 58 acres on the south end of the Holden city limits. The district also assists in maintaining a softball field at the Stub Roberts Memorial Baseball Complex in conjunction with the Holden Sports Association and a trap shooting facility north of Holden on highway 131.

The Eagles Nest Preschool offers preschool services to children ages 3 to 5 within the Holden R-III School District. Holden Elementary School serves children between Kindergarten and fifth grade. Sixth through eighth grade students attend Holden Middle School, and Holden High School houses grades nine through twelve. The Auxiliary Services Building houses the transportation and maintenance department. District Administration, Accounting Services, and Communications are located in the Central Office.

The Facility Master Plan consists of two phases. Phase 1 of the plan includes the compilation of two components. The first component is the facility assessment which was the evaluation of the physical condition of each of the facilities. Component two is the educational capacity analysis which helps determine the capacity of each facility to serve both our current students and our future student population. Phase 2 of the plan is to develop preventive maintenance plans, routine maintenance and cleaning schedules, as well as short and long term project plans.

Content: Phase 1 facility assessment contents include campus pictures and maps, roof maps, HVAC unit maps, parking lot maps, district topographic survey, staff facility survey and survey results, facility meeting agendas and results, building walk-through maintenance and upgrade lists, current work order list, and a vehicle/large equipment list.

The Phase 1 educational capacity analysis reviews the programs offered at each school and the size of the learning space provided for each program. This includes the current square footage and the type of learning space provided for each program. Current enrollment and future enrollment projections are also included.

Phase 2 contents include 2019 Bond Issue Project List, Routine Inspection List, Disease Control Measures, Custodial, Maintenance and Grounds Scope of Services, and short/long term facility improvement plan.

Planning Process: In the Spring of 2018, a survey (Appendix A) was sent to the staff of the Holden R-III School District. The purpose of the survey was to engage the staff in evaluating the effectiveness of the custodial, maintenance, and grounds services as well as the development of a district facility improvement list. After reviewing the data received from the survey (Appendix B), the data regarding facilities maintenance and custodial services was reviewed with Operational Professional Services (OPS) to assist them in a review and improvement plan for services to the district. The second part of the survey was utilized to collect data from staff members for possible inclusion on a long-range facility plan. The data was categorized around the following areas, merged, and sorted by site (Appendix C). Administrators and maintenance personnel also completed walk-throughs of each building and grounds to develop a facility needs list. (Appendix D).

	Category	Examples				
1.	Site	Parking Lots, Driveways, Walkways, Outdoor Equipment, Landscaping, Playgrounds, Athletic Facilities				
2.	Building Exterior/Envelope	Roof, Walls, Doors, Canopies				
3.	Building Interior	Renovations, Remodeling, Painting, Floors, Ceilings				
4.	Educational Adequacy	Classroom Functionality, Space Planning and Redesign, Special Programs, Support Programs				
5.	Mechanical Systems	Plumbing Systems, HVAC Systems, Temperature Control, Energy Analysis and Efficiency				
6.	Electrical Systems	Electrical Power Capacity, Lighting, Phone/Intercom Systems, Data Systems, Technology Infrastructure				
7.	Safety	Vestibules, Security/Safety Glass, Door Access/Locking Systems, Security Cameras, Entry Alarm Systems, Fire Detection, Suppression, & Alarm Systems				
8.	Equipment	Built-In Equipment - Kitchen Equipment, Science Labs, Industrial Technology/Agriculture Equipment, Kilns, Fume Hoods, Dishwashers, etc.				
9.	ADA	Handicapped Accessibility				
10.	Other Long-Range Planning Considerations	Facility Additions, Land Acquisition, Capacity Reviews				

Building administrators were asked to submit names of certified staff, support staff, parents, students, and patrons to participate in building level facility planning committees. School Board members were asked to volunteer to be on these committees. After the committees were formed, each committee met on site to complete a walk-through of the building, review the survey data, develop a list of facility needs, and to prioritize the list to be reviewed from a district perspective.

See Appendix E for meeting agendas and data reviewed and prioritized by each site. Site meetings were held on 10/18/18, 10/29/18, & 11/1/18.

Utilizing the site reviews, a district-wide list was developed utilizing the prioritized items and all members of the site committees were invited back to review all the data. Each member was asked to prioritize their top 15 items by placing dots on a display board. Appendix F contains the district-wide list utilized during the meeting. This list was utilized to get estimated costs from Facility Solutions Group (FSG) who was contracted by the Holden R-III School Board to oversee facility improvement projects. The district-wide meeting was held in the Holden Middle School Library on January 3, 2019.

The final district-wide list was reviewed by administration and OPS to determine which projects would require a bond issue and which items could be completed through the district maintenance department. Appendix G is the compiled list of potential bond issue projects and their estimated costs as developed by FSG.

Facility Assessment Results and Planning Documents: On December 10, 2018, the Board of Education voted to begin working with L.J. Hart on a proposal to sell \$4,500,000 in bonds to begin work on the projected facility needs. On April 2, 2019, voters overwhelmingly approved the bond issue with 72.16% voting for the proposal.

The initial focus for the utilization of the bond funds is to do basic infrastructure work throughout the district and then prioritize the remaining projects dependent upon the funds remaining. An energy savings lighting plan will also be toward the top of the priority list as it will have a direct and immediate impact on the district's operating budget through energy savings. The initial projects to be completed will be prioritized in the following order:

- 1. Foundation repairs in all three buildings.
 - a. High School White Mile
 - b. Elementary Music Room, Art Room, and Cafeteria
 - c. Middle School Administrative and Nurse's Office
- 2. LED Lighting Project Convert all district lights (except sports fields) to LED
- 3. Elementary (1957) Roof and coordinating HVAC Units
- 4. High School (1995 & 1999) Roofs and coordinating HVAC Units
- 5. Middle School HVAC Units
- 6. Safety Entrances and Door Control Systems
- 7. Camera and Intercom/Communication Systems
- 8. Parking Lot/Bus Lane Repairs
- 9. Other Projects as listed on Bond Project List

This plan consists of many documents that can be utilized for information and future planning. It provides a roadmap for future projects that need to be addressed as well as preventative maintenance and custodial schedules. Technology infrastructure information is also included to assist in future planning.

Educational Capacity Analysis: Educational Capacity can be defined as the ability for a school facility to support both current and potential future educational programs. The physical structure of a facility can enhance or deter from instruction. The educational capacity analysis describes the relationship between the physical structure and the educational program and thus helps determine if the utilization of space is appropriate and effective for the delivery of the educational program to the Holden R-III students. Capacity calculations can be determined utilizing enrollment guidelines or classroom square footage available to students. The following

items are recommendations from the Missouri Department of Elementary and Secondary Education regarding classroom enrollments.

1. Student enrollment in individual classes will be consistent with the following guidelines:


Grades	Standard	Desirable Standard
K-2	25	17
3-4	27	20
5-6	30	22
7-12	33	25

2. Full-time elementary art, music, and physical education shall serve no more than seven hundred fifty (750) students per week.

Options:

- a) Student enrollment in a classroom may increase by as many as ten (10) students for any period that a paraprofessional assists the classroom teacher full time, or by as many as five (5) students when a paraprofessional assists the teacher half time. (Paraprofessionals paid for with Title I and special education funds cannot be used to increase class size. See the Consolidated Federal Programs Administrative Manual for guidelines on compliance and the use of paraprofessionals for Title I purposes).
- b) Elementary school classes may enroll students from two (2) consecutive grade levels. Total enrollment in such classes shall not exceed the class-size standards listed above for the lowest grade included in the combination.
- c) High schools can combine sections of a same subject in beginning and advanced levels (e.g., Spanish I and Spanish II or Spanish III and Spanish IV). Total combined enrollment in such classes shall not exceed twenty-five (25) students.
- d) Enrollment in performing arts classes may exceed regular class-size limits if adequate supervision and facilities are provided.
- e) High school physical education classes may enroll up to forty-five (45) students if appropriate supervision and facilities are provided.

A second calculation will be utilized to determine the number of square feet that is available in each program space.



Johnson County, MO

Lafayette

CHILHOWEE (13) LEETON

58 B13

(3)



Owner Last Name

U.S. Highway

<all other values>

Lettered State Highway Numbered State Highway

Notes


498.1

249.03

498.1 Feet

This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.

THIS MAP IS NOT TO BE USED FOR NAVIGATION




S

SW 14.45.28


Z

Johnson County, MO

(S)



Johnson County, MO



Parcel

Lettered State Highway Numbered State Highway U.S. Highway <all other values> Address Point

911 Roads

Parcel Number/Acres

Owner Last Name

County Boundary

Section Corporate Limit

Notes

THIS MAP IS NOT TO BE USED FOR NAVIGATION








Holden Elementary School Building Map 2019-20

Revised 7/25/2019


1903 S. Market Holden, MO 64040







M# = Bu	uilding Exit	Holden Middle School Map					ap § =Storm She	Storm Shelter Area	
Room 204	Room 301	Room 302	Room 305	Room 306	M3 Exit	M Kitchen	M5 Art	Resource Room	
Roor		6th Street					Blue Parkway	Southwest Exit	
Room 203 R	Room 303 Girls' Restroom 7th		Computer Lab	Boys' Restroom Room 304	Γ 2	Π ນ		Boys' &	
Room 202	Room Room		Custodial Office		Eagles' Landing		Gym	Room	
Roo			anding		Girls'				
Room 201			Data Room One of the content of the	Girls' Restroom Data Room			Room		
Exit East		8th S	itreet				Talon Ave.	M Morthwest Exit	
Room 105	Room 104	Room 103	Room 102	Room 101	Foyer M1	Office	Music Room	Student Support Center	

















Ш

 $\mathbf{2}\mathbf{Q}\mathbf{a}$









Date: March, 2020

3A)

HOLDEN R-III ELEMENTARY SCHOOL

Address:

1903 S. Market

Holden, MO 64040

Phone:

816-732-6071

Fax:

816-732-2008

Building Specifics:

Land Purchase Date:

1956 & 1961

Construction Date:

1957 (mint green)

Additions:

1973—Middle Section (teal)

2003—Intermediate Addition (light blue) 2014—Early Childhood Building (peach)

Total Campus Size:

58 acres

Building Area:

Main Building—

77,187 sq. ft.

Early Childhood—

3,600 sq. ft.

Total—

80,787 sq. ft.

Education Specifics:

Grade Levels

Grades PK-5

Enrollment

523



Date: March, 2020

3B)

HOLDEN R-III MIDDLE SCHOOL

Address:

301 Eagle Drive

Holden, MO 64040

Phone:

816-732-4125

Fax:

816-732-2009

Building Specifics:

Land Purchase Date:

1962

Construction Date:

1995 (bright blue)

Additions:

Total Campus Size:

58 acres

Building Area:

Main Building—

49,600 sq. ft.

Total—

49,600 sq. ft.

Education Specifics:

Grade Levels

Grades 6-8

Enrollment

299



Date: March, 2020

3C)

HOLDEN R-III HIGH SCHOOL

Address:

1901 S. Main

Holden, MO 64040

Phone:

816-732-5523

Fax:

816-732-4142

Building Specifics:

Land Purchase Date:

1962

Construction Date:

1963 (grey)

Additions:

1980—Ag Building (pink)

1986—Locker Room (brown)

1988—Outside Storage Building (brick red)

1995—Tech Hallway (bright blue) 2001—Greenhouse (orange)

2003—Bright Futures Building (light blue)

2007—North Wing, Commons, Office, Cafeteria, Track Resurface (light green)

2010—Football Pressbox (kelly green) 2011—Baseball Pressbox (yellow) 2014—Multipurpose Building (peach)

Total Campus Size:

58 acres

Building Area:

Main Building— 89,163 sq. ft.

Locker Room— 1,800 sq. ft.
Storage Building— 1,800 sq. ft.
Greenhouse— 1,440 sq. ft.
Bright Futures— 1,000 sq. ft.
Multipurpose Bldg— 3,500 sq. ft.

Total—

98,703 sq. ft.


Education Specifics:


Grade Levels

Grades 9-12

Enrollment

361





Date: March, 2020

3D)

HOLDEN R-III CENTRAL OFFICE

Address:

1612 S. Main

Holden, MO 64040

Phone:

816-732-5568

Fax:

816-732-4336

Building Specifics:

Purchase Date:

2002

Additions:

2006 (magenta)

Total Site Size:

2.5 City Lots

Building Area:

Main Building--

1850 sq. ft.

Total--

1,850 sq. ft.





General Information:

Date: March, 2020

3E)

HOLDEN R-III AUXILIARY SERVICES

Address:

2000 S. Clay

Holden, MO 64040

Phone:

816-732-6541

Fax:

Building Specifics:

Construction Date:

2005 (red)

Additions:

Total Campus Size:

58 acres


Building Area:

Main Building—

6,000 sq. ft.

Total—

6,000 sq. ft.



General Information:

Date: March, 2020

3F)

HOLDEN R-III TENNIS COURTS

Address:

1614 S. Main

Holden, MO 64040

Phone:

Fax:

Building Specifics:

Land Purchase Date:

1956

Construction Date:

1971


Additions:

2007—Resurface Upgrades (light green)

Total Campus Size:

2 City Lots

Building Area:



HOLDEN R-III SCHOOL DISTRICT VEHICLE/EQUIPMENT INVENTORY



<u>YEAR</u>	VEHICLE DESCRIPTION	<u>VIN #</u>
1994	Ford Pickup Truck (Blue)	2FTHF26HXRCA71576
1999	Ford Van (Purple)	2FMZA5149XBB96012
2011	Chevrolet Utility Truck (White)	1GCRKREAXBZ255731
	TRAILER DESCRIPTION	
2005	Covered Trailer (FB Eagle)	4RACS16275C004636
2016	Utility Trailer (Mower)	4MYUL0811GT029065
2019	Covered Trailer (Band)	1DGCS2421KMO34495
	<u>EQUIPMENT</u>	
	Bobcat Model T190	Serial #527717224
1, 144	Scag Turf Tiger Zero Turn Mower	Model 3805Serial #0033870
9437	Massey Ferguson Tractor	Model 1230HSerial # D-33803
714	Sky Jack Scissor Lift	Model SJ111-3219Serial #22033-103



Holden Elementary School





Roof - High School (as of 2.1.18)

Bronze Section

Year Instl. - 2013

Type - EPDM

Installer - Black

Jack

Warranty - 20

Life Expec. - 25

Remaining life - 21

Condition - good

Yellow Section

Year Instl. - unkn.

Type - EPDM

Installer - unkn.

Warranty - 20

Life Expec. - 25

Remaining life - 0

Condition - poor

Purple Section

Year Instl. - 2012

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 19

Condition - good

Tan Section

Year Instl. - 2007

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 15

Condition - good

अनिस्

Red Section

Year Instl. - 2017

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 25

Condition - Excellent

mit.

Gold Section

Year Insti. - 2015

Type - EPDM

Installer – Blackjack

Warranty - 20

Life Expec. - 25

Remaining life - 22

Condition - Excellent

Blue Section

Year Instl. - 2015

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 23

Condition - good

Teal Section

Year Instl. - 2008

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 16

Condition - good

Green Section

Year Instl. - 2004

Type - EPDM


Installer - Weather Craft

Warranty - 20

Life Expec. - 25

Remaining life - 12





Roof – High School (as of 2.1.18)

Bronze Section

Year Instl. - 2013

Type - EPDM

Installer - Black

Jack

Warranty - 20

Life Expec. - 25

Remaining life - 21

Condition - good

Yellow Section

Year Instl. - unkn.

Type - EPDM

Installer - unkn.

Warranty - 20

Life Expec. - 25

Remaining life - 0

Condition - poor

Purple Section

Year Instl. - 2012

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 19

Condition - good

Tan Section

Year Instl. - 2007

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 15

Condition - good

ग्रन्थक)

Red Section

Year Instl. - 2017

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 25

Condition - Excellent

Gold Section

Year Insti. - 2015

Type - EPDM

Installer - Blackjack

Warranty - 20

Life Expec. - 25

Remaining life - 22

Condition - Excellent

Blue Section

Year Instl. - 2015

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 23

Condition - good

Teal Section

Year Instl. - 2008

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 16

Condition - good

Green Section

Year Instl. - 2004


Type - EPDM


Installer - Weather Craft

Warranty - 20

Life Expec. - 25

Remaining life - 12





Roof - High School (as of 2.1.18)

Bronze Section

Year Instl. - 2013

Type - EPDM

Installer - Black

Jack

Warranty - 20

Life Expec. - 25

Remaining life - 21

Condition - good

Yellow Section

Year Instl. - unkn.

Type - EPDM

Installer - unkn.

Warranty - 20

Life Expec. - 25

Remaining life - 0 Condition - poor

Purple Section

Year Instl. - 2012

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 19

Condition - good

Tan Section

Year Instl. - 2007

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 15

Condition - good

111005

Red Section

Year Instl. - 2017

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 25

Condition - Excellent

Gold Section

Year Insti. - 2015

Type - EPDM

Installer - Blackjack

Warranty - 20

Life Expec. - 25

Remaining life - 22

Condition - Excellent

Blue Section

Year Instl. - 2015

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 23

Condition - good

Teal Section

Year Instl. - 2008

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 16

Condition - good

Green Section

Year Instl. - 2004

Type - EPDM

Installer - Weather Craft


Warranty - 20

Life Expec. - 25

Remaining life - 12

4D)

Holden District Office





Roof - High School (as of 2.1.18)

Bronze Section

Year Instl. - 2013

Type - EPDM

Installer - Black

Jack

Warranty - 20

Life Expec. - 25

Remaining life - 21

Condition - good

Yellow Section

Year Instl. - unkn.

Type - EPDM

Installer - unkn.

Warranty - 20

Life Expec. - 25

Remaining life - 0

Condition - poor

Purple Section

Year Instl. - 2012

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 19

Condition - good

Tan Section

Year Instl. - 2007

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 15

Condition - good

Red Section

Year Instl. - 2017

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 25

Condition - Excellent

Gold Section

Year Insti. - 2015

Type - EPDM

Installer - Blackjack

Warranty - 20

Life Expec. - 25

Remaining life - 22

Condition - Excellent

Blue Section

Year Instl. - 2015

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 23

Teal Section

Year Instl. - 2008

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 16

Condition - good

Condition - good

Green Section

Year Instl. - 2004

Type - EPDM

Installer - Weather Craft


Warranty - 20

Life Expec. - 25

Remaining life - 12

Dugouts & Press Boxes







Roof – High School (as of 2.1.18)

Bronze Section

Year Instl. - 2013

Type - EPDM

Installer - Black

Jack

Warranty - 20

Life Expec. - 25

Remaining life - 21

Condition - good

Yellow Section

Year Instl. - unkn.

Type - EPDM

Installer - unkn.

Warranty - 20

Life Expec. - 25

Remaining life - 0

Condition - poor

Teal Section

Type - EPDM

Warranty - 20

Life Expec. - 25

Remaining life - 16

Condition - good

Year Instl. - 2008

Installer - Weathercraft

Purple Section

Year Instl. - 2012

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 19

Condition - good

Tan Section

Year Instl. - 2007

Type - EPDM

Installer - Weathercraft

Warranty - 20

Life Expec. - 25

Remaining life - 15

Condition - good

Red Section

Year Instl. - 2017

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 25

Condition - Excellent

Gold Section

Year Insti. - 2015

Type - EPDM

Installer - Blackjack

Warranty - 20

Life Expec. - 25

Remaining life - 22

Condition - Excellent

Blue Section

Year Insti. - 2015

Type - EPDM

Installer - Black Jack

Warranty - 20

Life Expec. - 25

Remaining life - 23

Condition - good

Year Instl. - 2004


Type - EPDM

Installer - Weather Craft

Warranty - 20

Life Expec. - 25

Remaining life - 12



1 4	i
_ /	
4	H
1 1	

		Year	Square	Warranty		1				
Building	Section	Installed Type	Footage	(Years)	2019-2020		2020-2021	2020-2021 2021-2022		2021-2022
Central Office	Green	2007								
HES	Blue	2003								
	Pink	2012				_				
	Peach	2014								
	Maroon	1957			\$345,000	0	Ō	0	0	0
SWH	Peach	2014								
Aux. Services	Red	2005								
SHH	Royal Blue	1995			\$66,000	8	000	000	000	000
	Maroon	1999			\$295,064)64)64)64	064	064
	Light Blue	2003								
	Red	2005							100	
1	Green	2007								
	Yellow	2011								
	Peach	2014								
	Lilac	2018								
S	:									
Dugouts	Yellow	2011								
Press Boxes	Green	2010								
	Yellow	2011								
Field Storage	٠	٠,٠								
Total					\$706,064)64)64)64	064	064

_		
1	1 T	_ ,


R-III Dist	rict Roof Repla	R-III District Roof Replacement Schedule	°									
		Year		Square	Warranty							
Building	Section	Installed Type	Эе	Footage	(Years)	2026-2027	2027-2028	2028-2029	2029-2030	2030-2031	2031-2032	2032-2033
Central Office	Green	$ \gamma $										
HES	Blue	2003										
	Pink	2012										
	Peach	2014										
	Maroon	1957										
HMS	Peach	2014										
Aux. Services	Red	2005										
HHS	Royal Blue	1995										
	Maroon	1999										
	Light Blue	2003										
	Red	2005										
	Green	2007										
	Yellow	2011										
	Peach	2014										
	Lilac	2018										
Dugouts	Yellow	2011										
											2	
Press Boxes	Green	2010										
	Yellow	2011										
Field Storage	,	-2										
Total												


F)							
	R-III District Roof Replacement Schedule	cement Sche	dule				
Building	Section	Year Installed	Туре	Square	Warranty (Years)	2033-2034	2034-2035
Central Office	Green	27					
HES	Blue	2003					
	Pink	2012					
	Peach	2014					
	Maroon	1957					
	•						
	5	1					
Aux. Services	Red	2005					
SHH	Royal Blue	1995					
	Maroon	1999					
	Light Blue	2003					
	Red	2005					
	Green	2007					
	Yellow	2011					
	Peach	2014					
	Lilac	2018					
Dugouts	Yellow	2011					
Press Boxes	Green	2010					
	Yellow	2011					
Field Storage	٠	٠٠					
Total							















- Asset
H
lal (

Aux. Services A	_	A	Aı	Aı	A	HHS	A	A	A	HMS A		A	Α	HES A		Office			R-III District
	Area N	Area M	Area L	Area K	Area J	Area H	Area G	Area F	Area E	Area D		Area C	Area B	Area A		All	5		t Parking Lot
	2005		2007		2007	2007	1995			1995		2003		2003		Installed			R-III District Parking Lot Maintenance Schedule
	Gravel	Gravel	2007 Pavement/Concrete	Gravel	2007 Pavement	2007 Pavement	1995 Gravel	Pavement/Concrete	Pavement	1995 Pavement		Pavement	Pavement	2003 Pavement		Pavement	Tibo		ce Schedule
417,525	66,000	7,500	41,275	27,800	28,550	97,800	24,500	19,850	6,500	39,850		24,250	11,300	17,000	0,000	2 3 3 5 O	Square		
																(Tedis)	Warranty		
\$0																707-6107			
																7070-2021	,		
																7071-7077	7	21	
																2022-2023			
											,					2023-2024			
																2024-2025			

Total	Aux. Services					SHH				SWH			HES	Central Office	Building		5	F
	vices													Office			R-III Distr	
	Area N	Area M	Area L	Area K	Area J	Area H	Area G	Area F	Area E	Area D	Area C	Area B	Area A	All	Section		ict Parking L	
	2005		2007		2007	2007	1995			1995	2003		2003		Installed	Year	R-III District Parking Lot Maintenance Schedule	
	Gravel	Gravel	2007 Pavement/Concrete	Gravel	2007 Pavement	2007 Pavement	1995 Gravel	Pavement/Concrete	Pavement	1995 Pavement	2003 Pavement	Pavement	Pavement	Pavement	Туре		ce Schedule	
417.525	66,000	7,500	41,275	27,800	28,550	97,800	24,500	19,850	6,500	39,850	24,250	11,300	17,000	5.350	Footage	Square		_
															(Years)	Warranty		
															2025-2026			
															2026-2027			
															2027-2028			
															2028-2029			
															2029-2030			
															2030-2031			

Building Central Office HES HMS HMS	R-III District Parking Lot Maintenance Schedule Year Year Year Year Area A Area B Area C Area E Area F Area G Area H Area J Area J Area C 2003 Pavement Pavement	Year Installed 2003 2003 1995 2007 2007	lled Type Pavement 2003 Pavement 2003 Pavement Pavement Pavement 1995 Pavement	Squ	Jare 5,350 17,000 11,300 24,250 24,250 39,850 6,500 19,850 24,500 24,500 27,800	are Warranty 5,350 5,350 17,000 11,300 24,250 24,250 39,850 6,500 19,850 24,500 27,800 97,800 97,800	850 S00 S00	Warranty e (Years) 350 300 300 250 250 850 850 850	Warranty e (Years) 2031-2032 350 300 300 250 850 850 850
Se	ction	Year	Type	Squ	Square	l o	Warranty e (Years)	Warranty e (Years) 2031-2032	Warranty
	All		Pavement	О	,350	50	50	50	50
1 1	Area A	2003	Pavement	17,	000	000	,000	,000	.000
	Area B		Pavement	11,	300	300	300	300	300
	Area C	2003	Pavement	24,2	50	50	50	50	50
IS	Area D	1995	Pavement	39,8	50	50	50	50	50
	Area E		Pavement	6,5	00	00	00	00	00
	Area F		Pavement/Concrete	19,8	50	50	50	50	50
	Area G		Gravel	24,	500	500	500	500	500
HS	Area H	2007	Pavement	97	,800	,800	,800	,800	,800
	Area J	2007	Pavement	2	8,550	8,550	8,550	8,550	8,550
	Area K		Gravel		27,800	27,800	27,800	27,800	27,800
	Area L	2007	Pavement/Concrete		41,275	41,275	41,275	41,275	41,275
	Area M		Gravel		7,500	7,500	7,500	7,500	7,500
Aux. Services	Area N	2005	2005 Gravel		66,000	66,000	66,000	66,000	66,000
1					/17 EDE	417 EDE	417 525	17 E2E	77 57 5



olden

Boiler Units - 2

Installed - 2013

Location - 1st floor

Carrier Fan Coil Unit

Installed - 1990

Refrigerant -

Trane Chiller Unit

Location - 1st floor

Installed - 1990

Tons - 240

R22 - 575 lbs.

Cooling Tower

Location - Outside

Installed - 2017

Aaon Unit

Installed - 2013

Refrigerant - R410A

Cooling Tower

Location - Outside

Installed -?

Dailor

Boiler Units - 2 Location - 2nd floor

Installed - 2017

Trane Chiller Unit

Location - basement

Installed - 1989

Tons = 160

R22 - 300 lbs.

Chiller Unit

MATE S

Location - 2nd floor

Installed - 2017

Tons -

R

Boiler Units - 2

Location - basement

Installed - 2005

Aaon Unit

Installed - 2017

Refrigerant - R410A

Aaon Unit

Installed - 2013

Refrigerant - R410A

Traine Unit

Installed - 1990


Refrigerant - R22

Traine Unit

Installed - 1990

Refrigerant - R22

6B)



Carrier Fan Coil Unit

Installed – 1990

Refrigerant -

Boiler Units - 2

Location – 1st floor Installed – 2013 Trane Chiller Unit

Location - 1st floor

Installed - 1990

Tons - 240

R22 - 575 lbs.

Cooling Tower

Location - Outside

Installed - 2017

Aaon Unit

Installed - 2013

Refrigerant - R410A

Cooling Tower

Location - Outside

Installed -?

Trane Chiller Unit

Location - basement

Installed - 1989

Tons = 160

R22 - 300 lbs.

Boiler Units - 2

Location - basement

Installed - 2005

Aaon Unit

Installed - 2013

Refrigerant - R410A

70007

Boiler Units - 2

Location - 2nd floor

Installed - 2017

Chiller Unit

Location - 2nd floor

installed - 2017

Tons -

R

Aaon Unit

Installed - 2017

Refrigerant - R410A

Traine Unit

Installed - 1990


Refrigerant - R22

Traine Unit

Installed - 1990

Refrigerant - R22





Holden High School

Boiler Units - 2

Installed - 2013

Location - 1st floor

Carrier Fan Coil Unit

Installed - 1990

Refrigerant -

Trane Chiller Unit

Location - 1st floor

Installed - 1990

Tons - 240

R22 - 575 lbs.

Cooling Tower

Location - Outside

Installed - 2017

Boiler Units - 2

Installed - 2017

Location - 2nd floor

Aaon Unit

Installed - 2013

Refrigerant - R410A

Cooling Tower

Location - Outside

Installed -?

Trane Chiller Unit

Location - basement

Installed - 1989

Tons = 160

R22 - 300 lbs.

Chiller Unit

NAL S

Location - 2nd floor

Installed - 2017

Tons -

R

Boiler Units - 2

Location - basement

Installed - 2005

Aaon Unit

Installed - 2017

Refrigerant - R410A

Aaon Unit

Installed - 2013

Refrigerant - R410A

Traine Unit


Installed - 1990

Refrigerant - R22

Traine Unit

Installed - 1990

Refrigerant - R22





Carrier Fan Coil Unit

Installed - 1990

Refrigerant -

Boiler Units - 2

Location - 1st floor

Installed - 2013

Trane Chiller Unit

Location - 1st floor

Installed - 1990

Tons - 240

R22 - 575 lbs.

Cooling Tower

Location - Outside

Installed - 2017

Aaon Unit

Installed - 2013

Refrigerant - R410A

Cooling Tower

Location - Outside

installed -?

Trane Chiller Unit

Location - basement

Installed - 1989

Tons = 160

R22 - 300 lbs.

Boiler Units - 2

Location - basement

Installed - 2005

Aaon Unit

Installed - 2013

Refrigerant - R410A

Boiler Units - 2

Location - 2nd floor

Installed - 2017

Chiller Unit

SAMES!

Location - 2nd floor

Installed - 2017

Tons -

R

Aaon Unit

Installed - 2017

Refrigerant - R410A

Traine Unit


Installed - 1990

Refrigerant - R22

Traine Unit

Installed - 1990

Refrigerant - R22



HVAC - High School (as of 1.8.18)

Carrier Fan Coil Unit

Installed - 1990

Refrigerant -

Boiler Units - 2

Location - 1st floor

Installed - 2013

Trane Chiller Unit

Location - 1st floor

Installed - 1990

Tons - 240

R22 - 575 lbs.

Cooling Tower

Location - Outside

Installed - 2017

Aaon Unit

Installed - 2013

Refrigerant - R410A

Cooling Tower

Location - Outside

Installed -?

Trane Chiller Unit

Location - basement

Installed - 1989

Tons = 160

R22 - 300 lbs.

Boiler Units - 2

Location - basement

Installed - 2005

Aaon Unit

Installed - 2013

Refrigerant - R410A

Boiler Units - 2 Location - 2nd floor

Installed - 2017

Chiller Unit

NAME OF THE PERSON

Location - 2nd floor

Installed - 2017

Tons -

R

Aaon Unit

Installed - 2017

Refrigerant - R410A

Traine Unit

Installed - 1990

Refrigerant - R22

Traine Unit

Installed - 1990


Refrigerant - R22


Sample

Туре	Map #	Brand	Model #	Serial #	Date of Manufacture	041		the second control of the second control of the second control of the second of the se
HVAC	Charles a	Trane	WCD1B0B4DADB	The second secon	Date of Manufacture	C/N		The second secon
and Andrews Co.	Committee and	Trane	WCD1B0B4DADB	K0B101133D	2/1995		MS	a process of the commencer will be
gull have man vari	0.4 2 2 -		and the state of t	K0B101128D	2/1995		MS	
e i saa saa gowl	4 - 55 1	Trane	WCD036C40ABC	K08101005D	2/1995	s 11.9	MS	Form the state of
		Trane	WCD060c40CBC	K0B101006D	2/1995		MS	1
	558 9	Trane	WCD120B40ADB	K0B101130D	2/1995		MS	
Mark Section 1		Trane	WCD120B4OADB	K0B101131D	2/1995		MS	
	enegle ik interioris	Trane	WCD120B40ADB	K0B101128D	2/1995		MS	
	8	Trane	WCD160B40ADB	K0B101137D	2/1995		MS	A 100 March 100
e i deservir inscienti il liga	9	Lennox	KHA18054BN1G	5610G14054	2014	L0339	MS	
	10	Trane	WCD075C40ABC	K0B101008D	2/1995		MS	TOTAL STREET,
CONTRACTOR MAN S.	11	Trane	WCD075C40ABC	K0B101007D	2/1995	*** · · · · · · · · · · · · · · · · · ·	MS	1
	12	Trane	WCD075C40ABC	K0B101009D	2/1995		MS	OF THE STATE OF TH
	13	York	XP150E54N4BAA5A	N1C2622747			MS	THE THE PERSON OF THE OWNER OF THE OWNER.
	14	Trane	WCD180B40ADB	K0B101360D	2/1995		MS	
	15	Trane	WCD180B40ADB	The second of the second of the second	2/1995		MS	to a commence of
	16	Carrier	48HJE004G-541HY	3407G50532	2007	****		White Mile
o deta university or		Carrier	48HJE004G-541HY	3407G50528	2007	er i ir ing	HS	White Mile
TOTAL AND A TARREST OF		Carrier	48HJE004G-541HY	3407G50519	the same of the sa		HS	White Mile
* A. B. C. S. C	regio mos amount i	Carrier	48HJE004G541HY	The grant of the party of the p	2007		HS	White Mile
* ***** * * * · ·	person is more t	Carrier		3407G5O526	2007		HS	White Mile
	a see a seeming	management of a sec-	48HJE004G-541HY	3407G5O524	2007		HS	White Mile
Distribution 1	7	Carrier	48HJE004G-541HY	2907G20565	2007		HS	White Mile
(MM) (40 - 10 - 1	- In	Carrier	48HJE004G-541HY	3407G40606	2007		HS	White Mile
		Carrier	48HJE004G-541HY	3407G50531	2007		HS	White Mile
**		Carrier	48HJE004G-541HY	3407G50530	2007		HS	White Mile
	The second	Carrier	48HJE004G-541HY	3407G50527	2007		HS	White Mile
* 1000 TAX 1 (1) (1) (1)	26	Carrier	48HJE004G-541HY	3407G50516	2007	i	HS	White Mile
Marian man a	27	Carrier	48HJE004G-541HY	3407G50517	2007	;	HS	White Mile
The Contract of the Contract o	28	Carrier	48HJE004G-541HY	3407G50529	2007		HS	Middle Row S of White Mile
the science has provide	29	Carrier	48HJE004G-541HY	3407G50525	2007		HS	Middle Row S of White Mile
· ·	30	Carrier	4850030040311	3207G11924	2007		HS	Middle Row S of White Mile
W	31	Carrier	48HJD0056-551HY	3407G50596	2007	comment of the	HS	Middle Row S of White Mile
	32	Carrier	The state of the s	3407G40595	2007		HS	Middle Row S of White Mile
	33	Carrier	-	3407G40597	2007	1-	HS	Middle Row S of White Mile
	34	Carrier		3407G40499	2007	- 1	HS	Middle Row S of White Mile
		Lennox	LGC036S2BS1Y	5604F04366	2004		HS	Middle Row S of White Mile
	36	Lennox	1 C2202-001-0-10 (Amor - 4 = 1 - 1 - 1	5604F04358	2004	100 F 100	HS	Middle Row S of White Mile
1 100 -1140 Mr 11	37	Lennox	0.700 1.00 (0.00) 1. 1.	5604F04357	2004	Arm on the land	HS	Control of the accesses among the annual control of an access and an access and an access as a
1 2520	the same is	Lennox	received the man in the	5604F04357	The state of the s			Middle Row S of White Mile
the property		Lennox	A Delice of the Control of the	5604F04237	2004	er comp-	HS	Middle Row S of White Mile
- Hann 2 1466 - 1		Lennox	LGA060H2BH2Y	Territoria de la composición del composición de la composición de	2004		HS	Middle Row S of White Mile
	it is the second of	Lennox	The second of the second second second second second second	5604F03801	2004	e com a je	HS	Middle Row S of White Mile
an enterior and a	.,.		LGC060S2BS1Y	5604F04386	2004		HS	Middle Row S of White Mile
180		Lennox	LGC036S2BS1Y	5604F04361	2004		HS	Middle Row S of White Mile
	1 - 1	Lennox	LGA042H2BS2Y	5604F04328	2004		HS	Office Roof
0.000	7	Lennox	LGC060S2BS1Y	5604F04346	2004	ŀ	HS	Office Roof
2 2 5 to	Pro	Lennox	merce comment	5604F03870	2003	į.	HS	N side of gym
#0 VO 0		Lennox	LGC048S2BS1Y	5604F03743	2003	1	HS	N side of gym
Note: epidentic	47 1	Lennox	of the delication and the same	5604F03871	2003	ŀ	HS	N side of gym
Total and	48 1	Lennox	TGA090S2BS1Y	5604E11332	2011	ŀ	HS.	N side of gym
		Lennox	LGC036S2BS1Y	5604F04362	2004	2000 DOS 9 (840	HS .	Old Hallway
	50 1	Lennox	LGC036S2BS1Y	5604F044363	2004	ŀ	HS	Old Hallway
	51	ennox	LGC036S2BS1Y	5604F04365	2004		HS	Classrooms on S side of old hallway
**	52 1	ennox	LGC036S2BS1Y	5604F04364	2004		HS .	Classrooms on S side of old hallway
	1 11	ennox	LGC036S2BS1Y	5604F04360	2004		HS	and the same of th
		ennox	LGC036S2BS1Y	5604G01042	2004			Classrooms on S side of old hallway
3 160 A. A.		_ennox	LGC072S2BT1Y	5604F03816	the state of the s	* * *	IS	Classrooms on S side of old hallway
v and or	and the	ennox	With the second distance of the terror of the second of th	The second secon	2004	one or the opinion	HS .	E side of gym
14 - Maria de 127 de 124	1	1000	LGC000S2BM2V	5604F04359	2004	E-m	-IS	E side of gym
ceco a se se se	2 10 10 40	_ennox	LGC090S2BM2Y	5604F04113	2004		HS.	E side of gym
	CO 4					1	10	
g where v	58 (48HJD005G-551HY	3407G49593	2007	1	4S	E side of gym
	59 (Carrier Carrier Frane	48HJD005G-551HY YCD086C3LABD	3407G49593 3407G40594 K0B101092D	2007		15	E side of gym


	61 Trane	YCD037C3LABD	K0B101089D		2/1995	HS	Tech Hall
and or	62 Trane	YCD049C3LABD	K0B101091D		2/1995	HS	Tech Hall
2 2	63 Trane	YCD037C3LABD	K0B101090D		2/1995	HS	Tech Hall
2.62	64 Trane	YCD037C3LABD	K0B101088D	francis en en	2/1995	HS	Tech Hall
roping v	65 Carrier	48SD-030040311	TO BE STITUTED AND A STATE OF	12 - 12 F 38 19	100 9 9 90		to the manufacture of the party
	66 Carrier		3207G11921		2007	HS	Cafeteria/Kitchen
	25 2550 BOS	48HJD012G-571HY	3407G20834		2007	HS	Cafeteria/Kitchen
1244	67 Carrier	48HJD012G-571HY	3407G20833		2007	HS	Cafeteria/Kitchen
	68 Lennox	TGA090S2BS1Y	5604F03358	Section were	2004	HS	Land Santa Control of the Control of
** - * * * *	69 Lennox	TGA090S2BS1Y	5604F00257	i	2004	HS	Cafeteria/Kitchen
*****	70 Carrier	48HJE004G-541HY	3407G50518		2007	HS	Cafeteria/Kitchen
	71 Carrier	48SD-030040311	3307G31183	FOR THE PROPERTY AND ASSOCIATION OF THE	2007	HS	S side of gym
TO THE STATE OF THE STATE OF	72 Lennox	LGC090S2BH2Y	5604F04112	Second Control of the	2004	HS	S side of gym
	73 Lennox	LGC048S2BH1Y	5604F04238	1	2004	HS	S side of gym
	74 Trane	TSC060E1EFA1RDZ	142813483L	*** ***	8/2014	HS	Multi
	75 Trane	TSC060E1EFA1RDZ	142813427L	X X 30000	8/2014	HS	Multi
1960	76 Lennox	GCS16-060-120-4Y	5603E04378		2003	ES	Gym
27 505	77 Lennox	GCS16-060-120-4Y	5603E07375	i mari	2003	ES	a print and a second of the se
-0.	78 Lennox	**** **********************************	Contract of the contract of th		25 min 27 min		Gym
P 0 0 0		GCS16-060-120-4Y	5603E04379		2003	ES	Gym
1.18	79 Lennox	GCS16-072-160-1Y	5603G06450	20 10 17 152	2003	ES	Kitchen
	80 Trane	TSC060E1EFA1RDZ	142813399L		7/2014	ES	Eagles Nest
	81 Trane	TSC060E1EFA1RDZ	142813455L	× 2	8/2014	ES	Eagles Nest
ere e	82 Lennox	GCS16-036-90-5Y	5603G06748	to exam	2003	ES	Old Entrance
	83 Lennox	GCS16-036-90-5Y	5603H01477		2003	ES	Old Entrance
	84 Lennox	GCS16-048-120-5Y	5603H06859	2 100	2003	ES	Old Entrance
	85 Lennox	GCS16-048-120-5Y	5603G06799		2003	ES	Old Entrance
	86 Lennox	GCS16-048-120-4Y	5603E07311		2003	ES	1st grade hall
	87 Lennox	GCS16-048-120-4Y	5603H06860	10.00	2003	ES	1st grade hall
	88 Lennox	GCS16-048-120-5Y	5603H04118		2003	ES	1st grade hall
	89 Lennox	GCS16-048-120-5Y	5603H04122	*	2003	ES	THE R. DECEMBER AND ADDRESS OF THE PARTY OF
	90 Lennox	GCS16-060-120-4Y	5603E10331	- 3	CONTRACTOR OF		1st grade hall
	91 Lennox	compared to the second of the	The short of the same of the same of		2003	ES	1st grade hall
	U 1991 KW	GCS16-060-120-4Y	5603E07312		2003	ES	1st grade hall
	92 Lennox	GCS16-036-90-5Y	5603H01398		2003	ES	hallway
	93 Lennox	GCS16-036-90-5Y	5603H01483		2003	ES	hallway
	94 Lennox	GCS16-036-90-5Y	5603F01688		2003	ES	hallway
	95 Lennox	GCS16-048-120-5Y	5603H06858		2003	ES	South classroom row
	96 Lennox	GCS16-048-120-5Y	5603H04121	v.	2003	ES	South classroom row
	97 Lennox	GCS16-048-75-5Y	5603H07048		2003	ES	South classroom row
	98 Lennox	GCS16-048-75-5Y	5603H04119		2003	ES	South classroom row
	99 Lennox	GCS16-060-120-4Y	5603H10407		2003	ES	South classroom row
	100 Lennox	GCS16-060-120-4Y	5603E04377		2003	ES	South classroom row
	101 Seasons 4		A8288-0304MZU-1		1982	ES	The state of the s
	102 Trane	YSC12843 M 20P			1902	64	Library
	Same and second	- 1 - 10 - 10 - 10 - 10 - 10 - 10 - 10	421102215 422100288D		E/0004	ES	Library
* -	103 Trane	YFD150D3HABA	422100388D		5/2004	ES	Library
	104 Trane	YFD150D3HABA	422100401D		5/2004	ES	Library
	105 Trane	YSC048A3RMA00VK	4221003011		12	ES	North side of gym
	106 Trane	YSC048A3RMA00VK	422100374L		•	ES	North side of gym
	107 Trane	YSC090A3RMA00VK	422100214L			ES	North side of gym
	108 Trane	YCC024F1L0BJ	4062JJ32H			ES	North side of gym
	109 Trane	YSC048A3RMA00VK	422100384L			ES	North side of gym
	110 Trane	YSC090A3RMA00VK	421102451L			ES	North side of gym
	111 Trane	YSC048A3RHA00VK	422100179L			ES	North side of gym
	112 Trane	YCC030F1M0BJ	4134Z101H		1,000	ES	East side of gym
2.	113 Trane	YFD150D3HABA	422100364D		# 5		
			1 (8.5) 10 10 10			ES	3-5 Kitchen/Cafeteria
	114 Trane	YSC090A3RLA020P	421102385L			ES	3-5 Kitchen/Cafeteria
	115 Trane	YSC036A3RMA00VK	421102255L			ES	3-5 Kitchen/Cafeteria
B	116 Trane	YSC090A3RLA020P	421102255L		- 1 6	ES	3-5 Kitchen/Cafeteria
	117 Trane	YSC036A3RMA00VK	421102358L			ES	3-5 Kitchen/Cafeteria
	118 Trane	YSC048A3RMA00VK	422100110L		1	ES	3-5 Kitchen/Cafeteria
		VSC04843DMA00VK	422100365L		9	ES	3-5 Kitchen/Cafeteria
	119 Trane	YSC048A3RMA00VK	TELTOCOCCE				
	119 Trane 120 Trane	YSC048A3RMA00VK	422100407L		60	ES	5th grade hall


Andrew Committee of the	122	Trane	YSC048A3RMA00VK	421102203L	ES	5th grade hall
AL SO FEED THE STATE OF STREET	123	Trane	YSC048A3RMA00VK	422100413L	. ES	5th grade hall
	124	Trane	YSC048A3RMA00VK	422100391L	ES	5th grade hall
	125	Trane	YSC048A3RMA00VK	422100404L	ES	5th grade hall
	126	Trane	YSC048A3RMA00VK	422100397L	ES	5th grade hall
	127	Trane	YSC048A3RMA00VK	422100401L	ES	5th grade hall
**************************************	128	Trane	YSC048A3RMA00VK	422100343L	ES	5th grade hall
	129	Trane	YSC048A3RHA00VK	422100297L	ES	South side of gym - west
The street	130	Trane	YSC090A3RMA00VK	421102389L	ES	office
**************************************	131	Trane	YSC048A3RMA00VK	422100347L	ES	break area
	132	Trane	YSC090A3RMA00VK	421102259L	ES	south side of gym - east





AP 130









Link to large copy.

Square A. Calas and Shdont Enrollment **T** 8

Same as 8A)



Same as 8A





THIRTY YEAR STUDY SEPTEMBER COUNT HEAD COUNT ENROLLMENT

ELEM. CERTIFIED STAFF M.S. CERTIFIED STAFF H.S. CERTIFIED STAFF TOTAL CERTIFIED STAFF	DIFF. FROM PREVIOUS YEAR	DIST. TOTAL	TOTAL H.S.	NINTH TENTH ELEVENTH TWELFTH	TOTAL M.S.	SIXTH SEVENTH EIGHTH	TOTAL ELEM.	PRE-K KIND. FIRST SECOND THIRD FOURTH FIFTH
44 23 34 101	+36	1183	361	102 97 89 73	299	95 109 95	523	9/25/19 20 20 94 74 81 102 75
42 23 35 100	+9	1147	353	93 91 78 91	292	101 92 99	503	9/26/18 6 74 87 103 74 77 82
43 23 35 101	-32	1138	364	95 84 91 94	277	84 104 89	497	9/27/17 NA 74 98 73 72 85 95
45 22 39 106	-20	1170	378	87 94 96 101	273	99 88 86	518	9/28/16 NA 105 78 72 86 96 81
47 23 39 109	-38	1190	395	95 100 112 88	272	93 91 88	523	9/30/15 NA 88 72 85 93 85 100
47 23 39 109	-29	1228	415	106 118 93 98	271	91 88 92	542	9/24/14 NA 77 91 97 87 100 90
48 24 41 113	-62	1257	400	112 105 107 76	295	85 98 112	562	9/25/13 NA 92 96 84 96 101 93
49 23 40 112	-22	1319	408	113 116 84 95	333	93 119 121	578	9/26/12 NA 101 87 99 104 101 86
49 24 40 113	-55	1341	406	126 89 99 92	363	122 121 120	572	9/28/11 NA 79 99 105 101 88 100
50 24 41 115	-40	1396	430	100 114 102 114	349	125 113 111	617	9/29/10 NA 99 101 102 86 109 120



ELEM. CERTIFIED STAFF M.S. CERTIFIED STAFF H.S. CERTIFIED STAFF TOTAL CERTIFIED STAFF	DIFFERENCE FROM PREVIOUS YEAR	DIST. TOTAL	TOTAL H.S.	ELEVENTH	NINTH	TOTAL M.S.	SIXTH SEVENTH EIGHTH	TOTAL ELEM.	KIND. FIRST SECOND THIRD FOURTH FIFTH
52 24 41 117	+11	1436	464	111 106	127 120	327	114 113 100	645	9/30/09 96 106 91 110 1118 124
52 24 41 117	-63	1425	459	118 93	122 126	323	114 103 106	643	9/24/08 98 92 106 114 122 111
49 29 41 119	4	1488	504	113 132	129 130	338	106 110 122	646	9/26/07 89 100 111 117 110 119
48 30 39 117	+49	1492	502	128 110	133 131	362	110 123 129	628	9/27/06 95 105 119 103 102 104
44 30 38 112	4	1443	484	1111 95	141 137	348	107 124 117	611	9/28/05 102 111 95 103 99 101
44 27 38 109	+75	1447	497	107 103	162 125	366	124 115 127	584	9/29/04 104 87 95 89 100 109
49 24 39 112	-16	1372	439	109 88	131 111	368	113 116 139	565	9/24/03 82 87 77 92 103 124
44 22 38 104	-12	1388	445	107 101	125 112	376	117 138 121	567	9/25/02 86 79 85 95 114 108
43 22 38 103	-30	1400	451	120 104	107 120	356	125 118 113	593	9/26/01 76 90 95 114 109
53 25 36 114	-38	1430	464	117 106	118 123	324	113 112 99	642	9/27/00 88 91 121 111 1110 121



ELEM. CERTIFIED STAFF M.S. CERTIFIED STAFF H.S. CERTIFIED STAFF TOTAL CERTIFIED STAFF	DIFFERENCE FROM PREVIOUS YEAR	DIST. TOTAL	TOTAL H.S.	NINTH TENTH ELEVENTH TWELFTH	TOTAL M.S.	SIXTH SEVENTH EIGHTH	TOTAL ELEM.	KIND. FIRST SECOND THIRD FOURTH FIFTH
53 29 40 122	-9	1468	473	132 125 119 97	335	111 111 113	660	9/29/99 90 122 109 103 124 112
51 24 36 111	+44	1477	464	128 134 108 94	344	106 112 126	669	9/30/98 119 105 100 125 110 110
45 26 27 98	+33	1433	432	133 130 103 66	346	102 120 124	655	9/24/97 101 108 126 115 100 105
48 28 30 106	-14	1400	407	128 111 81 87	367	115 127 125	626	9/25/96 96 122 108 102 100 98
44 26 30 100	+75	1414	399	135 93 81 90	372	129 121 122	643	9/27/95 127 108 101 97 102 108
45 23 29 97	+75	1339	370	110 101 91 68	342	111 112 119	627	9/28/94 97 105 85 108 109 123
44 23 29 96	+6	1264	359	114 102 81 62	297	99 110 88	608	9/29/93 103 76 110 110 102 110
37 24 26 8 7	+70	1258	350	106 100 69 75	305	113 93 99	603	9/30/92 87 97 101 107 109 102
36 24 25 85	+49	1188	305	92 74 76 63	291	98 95 98	592	9/25/91 87 96 107 102 92 108
36 25 24 85	፟∞	1139	277	75 78 71 53	284	96 101 87	578	9/26/90 87 102 98 84 109 98

8E)

Cohort Survival Enrollment Projection

Holden R-III School District- Johnson Country, MO

Based on average K enrollment for 5 years

Grade 77 88 105 701 87 74 75 84 <t< th=""><th></th><th></th><th></th><th>Historical Data</th><th></th><th></th><th></th><th>۵</th><th>Projection Data</th><th></th><th></th></t<>				Historical Data				۵	Projection Data		
77 88 105 74 75 84 84 84 84 84 91 72 78 97 74 75 81 82 77 81 81 81 82 82 77 81 82 82 82 82 77 82 80<	Grade	2015-2016	2016-2017	2017-2018	2018-2019	2019-2020	2020-2021	2021-2022	2022-2023	2023-2024	2024-2025
91 72 78 97 87 74 82 82 82 97 84% 89% 92% 118% 98.02%	¥	77	88	105	74	75	84	84	84	84	84
91 72 78 97 87 74 82 82 82 97 844 72 118% 98.02%	:									The second secon	
97 884 92% 118% 98.02%	,	91	72	78	97	87	74	82	82	82	82
97 84 72 73 103 85 72 81	4		94%	%68	95%	118%	98.02%	98.02%	98.02%	98.02%	98.02%
87 932% 100% 94% 106% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 98.02% 99.02% 99.03% 99.04 99.04% 99.04% <	,	97	84	72	73	103	85	72	81	81	81
87 93 86 72 74 103 85 72 86 72 80 86 72 74 103 85 77 75 105 99.31% 99.43% </td <td>7</td> <td></td> <td>92%</td> <td>100%</td> <td>94%</td> <td>106%</td> <td>98.02%</td> <td>98.02%</td> <td>98.02%</td> <td>98.02%</td> <td>98.02%</td>	7		92%	100%	94%	106%	98.02%	98.02%	98.02%	98.02%	98.02%
100 96% 102% 100% 101% 99918% 99.91% 99.91% 99.91% 73 73 73 73 73 73 73 73 73 73 73 74.3% 99.91% 101.68% 10	٣	87	93	98	72	74	103	85	72	80	81
100 85 96 85 77 75 105 73 90 98% 103% 99% 107% 101.68% 101. 101.68% 100.68 100.69 100.69 100.69 100.60 <td>,</td> <td></td> <td>%96</td> <td>102%</td> <td>100%</td> <td>101%</td> <td>99.91%</td> <td>99.91%</td> <td>99.01</td> <td>99.91%</td> <td>99.91%</td>	,		%96	102%	100%	101%	99.91%	99.91%	99.01	99.91%	99.91%
98% 103% 99% 107% 101.68% 101.1 101.68% 101.68% 101.1 101.68% 102.30%	٧	100	85	96	85	77	75	105		73	82
90 99 81 95 82 75 73 84 84 101 85 78 74.3% 97.43% 97.74% 97.71%<	•		%86	103%	%66	107%	101.68%	101.t	C	101.68%	101.68%
91 95% 95% 96% 97.43% 97.71% 97.81% 97.81% 97.81% 97.81% 97.81% 96.41% 96.41% 96.41% 96.41% 96.41% 96.41%	Ľ	90	66	81	95	82	75	73	O	84	71
91 93 84 101 85 78 105 105 107 105 107 105 107 103 105 104 92 103 87 34% 105 104 92 103 87 34%	י		%66	826	%66	%96	97.43%	97.43%		7.43%	97.43%
88 103% 100% 104% 106% 103.34% 103.34% 103.34% 103.34% 34% 88 91 88 104 92 103 87 % 92 88 86 89 99 90 101 % % 106 95 101% 95% 97.71% 97.71% 97.71% 97.71% 106 95 87 95 93 104.27% 104.27% 104.27% 108 95 110% 95 93 104.27% 104.27% 104.27% 118 100 94 84 91 96 41.6 96.41%	ų	91	93	66	84	101	85	78	Jan Daniel Control	105	87
88 91 88 104 92 103 87 7 92 88 86 89 99 90 101 7 92 88 86 89 99 90 101 7 106 95 101% 95% 101% 95% 97.71% 97.71% 97.71% 106 95 87 95 93 103 94 104.27% 104.27% 104.27% 118 100 94 84 91 90 100 90 101 94 112 95% 97% 96% 96.41% 96.41% 96.41% 96.41% 96.41% 94 112 97% 89 78 86 85 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 96.41% 96.41% 96.41% 96.41% 96.41% 96.41% 96.41% 96.41% 96.41% 96.86% 94.86% 94.86%	>		103%	100%	104%	106%	103.34%	103.34%	e	34%	103.34%
92 88 100% 95% 105% 110% 100.30% 101 % 92 88 86 89 99 90 101 7 7% 106 95 101% 95% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 88 88 97.71% 104.27%	^	88	91	88	104	92	103	87		-	108
92 88 86 89 99 90 101 ,			100%	95%	105%	110%	102.30%	102.30%		%	102.30%
106 95% 101% 95% 101% 95.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 97.71% 104.27% 104.2	œ	92	88	98	89	. 66	06	101		1	76
106 95 87 95 93 103 94 104.57% 104.27	•		100%	82%	101%	%56	97.71%	97.71%	6	97.71%	97.71%
118 103% 99% 110% 104,27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104.27% 104<	σ	106	95	87	95	93	103	94	1.05	88	81
118 100 94 84 91 90 100 90 101 90 101 90 101 90 101 96.41%)		103%	%66	110%	104%	104.27%	104.27%	104.27%	104.27%	104.27%
94 99% 97% 96% 96.41%	10	118	100	94	84	91	06	100	06	101	85
94 112 97 89 78 86 85 94.86% 91.86 91.86 91.8 91.11 91.8 91.8 91.8 91.8 <td>2</td> <td></td> <td>94%</td> <td>%66</td> <td>%26</td> <td>%96</td> <td>96.41%</td> <td>96.41%</td> <td>96.41%</td> <td>96.41%</td> <td>96.41%</td>	2		94%	%66	%26	%96	96.41%	96.41%	96.41%	96.41%	96.41%
98 97% 95% 93% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 94.86% 91 92 91 92 91 92 91 92 </td <td>11</td> <td>94</td> <td>112</td> <td>97</td> <td>68</td> <td>78</td> <td>98</td> <td>85</td> <td>94</td> <td>98</td> <td>96</td>	11	94	112	97	68	78	98	85	94	98	96
98 89 101 94 91 75 83 82 91 7 1229 1189 1170 1135 1143 1128 1119 1112	1		95%	%26	95%	93%	94.86%	94.86%	94.86%	94.86%	94.86%
45% 50% 50% 50.00% 56.00% 56% 5	12	86	89	101	94	91	75	83	82	91	82
1229 1189 1170 1135 1143 1128 1128 1119 1112 97% 98% 97% 101% 99% 99% 99%			95%	%06	%26	102%	%00.96	%96	%96	%96	%96
97% 97% 101% 99% 100% 99%	K-12	1229	1189	1170	1135	1143	1128	1128	1119	1112	1096
	77 V		%26	%86	%26	101%	%66	100%	%66	%66	%66





"Honesty, Integrity, Accountability"

EXHIBIT A: CUSTODIAL SCOPE OF SERVICES

Office Areas	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Vacuum all main carpeted areas		Х	Х			
Clean counter (glass, wood, etc), tops (desks, tables, etc), free of paperwork		Х	X			
Empty all wastebaskets, and replace liners if wet, torn, or soiled	Х	X	X			
Clean drinking fountains		X	X			
Straighten chairs and wipe horizontal tables		X	X			
Empty pencil sharpeners		X	X			
Detail vacuum under cubicles, desks, tables, and furniture in open floor space. Will not be moved		Х	X			
Dust picture frames, woodwork, and ledges		<u> </u>		Х		
Spot clean glass in furniture partitions or other building parts				X		
Dust desks, chairs, credenza, file cabinets, window ledges, furniture tops, counter tops, etc, clear of paper				X		
Dust vertical surfaces, chair rungs, furniture legs, etc		Х			Х	
Dust baseboards		X			X	
Dust exposed bookshelf areas		X			X	

Class Room Areas	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Vacuum all carpeted areas		Х	X	,	,	
Sweep and spot-mop daily hard surface areas		X	X			
Wipe clean desk tops, chairs, counter tops, door knobs		X	X			
Clean counter tops free of paperwork		X	X			
Empty all wastebaskets, and replace liners if wet, torn, or soiled		Х	X			
Refill soap, paper towel, toilet paper, and facial tissue dispensers as needed	Х	X	X			8
Clean all chalk/white boards as directed by teachers. Trays cleaned as needed		Х	Х			
Straighten all chairs		Х	Х			
Clean around light-switches, remove smudges and fingerprints from doors, doorframes, and all painted surfaces		Х		Х		
Detail vacuum under cubicles, desks, tables, and furniture that has space under it. Furniture will not be moved				X		
Dust all picture frames, woodwork and ledges under 10' in height				Х		
Spot clean all glass partitions in either furniture pieces or parts of the building		Х		Х		
Report all lights out, plumbing problems and other related maintenance items to management	Х	X		X		
Edge vacuum carpet on all walls of building, walls of cube furniture, around all filing cabinets, etc					Х	
Dust exposed areas of all book shelves					X	
Clean janitorial closets. (Janitorial closets will be maintained on the same level of cleanliness as office areas)					X	
Clean air supply and exhaust diffusers, vacuum adjacent soiled ceiling tiles						X
Dust all light fixtures						X

GYM	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Sweep floors as needed or directed.	Х	Х	X	•		
Empty all wastebaskets, and replace liners if wet, torn, or soiled.	X	X	X			
Report all lights out, plumbing problems and other related maintenance items to management	X	X	X			
Clean around light-switches, remove smudges and fingerprints from doors, doorframes, and all painted surfaces.		Х		X		
Clean glass doors, partitions, sidelights, etc		X		X		





"Honesty, Integrity, Accountability"

CUSTODIAL SCOPE OF SERVICES CONTINUED

Common Areas	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Vacuum all main carpeted areas		Х	Х			
Empty all wastebaskets, and replace liners if wet, torn, or soiled		Х	X			
Clean around light-switches, remove smudges and fingerprints from doors, doorframes, and all painted surfaces		Х	Х			
Throw away paper wrappers, paper cups, open food and beverages when cleaning areas	Х	Х	Х			
Dust and/or spot-clean all fronts of lockers on outside		Х		Х		
Edge vacuum carpet on all walls of building and under furniture		Х			Х	
Clean all glass doors, partitions, sidelights, etc	Х	Х			X	
Clean air supply and exhaust diffusers, vacuum adjacent soiled ceiling tiles		Х				Х
Dust all light fixtures		Х				X

Restrooms	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Sweep and mop floors with germicidal solution.		Х	X			
Clean inside and out and disinfect washbasins, toilets, urinals, and underside and tips of toilet seats using non-toxic		Х	Х			
Clean mirrors, shelves and counter tops.		Х	Х			
Clean and polish all bright work (wipe dry) to include all doors, push plates, kick plates, and door pulls.		Х	Х			
Empty and wipe clean all waste paper containers.	Х	Х	X			
Empty, clean, and disinfect sanitary napkin containers replacing liners daily.	Х	Х	X			
Refill soap, paper towel, toilet paper, and facial tissue dispensers, as needed.	Х	Х	Х		-	
Spot clean walls and toilet partitions	Х	Х	Х			
Pour water and disinfectant down restroom floor drain to insure that traps are full of water.		Х		X		
Wipe clean entrance doors, jambs, ledges and high areas		Х		X		
Clean all supply and exhaust vents.		Х				ANNUALLY
Dust all light fixtures. Wipe clean all tile walls and partitions, as needed		X			Х	
Refill air freshners		Х				AS REQUIRED

Break Rooms	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Clean Counter tops and adjacent wall area	Х	Х	Х			
Empty and wipe clean all waste paper containers & wipe outside	Х	Х	Х			
Refill paper towel dispensers	Х	Х	Х			
Clean sink	Х	Х	Х			
Spot clean fronts of all cabinets		Х	X			
Clean table tops and chair seats		Х	Х			
Clean around light-switches, remove smudges and fingerprints from doors, doorframes, and all painted surfaces.		Х		Х		
Detail vacuum under tables, and furniture that has space under it. Furniture will not be moved.				Х	_	
Dust all picture frames, woodwork and ledges under 10' in height.				X		
Spot clean all glass partitions in either furniture pieces or parts of the building				X		
Report all lights out, plumbing problems and other related maintenance items to management			X			
Clean all supply and exhaust vents - Bi-Annually		X				X
Wipe off outside of all fixtures and appliances	Х	Х			Х	
Clean and polish all bright work to include all door push plates, kick plates and door pulls.	X	X			X	
Clean inside & out of microwave	Х	X			X	



"Honesty, Integrity, Accountability"

CUSTODIAL SCOPE OF SERVICES CONTINUED

Building Entrances	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Police 10 ft. outside entrances and remove trash	Х	Х	Х			
Wipe clean entrance doorjambs ledges and high areas.	X	Х			Х	
Clean inside and outside of any sidelights (first floor only).	X	Х			X	
Clean inside and outside of glass doors - or as needed	X	Х Х			Х	
Cafeteria and Kitchen Areas	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Sween all floors		v	v		1.10 Helli	DOMIN TARRIBUM

1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
	Х	Х			
	Х	Х		-	
	Х		Х		
	Х		Х		
	1st Shift	1st Shift 2nd Shift X X X X X	V V	V V	v v

Hard Surfaced Floors	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Sweep all floors.	X	Х	Х		•	
Spot Mop all floors as needed.	Х	Х	Х			
Mop all floors		Х		Х		
Certain areas of the school and other special areas may require buffing nightly at the direction of O.P.S. Mgt	X	X	Х	-		
Buff all VCT floors up to 1 time per week	Х	X		х		
Striping and Waxing of VCT Floors				- 1		Annual

Carpet Surfaced Floors	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Spot clean as needed or directed	Х	Х		7.5		As Directed
Full carpet Cleaning and extraction						ANNUALLY

Window Cleaning	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
1 time per year all windows (Interior and Exterior) will be cleaned (first floor only)	Х	Х				ANNUALLY
Clean all entrance way windows	X		X			

Lunch set up and special events & scheduling	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Staffing will be determined via discussion and input from client facility managers. All Schedules and set up	Х	Х			_	
to be discussed with and approved through management staff. Day staff will also spot clean and stock	Х	Х			AS SCHED	ULED
building restrooms and other areas throughout the day as needed.						

Miscellaneous Duties	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
O.P.S. staff can at any time shovel snow from sidewalks, change interior lighting up to an agreed upon height, and	Х					
do minor yard work such as weed eating, trimming, or other duties as assigned by and approved by client	X					
and O.P.S. management staff. These duties must be part of their 40 hours per week and not overtime hours.	Х					
Should overtime occur due to the necessity of the projects assigned then it will be billed back to client at	Х					
overtime rates of fully burdened time and 1/2 hourly rate.	Х					
Some of these duties may also include cleaning up spills throughout the day, setting up class rooms, lending a	Х					
helping hand to others, etc	Х					





"Honesty, Integrity, Accountability"

GROUNDS SCOPE OF SERVICES

Grounds Duties	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annua
District provides grounds equipment and items required to maintain grounds				Westing	Monthly	ociii-rainua
Spring/Summer/Fall						
Mowing of entire grounds.	X			As Neede	d	
Weed Eating of entire grounds.	X			As Neede		
Trimming of trees, shrubs and bushes of grounds.	X			As Neede		
Spraying for weed control of grounds.	X			As Neede		
Trash collection of all outside trash cans around buildings and sports complexes.	X		X	120 110000	-u	
Collection of trash in bleachers, stadiums, parking lots, track, sports fields,						
and all complexes inside, around and outside of buildings and grounds	Х		X			
Mowing and maintenance of sports fields	X			As Neede	d	
Provide labor for fertilization and pest control of grounds and sports fields	X			As Neede		***
Perform general upkeep and maintenance of district equipment	X			As Neede		
				TAS MEEGE	u	

1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annual
Х	Х				Deini Tranquai
Х	Х				
-					
	1st Shift X X	1st Shift 2nd Shift X X X X	1st Shift 2nd Shift Daily X X X X X X X X X	X X As Neede	1st Shift 2nd Shift Daily Weekly Monthly X X As Needed X X As Needed





"Honesty, Integrity, Accountability"

MAINTENANCE SCOPE OF SERVICES

Maintenance Duties	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annu
District provides maintenance equipment and Vendor provides general maintenance.					1	
Spring/Summer/Fall						
Mowing of district grounds.	X					
Weed eating of district grounds.	X		1			
Trimming of trees, shrubs and bushes on district grounds. Spraying for weed control of district grounds.	X			SONALI REQUIRI		
Trash collection of all outside trash cans around buildings and sports complexes.	X					
Collection of trash in bleachers, stadiums, parking lots, track, sports fields, and complexes inside,	X	-				
around and outside of buildings and grounds	X					
and the decide of decides and product				<u> </u>	1	
Winter	1et Shift	2nd Shift	Daily	XX/a a labor] N. C 43.1.	<u> </u>
Snow Removal and treatment from all sidewalks and and exterior building access areas.	X	X	Dany	As Need		Semi-Annu
Snow Removal during school hours as needed.	X	X		As Need		
	- A			AS NEED	I	-
					1-	1
As Needed Daily Items	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annua
Change light bulbs throughout all facilities.	Х			As Need	ed	
Preventative maintenance of HVAC units as required.	Х		As Needed		ed	
Fix minor plumbing issues as the need arises.	X		As Needed		ed	
Fix minor electrical issues as the need arises.	X			As Needed		
Light maintenance work such as hanging shelves, fixing desks, painting, repairing doors, locks, flooring, hanging	X			As Needed		
pictures, assisting teachers, tile work, etc(light carpentry) Ballast changing.	X			As Needed		
Distribution of mail, supplies, and other items that are needed for daily operations	X			As Needed		
bistilibation of mail, supplies, and other items that are needed for daily operations	Х			As Needed		
After Hour Availability Monday-Sunday	1.4 CLIA	2nd Shift	D-11			
On call for after hour plumbing emergencies	1st Snin	2nd Shift	Daily	Weekly	Monthly	Semi-Annua
On call for break-in or after hour emergencies				4 - 27 - 1		
On call for any other type of building emergencies	+			As Need	e a	
	-					
Special Events Monday-Sunday	1 -					
Set up and tear down of equipment needed for special events such as choir, band, basketball games, volleyball	+			A - NT - 1		
games, programs, football games, dances, parent teacher conferences, debates, wrestling, community activities,	-			As Need	a	
class rooms, etc.						
	-					
Excluded Services	1st Shift	2nd Shift	Daily	Weekly	Monthly	Semi-Annua
Disposal of Biohazard waste.				N/A		
Paper product supplies, including trash bags, urinal blocks, hand soap, and deodorizer, if specifically excluded.				N/A		
Termite/Pest treatment.				N/A		
Major construction, unless contracted through affiliate company.				N/A		
Major HVAC except as stated in contract and agreed upon by client and company				N/A		
Major electrical and major plumbing that requires a license, unless contracted				N/A		
Min Mark R 1 Va	g 300					
	, , , , , , , , , , , , , , , , , , , 					S
Exceptions to Exclusions:						
D.P.S. staff, at any time, can provide other duties as assigned by and approved by client and O.P.S. Mgt.						
staff. These duties must be part of their 40 hours per week and not incur overtime hours. Should overtime						
occur due to the necessity of the projects assigned then it will be billed back at overtime rates of time and 1/2	1					





JOB CARD Office Cleaning



Periodic Tasks:		Product	Application Method					
Remove mineral de	posits from sinks / drin	king fountains (Allow	dwell time)	Enzymatic	White Hand Pad			
Clean glass	Brite Glass	Trigger Sprayer						
Clean whiteboards				Brite Glass	Trigger Sprayer			
Clean desks / tables	s / chairs			Quat 64	Trigger Sprayer			
Clean air vents				Quat 64	Trigger Sprayer			
Clean vertical and h	norizontal surfaces	Quat 64	Trigger Sprayer					
Apply carpet prespr	ay			Enzymatic	Pump Up Sprayer			
Extract carpet				Enzymatic	Carpet Extractor			
Equipment Needed			Precautions:		一,其中自己在1962年中198			
Housekeeping Cart	Std. Spd. Floor Machine	Carpet Extractor	Always wear appr	opriate Personal I	Protective Equipment.			
Cleaning Cloths/Wipers	Carpet Bonnets	Appropriate PPE	Display wet floor	Display wet floor signs during damp mopping until floor dries.				
White Hand Pads	Burnisher	"Wet Floor" Signs	Never place hand	Never place hand inside of trash container; pull liner out, then t				
Mop Bucket/Wringer Putty Knife Allow disinfectant/cleaner to dwell on surfaces for 1								



Trash Can Liners

Vacuum Cleaner

Extension Duster

Cleaning Cloths/Wipers

Damp Mop

Dust Mop

Lobby Broom

Lobby Dust Pan

Mop Bucket/Wringer

JOB CARD Office Cleaning



Allow heavy duty restroom cleaners to dwell on surfaces for 10-1

Display wet floor signs during damp mopping until floor dries.

Allow disinfectant/cleaner to dwell on surfaces for 10 minutes

Never place hand inside of trash container; pull liner out, then tie.

Allow heavy duty restroom cleaners to dwell on surfaces for 10-15

THE RESIDENCE OF THE PARTY OF T	And the second s			21,212,214,000,000	三、新山村、西山村、西山村、西山村、西山村、西山村、
Daily Tasks: 🚙				Product	Application Method
Empty trash / spr	ay interior / spot cle	an exterior / reline		Quat 64	Trigger Sprayer
Dust using dustin	g cloth / extension o	luster (1/4 of area)			
Disinfect sinks an	d counters / drinking	g fountain(s) - (10 min.	dwell time)	Quat 64	Trigger Sprayer
Check and refill d	ispensers / disinfect	dispensers		Quat 64	Trigger Sprayer
Erase chalkboards	s / whiteboards, as i	nstructed / clean tray			
Clean vertical and	horizontal surfaces		-	Quat 64	Trigger Sprayer
Clean glass				Brite Glass	Trigger Sprayer
Straighten desks	/ tables / chairs				
Clean desks / tabl	les / chairs			Quat 64	Trigger Sprayer
Clean carpet and	walk-off mats			Enzymatic	Trigger Sprayer
Vacuum carpet an	nd walk-off mats				
Dust mop and dar	np mop floor			AP7	Mop Bucket
Equipment Need	ed:	- Land Company	Precautio	ns:	
Housekeeping Cart	Damp Mop	Putty Knife	Manager of the Control of the Contro	the law of the control of the law of the	Protective Equipment.

Hand Soap

Paper Towels

Appropriate PPE

"Wet Floor" Signs





JOB CARD

Classroom Cleaning



Product	Application Method
The second secon	White Hand Pad
	Trigger Sprayer
	Trigger Sprayer
	Trigger Sprayer
	mgger oprayer
Enzymatic	Pump Up Sprayer
Enzymatic	Carpet Extractor
	Product Enzymatic Enzymatic Brite Glass Brite Glass Enzymatic Enzymatic

Equipment Needed			Precautions:
Housekeeping Cart Cleaning Cloths/Wipers Mop Bucket/Wringer Damp Mop Std. Spd. Floor Machine	Carpet Bonnets Burnisher Carpet Extractor Putty Knife	Appropriate PPE "Wet Floor" Signs	Always wear appropriate Personal Protective Equipment. Display wet floor signs during damp mopping until floor dries. Never place hand inside of trash container; pull liner out, then tie. Allow disinfectant/cleaner to dwell on surfaces for 10 minutes Allow heavy duty restroom cleaners to dwell on surfaces for 10-15



JOB CARD

Classroom Cleaning



Product	Application Method
Quat 64	Trigger Sprayer

Quat 64	Trigger Sprayer
Quat 64	Trigger Sprayer
Brite Glass	Trigger Sprayer
Quat 64	Trigger Sprayer
Brite Glass	Trigger Sprayer
	Martin Committee
Quat 64	Trigger Sprayer
Quat 64	Trigger Sprayer
AP7	Mop Bucket
	Quat 64 Quat 64 Quat 64 Brite Glass Quat 64 Brite Glass Quat 64 Quat 64 Quat 64

Past mob and damp mob noor		and the second section of the second second	AP7	Mop Bucket	
Equipment Needed:		Precautions:			
Housekeeping Cart	Damp Mop	Putty Knife	Always wear appro	opriate Personal	Protective Equipment.
Dust Mop	Extension Duster	Hand Soap	Display wet floor s	signs during dam	p mopping until floor dries.
Lobby Broom	Vacuum Cleaner	Paper Towels	Never place hand	inside of trash co	ontainer; pull liner out, then tie
Lobby Dust Pan	Trash Can Liners	Appropriate PPE	Allow disinfectant/	cleaner to dwell	on surfaces for 10 minutes
Mop Bucket/Wringer	Cleaning Cloths/Wipers	"Wet Floor" Signs	Allow heavy duty	restroom cleaner	s to dwell on surfaces for 10-1
					4





JOB CARD Restroom Cleaning

THE RESERVE OF THE PARTY OF THE



Product	Application Method	
Enzymatic	Bowl Brush / Swab	
Enzymatic	Bowl Brush / Swab	
Enzymatic	White Hand Pad	
Enzymatic	Bowl Brush / Swab	
Enzymatic	Bowl Brush / Swab	
Enzymatic	White Hand Pad	
Quat 64	Trigger Sprayer	
Quat 64	Trigger Sprayer	
Brite Glass	Trigger Sprayer	
Quat 64	Mop Bucket	
	. Top Booket	
	Enzymatic Enzymatic Enzymatic Enzymatic Enzymatic Enzymatic Quat 64 Quat 64 Brite Glass	

Equipment Needed: Precautions:

Housekeeping Cart

Cleaning Cloths/Wipers

Wet/Dry Vac

Push Broom

White Hand Pads

Appropriate PPE

Lobby Broom/Dust Pan

Bowl Brush / Swab Std. Spd. Floor Machine "Wet Floor" Signs

Mop Bucket/Wringer Dedicated Damp Mop

Burnisher

Always wear appropriate Personal Protective Equipment.
Display wet floor signs during damp mopping until floor dries.
Never place hand inside of trash container; pull liner out, then tie.
Allow disinfectant/cleaner to dwell on surfaces for 10 minutes
Allow heavy duty restroom cleaners to dwell on surfaces for 10-15 r



JOB CARD

Restroom Cleaning



Daily Tasks:	Product	Application Method
Sweep floor. Pick up with lobby broom and dust pan		
Empty trash containers / spray interior / spot clean exterior / reline	Quat 64	Trigger Sprayer
Check / empty / disinfect and reline sanitary receptacles	Quat 64	Trigger Sprayer
Dust using dusting cloth / extension duster		
Check and refill restroom dispensers / disinfect dispensers	Quat 64	Trigger Sprayer
Spray all fixtures/dispensers with disinfectant (10 min. dwell time)	Quat 64	Trigger Sprayer
Spot disinfect walls / partitions / vertical and horizontal surfaces	Quat 64	Trigger Sprayer
Scrub urinals and toilets with bowl swab or brush-flush for clean water	Quat 64	Trigger Sprayer
Rinse the bowl swab, the toilet seat, and the rest of the fixture		
Damp wipe sinks / counters and outsides of all fixtures / dispensers	Quat 64	Trigger Sprayer
Clean mirrors	Brite Glass	Trigger Sprayer
Damp mop floor with disinfectant	Quat 64	Mop Bucket

Clean mirrors		The state of the s		Brite Glass	Trigger Sprayer
Damp mop floor with disinfectant			Quat 64	Mop Bucket	
			Prec	Precautions:	
Housekeeping Cart	Mop Bucket/Wringer	Paper Towels Always wear appropriate Personal Protectiv			Personal Protective Equipment.
Push Broom	Dedicated Damp Mop	Toilet Tissue Display wet floor signs during dam		ing damp mopping until floor dries.	
Lobby Broom	Trash Can Liners	Appropriate PPE Neve		place hand inside of	trash container; pull liner out, then t
Lobby Dust Pan Cleaning Cloths/Wipers "Wet Floor" Signs		Allow disinfectant/cleaner to dwell on surfaces for 10 minute			
Extension Duster	Hand Soap		Allow	heavy duty restroom	cleaners to dwell on surfaces for 10-





JOB CARD

Hallway Cleaning



	A Manada A Transport Andrews		
Periodic Tasks:	Product	Application Method	
Remove mineral deposits from drinking fountains (Allow dwell time)	Enzymatic	White Hand Pad	
Clean glass	Brite Glass	Trigger Sprayer	
Clean air vents	Enzymatic	Trigger Sprayer	
Clean vertical and horizontal surfaces	Enzymatic	Trigger Sprayer	
Extract upholstery	Enzymatic	Carpet Extractor	
Wipe walls	Enzymatic	Trigger Sprayer	
Burnish floor			
Extract carpet	Enzymatic	Carpet Extractor	
		*	

Equipment Needed:

Housekeeping Cart

White Hand Pads

Std. Spd. Floor Machine

Appropriate PPE
"Wet Floor" Signs

Mop Bucket/Wringer Damp Mop

Carpet Bonnets

Putty Knife Cleaning Cloths/Wipers Burnisher

Carpet Extractor

Precautions:

Always wear appropriate Personal Protective Equipment.

Display wet floor signs during damp mopping until floor dries.

Never place hand inside of trash container; pull liner out, then tie.

Allow disinfectant/cleaner to dwell on surfaces for 10 minutes

Allow heavy duty restroom cleaners to dwell on surfaces for 10-15



JOB CARD

Hallway Cleaning



Daily Tasks:	Product	Application Method
Empty trash containers / spray interior / spot clean exterior / reline	Quat 64	Trigger Sprayer
Dust using dusting cloth / extension duster		
Disinfect drinking fountain(s) - (10 min. dwell time)	Quat 64	Trigger Sprayer
Clean vertical and horizontal surfaces	Quat 64	Trigger Sprayer
Straighten tables and chairs	,	
Clean tables and chairs	Quat 64	Trigger Sprayer
Clean glass	Quat 64	Trigger Sprayer
Clean carpet and walk-off mats	Enzymatic	Trigger Sprayer
Vacuum carpet and walk-off mats		
Dust mop floor		
Damp mop or autoscrub floor	AP7	Mop Bucket
	1	

Equipment Needed:			Precautions:		
Housekeeping Cart	Damp Mop	Putty Knife	Always wear appropriate Personal Protective Equipment.		
Dust Mop	Autoscrubber	Appropriate PPE	Display wet floor signs during damp mopping until floor dries.		
Lobby Broom	Vacuum	"Wet Floor" Signs	Never place hand inside of trash container; pull liner out, then tie.		
Lobby Dust Pan	Cleaning Cloths/Wipers		Allow disinfectant/cleaner to dwell on surfaces for 10 minutes		
Mop Bucket/Wringer	Extension Duster		Allow heavy duty restroom cleaners to dwell on surfaces for 10-15		
l .					





JOB CARD

Cafeteria Cleaning



THE RESERVE OF THE PROPERTY OF	295	《新闻》	
Periodic Tasks:	Product	Application Method	
Remove mineral deposits from sinks / drinking fountains (Allow dwell time)	Enzymatic	White Hand Pad	
Clean glass	Brite Glass	Trigger Sprayer	
Clean air vents	Enzymatic	Trigger Sprayer	
Wipe walls	Enzymatic	Trigger Sprayer	
Wipe down equipment	Enzymatic	Trigger Sprayer	
Extract carpet	Enzymatic	Carpet Extractor	

Equipment Needed:

Housekeeping Cart Cleaning Cloths/Wipers Std. Spd. Floor Machine Carpet Bonnets

Appropriate PPE "Wet Floor" Signs

Mop Bucket/Wringer

Carpet Extractor

Damp Mop

Putty Knife

Burnisher

Precautions:

Always wear appropriate Personal Protective Equipment. Display wet floor signs during damp mopping until floor dries. Never place hand inside of trash container; pull liner out, then tie. Allow disinfectant/cleaner to dwell on surfaces for 10 minutes Allow heavy duty restroom cleaners to dwell on surfaces for 10-15 min.



JOB CARD

Cafeteria Cleaning



Daily Tasks:	Product	Application Method
Empty large trash receptacles/spray interior/spot clean exterior/reline	Quat 64	Trigger Sprayer
Clean and tear down tables and chairs or cafeteria tables	Quat 64	Trigger Sprayer
Vacuum carpeted areas and walk-off mats		
Dust mop or sweep floor		
Disinfect sinks and counters / drinking fountain(s) - (10 min. dwell time)	Quat 64	Trigger Sprayer
Check and refill dispensers / disinfect dispensers	Quat 64	Trigger Sprayer
Dust using dusting cloth / extension duster. Spot clean glass	Brite Glass	Trigger Sprayer
Clean vertical and horizontal surfaces	Quat 64	Trigger Sprayer
Clean door handle and door facing on both sides	Quat 64	Trigger Sprayer
Clean carpet and walk-off mats	Enzymatic	Trigger Sprayer
Damp mop or autoscrub floor	AP7	Mop Bucket/Autoscrubber
Set up tables and chairs or cafeteria tables		

Equipment Needed:

Housekeeping Cart Dust Mop / Push Broom Lobby Broom & Dust Pan

Mop Bucket/Wringer

Vacuum Cleaner Extension Duster Trash Can Liners

Cleaning Cloths/Wipers

Hand Soap

Paper Towels

Damp Mop or Autoscrubber Putty Knife

Appropriate PPE "Wet Floor" Signs

Precautions:

Always wear appropriate Personal Protective Equipment. Display wet floor signs during damp mopping until floor dries. Never place hand inside of trash container; pull liner out, then tie. Allow disinfectant/cleaner to dwell on surfaces for 10 minutes Allow heavy duty restroom cleaners to dwell on surfaces for 10-15

Total	Aux. Services			SHH			NS			HES	Central Office	Building		R-III D	E)
						Area ?	Hall?	Area ?	Area ?	Area?	All	Section		istrict Flooring	
										2003 Tile		lled	Year	Maintenance S	
										Tile	Carpet	Туре		chedule	
												Footage	Square		
0													Warranty		,
\$0												2019-2020			
												2020-2021			
												2021-2022			
												2022-2023			
												2023-2024			
												2024-2025			

Develop W/OPS

1		
	L	1
_	L	()


	Aux. Services			HHS		Area ?	HMS Hall?	Area ?	Area ?	HES Area?	Central Office All	Building Section II	4	R-III District Flooring Mair	E)
										2003 Tile	ດ	Installed Ty	Year	ntenance Sch	
										le	Carpet	Туре		nedule	·
0												()	Square		
												(Years)	Warranty		
												2025-2026			
												2026-2027			
												2027-2028			
												2028-2029			
												2029-2030			
												2030-2031			




Holden Elementary School Building Map 2019-20


Revised 7/25/2019


1903 S. Market Holden, MO 64040



M# = Bu	uilding Exit	Н	olden	Midd	le Sch	ool M	lap 🐧 =Storm She	elter Area
Room 204	Room 301	Room 302	Room 305	Room 306	M3 Exit	M Kitchen	Art Room	Resource Room
Roor		6th S	itreet	Blue Parkway	Southwest Exit			
Room 203 Room 202 Room 201	7th Street	N CO	Computer Lab Modia Contary	Boys' Restroom Office Store Store Carbol Store Store Data Room Room 304	(Commons)	Fagles' Landing	Gym	Boys' Girls' Locker Room Locker Room
Exit Est		8th S	treet				Talon Ave.	M8 Northwest Exit
Room 105	Room 104	Room 103	Room 102	Room 101	Foyer M1	Office	Music Room	Student Support Center







HOLDEN R-III SAFETY INSPECTIONS

- 1. Asbestos Annual OPS
- 2. Asbestos Every 3 Years Terracon
- 3. Basketball Goals Annual Carroll Seating Company
- 4. Bleachers (Indoor and Outdoor) Annual Carroll Seating Company
- 5. Boiler/Hot Water Heater Inspections Annual- Hartford Boiler
- 6. Bus Annual (Scheduled) Dept. of Transportation/MO Highway Patrol
- 7. Bus Annual (Unscheduled) Dept. of Transportation/MO Highway Patrol
- 8. Bus Bumper-to-Bumper Annual (Summer) Apple Mechanic
- 9. Bus Mechanical Monthly Apple Mechanic
- 10. Bus Pre/Post Trip Safety Checklists Daily Drivers
- 11. Classroom Signage Annual Principals and Teachers
- 12. Defibrillator (AED) Biannual Nursing Staff
- 13. District-wide Safety Inspection Annual Walkthrough M.U.S.I.C.
- 14. Elevator Annual Elevator Safety Services
- 15. Eye Wash Stations Annual OPS/M.U.S.I.C.
- 16. Fire Alarm Systems Annual Nightwatch Security
- 17. Fire Extinguishers Annual Red Force
- 18. Fire Suppression Systems (Kitchens, FACS) Annual Red Force
- 19. Fume Hoods (Kitchens, FACS, Science) Biannual Red Force
- 20. Grease Traps Biannual Honeywagon
- 21. Kitchen/Food 2/3 per year Health Department
- 22. Kiln Annual Red Force
- 23. Pest Control (Kitchens) Monthly Assured Pest Control
- 24. Playground Biannual OPS (Daily Teaching Staff)
- 25. Roof (Middle School) Biannual OPS
- 26. Safety Kit for Classrooms Annual Principals and Teachers
- 27. Sewer Backflow Annual Fleming Reported to O&M/State
- 28. Storm Shelters Annual OPS & Staying Home Corporation

HOLDEN SCHOOL DISTRICT PRIORITES

 	161-4	1-41

SCHOOL	SCOPE	NOTES	1-2 YEARS	BUDGET ESTIMATE 5-6 YEARS		7
1 DISTRICT-WIDE	ROOFING REPLACEMENT	MOLES	1-2 YEARS	5-6 YEARS	10-12 YEARS	Actua
I DISTRICT-WIDE			A			4
	- ELEMENTARY TAR ROOF REPLACEMENT WITH NEW EPDM ROOF	1	\$ 345,000.00			\$
	- HIGH SCHOOL GRAVEL ROOF REPLACEMENT		\$ 66,000.00			4
	-HIGH SCHOOL EPDM REPLACEMENT WITH WET INSULATION REPLACED - OLDER ROOF (EXCLUDES GYM)		\$ 295,064.00			1
			\$ 706,064.00	\$ -	\$ -	
2 DISTRICT-WIDE	ASPHALT REPLACEMENT					1
	- ELEMENTARY/INTERMEDIATE SCHOOL	2				1
Loine	- AREA A			\$ 68,000.00		1
Carolia (Trut	- AREA B			\$ 45,200.00		1
	- AREA C			\$ 97,000.00		1
	-MIDDLE SCHOOL	2		3 37,000.00		-
	- AREA D			\$ 159,400.00		-
				202,100,00		4
1 11 1 20	- AREA E			\$ 26,000.00		-1
Sivis bigner	- AREA F			\$ 79,400.00		1
	- AREA G			\$ 98,000.00]
	- HIGH SCHOOL	2				_
1 19.5	- AREA H			\$ 391,200.00		1
	- AREA J			\$ 114,600.00		1
	- AREA K			\$ 111,200.00		1
Fire Lane	- AREA L			\$ 165,100.00		1
1.4.7	- AREA M					1
		L	^	\$ 30,000.00		-
- Investor tour			\$ -	\$ 1,385,100.00	- 4	4
3 DISTRICT-WIDE	HVAC MODERNIZATION	,				1
	-ELEMENTARY/INTERMEDIATE SCHOOL (BIG BERTHA ONLY) ROOFTOP HVAC REPLACEMENT	3		\$ 927,875.00		\$
	- MIDDLE SCHOOL HVAC ZONING			\$ 325,000.00		
	- EXHAUST FAN REPLACEMENT (ELEMENTARY AND HIGH SCHOOL)			\$ 125,000.00		1
	-HIGH SCHOOL ROOFTOP HVAC REPLACEMENT WITH CONDENSATE DRAIN SYSTEM			\$ 585,000.00		1
			\$ -	\$ 1,962,875.00	ė .	1
4 DISTRICT-WIDE	LED LIGHTING RETROFIT		·	2,302,073.00		1
- D.S.IMICI-TRIDE			A 100 000			4
 	- ELEMENTARY/INTERMEDIATE LED FIXTURE REPLACEMENT	4				-
+	- MIDDLE SCHOOL LED FIXTURE REPLACEMENT	4				4
	- HIGH SCHOOL LED FIXTURE REPLACEMENT	4				1
	DIMMING FOR ELEMENTARY, MIDDLE, AND HIGH SCHOOL		\$ 128,315.00			
			\$ 690,175.00	\$ -	\$ -	s
5 DISTRICT-WIDE	SECURITY ENTRANCE MODIFICATIONS					1
						1
	ELEMENTA DY MATERIA DE PROCESTE CONTROL AND DISCOURT AND DISCOURT AND DESCRIPTION OF THE PROCESS AND DESCRIPTION OF THE PROC		£ 20,000,00		535	1
 	- ELEMENTARY/INTERMEDIATE SCHOOL (RELOCATE STOREFRONT, ADD BULLETPROOF PASS THROUGH WINDOW, MODIFY FLOORING)		\$ 20,000.00			1
1	- MIDDLE SCHOOL (REWORK MASONRY WALLS, ADD BULLET RESISTANT WINDOW, ADD VISION GLASS INTO COMMONS, EXCLUDES MOVING				l	1
ļ	INTERCOM PANEL)		\$ 53,000.00			1
	- HIGH SCHOOL (REPLACE STOREFRONT WITH LAMINATED GLASS, ADD BULLETPROOF PASS THROUGH WINDOW)		\$ 25,000.00			1
1	- ADD BULLETPROOF FILM TO ALL SECONDARY ENTRANCES					1
			\$ 98,000.00	\$ -	\$ -	1
6 ELEMENTARY/INTERMEDIATE	PLAYGROUND RELOCATION AND REPAIRS (NEW EQUIPMENT EXCLUDED)	6				1
						_
						1 6
	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER)		\$ 15,000.00			\$
7 ELEMENTARY/INTERMEDIATE	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER)		\$ 15,000.00			\$:0.1
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS)		\$ 15,000.00 \$ 42,000.00			: -Ada
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS)		\$ 15,000.00 \$ 42,000.00 \$ 168,000.00			-Ade
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS)		\$ 15,000.00 \$ 42,000.00			; —Ada
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS)		\$ 15,000.00 \$ 42,000.00 \$ 168,000.00	-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		s -Add
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS		\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00			: -Adc
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS)		\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00			-Add
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR		\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00			-Adc
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERNITION REPAIR*	7	\$ 15,000.00 \$ 42,000.00 \$ 169,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ -			; -Add
7 ELEMENTARY/INTERMEDIATE B ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5,000.00			: Adc
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRARGE DOOR TO TRASH RECEPTACLE AREA*	7	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5,000.00 \$ -			: Adc
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 6 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 8 MIDDLE SCHOOL 8 MIDDLE SCHOOL	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERNITION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA*	7	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5,000.00 \$ - \$ 5,000.00			; —Ack
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 (LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING)	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ - \$ 5,000.00 \$ - \$ 2,000.00			; /Aclc
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 5 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF HLOOR SANDING AND BEPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00			; -Ada
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 11 MIDDLE SCHOOL 12 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO JIST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRADES DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ - \$ 5,000.00 \$ - \$ 2,000.00			
7 ELEMENTARY/INTERMEDIATE B ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF HLOOR SANDING AND BEPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00			: -Adc
7 ELEMENTARY/INTERMEDIATE B ELEMENTARY/INTERMEDIATE J ELEMENTARY/INTERMEDIATE LEMENTARY/INTERMEDIATE LEMENTARY/INTERMEDIATE B MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO JIST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRADES DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 6 MIDDLE SCHOOL 8 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF HLOOR SANDING AND BEPAIR BUS LOADING ARROA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRANGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) REPONITY GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION FERS AT FRONT OF BUILDING	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 25,000.00 \$ -5 \$ 5,000.00 \$ -2,000.00 \$ -2,000.00 \$ 2,000.00 \$ 15,000.00 \$ 15,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 11 MIDDLE SCHOOL 12 MIDDLE SCHOOL 12 MIDDLE SCHOOL 12 MIDDLE SCHOOL 13 MIDDLE SCHOOL 14 MIDDLE SCHOOL 15 MIDDLE SCHOOL 16 MIDDLE SCHOOL 17 MIDDLE SCHOOL 17 MIDDLE SCHOOL 18 MIDDLE SCHOOL 18 MIDDLE SCHOOL 18 MIDDLE SCHOOL 18 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 (LOCATIONS ADD ROOF AND GRADED OOR TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,950.00 \$ 31,950.00 \$ 5,000.00 \$ 5,000.00 \$ 5,000.00 \$ 15,000.00 \$ 5,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 2 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDLE SCHOOL 4 MIDDLE SCHOOL 4 MIDLE SCHOOL 8 MIDDLE SCHOOL 1 MIDLE SCHOOL 1 MIDLE SCHOOL 4 MIGH SCHOOL 1 HIGH SCHOOL	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRANGE ODOR TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FONT OF BUILDING RET, WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS	7	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 80,000.00 \$ 31,950.00 \$ 7,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 2 MIDDLE SCHOOL 10 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL	REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND BEPAIR BUS LOADING ARD BEPAIR BUS LOADING ARD BEPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) REPONIT GYM WALLS (NOT INCLUDING SEPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION HERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 25,000.00 \$ -5 \$ 5,000.00 \$ -7,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 17,000.00 \$ 1,7,000.00 \$ 1,7,000.00 \$ 11,475.00 \$ 11,475.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 2 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIGH SCHOOL 4 MIGH SCHOOL 6 HIGH SCHOOL 7 MIGH SCHOOL 6 HIGH SCHOOL 6 HIGH SCHOOL 7 MIGH SCHOOL 6 HIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SUS LOADING AREA - WATER DETENTION REPAIR* SUS LOADING AREA - WATER DETENTION REPAIR* ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK LEVEL FARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF)	7	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,950.00 \$ 2,000.00 \$ 2,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 115,000.00 \$ 15,000.00 \$ 15,000.00 \$ 11,475.00 \$ 11,400.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 11 MIDDLE SCHOOL 12 MIDDLE SCHOOL 13 MIDDLE SCHOOL 14 MIDDLE SCHOOL 14 MIDDLE SCHOOL 15 MIGH SCHOOL 16 HIGH SCHOOL 16 HIGH SCHOOL 17 HIGH SCHOOL 18 HIGH SCHOOL 18 HIGH SCHOOL 18 HIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND BEPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRANGE DODR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM HINCUIDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING REPLACE AGP/ETW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CHILM GRALD HORSEN HE LOCKER FADS IN LOBBY (ROUGHLY 4,000 SF) PAINT CHILM GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF)	77	\$ 15,000,00 \$ 42,000,00 \$ 166,000,00 \$ 80,000,00 \$ 25,000,00 \$ 31,950,00 \$ 7,000,00 \$ 15,000,00 \$ 15,000,00 \$ 15,000,00 \$ 15,000,00 \$ 15,000,00 \$ 11,475,00 \$ 11,475,00 \$ 11,000,00 \$ 11,000,00 \$ 11,000,00 \$ 11,000,00 \$ 11,000,00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIGH SCHOOL 10 MIGH SCHOOL 10 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 (LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING FLOOR SIDE OF EXISTING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK LEVEL PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF)	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,4			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 4 MIDDLE SCHOOL 4 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 10 MIGH SCHOOL 10 MIGH SCHOOL 11 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PRESS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT GYM WALLS (NOT INCLUDING CEILING) REPURACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT GYM WALLS (NOT INCLUDING CEILING) REPURBISH / REPLACE DOL LOCKERS DOWN BLUE BLVD (NEED # OF LOCKERS)	77	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,4			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 4 MIDDLE SCHOOL 4 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 10 MIGH SCHOOL 10 MIGH SCHOOL 11 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 (LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING FLOOR SIDE OF EXISTING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK LEVEL PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOSBY (ROUGHLY 4,000 SF)	77 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,4			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 5 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL 11 MIGH SCHOOL 11 MIGH SCHOOL 12 MIGH SCHOOL 13 MIGH SCHOOL 14 MIGH SCHOOL 15 MIGH SCHOOL 16 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF HLOOR SANDING AND BEPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRANGE DODR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING REPURSE AT FRONT OF BUILDING CEILING) REPURSES AT FRONT OF BUILDING (NEED # OF LOCKERS) REPURSES AT REPLACE DOLD KEERS FOOM IN LOBBY (ROUGHLY 4,000 SF) PAINT CYM WALLS (NOT INCLUDING CEILING) REPURSES AT FRENCE OF THE PARKING LOT PAINT CYM WALLS (NOT INCLUDING CEILING) REPURSES AT FRENCE OF THE PARKING LOT SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STOFFRONT OUTSISE OF ROOM 151. AND ADD DOOR INTO 151)	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 25,000.00 \$ 31,550.00 \$ 5 5,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,475.00 \$ 14,000.00 \$ 14,000.00 \$ 45,000.00 \$ 45,000.00 \$ 5 5 5,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 HIGH SCHOOL 5 HIGH SCHOOL 5 HIGH SCHOOL 6 HIGH SCHOOL 7 HIGH SCHOOL 9 HIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERTION REPAIR* BUS LOADING AREA - WATER DETERTION REPAIR* SUSEWALK LEVEUNGS AT 2 LOCATIONS ADD ROOF AND GRAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK LEVER PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTBANCE AT MENTAL HEALTH FACILITY (ADD STOREFRONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOPT OO LD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP)	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 5 31,950.00 \$ 5 2,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 11,475.00 \$ 14,000.00 \$ 14,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR FRAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT GETING GRID AND REPLACE PAD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GETING GRID AND REPLACE PAD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GETING GRID AND REPLACE PAD SIN LOBBY (ROUGHLY 4,000 SF) SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STOREFRONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ADT ROOM TO MAIN HALLWAY (RELOCATE KINS/EXHAUST, ADD EXHAUST FOR NEW PLTW ROOM)	77 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	\$ 15,000,00 \$ 42,000,00 \$ 166,000,00 \$ 25,000,00 \$ 31,950,00 \$ 7,000,00 \$ 15,000,00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDLE SCHOOL 10 MIDLE SCHOOL 10 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY COARIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVEUING AT 2 (LOCATIONS ADD ROOF AND GRADED ON TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REPUBBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REPUBBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REPUBBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK LEV WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT GYM WALLS (NOT INCLUDING CEILING) REFURBISH / REPLACE OLD LOCKERS DOWN BLUE BLVD (NEED # OF LOCKERS) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTRANCE AT MENTAL HEALTH FACILITY ALDOT STOREFRONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ART ROOM TO MAIN HALLWAY (RELOCATE KILNS/EXHAUST, ADD EXHAUST FOR NEW PLTW ROOM)	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,4			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDLE SCHOOL 3 HIGH SCHOOL 4 HIGH SCHOOL 5 HIGH SCHOOL 1 HIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* BUS LOADING AREA - WATER DETERMITION REPAIR* SUSDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION MERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADDS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STOREFRONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION ARE REMOVE BE RESENTLY IN COFFEE SHOP) MOVE CART ROOM TO MAIN HALLWAY (RELOCATE KILLS/EXHAUST, ADD EXHAUST FOR NEW PLTW ROOM) ADD ELECTRICAL RECEPTACLES NEW PANELS FOR CLASSROOMS DOWN BLUE BLUD ADD ELECTRICAL RECEPTACLES NEW PANELS FOR CLASSROOMS DOWN BLUE BLUD ADD ELECTRICAL RECEPTACLES NEW	77 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5 7,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 10			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL LUPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* BUS LOADING AREA - WATER DETERMITION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN 80YS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REFURBISH / REPLACE OLD LOCKERS DOWN BLUE BLVD (NEED # OF LOCKERS) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTERANCE AT MENTAL HEALTH FACILITY (ADD STORFERONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ART ROOM TO MAIN HALLWAY (RELOCATE KLINS/SEMALUST, ADD EXHALDST FOR NEW PLTW ROOM) ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD WINDOW REFIECTIVE TITY TO CAFETER WANDOWS	77 8 8 8 10 10 9 9	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 15,000.00 \$ 31,550.00 \$ 5 5,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,475.00 \$ 14,000.00 \$ 45,000.00 \$ 45,000.00 \$ 3 15,000.00 \$ 15,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDDLE SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* BUS LOADING AREA - WATER DETERMITION REPAIR* SUSDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION MERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADDS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) PAINT GET GRID AND REPLACE PADD SIN LOBBY (ROUGHLY 4,000 SF) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STOREFRONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION ARE REMOVE BE RESENTLY IN COFFEE SHOP) MOVE CART ROOM TO MAIN HALLWAY (RELOCATE KILLS/EXHAUST, ADD EXHAUST FOR NEW PLTW ROOM) ADD ELECTRICAL RECEPTACLES NEW PANELS FOR CLASSROOMS DOWN BLUE BLUD ADD ELECTRICAL RECEPTACLES NEW PANELS FOR CLASSROOMS DOWN BLUE BLUD ADD ELECTRICAL RECEPTACLES NEW	77 8 8 8 10 10 9 9	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 5 7,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 10			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 0 ELEMENTARY/INTERMEDIATE 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 2 MIDDLE SCHOOL 3 MIDDLE SCHOOL 4 MIGH SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIGH SCHOOL 9 MIDDLE SCHOOL 1 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERTION REPAIR* BUS LOADING AREA - WATER DETERTION REPAIR* SUSEWALK LEVEUNG AT 2 LOCATIONS ADD ROOF AND GRARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING NEED REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING PIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT GYM WALLS (NOT INCLUDING CEILING) REPURBISH / PREPLACE OLD CHORSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ART ROOM TO MAIN HALLWAY (RELOCATE KLINS/CKHAUST, ADD EXHAUST FOR NEW PLTW ROOM) ADD LICETTICAL RECEPTACLES IN PAIR (RICHOUSE STAGE)	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 25,000.00 \$ 3,1,950.00 \$ 15,000.00 \$ 15			s
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 3 BLEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 M	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYMF FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* BUS LOADING AREA - WATER DETENTION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR FRAINT GYMWALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION DHESS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING ROIL AND REPAIR LOBBY (ROUGHLY 4,000 SF) PAINT CEILING ROIL AND REPAIR LOBBY (ROUGHLY 4,000 SF) PAINT CEILING ROIL AND REPAIR LOBBY (ROUGHLY 4,000 SF) PAINT CEILING ROIL AND REPAIR LOBBY (ROUGHLY 4,000 SF) PAINT CEILING ROIL AND REPAIR LOBBY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STORERONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE CAFFEE SHOP TO THE ANALLS ARE REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE CAFFEE SHOP TO THE ANALLS ARE REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE CAFFEE SHOP TO THE ANALLS ARE REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE CAFFEE SHOP TO GLO CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE CAFFEE SHOP TO GLO CONCESSION AREA (REMOVE BRICK	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 15,000.00 \$ 31,550.00 \$ 5 5,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,475.00 \$ 14,000.00 \$ 45,000.00 \$ 45,000.00 \$ 3 15,000.00 \$ 15,000.00			
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 9 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDLE SCHOOL 1 MIDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDLE SCHOOL 2 MIDLE SCHOOL 1 MIGH SCHOOL 1 MIGH SCHOOL 1 HIGH SCHOOL 9 HIGH SCHOOL 1 HIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRADES OF TO TRASH RECEPTACLE AREA* OUTDOOR TILE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING SEPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN 80YS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACES AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACES FOR THE MILE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACES FOR THE MILE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACES FOR THE PARKING LOT AND REPORT OF THE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACES FOR THE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACES FOR THE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REPLACES FOR TO TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE CATE FOR THE PARKING LOT FOR THE PARKING LOT SECOND AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ART FROOM TO MAIN HALLWAYS FOR CLASSROOMS DOWN BLUE BLVD ADD LICCTRICAL RECEPTACLES	10 9	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,550.00 \$ 5,000.00 \$ 15,000.00 \$ 15,000.00 \$ 11,000.00 \$ 11,475.00 \$ 11,4			s
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 1 MIDDLE SCHOOL 2 MIDDLE SCHOOL 9 MIDDLE SCHOOL 1 MIDDLE SCHOOL 9 MIDLE SCHOOL 1 MIDDLE SCHOOL 9 MIDLE SCHOOL 1 MIGH SCHOOL 9 MIGH SCHOOL 9 MIGH SCHOOL 9 MIGH SCHOOL 1 MIGH SCHOOL 9 MIGH SCHOOL 1 MIGH SCHOOL 9 MIGH SCHOOL 1 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* BUS LOADING AREA - WATER DETENTION REPAIR* SUS LOADING AREA - WATER DETENTION REPAIR* BUS LOADING THE REPAIR REPAINT GENUR WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REPUBBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM FOUNDATION MERS AT FROOT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM [2 NEW HOODS, CABINTRY, ETC.) SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STOREFRONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION ARE (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE CAST ROOM TO MAIN HALLWAY PRICECATE KILLS/EXHAUST, ADD EXHAUST FOR NEW PLTW ROOM) ADD ELE	77 8 8 10 10 10 3 3	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 25,000.00 \$ 31,950.00 \$ 15,000.00			s
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 10 ELEMENTARY/INTERMEDIATE 11 MIDDLE SCHOOL 13 MIDDLE SCHOOL 15 MIDDLE SCHOOL 16 MIDDLE SCHOOL 17 MIDDLE SCHOOL 18 MIDDLE SCHOOL 19 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 10 MIDDLE SCHOOL 11 MIDDLE SCHOOL 12 MIDDLE SCHOOL 13 MIDDLE SCHOOL 14 MIDLE SCHOOL 15 MIGH SCHOOL 16 MIGH SCHOOL 17 MIGH SCHOOL 18 MIGH SCHOOL 19 MIGH SCHOOL 19 MIGH SCHOOL 10 MIGH SCHOOL 10 MIGH SCHOOL 10 MIGH SCHOOL 10 MIGH SCHOOL 11 MIGH SCHOOL 11 MIGH SCHOOL 12 MIGH SCHOOL 13 MIGH SCHOOL 14 MIGH SCHOOL 14 MIGH SCHOOL 15 MIGH SCHOOL 16 MIGH SCHOOL 16 MIGH SCHOOL 17 MIGH SCHOOL 18 MIGH SCHOOL 18 MIGH SCHOOL 18 MIGH SCHOOL 19 MIGH SCHOOL 10 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, ADD ELECTRICAL COUTLETS TO SITS AND SECOND GRADE HALLWAYS ELECTRICAL LUPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* BUS LOADING AREA - WATER DETERMITION REPAIR* BUS LOADING AREA - WATER DETERMITION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRADES DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM HOVELDING SEPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN 80YS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REFURBISH / REPLACE OLD LOCKERS DOWN BLUE BLVD (NEED # OF LOCKERS) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STORFERONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ART ROOM TO MAIN HALLWAY (RELOCATE KLINJS/FAHALUST, ADD EXHALDST FOR NEW PLTW ROOM) ADD ELECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICA	10099	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 25,000.00 \$ 31,500.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 14,000.00 \$ 45,000.00 \$ 45,000.00 \$ 3,000.00 \$ 15,000.00			\$
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 10 ELEMENTARY/INTERMEDIATE 3 MIDDLE SCHOOL 4 MIDDLE SCHOOL 5 MIDDLE SCHOOL 6 MIDDLE SCHOOL 7 MIDDLE SCHOOL 8 MIDDLE SCHOOL 9 MIDDLE SCHOOL 10 MIDLE SCHOOL 10 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY COARIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS) ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS ELECTRICAL UTGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETENTION REPAIR* BUS LOADING AREA - WATER DETENTION REPAIR* SUS ELOADING AREA - WATER DETENTION REPAIR* BUS LOADING AREA - WATER DETENTION REPAIR* SUS ELOADING AREA - WATER DETENTION REPAIR* BUS LOADING AREA - WATER DETENTION REPAIR* BUS LOADING AREA - WATER DETENTION REPAIR* SUS ELOADING AREA - WATER DETENTION REPAIR* BUS LOADING THE REPAIR ADD PARTITIONS TO LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM HOVERS IN BOYS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT CEILING GRID AND REPLACE PADS IN LOBBY (ROUGHLY 4,000 SF) PAINT ON WALLS (NOT INCLUDING CEILING) REPURBISH / PERLACE OLD LOCKERS DOWN BILUE BLVD (NEED # OF LOCKERS) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOMS (DOWN BLUE BLVD KIND LINE PRESENTLY IN COFFEE SHOP) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ART ROOM TO MAIN HALLWAY (RELOCATE KILNS/EXHAUST, ADD EXHAUST FOR NEW PLTW ROOM) ADD LECTRICA RECEPTACLES FOR OWN AND STAGE LIGHTING ADD WINDOW REPLECTIVE TINT TO	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 168,000.00 \$ 80,000.00 \$ 31,950.00 \$ 5,000.00 \$ 15,000.00			s
7 ELEMENTARY/INTERMEDIATE 8 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 9 ELEMENTARY/INTERMEDIATE 10 ELEMENTARY/INTERMEDIATE 10 ELEMENTARY/INTERMEDIATE 11 MIDDLE SCHOOL 12 MIDDLE SCHOOL 13 MIDDLE SCHOOL 14 MIDDLE SCHOOL 15 MIDDLE SCHOOL 16 MIDDLE SCHOOL 17 MIDDLE SCHOOL 18 MIDDLE SCHOOL 18 MIDDLE SCHOOL 19 MIDDLE SCHOOL 10 MIDDLE SCHOOL 11 MIGH SCHOOL	RECOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING) (ADDED CAFETERIA LATER) NEW LAY-IN CEILING IN ELEMENTARY CASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS) NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, ADD ELECTRICAL COUTLETS TO SITS AND SECOND GRADE HALLWAYS ELECTRICAL LUPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS GYM FLOOR SANDING AND REPAIR BUS LOADING AREA - WATER DETERMITION REPAIR* BUS LOADING AREA - WATER DETERMITION REPAIR* BUS LOADING AREA - WATER DETERMITION REPAIR* SIDEWALK LEVELING AT 2 LOCATIONS ADD ROOF AND GRADES DOOR TO TRASH RECEPTACLE AREA* OUTDOOR THE REPAIR REPAINT GYM WALLS (NOT INCLUDING CEILING) RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM HOVELDING SEPURBISHING MOST OF EXISTING ADD PARTITIONS TO LOCKER ROOM SHOWERS IN 80YS LOCKER ROOM FOUNDATION PIERS AT FRONT OF BUILDING FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD REPLACE AG/PLTW WINDOWS SIDEWALK AT WHITE MILE PARKING LOT PAINT GYM WALLS (NOT INCLUDING CEILING) REFURBISH / REPLACE OLD LOCKERS DOWN BLUE BLVD (NEED # OF LOCKERS) REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.) SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STORFERONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151) MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP) MOVE ART ROOM TO MAIN HALLWAY (RELOCATE KLINJS/FAHALUST, ADD EXHALDST FOR NEW PLTW ROOM) ADD ELECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD ADD LECTRICA	77 8 8	\$ 15,000.00 \$ 42,000.00 \$ 166,000.00 \$ 25,000.00 \$ 31,500.00 \$ 15,000.00 \$ 15,000.00 \$ 15,000.00 \$ 14,000.00 \$ 45,000.00 \$ 45,000.00 \$ 3,000.00 \$ 15,000.00			\$

NOTES 1 CONTAINS SOLAR PANELS

2 SEE SEPARATE SHEETS FOR AREA BREAKDOWN. ADDED SURFACE THICKNESS FOR HEAVY BUS TRAFFIC NOT INCLUDED IN THIS BUDGET PRICE

3 103.5 TONS FOR ELEMENTARY, 182 TONS FOR INTERMEDIATE. TO BE REFINED WITH MARK'S INFO COST INCLUDES OCCUPANCY SENSORS, EXCLUDES LIGHTING AND SENSOR REBATES

5 BASED ON 1700 SQ FT BUILDING ADDITION WITH NEW CANOPY TO MATCH EXISTING SCHOOLS
6 INCLUDES IMPORTED FILL, 4000 SQ FT OF PLAYGROUND SURFACE, FENCING, SUBDRAINS, CURBS, AND LABOR TO RELOCATE
HALF OF EXISTING EQUIPMENT. NEW EQUIPMENT NOT INCLUDED.

7 REPAIRS INCLUDED IN ASPHALT SITE WORK

A REPAIRS INCLUDED IN ASPIRAL SILE WORK

8 NOT FEASIBLE DUE TO EXISTING WATER DAMAGE

9 INCLUDES REPLACE FLOORING, CEILINGS, WOOD CASEWORK, ELECTRICAL, PLUMBING, 3 LAB HOODS, VISUAL DISPLAY AND PAINTING. THE HVAC COST FOR SCIENCE
EXHAUST FOR THE LAB HOODS IS \$50,000 OF THE OVERALL BUDGET.

10 THE BUDGET INCLUDES REPLACING 150 LOCKERS. WE'VE ASSUMED A BUDGET OF \$300/LOCKER. THIS BUDGET CAN BE MODIFIED BASED ON ACTUAL NEEDS.

Under Contract

2,513,543.C 2,909,914.00 \$ 3,347,975.00 \$ \$ 6,257,889.00

Total Bond Issue Funds Remaining

1,817,775.9

Executive Summary of General Obligation Bond Options Exhibit A

Holden R-III School District of Johnson County, Missouri

General Obligation Bonds

Total:	Schedule 8		Schedule 7		Corresponding Schedule
\$11,000,000	\$2,500,000		100		Amount of Financing
	April 2, 2030		\$8,500,000 April 8, 2025		Election
	20 Years		20 Years		Repayment Period
	G.O. Bonds	Ge	G.O. Bonds	Ge	Type of Financing
	Four-Sevenths or 57.143%	General Obligation Bonds, Series 2030	Four-Sevenths or 57.143%	General Obligation Bonds, Series 2025	Type of Financing Voter Approval Required
	\$0.8400	Series 2030	\$0.8400	; Series 2025	Required Debt Service Fund Levy
	ı		1		Cost for a \$100,000 Home
\$159,900	\$46,200		\$113,700		Estimated Costs of Issuance
\$870,310	\$218,975		\$651,335		Estimated Projected Net Reoffering Premium Proceeds Available
\$11,710,410	\$2,672,775		\$9,037,635		Projected Net Proceeds Available

District will be in a position to pursue the legal capacities if the annual growth rate in assessed valuation exceeds one and one-half percent (1.50%) and/or the Series 2019/Series Note: The District's respective legal bonding capacities at the April 8, 2025 and April 2, 2030 elections are approximately \$11,000,000 and \$4,000,000 (\$15,000,000 Total). The 2025 Bonds are able to be refinanced.



Holden R-III Long-Range Facility Planning

As we develop a long-range facility plan for the district, we would like to gather your input regarding the facilities in which you work.

which you work.								
1. In which building	g do y	ou wo	rk?					
2. I am a		•				4		
3. The level of faci	lities-r	elated	l comi	munic	ation I	receive is satisfactory.		
	1	2	3	4	5			
Strongly Disagree	0	0	0	0	0	Strongly Agree		
4. Custodial servic	es, sp	ecifica	ally cla	assroc	m and	office cleaning, meet my expectations.		
	1	2	3	4	5			
Strongly Disagree	0	0	0	0	0	Strongly Agree		
5. Outside facilities	s and (ground	ds are	well-r	nainta	ined/attractive.		
	1	2	3	4	5			
Strongly Disagree	0	0	0	0	0	Strongly Agree		
6. Trash and recycling pick-up meets my expectations.								
	1	2	3	4	5			
Strongly Disagree	0	0	0	0	0	Strongly Agree		
7. Restrooms are stocked and clean.								
	1	2	3	4	5			
Strongly Disagree	0	0	0	0	0	Strongly Agree		

8. Maintenance (li	ghts, F	IVAC,	plumb	oing) r	eques	ts are resolved in a timely manner.
	1	2	3	4	5	
Strongly Disagree	0	0	0	0	0	Strongly Agree
9. Maintenance an	d cust	odial	staff a	ire coi	urteou	s and professional.
Strongly Disagree	0	0	0	0	0	Strongly Agree
10. Overall, I am sa	atisfied	d with	the fa	cilities	s mana	agement services I receive.
Strongly Disagree	0	0	0	0	0	Strongly Agree
NEXT						Page 1 of 2
Never submit passwords throug	gh Google	Forms.				

This form was created inside of Holden R-3 School District. Report Abuse
Google Forms

httm://door coords com/former/1/-/17-AT-OT O / OTT OTT 11. Trotting of

至是

Holden R-III Long-Range Facility Planning

Please take an opportunity to consider each of the following categories and make any comments that you feel would assist us in prioritizing facility needs. We will form committees at each building that will review all of the data gathered and develop a priority list.

1. Site

(Ex. Parking Lots, Driveways, Walkways, Outdoor Equipment, Landscaping, Playgrounds, Athletic Facilities)

Your answer

2. Building Exterior/Envelope

(Ex. Roof, Walls, Doors, Canopies)

Your answer

3. Building Interior

(Ex. Renovations, Remodeling, Painting, Floors, Ceilings)

Your answer

4. Educational Adequacy

(Ex. Classroom Functionality, Space Planning and Redesign, Special Programs, Support Programs)

Your answer

5. Mechanical Systems

(Ex. Plumbing Systems, HVAC Systems, Temperature Control, Energy Analysis and Efficiency)

Your answer

6. Electrical Systems

(Ex. Electrical Power Capacity, Lighting, Phone/Intercom Systems, Data Systems, Technology Infrastructure)

Your answer

7. Safety

(Ex. Vestibules, Security/Safety Glass, Door Access/Locking Systems, Security Cameras, Entry Alarm Systems, Fire Detection, Suppression, & Alarm Systems)

Your answer

8. Equipment (Ex. Built-In Equipment - Kitchen Equipment, Science Labs, Industrial Technology Equipment, Kilns, Fume Hoods, Dishwashers, etc.)	ology/Agriculture
Your answer	
9. ADA (Ex. Handicapped Accessibility)	
Your answer	
10. Other Long-Range Planning Considerations (Ex. Facility Additions, Land Acquisition, Capacity Reviews)	
Your answer	
Name: (Optional)	
Your answer	
BACK SUBMIT	Page 2 of
Never submit passwords through Google Forms.	

This form was created inside of Holden R-3 School District. $\underline{\text{Report Abuse}}$

Google Forms

113



Holden R-III Long-Range Facility Planning


104 responses

As we develop a long-range facility plan for the district, we would like to gather your input regarding the facilities in which you work.


r

1. In which building do you work?

99 responses









3. The level of facilities-related communication I receive is satisfactory.

102 responses




4. Custodial services, specifically classroom and office cleaning, meet my expectal 102 responses




5. Outside facilities and grounds are well-maintained/attractive.

6. Trash and recycling pick-up meets my expectations.


102 responses




7. Restrooms are stocked and clean.



8. Maintenance (lights, HVAC, plumbing) requests are resolved in a timely manner. 101 responses



9. Maintenance and custodial staff are courteous and professional.



Please take an opportunity to consider each of the following categories and make any comments that you feel would assist us in prioritizing facility needs. We will form committees at each building that will review all of the data gathered and develop a priority list.

1. Site

60 responses

Too

many cigarette butts. some from custodial staff. If they're going to smoke on campus despite our policy, lets get a butt can or something so they aren't littering right in front of our school.

wish the sidewalks and parking lots would be covered in ice melt when we have winter storms much earlier than they are. I often am afraid of falling walking across the parking lot after we have have had bad weather....for days it stays icy...not safe. And I know it is hard with timing and such to get ice melt down but it is scary to walk across a sheet of ice to get to the building. Also the preschool playground seems to be mowed less than other places... Also the carabiner that are to be on the preschool playground gates are never on there. One gate has one missing all the time. It isn't safe when we have students who run away a lot.

Pot holes

Playground parking lots

The

Elementary playground is in need of a serious upgrade, from equipment repairs, to resurfacing, to additional equipment needs like basketball goals and a kickball area. In addition, the landscaping that was put in at the entrance has not been maintained and does not look inviting to guests. The drop off circle drive and entrance could also use some attention.

Walkways

are pretty run down near the older part of the elementary. The landscape of the older part of the building is not up to par; trash and unmowed at times, no beautification at all. The circle drive has potholes, parking lot has potholes and is not cleared adaquately in the winter. We had several people (children and almost some adults) fall because of ice under the pavilion at the parent drop off area.

Playground

needs to be converted to a soft mat rather than woodchips. It would be safer for

our students and better for the districts budget in the long run. Parking lots also need repainted and holes filled.

Outdoor

educational area with more tables (currently only have two picnic tables)

Playground

needs to be more secure and updated.

Playground

with the rubber surface

Parking

lot needs new parking spaces. Lines are faded and hard to see.

If

anything, I think the parking lot could use some work, but it isn't horrible.

Need

rock behind high school, when it rains that parking lot becomes mud hole.

Good.

They have

gotten better this year, looks very nice, except parking lots and driveways which are worse.

N/A

Playground

needs some TLC. The elementary landscaping is not attractive.

Parking

lot lines are faded

l

have to park in the back when it rains hard or snow the ground becomes very muddy-The doors outside of the middles school students are unable to walk out must walk around a large puddle to the buses.

cracks

and water in parking lot; snow removal in parking lot better, not creating mounds to walk through

Parking

lot should probably be sealed to make it last longer

The

only thing I have noticed being inadequate with the facilities that I come into contact with is the snow removal in the parking lot at the middle school. Our custodians did the best they could to keep the sidewalks free from ice, but sometimes the parking lot didn't even look like it had been touched.

All of the

options above are usually great. The only one that is not always okay is the playground. Sometimes we are mowing in the field where our students are playing. Sometimes when requests for sent in to fix things or exterminate wasps, it isn't always completed in a timely manner.

Parking

lot behind high school needs attention due to ruts

Playground

at the Elementary needs updated with new, safe equipment and all-weather flooring (no more wood chips!!)

Elementary

landscaping could use a touch up

lt'd

be nice if the lots behind the high school were paved over instead of gravel. While it's fun playing dodge the potholes in the elementary drop off/pick up drive, those need to be fixed. The high school student parking lot could be leveled. Track could be redone.

The

middle school parking lot could use a little love.

The

main parking lot is deteriorating quickly, with pot holes, dips, waves, etc. And a large section of concrete was cut out in the bus lane and filled with gravel. Is that going to get fixed?

No

comment

The

landscape in front of the elementary needs some serious work. The stones are not in the right spot since the sidewalk repair. The bushes and flowers need to be tended to. Since this was a senior project, I have often wondered who would be in charge of it. I pull weeds from time to time, but can't devote time away from students to help much.

The

facilities within the district are of high quality. I have visited many other schools and I think the Holden campus is better than most. The largest area of improvement is the parking lots. The high school parking lot is an obvious area of improvement. I also feel like the middle school parking lot could be repainted.

1

think more could be done to make sure the parking lots and roads around the school are cleared before we get to school.

We

need to begin to "save" for future parking lot maintenance. The track and field - field events areas could use some water drainage improvement. Unsure of how we could do it but moving the javelin area closer have been mentioned as a need. High School Gym Floor-Evaluate and place in long range plan for refinish/replacement as needed.

Parents

have complained about circle drive pot holes.. There is a gate on the north east end that hasn't worked in some time. However i have not requested it to be fixed by grounds crew.

Parking

lots need paved/striped. Playground needs to be surfaced. Landscaping at middle school and elementary. High School and Middle School parking lots behind schools need to be paved - not gravel. Central Office back patio needs to be fixed.

good

cleaning

sidewalks when there is snow and to the kitchen doors to and the sidewalk from the high school staff parking and the elementary doors

Our

playground could use a little love. Things frequently break and it takes a while to get it fixed.

Roads

around school are not great. Muddle/lack of gravel in back of high school.

Elementary

playground needs some love and attention. Possibly new equipment and new surfacing? Know that's expensive but we have a lot of kids that play on that each day and right now, several parts of it are unsafe.

The

playground and sidewalk to our playground sometimes is not well mowed. The trashcan on the playground sometimes overflows and the gate normally doesn't latch to being broke.

The

HS parking lot and bus lanes need to be repaved. The front of the high school has curbing falling apart. The drive in front of Day Plus is horrible.

Playground:

I would love to see a different playground covering rather than the mulch, grass, and blacktop. Students would also like some new equipment.

Elementary


playground is not in an ideal location, however, not sure where it could move to. Landscape fabric around tree has been a tripping hazard. Update painted lines on black top. n]]

At

least one street light in HS parking lot (east end) has been non-operational for quite some time. A more outdoor "classroom" friendly environment. Perhaps some kind of permanent seating and shaded area.

With

regard to the playground, balls constantly go over the fence, into the parking areas. Cars will go past, or even drive through the field when the kids are



need to move the playground. It is a safety issue.

https://doca goodle com/forma/1/1- VO-1 10100TDT

The

playground needs to be more kid friendly. I believe that the playground would benefit from a tall privacy fence to help keep the balls in and outside adults out. I also believe we need some way to separate the field due to cars driving in the field to get to their apartments. We would really benefit from having basketballs or some activity on the court. The mulch also is a concern due to it is injuring students if they fall and is hard to manage.

Gravel

area behind High School is a muddy mess after a rain.

NA

The

elementary playground is a very sad representation of our district. Over 500 students use the facility daily. I understand equipment is expensive, but this area needs to be a priority. Mulch and loose rock are most always on the asphalt area and numerous students are injured due to falls because of this. Much of the equipment is old. A few of the swings have sharp pieces on them. The matting under the mulch has been coming out for the past 3 years and no attempt has been made to improve this. There are areas that are not safe for students and I feel very passionate about this being resolved and would be willing to help in anyway.

It

would be WONDERFUL to have a new playground!!

The

playground surface needs to be updated and it would be nice to have surface under the picnic tables at the middle school other than grass so it can be used more, maybe add an outdoor classroom that can be booked. Would love to have an performing arts center—maybe connecting the HS and MS. A lot of focus and \$ seems to go to sports.

Bic

potholes in parking lot. Where they were fixed with concrete, the concrete came loose and flipped up hitting my car.

1

often wonder if we could add a small playground just outside the E. Main Street doors (east of the building). Drainage is already an issue. It gets super muddy when it rains. If we need to fix that (and we're dreaming years ahead), let's put in a playground or something for kids to do if they finish lunch early.

Overall,

site components are in fair shape but should be on a rotation for regular repair or replacement.

1

feel like these areas are ok, but the high school parking lot is pretty rough.

2. Building Exterior/Envelope

52 responses

we

need roofs that don't leak!!! Every time it rains we are ruining district equipment, student work, etc.

Everything

is fine but it would be great to have key fabs on the remaining doors in our building.

```
Leaking
 roof
 Roofs
 There a
 several areas in the Elementary where the roof leaks.
 Roof
 leaks everywhere
 The
 roof of the canopy at the parent drop off is unpainted. The repairs of this
 structure were below par. The patio was left with holes or unsightly crevices
 which is also a tripping hazard. In many parts of our building we have leaky
 ceilings; really leaky ceilings that leak through the light fixtures. Isn't
 that a fire hazard?
 Still
 have leaks inside with heavy rain.
 Roof
 that doesn't leak
 Leaks
in roof when it rains.
 Some
leaks in the roof.
Leaking
roof.
N/A
Exterior
doors stick and it is hard to open them
fine
leaking roof in the elementary library has gotten better with the numerous
repairs, but there are still leaks.
roof
at the school
in wall to the outside world in classrooms; lack of insulated walls; many
ceiling leaks
Roof
leaks in several classrooms at the high school "unacceptable".
some
areas of the roof still leak
The
building is usually wonderful. I don't have any comments here.
There
are leaks. There has been a bucket in middle of hallway by lunch area for quite
a long time.
```

https://dogg.coogle.com/forms/4/1-370-340/00TDT 1:0 370 0 000

Several

leaks in roof causing issues inside classrooms

The

roofs need major fixing to fix the leaks.

Middle

school still has some areas that leak.

The

roof is a major concern. Dana had to move desks because of the leaking roof. Buckets all over the place when it rains.

The

roof on the older part of the elementary leaks - a lot!

1

know you are aware of the various roof leaks and are working towards resolving the problem.

The

building exterior is clean and functional. As far as I can tell, when an issue arises with the building, it is dealt with in a timely manner.

1

know the roof at the elementary is leaking. It saddens me that we have trash cans collecting water in classrooms and hallways when it rains.

We need to

begin to "save" to redesign and install newly designed roofing when the current flat roofs need replacement.

Ceiling

in Elementary office leaks into the girls bathroom

Roof

leaks in all buildings need to be repaired.

good

new roofs

are needed

exterior

not bad, improvements have been made.

We

constantly have leaks throughout the building... mostly 2nd grade hallway.

The

roof leaks around the window outside of Mrs. Walter's door. It has leaked for several years. It leaves larger puddles on the floor and people have fallen and slipped many times. This includes teachers, kids, and parents.

The

security of the doors the magnetic strips are wearing and lock always locking properly, Fixing the roof properly until it can be replaced.

1

would love to see some color on the walls rather than all white.

Roof leaks

in MANY areas of high school.

The

door by the 5th grade hallway does not lock unless it is slammed. This is a safety concern, as people have been able to walk in those doors. I would also suggest keypad/fob entries on every door as a safety feature.

Secure

any roof building leaks.

Maintenance

needs a new leader

Some

of the rooms need roof repair

NA

My classroom

roof leaks and has for the past 2 years. Still leaks when it rains hard. Room 109

There

are walls in the elementary that are cracked. You can see the classroom next door through the cracks.

Handicap accessible doors.

front

of middle school has chipped paint/tiles

Several

roofs have needed patching. All three large buildings seem to need additional work.

When

it's rainy, there are some leaks right next to my door (Room 301) in the Middle School. This is very distracting when it rains.

3. Building Interior

54 responses

Renovations

need to be completed when asked due to keeping kids' safe.

Looks

great!

Public

bathrooms need to be renovated.

All

of it

Carpeted

classrooms need an upgrade, as do the paint colors in the Elementary hallways. Ceiling tiles need replaced in areas where the roof has leaked. Restrooms in the older areas of the Elementary building need renovated.

The

older part of the building is very dreary in many of the classrooms because of the condition of paint. Also, the wires that hang out all over the place in the older part of the building is a bit ridiculous.

The

elementary is very boring and bland inside. It would feel much cozier with warm colors on the walls. It would also be important to replace the ceilings in the old part of the building so that we can actually have up to date projectors. The rest of the building received new ones but since our ceilings have asbestos we get stuck with the crappy ones.

Bathrooms

that work and classrooms that don't have leaks/bugs

None.

Tiles

missing from ceiling or damaged from leaks.

Last

year was the first time our offices have been cleaned in 4 years. Don't mind cleaning during the year but would like a deep clean during the summer.

N/A

Lots of

places and classrooms need painting. The student bathrooms in the old part of the building are really gross and not pleasant to even peek your head into.

ok

retile some

floors.

Ceilings

still have water stain, lights has sitting water in them.

Pain^a

frame around windows in classroom doors; replacing ceiling tiles when they are removed

Our

summer paint crew is great. Lisa Fee and Renne Wright do a great job.

multiple

requests have been put in for the same maintenance that never gets done

1

have titles in my room that have water spots on them, and they have been like that for two years. The window seals have dirty in them constantly. I have. I am not sure where it comes from. I also have dirt on the metal part of the windows (when I open up my windows). I am not sure how it accumulates there.

Due to high

turnover of custodians, many times trash is not picked up, creating the opportunity for rodents to come into classroom because of the food left by breakfast on the go in the trash cans.

Lots

of ceiling tiles are water stained. We could do some interior work to make our

buildings look more modern/homey and less industrial/prison-like with more open areas.

Fix

ceiling tiles. Some of the bathrooms could be updated and the stalls painted over.

Leaks

in ceiling causing mold issues for allergies

The

doors leading to the outside by the boy gym entrance needs weather stripping at the bottom to keep the cold air and bugs out.

The

gym floor takes a beating though. Custodial needs to take better care of the floor, and there needs to be a floor cover bought for events to protect it. I don't see a better place for this, but I have numerous door and lock issues that have no been resolved. I don't know if the issue is money, time, equipment, or what, but these issues have safety concerns.

Ceilings

in the older part of the elementary need work from water damage.

acceptable

The

buildings we teach in provide a safe, clean, and comfortable learning environment. I do not have any issues with the interior of any of the middle school.

Restrooms

modern and functional

The

floor tiles are falling apart or coming loose already. I don't know if this is the place to put this but I don't know where this would be appropriate to put it. I feel Karen Parks works hard to keep up with 6 lunch duties in 2 cafeterias during the day. She manages to get 2 large cafeterias clean and still keep up with the unexpected spills or messes in the entire school by herself. The night custodians don't work as hard as she does and there are 3 of them. I have come into my room and still have trash in the trash cans or the floors are still dirty. This didn't happen when Tina Crust was here. She took pride in her areas.

Restrooms

need updating in all buildings, I am unsure about staff restrooms and break rooms but those should be up to date as well. High School locker rooms need attention.

Girls

bathroom ceiling is about to come down, bad leaks in the girls bathroom and in hall next to girls bathroom leaks. Buckets are placed to catch the water when it rains. Furniture such as tan shelf needs to be moved out of k-2 cafeteria to surplus. The students water fountain in the K-2 cafeteria has been non functioning for 2 years. I believe parts were purchased however still not working. Student bathrooms do not have warm or hot water to wash their hands, this would be a health issue

Painting

 elementary. Ceiling tiles replaced. Wiring in elementary needs to be in conduits in 2nd grade hallway. Bathrooms at the high school and elementary need to be remodeled. Elementary bathrooms are in disarray.

good

girls

bathroom in elementary needs remodeled

There

are several leaks that have left tiles looking nasty.

Our

bathrooms are outdated and poorly maintained for extracurricular activities. Urinals repeated not sufficient to keep with flow. Some of that is just the age of the facility. Complete tearout/remodel needed i assume at great cost. Tap com holes in wall look poor in hallways through the hallways and bathrooms.

Because

of the leaking, some of the ceilings look rough / trashy. Tiles have fallen down, too.

Repaint

HS gym, many classrooms and bathrooms need to be repainted, remodel interior locker room and restrooms by gym and Ag room, floor in hall of fame is cracking in a major way

Stained

ceiling tiles make a terrible impression, they look awful - but the leaking roof stains whatever is replaced Cracks in walls and floors (even newer construction)

Ceilings:

We have a leak in the first grade hallway, we also had a safety problem in the second grade bathroom regarding chipping/leaks, which has been shut down for months. The floors are amazingly waxed, Thank you! Walls: A fresh coat of paint would be nice! Other appearances that need work: All the cords and wires from Technology is disappointing. They are visible and hanging out everywhere.

Your

custodians do the best they can with very little help. There is a reason the school has had such big turn over in the area of custodians. They deserve a new leader!

The

2nd grade hallway leaks under the skylight. We also are concerned with the asbestos ceilings. We're told it's safe if untouched, but we still don't feel comfortable wondering if we are breathing in something that will eventually cause problems. We also have a HUGE problem with ROACHES! It's terribly disgusting and distracting to be teaching a math lesson and while the kids are looking at the math wall.....a big, fat roach saunters across my hundred number chart. Ugh...Please and Thank you.

Floors

look good. Rooms need colors other than white.

Remolding

Ceiling

tiles honestly are bowed and look filthy and are water stained. The walls in my room are so unpresentable they must be covered with paper.

There

are ceilings in the elementary classrooms and library that leak and have noticeable water stains.

There

are areas of the building that the floors appear to be sinking and separating

from the walls. This is also a problem when animals find their way into the building (snakes etc.)

ı

feel a different flooring needs to be in the STEAM lab at the middle school.

There

is no storage in the middle school.

Third

grade decorates their hallways each year with their incredible, multi-disciplinary biome projects. It's a huge deal - something their students will remember forever. I think it would be amazing if we could paint the backgrounds for their biomes (ocean, rain forest, arctic tundra, desert, etc.) as a permanent part of our building decor. It would be beautiful and welcoming AND a great teaching tool. The foundation is shifting at the "new" end of the elementary. The art room counter trim is separating from the counter top as the floor shift downwards. It's not a big deal yet, but I know my former classroom (141) is having more serious issues.

Floors

in middle school and elementary have had areas of patching or replacement. Elementary bathroom floors need replacing. Updated equipment is needed in bathrooms, several have original equipment.

No

concern here.

4. Educational Adequacy

38 responses

NA

good

Great in the elementary!

Great

Good space!!!!

No concerns

1

was needing my classroom cleared out of excess materials and furniture/equipment (which took up half the room) and that never happened. There didn't seem to be a lot of effort in planning how the materials and furniture/equipment were to be stacked if they HAD to leave it in the room. So, when some of those things were needed it was incredibly difficult to access or find at all. As a result, my portion of the room was disrupted and added extra work and time to making sure I was ready to conduct class. I'm not sure why it was not cleared out but it made

it very difficult to conduct class. I made the best of it but it was disheartening.

Bigger

classrooms

Storm

shelter takes up a ton of space in classrooms and can be distraction for teaching at times.

There

are a lot of times where I don't feel like my room is adequately cleaned. There are things that aren't swept up, liners aren't put in my trash can so the can starts to smell, I can't remember the last time that my white board was cleaned. These things can affect the functionality of my classroom.

Fine.

Just

cleaning the rooms would be nice. Have an extreme amount of dust consistently, stuff is left on the ground, etc.

ok

more

rechargeable calculators, more of the bigger individual desks

1

just wish we had more money to make each section better. Other than that I think we are doing the best we can at the moment.

none

Special

programs and space planning—more flexible space options for collaboration among larger groups. If teachers want to coteach a project, we don't really have the space to accommodate two classes of students.

If

there were more science rooms that were set up like lott's room, that'd be neat. The stationary work spaces in the other two, while nice with all of the sinks and gas hook ups makes it hard to do more collaborative or flexible seating.

As our class

sizes grow, our classrooms become tighter.

Third

grade hallway needs to be painted to accommodate habitat projects in the spring.

Any

issues I have had in the past have been remedied.

1

think this should be our greatest focus.

Will

defer to teachers / building administrators on needs in this area

space

for program is adequate.

PLTW

Classrooms need revisions for PLTW purposes, more workspace is needed.

We

do awesome at working with what we have and making the best out of our building!

Mental

health facility within building, change location of coffee shop, move art room with kilns which will increase the space for PLTW

Electrical

outlets for ever-increasing technology needs are inadequate. Ceiling mounted projectors are not placed at the proper distance from screens

The

classrooms are great, however in future planning, single desks would be more functional and aid in classroom management and planning.

The

space in our rooms are excellent compared to other schools!

no

changes necessary

Technology

is great, however, there are unpresentable wires hanging in many places.

3-5

need bigger classrooms with the bigger kids and larger class sizes. The K-2 classrooms are larger and they have smaller kids, smaller class sizes.

Nο

scripted lessons. Have faith in the teachers and support their creativity and special talents.

Science

labs should be updated in middle and high school and created for the elementary. Increased access to STEM/STEAM should demand more lab space. High school and middle school focus upon 'career ready' could also require additional space for tech learning and ag learning. Computer labs and media access, especially in middle and high school, should be updated with remodeling to create more focused access to equipment.

No

concern here.

5. Mechanical Systems

46 responses

The

temperature control in the middle school needs some work. One day this winter it was 88 degrees Fahrenheit in my classroom, and just a few days ago it was 67 degrees while students were map testing. There seems to be no working vents in the SSC either and the room is very cold in the winter.

lt

is ok.

Ok

No

concerns

This

seems to be good in my areas.

HVAC:

My room is either freezing or really hot

Working

drinking fountains

Temperature

can be same as weather. Hot outside, and hot inside. Cold outside and cold inside.

Boys

bathroom in hall of fame hallway has had urinal issues most of year.

HVAC is

inconsistent in its operation.

Our

rooms are either freezing or hot. Make you feel bad if you 'complain'.

Plumbing

seems to be a problem in the older part of the building in the student bathrooms.

HVAC

& Temp Control is none existent in my room

ok

if over the

winter the temperature in the classrooms is going to kick down below 60 over night then have it kick back up before students and teachers get here. There are times where I would come in and my room be 58*

Boys'

bathroom floods often

We

have had problems with the hvac since it was put in and continues

The

thermostat went out in my room, but it was fixed. It just took awhile for it to be repaired.

There

is a WIDE variety of temperatures across classrooms. Some of them are SO cold that student computers are cold to the touch and fingers are frosty (e.g. SSC, Chambers). Other rooms can be stifling hot (e.g. Orton). It's very unpleasant for staff and students. The office area/rooms are usually adequate.

Hot

water does not reach science rooms or does all sinks work in all science rooms even after requests

HVAC

systems at MS (It's either freezing or super hot and it varies between classrooms). It would be nice to control our own room temperature within a range.

AC

units in switch rooms in the HS need to be looked at. Those rooms get warm. Some of the bathroom plumbing could be updated.

The

HVAC in the middle school seems unreliable/temperamental. All classrooms seem to run on a different temp and are at times way too hot/cold.

NA

acceptable

I do

not have any issues with the mechanical systems in the district.

Meh. Some

days they work, the next they don't. I guess that's why some people have portable heaters in their rooms during the winter. There must be plumbing issues because the girls restroom in the 2nd grade has been closed for several months.

Need

end of life analysis of these systems and develop a replacement master plan. Also incorporate analysis of energy efficiency improvements in this master plan. Consider engineering services such as Navitas that can identify and "guarantee" energy savings paybacks.

good

I'm

sure there are problems but they appear to try to keep them functioning, I assume a lot of that is dictated by age of equipment.

Plumbing

issues in restrooms - Mrs. Brockhaus sink is awful.

Update

the urinals in the boys restroom by the gym, update both restrooms by the $\ensuremath{\mathsf{gym}}$

Need

to be able to control temperature of classrooms.

More

control over classroom temperature would be appreciated. I'm curious about the overall energy efficiency of the physical plant. Motion activated lights? Or some kind of mechanism (glow in the dark switch plates?) in dark conditions that indicate light switch locations.

An

updated HVAC system. In the first grade classrooms, when the AC comes on it blows extremely hard and blows things off our walls, and when it's off, it gets hot. It is always one extreme temperature or the other.

The

building is either cold, hot and the roof leaks!!

Ou

sinks in the 2nd grade rooms don't drain properly. This causes them to become coated in mold.

More

efficient windows in ag area classrooms

Temperature control is poor.

The

heating and cooling in my room has not worked properly on and off this year. The girls bathroom in the old part of the elementary has been out of order for several months. Unless you are in the classroom, you may not realize how this takes away from instructional time and causes behaviors to send students down to the new part of the building.

Work great!

Seems

like the temp in the MS is always too hot or too cold.

The

middle school heating and cooling system is poorly designed and old. We are either freezing or burning up.

One

of the sinks in the art room hasn't drained properly since March of 2017. Another has started having trouble this spring. I finally had someone respond to a work order just over a month ago. He said he'd be back the next day to clean out the sink traps, so I moved all of the supplies out from the cupboards beneath them. All that stuff has been sitting on my floor ever since, and the sinks have yet to be fixed. I'm going to have to move it all back in, in order to pack up for the summer. It's been a major inconvenience the past few months because the worst sink is the shortest sink – the exact one my kindergartners need. It's really starting to smell and horrible black gunk rises up out of the drains whenever we HAVE to use it. I need this fixed. I imagine the summer school classes will need to use all 3 sinks as well.

HVAC

systems are old, many of comparable age. Replacement rotation should be established and an energy efficiency plan developed. Plumbing in the elementary is a concern. All buildings have old plumbing.

The

6th grade team thermostat and Tobi Chamber's 7th grade room are all connected and when it's really hot it's REALLY hot. (Vice Versa for cold). I would prefer that this get fixed over the summer if possible.

6. Electrical Systems

44 responses

We

need more outlets in classrooms.

Ok

Intercom

system - can't hear in the classroom when sound comes through phones only. Very happy with data system and technology infrastructure.

https://d-ca.a.a.l. /C /1/1 370 370 007071 4 0 0070

There

are not enough plug-ins in the older part of the building.

Adjustable

lighting would be nice in the classrooms and I need technology infrastructure to hook up a desktop computer for student use in my room.

Louder

intercom through the phone or put in an intercom system that we can hear

None.

Fine.

Our phones

have been going off when we have been talking to parents quite a bit this year.

N/A

Intercoms in

the hallway are hard to hear.

It

took until April to get four lights fixed in my room. They were turned in back in August

had

lights out for weeks without them being fixed-

There

is only one phone at one end of the library. The library is a very large space. It is difficult to hear announcements made over the phone when having students at the opposite end of the library. It would also be difficult to hear intruder location updates from the library hiding place (RTI library room).

more

outlets in some rooms. Or a more permanent power surge so it cannot be moved by students

Difficult

to hear announcements- sounds muffled; phones showing correct time and in coordination with bells; students being able to record video on devices; extra charging devices

Lots

of electrical cords hanging from the ceiling

All

works well.

Concern

with server room getting too hot as well as the copier room down white blvd

Wifi

could always be improved to keep pace with our tech usage

Possible

put lightning rods on the roofs to help mitigate damage from lightning strikes.

Seems

fine. Sometimes I'll be in on the weekends and find ALL the gym lights on.

Aren't they supposed to be on a timer and motion sensor? Seems like a waste of energy.

The

exposed cords for all of the various technologies are an eyesore. Some of them dangle while others are a huge mass on the floor. Many of the older parts of the buildings can't have more than one thing plugged in at a time or it blows a fuse.

Announcements

are not heard in either of the cafeterias. This is a major safety issue when a grade is at lunch, and we go on lock-down.

1

do not have any issues with the electrical systems.

More

efficient lighting

1

don't see issue with this category.

Sustain

current capabilities with a maintenance and replacement plan as needed

Lighting at

the back of Central Office needs to be working at all times. No light when it is dark now. Safety concern.

ok

See above

answer

Intercom

system needs some work - especially with cafeterias and gym. Can't hear announcements in those locations.

Install

LED lighting, Correct the clocks--all work on the atomic system

Electrical

outlets for ever-increasing technology needs are inadequate. SIS needs more functionality at the instructor level. Not sure how robust the network is for future growth.

In

my opinion, all is good here!

Technology

department is good

We

can't plug in too many items or we blow breakers in the 2nd grade rooms. We tried to plug in a few griddles for pancakes and ended up having to go to the workroom.

No

changes necessary

Lighting

Worked

great this year!

The

technology seems to work well most of the time. However, this year Apple tv has had lots of issues in my classroom. This makes it hard to teach when I was planning to use apple tv to connect my device for class.

Technology

goes in and out. No fault of our tech team though. Internet is just not great in rural areas. Also, it seems MS students have problems moving from classrooms with their devices or keeping them safe in their lockers and at home. Maybe switch to where each class have a classroom set instead of individual ones.

Secure data

systems are a must. Technology infrastructure is an ongoing concern. All parts of each building should be accessible by phone or intercom. Rewiring in order to achieve needed electricity may be needed, especially in older buildings.

The

apple TV continues to disconnect when you connect from your computer. It would be really helpful if we could get this fixed. This for me is more important than the temperature.

7. Safety

46 responses

Fine.

Foh

doors need to be checked frequently to check latching. Consequences needs to be in place when teachers prop doors, put magnets in place to keep them open.

Seems

ok.

Good

Cameras can be an issue

Several

doors do not close tightly unless slammed. Need keyless entry points at locations currently without.

Seems

adequate!

It

is very inconvenient that all doors have key fob entrances. Such as the 1st and 5th grade doors.

Safety

entryway for the middle school like the other buildings

None.

We do not

have a working alarm system, it has always gone off in the middle of the night, it has a problem.

N/A

ok

procedure for students in the cafeteria during lunch

Bullet-proof

glass in doors and windows; viewing cameras in parking lot

in the H.S. needs new entry doors, there are dead zones for the cameras also

Double

doors by the 2nd grade hallway do not lock properly. This has been a concern for a long time.

might be nice to have better placements for the cameras on the play ground. Sometimes we have serious issues, and no stories add up. It is hard to see what really happened because the cameras cannot see what is going on or they are too far away. I also know there are some spots in the elementary building where there are no cameras or the cameras cannot see all the way down the hall and what not.

I'd

like to see more security cameras and/or better quality as a way to better monitor students and to investigate reports of bullying, etc.

none

Upgrade

security cameras for better picture. Don't let people prop open back doors.

kitchen

back door is very hard to open, might be a problem in case of emergency

acceptable

has never been a time where I felt unsafe at school.

am not sure what else we could do in this area.

improvements as identified to improve security. Address Middle School visitor access for adequacy.

alarm

system for day plus program had been needed for quite sometime superintendent made it happen. a camera was placed in classroom, however monitors if any were supposed to be in place, are not.

doors do not always shut and latch on their own which is a safety concern

Middle

School entrance possibly needs a better security entrance.

good

i like our system

Many

teachers prefer to use the door in the first grade hallway. It does not have a key fob. It would be nice if it did.

Door

access/locking system—the doors do not always secure themselves and a real safety concern, bullet proof glass in the front entry and cafeteria area install more cameras and update other cameras

Blue

Boulevard classrooms in HS stay locked when locked; White Mile classrooms unlock when the handle is turned from the inside - very problematic when securing classroom.

As

mentioned above, keypad/fob entry on all doors would be an extra safety feature.

would like to request a key fob entry for the end of the first grade hallway.

Sometimes

the double doors lock in our wing and sometimes they don't.

Doors

with vertical viewing area instead of complete window

Security

needs updated

Work

orders and suggestions have been made regarding door locking and safety in the elementary building. We really must take a serious look at this. The recess door the faces the ball field often gets pea gravel in the threshold and keeps the doors from locking. PLEASE address this.

Work

fine!

There

is a cracked glass cover on a fire extinguisher outside the music room that should be checked and possibly replaced.

1

feel that there needs to an extra lock on the doors of the Data Room that are used for a safe room.

Middle

school needs a secure entry and all vestibules should have security glass. More cameras in middle school and elementary.

No

concern here.

otton//docs and - 1/1 T/O MO OND T 1 10 TIO

8. Equipment

36 responses

N/A

good

The traps

under the sinks in science classrooms are never cleaned.

Good

No

problems

Need

more chrome books

No

concerns

None.

Fine.

science

sinks smell and eye sprayers do not work

in in 102 lab tables do not drain properly. gas lines and valves are not reliable to leave on. sinks in 126 have doors that wont unlock and faucets that need to be replaced after several work orders. the server room is doomed for failure because it is too hot. (i have been in there,I know)

All

is good here.

Science

lab stations are not being treated in timely manner. Room 102 has unreliable gas valves preventing the use of the stations

l'm

not sure if furniture fits into this category, but a vast majority of our desks/tables/chairs are dated and have to continually be repaired. More modern and flexible seating options that facilitate greater collaboration (for students and staff) would be ideal. Science labs could use updated areas and equipment to more closely reflect real-world labs.

Science

rooms in performance parkway need safety showers and proper cabinets to store more caustic chemicals such as various acids. The sinks in the two science rooms down across from the band hall should be looked at. Pressure is inconsistent and the faucets leak. It would be nice if the science rooms were redesigned in ways where kids could be more mobile.

Middle

School Kiln plus a fume hood would be beneficial for the art room.

Fine

acceptable

I feel my

computer lab at the middle school is very adequate. I have seen other computer labs at different schools and I feel my lab provides more opportunities for students.

ı

don't use any of this type of equipment.

Budget

for a new Green House cooling system (~\$2000)

Access

to the kitchen area door remains locked to keep everyone out. However Day Plus staff work with children on projects sometimes water is needed to clean tables, art brushes, hands, fill our water cooler, etc.. I was issued a key when i began at Day Plus, just in case we needed the kitchen for any reason. My access to the school kitchen K-2 is frowned upon by Tabitha manager of kitchen. We do not allow students in the kitchen..

Water

fountains and bathrooms frequently have issues

PI TW

classrooms may need revamped to accommodate working space.

Installation

of dishwashers that are being stored, Biology lab redesign, chemistry room changes, physical science room to have the capability of students performing labs

Keys

to lock classroom built in cabinets are needed

The

maker space in the elementary is amazing, and I know that it will be organized this summer. It would really benefit the students to be able to utilize this space as intended. In addition to teachers using the space, could this be added to the library/art curriculum? For instance, the 3-D printer?

When

a job order is put in, it needs to be completed instead the maintenance leader states things are complete when he has never even started the job

No changes necessary

NA

Work

fine!

Love

to have a poster maker in the library.

ı

mentioned some of these needs in another area. Science labs, industrial tech and more equipment to support career ready graduates. The upper elementary is in need of a science lab and beginning STEM support systems.

No

concern here.

9. ADA

```
25 responses
  good
  Ok
  Great!!
  Playground
  upgrade needed.
  Seems
  adequate but I do not know all of the laws pertaining to ADA.
  None.
  Doors not
  handicapped accessible.
  N/A
  Not
  acceptable.
  have never heard or have seen a problem with it.
  none
  Fine
 acceptable
 I do
 feel our district should implement automatic doors at the entrances of each
 building for students with physical disabilities.
 am not sure on this issue
 have accessibility however our handicap ramp is quite steep
 am unaware of what modifications may be needed.
 I think the elementary is handicapped accessible.
 Needs
 improvement
 think we are good
 NA
```

Handicap accessible doors. (Push Button) Lily Walker has a tough time with some of the doors.

The

elementary and early childhood playgrounds need ADA approved play structures.

No

concern here.

10. Other Long-Range Planning Considerations

30 responses

There is

very little storage room in my building.

Ιt

would be neat if we could buy the land north of the MS.

l and

acquisition so that softball field is on campus.

lt

would be so nice to have a Liberal Arts Performance Center! Also, improve and expand on the outdoor classroom! Have to keep hoping!

None.

N/A

Teacher

check out laptop cart for printing purposes not choosing bids from services used prior that have proven to be ineffective that cost more repairs later on

take

care of what we have better. it has gone down hill since we hired it out. full time custodial staff instead of a revolving part time situation

lt

would be nice to move our playground, elementary. We have people who live in the apartments drive along the fence line, in the grass, and on the field when our students are outside at recess.

none

It would be

nice to one day add an addition between the MS and HS for teachers that are shared between buildings to have their own space, maybe even an auditorium. Our athletic facilities (for specific sports) seem to have been the focus in the past, but we should shift focus to our academic facilities.

May

need to make more space for Project Lead the Way classes. Some of those rooms are not big enough. There needs to be enough space to store materials and supplies as well as have kids build and test their designs. Take another look at

-4---//1---- 1 /C /1/1 TYO 3 (0.00T) TI 4 0 --

the layout of the science rooms. It'd be nice if they had a lecture space and a lab space and a slightly bigger lab prep area for teachers.

would

love to have our new steam table installed this year

1

am very passionate about pushing for a building addition between the middle school and high school. This addition would be the home of these things: MS/HS band room, MS/HS choir room, auditorium/Performing Arts Center, Ag shop, greenhouse, MS science lab, a real MS concession stand (that can be shared for events at the PAC), additional MS lockerrooms (and renovate current lockerrooms), a loading dock for getting things into the building, and maybe even Central Office staff. The MS music room would be free to be converted into a large classroom, or event 2 smaller one. The HS music room would be available for theater storage, show choir rehearsing, or anything else where the platforms would be helpful. I think I've given away who I am now, but having 2 sets of band equipment is going to be difficult to maintain, and sharing with choir is a challenge. If we each had our own dedicated room between buildings, both MS and HS can come to the same location. Furthermore, our HS students who mentor in the MS would no longer have to sign out and travel outside, in all sorts of weather, to get to the MS. That is also a safety concern. I would LOVE the opportunity to help with possible project planning for this, if there is bonding capacity. It's not just about the band, choir and PAC; many people would benefit from this. We would lose the bus lane, but if we pave the one in the rear, that can server our purpose just fine. As you can see, I've put a lot of thought into this. There is a LOT of potential in this district. I hope to see this happen, and I want to help.

There

are some serious plumbing issues especially in the older part of the elementary particularly the 2nd grade classrooms. The sinks do not drain and when they get "plunged" the disgusting mess is left behind and sometimes the plunger is left too.

acceptable

United

States

At

the current time I have 7 middle school children that attend day plus. As long as children get along with students younger than them i believe this would be an avenue to revue in adding 6th grade to our program. It would bring in more funds.. however 6th grade students must be able to have patience with the younger children

Music

Rooms to accommodate both band and music

ok

Gym

Floor/appearance of gym walls/old and dated but that is a huge cost I'm sure.

Change

location of the playground and upgrade

Α

general purpose room, (like the one that was lost to weight room, not a free-standing facility such as the multi-purpose building) - would provide MUCH needed functionality for all content areas, co-curricular classes, special needs students and extra-curricular groups.

An updated playground would be nice! just want to clarify a previous response. Custodial staff at the middle school is exceptional. The maintenance is severely lacking. Many staff members, wether they will put it on here or not, have had tickets marked resolved without anything ever being done. If something is done, it is a long time away from the time of submission. Not at this time am passionate about our playground and am willing to look for grant money, work with the foundation and PTO and anyone else who is willing to take on a project of that magnitude. Also, would it be an option to have our classroom floors waxed every other year. Packing kindergarten room each year is overwhelming and it would be nice to skip years. Maybe a rotational basis. feel that our school district really needs an auditorium for large meetings such as all staff professional development, graduation ceremonies, and music concerts. Love to see a performing arts center. No concern here. Name: _ (Optional) 20 responses Morgan Burks John Jones Sarah Burks⊕ Tobi Chambers Audra Melody Hoffman Dylan Woodall

custodians at the high school do the best they can with lack of help. The head

1 11 11 1 10 1116 270 2 50 2 50

of maintenance has very poor leadership skills.

The

Amy Fennewald

Ewing
alesia
Andy Weldon
R. Brockhaus
Trina Davidson
Andrew Wakeman
Ray Briscoe
Thank you for the survey i believe this is an excellent form of communication, as often times the principal and assistant principal are out together
Robin Eissler
Shelli Tilden
Georgia Jarman

 $This \ content \ is \ neither \ created \ nor \ endorsed \ by \ Google. \ \underline{Report \ Abuse} - \underline{Terms \ of \ Service} - \underline{Privacy \ Policy}$

Google Forms

Playground

who run away a lot preschool playground gates are never on there. One gate has one missing all the time. It isn't safe when we have students often am afraid of falling walking across the parking lot after we have have had bad weather....for days it stays icy...not safe. I wish the sidewalks and parking lots would be covered in ice melt when we have winter storms much earlier than they are. I building. Also the preschool playground seems to be mowed less than other places... Also the carabiner that are to be on the And I know it is hard with timing and such to get ice melt down but it is scary to walk across a sheet of ice to get to the

Playground parking lots

maintained and does not look inviting to guests. The drop off circle drive and entrance could also use some attention. needs like basketball goals and a kickball area. In addition, the landscaping that was put in at the entrance has not been The Elementary playground is in need of a serious upgrade, from equipment repairs, to resurfacing, to additional equipment

districts budget in the long run. Parking lots also need repainted and holes filled Playground needs to be converted to a soft mat rather than woodchips. It would be safer for our students and better for the

Playground needs to be more secure and updated.

Playground with the rubber surface

Playground needs some TLC. The elementary landscaping is not attractive.

Our playground could use a little love. Things frequently break and it takes a while to get it fixed

but we have a lot of kids that play on that each day and right now, several parts of it are unsafe. Elementary playground needs some love and attention. Possibly new equipment and new surfacing? Know that's expensive

overflows and the gate normally doesn't latch to being broke. The playground and sidewalk to our playground sometimes is not well mowed. The trashcan on the playground sometimes

also like some new equipment. Playground: I would love to see a different playground covering rather than the mulch, grass, and blacktop. Students would

has been a tripping hazard. Update painted lines on black top. n]] Elementary playground is not in an ideal location, however, not sure where it could move to. Landscape fabric around tree

would be to have a tall, privacy fence on the parking lot side of the playground. An additional thought is to open the through the field when the kids are playing outside, and parents have come to the fence to talk with their kids. One suggestion playground up to the field area to create a fenced in kickball course. With regard to the playground, balls constantly go over the fence, into the parking areas. Cars will go past, or even drive

dips/holes fixed for safety. Playground: updated outdoor equipment, woods chips properly laid, gates on playground that properly work. Driveways:

We need to move the playground. It is a safety issue

keep the balls in and outside adults out. I also believe we need some way to separate the field due to cars driving in the field concern due to it is injuring students if they fall and is hard to manage. to get to their apartments. We would really benefit from having basketballs or some activity on the court. The mulch also is a The playground needs to be more kid friendly. I believe that the playground would benefit from a tall privacy fence to help

willing to help in anyway. equipment is expensive, but this area needs to be a priority. Mulch and loose rock are most always on the asphalt area and improve this. There are areas that are not safe for students and I feel very passionate about this being resolved and would be pieces on them. The matting under the mulch has been coming out for the past 3 years and no attempt has been made to numerous students are injured due to falls because of this. Much of the equipment is old. A few of the swings have sharp The elementary playground is a very sad representation of our district. Over 500 students use the facility daily. I understand

It would be WONDERFUL to have a new playground!!

Playground at the Elementary needs updated with new, safe equipment and all-weather flooring (no more wood chips!!)

other than grass so it can be used more, maybe add an outdoor classroom that can be booked. Would love to have an performing arts center--maybe connecting the HS and MS. A lot of focus and \$ seems to go to sports. The playground surface needs to be updated and it would be nice to have surface under the picnic tables at the middle school

School and Middle School parking lots behind schools need to be paved - not gravel. Central Office back patio needs to be Parking lots need paved/striped. Playground needs to be surfaced. Landscaping at middle school and elementary. High

Playground upgrade needed.

the grass, and on the field when our students are outside at recess It would be nice to move our playground, elementary. We have people who live in the apartments drive along the fence line, in

An updated playground would be nice!

else who is willing to take on a project of that magnitude. l am passionate about our playground and am willing to look for grant money, work with the foundation and PTO and anyone

overwhelming and it would be nice to skip years. Maybe a rotational basis Also, would it be an option to have our classroom floors waxed every other year. Packing kindergarten room each year is

Change location of the playground and upgrade

Playground upgrade needed

The elementary and early childhood playgrounds need ADA approved play structures.

Parking Lots

They have gotten better this year, looks very nice, except parking lots and driveways which are worse.

I wish the sidewalks and parking lots would be covered in ice melt when we have winter storms much earlier than they are. I often am afraid of falling walking across the parking lot after we have had bad weather....for days it stays icy...not safe. And I know it is hard with timing and such to get ice melt down but it is scary to walk across a sheet of ice to get to the building. Also the preschool playground seems to be mowed less than other places... students who run away a lot. Also the carabiner that are to be on the preschool playground gates are never on there. One gate has one missing all the time. It isn't safe when we have

Playground parking lots

times, no beautification at all. The circle drive has potholes, parking lot has potholes and is not cleared adaquately in the winter. We had several people Walkways are pretty run down near the older part of the elementary. The landscape of the older part of the building is not up to par; trash and unmowed (children and almost some adults) fall because of ice under the pavilion at the parent drop off area.

Parking lots also need repainted and holes filled. Playground needs to be converted to a soft mat rather than woodchips. It would be safer for our students and better for the districts budget in the long run

I think more could be done to make sure the parking lots and roads around the school are cleared before we get to school

cleaning sidewalks when there is snow and to the kitchen doors to and the sidewalk from the high school staff parking and the elementary doors

With regard to the playground, balls constantly go over the fence, into the parking areas. Cars will go past, or even drive through the field when the kids are playing outside, and parents have come to the fence to talk with their kids. One suggestion would be to have a tall, privacy fence on the parking lot side of the playground. An additional thought is to open the playground up to the field area to create a fenced in kickball course.

If anything, I think the parking lot could use some work, but it isn't horrible.

Need rock behind high school, when it rains that parking lot becomes mud hole.

cracks and water in parking lot; snow removal in parking lot better, not creating mounds to walk through

Parking lot should probably be sealed to make it last longer

Parking lot behind high school needs attention due to ruts

It'd be nice if the lots behind the high school were paved over instead of gravel. While it's fun playing dodge the potholes in the elementary drop off/pick up drive, those need to be fixed. The high school student parking lot could be leveled. Track could be redone.

gravel. Is that going to get fixed? The main parking lot is deteriorating quickly, with pot holes, dips, waves, etc. And a large section of concrete was cut out in the bus lane and filled with

The HS parking lot and bus lanes need to be repaved. The front of the high school has curbing falling apart. The drive in front of Day Plus is horrible

At least one street light in HS parking lot (east end) has been non-operational for quite some time

A more outdoor "classroom" friendly environment. Perhaps some kind of permanent seating and shaded area

Parking lot lines are faded

Our custodians did the best they could to keep the sidewalks free from ice, but sometimes the parking lot didn't even look like it had been touched. The only thing I have noticed being inadequate with the facilities that I come into contact with is the snow removal in the parking lot at the middle school.

The middle school parking lot could use a little love.

The facilities within the district are of high quality. I have visited many other schools and I think the Holden campus is better than most. The largest area of improvement is the parking lots. The high school parking lot is an obvious area of improvement. I also feel like the middle school parking lot could be

Big potholes in parking lot. Where they were fixed with concrete, the concrete came loose and flipped up hitting my car.

I feel like these areas are ok, but the high school parking lot is pretty rough.

Unsure of how we could do it but moving the javelin area closer have been mentioned as a need. We need to begin to "save" for future parking lot maintenance. The track and field - field events areas could use some water drainage improvement.

High School Gym Floor-Evaluate and place in long range plan for refinish/replacement as needed.

lots behind schools need to be paved - not gravel. Central Office back patio needs to be fixed. Parking lots need paved/striped. Playground needs to be surfaced. Landscaping at middle school and elementary. High School and Middle School parking

Parking lot needs new parking spaces. Lines are faded and hard to see.

Roots / Leaks / Tiles

Roofs

There a several areas in the Elementary where the roof leaks.

ceilings that leak through the light fixtures. Isn't that a fire hazard? The roof of the canopy at the parent drop off is unpainted. The repairs of this structure were below par. The patio was left with holes or unsightly crevices which is also a tripping hazard. In many parts of our building we have leaky ceilings; really leaky

where the roof has leaked. Restrooms in the older areas of the Elementary building need renovated. Carpeted classrooms need an upgrade, as do the paint colors in the Elementary hallways. Ceiling tiles need replaced in areas

Still have leaks inside with heavy rain.

Roof that doesn't leak

The leaking roof in the elementary library has gotten better with the numerous repairs, but there are still leaks

windows). I am not sure how it accumulates there. them constantly. I have. I am not sure where it comes from. I also have dirt on the metal part of the windows (when I open up my I have titles in my room that have water spots on them, and they have been like that for two years. The window seals have dirty in

Leaks in ceiling causing mold issues for allergies

The roof on the older part of the elementary leaks - a lot!

Ceilings in the older part of the elementary need work from water damage.

I know you are aware of the various roof leaks and are working towards resolving the problem.

The floor tiles are falling apart or coming loose already.

don't know if this is the place to put this but I don't know where this would be appropriate to put it.

cafeterias clean and still keep up with the unexpected spills or messes in the entire school by herself. I feel Karen Parks works hard to keep up with 6 lunch duties in 2 cafeterias during the day. She manages to get 2 large

the trash cans or the floors are still dirty. This didn't happen when Tina Crust was here. She took pride in her areas. The night custodians don't work as hard as she does and there are 3 of them. I have come into my room and still have trash in

Ceiling in Elementary office leaks into the girls bathroom

students water fountain in the K-2 cafeteria has been non functioning for 2 years. i believe parts were purchased however still not placed to catch the water when it rains. Furniture such as tan shelf needs to be moved out of k-2 cafeteria to surplus. The working. Student bathrooms do not have warm or hot water to wash their hands, this would be a health issue Girls bathroom ceiling is about to come down, bad leaks in the girls bathroom and in hall next to girls bathroom leaks. Buckets are

There are several leaks that have left tiles looking nasty.

We constantly have leaks throughout the building... mostly 2nd grade hallway

Because of the leaking, some of the ceilings look rough / trashy. Tiles have fallen down, too.

floor and people have fallen and slipped many times. This includes teachers, kids, and parents. The roof leaks around the window outside of Mrs. Walter's door. It has leaked for several years. It leaves larger puddles on the

Ceilings: We have a leak in the first grade hallway, we also had a safety problem in the second grade bathroom regarding chipping/leaks, which has been shut down for months. The floors are amazingly waxed, Thank you! Walls: A fresh coat of paint would be nice! Other appearances that need work: All the cords and wires from Technology is disappointing. They are visible and hanging out everywhere.

also have a HUGE problem with ROACHES! It's terribly disgusting and distracting to be teaching a math lesson and while the untouched, but we still don't feel comfortable wondering if we are breathing in something that will eventually cause problems. We kids are looking at the math wall.....a big, fat roach saunters across my hundred number chart. Ugh...Please and Thank you. The 2nd grade hallway leaks under the skylight. We also are concerned with the asbestos ceilings. We're told it's safe if

My classroom roof leaks and has for the past 2 years. Still leaks when it rains hard. Room 109

There are walls in the elementary that are cracked. You can see the classroom next door through the cracks

covered with paper. Ceiling tiles honestly are bowed and look filthy and are water stained. The walls in my room are so unpresentable they must be

There are ceilings in the elementary classrooms and library that leak and have noticeable water stains

we need roofs that don't leak!!! Every time it rains we are ruining district equipment, student work, etc.

Leaking roof

Roof leaks everywhere

Some leaks in the roof.

Tiles missing from ceiling or damaged from leaks.

Leaking roof.

Fix ceiling tiles. Some of the bathrooms could be updated and the stalls painted over.

roof at the school

Ceilings still have water stain, lights has sitting water in them.

Paint frame around windows in classroom doors; replacing ceiling tiles when they are removed

Cracks in wall to the outside world in classrooms; lack of insulated walls; many ceiling leaks

Roof leaks in several classrooms at the high school "unacceptable".

some areas of the roof still leak

Several leaks in roof causing issues inside classrooms

The roofs need major fixing to fix the leaks

The roof is a major concern. Dana had to move desks because of the leaking roof. Buckets all over the place when it rains

The security of the doors the magnetic strips are wearing and lock always locking properly, Fixing the roof properly until it can be

Cracks in walls and floors (even newer construction) Stained ceiling tiles make a terrible impression, they look awful - but the leaking roof stains whatever is replaced

Roof leaks in MANY areas of high school.

Some of the rooms need roof repair

There are leaks. There has been a bucket in middle of hallway by lunch area for quite a long time.

industrial/prison-like with more open areas. Lots of ceiling tiles are water stained. We could do some interior work to make our buildings look more modern/homey and less

Middle school still has some areas that leak.

When it's rainy, there are some leaks right next to my door (Room 301) in the Middle School. This is very distracting when it rains.

We need to begin to "save" to redesign and install newly designed roofing when the current flat roofs need replacement.

Roof leaks in all buildings need to be repaired.

Painting - elementary. Ceiling tiles replaced. Wiring in elementary needs to be in conduits in 2nd grade hallway. Bathrooms at the high school and elementary need to be remodeled. Elementary bathrooms are in disarray.

Several roofs have needed patching. All three large buildings seem to need additional work.

Leaks in roof when it rains.

new roofs are needed

TEMPERATURE / MECHANICAL SYSTEMS

gets hot. It is always one extreme temperature or the other. An updated HVAC system. In the first grade classrooms, when the AC comes on it blows extremely hard and blows things off our walls, and when it's off, it

Hot water does not reach science rooms or does all sinks work in all science rooms even after requests

HVAC systems at MS (It's either freezing or super hot and it varies between classrooms). It would be nice to control our own room temperature within a

HVAC: My room is either freezing or really hot

teachers get here. There are times where I would come in and my room be 58 if over the winter the temperature in the classrooms is going to kick down below 60 over night then have it kick back up before students and

More control over classroom temperature would be appreciated.

I'm curious about the overall energy efficiency of the physical plant.

Motion activated lights? Or some kind of mechanism (glow in the dark switch plates?) in dark conditions that indicate light switch locations.

Need to be able to control temperature of classrooms.

Our rooms are either freezing or hot. Make you feel bad if you 'complain'

Seems like the temp in the MS is always too hot or too cold.

Temperature can be same as weather. Hot outside, and hot inside. Cold outside and cold inside.

Temperature control is poor

would prefer that this get fixed over the summer if possible. The 6th grade team thermostat and Tobi Chamber's 7th grade room are all connected and when it's really hot it's REALLY hot. (Vice Versa for cold). I

The building is either cold, hot and the roof leaks!!

The HVAC in the middle school seems unreliable/temperamental. All classrooms seem to run on a different temp and are at times way too

a few days ago it was 67 degrees while students were map testing. There seems to be no working vents in the SSC either and the room is very cold in the winter. The temperature control in the middle school needs some work. One day this winter it was 88 degrees Fahrenheit in my classroom, and just

fingers are frosty (e.g. SSC, Chambers). Other rooms can be stifling hot (e.g. Orton). It's very unpleasant for staff and students. The office area/rooms are usually adequate. There is a WIDE variety of temperatures across classrooms. Some of them are SO cold that student computers are cold to the touch and

TECHNOLOGY - ELECTRICAL SYSTEMS

Adjustable lighting would be nice in the classrooms and I need technology infrastructure to hook up a desktop computer for student use in my

Announcements are not heard in either of the cafeterias. This is a major safety issue when a grade is at lunch, and we go on lock-down.

video on devices; extra charging devices Difficult to hear announcements- sounds muffled; phones showing correct time and in coordination with bells; students being able to record

Electrical outlets for ever-increasing technology needs are inadequate

SIS needs more functionality at the instructor level.

Not sure how robust the network is for future growth.

infrastructure. Intercom system - can't hear in the classroom when sound comes through phones only. Very happy with data system and technology

Intercom system needs some work - especially with cafeterias and gym. Can't hear announcements in those locations.

Intercoms in the hallway are hard to hear.

Louder intercom through the phone or put in an intercom system that we can hear

or intercom. Rewiring in order to achieve needed electricity may be needed, especially in older buildings. Secure data systems are a must. Technology infrastructure is an ongoing concern. All parts of each building should be accessible by phone

Technology department is good

Technology goes in and out. No fault of our tech team though. Internet is just not great in rural areas. Also, it seems MS students have problems moving from classrooms with their devices or keeping them safe in their lockers and at home. Maybe switch to where each class have a classroom set instead of individual ones.

to teach when I was planning to use apple tv to connect my device for class The technology seems to work well most of the time. However, this year Apple tv has had lots of issues in my classroom. This makes it hard

phone when having students at the opposite end of the library. It would also be difficult to hear intruder location updates from the library hiding place (RTI library room). There is only one phone at one end of the library. The library is a very large space. It is difficult to hear announcements made over the

CAMERAS, DOORS, SAFETY

alarm system for day plus program had been needed for quite sometime superintendent made it happen. a camera was placed in classroom, however monitors if any were supposed to be in place, are not.

As mentioned above, keypad/fob entry on all doors would be an extra safety feature.

Bullet-proof glass in doors and windows; viewing cameras in parking lot

cateteria area install more cameras and update other cameras Door access/locking system--the doors do not always secure themselves and a real safety concern, bullet proof glass in the front entry and

Doors with vertical viewing area instead of complete window

Double doors by the 2nd grade hallway do not lock properly. This has been a concern for a long time.

Exterior doors do not always shut and latch on their own which is a safety concern

place to keep them open. Fob doors need to be checked frequently to check latching. Consequences needs to be in place when teachers prop doors, put magnets in

I feel that there needs to an extra lock on the doors of the Data Room that are used for a safe room

I'd like to see more security cameras and/or better quality as a way to better monitor students and to investigate reports of bullying, etc.

It is very inconvenient that all doors have key fob entrances. Such as the 1st and 5th grade doors.

spots in the elementary building where there are no cameras or the cameras cannot see all the way down the hall and what not. is hard to see what really happened because the cameras cannot see what is going on or they are too far away. I also know there are some It might be nice to have better placements for the cameras on the play ground. Sometimes we have serious issues, and no stories add up. It

kitchen back door is very hard to open, might be a problem in case of emergency

library in the H.S. needs new entry doors. there are dead zones for the cameras also

Many teachers prefer to use the door in the first grade hallway. It does not have a key fob. It would be nice if it did

Middle school needs a secure entry and all vestibules should have security glass. More cameras in middle school and elementary.

Several doors do not close tightly unless slammed. Need keyless entry points at locations currently without.

Sometimes the double doors lock in our wing and sometimes they don't.

Upgrade security cameras for better picture. Don't let people prop open back doors.

look at this. The recess door the faces the ball field often gets pea gravel in the threshold and keeps the doors from locking. PLEASE Work orders and suggestions have been made regarding door locking and safety in the elementary building. We really must take a serious

I would like to request a key fob entry for the end of the first grade hallway.

Safety entryway for the middle school like the other buildings

SCIENCE LABS

Science lab stations are not being treated in timely manner. Room 102 has unreliable gas valves preventing the use of the stations

Science rooms in performance parkway need safety showers and proper cabinets to store more caustic chemicals such as various acids. The sinks in the were redesigned in ways where kids could be more mobile. two science rooms down across from the band hall should be looked at. Pressure is inconsistent and the faucets leak. It would be nice if the science rooms

performing labs Installation of dishwashers that are being stored, Biology lab redesign, chemistry room changes, physical science room to have the capability of students

The traps under the sinks in science classrooms are never cleaned.

science sinks smell and eye sprayers do not work

more closely reflect real-world labs. flexible seating options that facilitate greater collaboration (for students and staff) would be ideal. Science labs could use updated areas and equipment to I'm not sure if furniture fits into this category, but a vast majority of our desks/tables/chairs are dated and have to continually be repaired. More modern and

elementary is in need of a science lab and beginning STEM support systems. I mentioned some of these needs in another area. Science labs, industrial tech and more equipment to support career ready graduates. The upper

DOORS (ADA)

Doors not handicapped accessible.

I do feel our district should implement automatic doors at the entrances of each building for students with physical disabilities. Handicap accessible doors. (Push Button) Lily Walker has a tough time with some of the doors.

The elementary and early childhood playgrounds need ADA approved play structures.

MUSIC, LAND, MULTIPURPOSE, OTHER

Land acquisition so that softball field is on campus.

on the field when our students are outside at recess. It would be nice to move our playground, elementary. We have people who live in the apartments drive along the fence line, in the grass, and It would be so nice to have a Liberal Arts Performance Center! Also, improve and expand on the outdoor classroom! Have to keep hoping!

not drain and when they get "plunged" the disgusting mess is left behind and sometimes the plunger is left too. There are some serious plumbing issues especially in the older part of the elementary particularly the 2nd grade classrooms. The sinks do

be able to have patience with the younger children believe this would be an avenue to revue in adding 6th grade to our program. It would bring in more funds.. however 6th grade students must At the current time I have 7 middle school children that attend day plus. As long as children get along with students younger than them i

An updated playground would be nice!

willing to take on a project of that magnitude. I am passionate about our playground and am willing to look for grant money, work with the foundation and PTO and anyone else who is

Also, would it be an option to have our classroom floors waxed every other year. Packing kindergarten room each year is overwhelming and it would be nice to skip years. Maybe a rotational basis.

I feel that our school district really needs an auditorium for large meetings such as all staff professional development, graduation ceremonies

It would be neat if we could buy the land north of the MS.

Teacher check out laptop cart for printing purposes. not choosing bids from services used prior that have proven to be ineffective that cost more repairs later on

space to store materials and supplies as well as have kids build and test their designs. Take another look at the layout of the science rooms May need to make more space for Project Lead the Way classes. Some of those rooms are not big enough. There needs to be enough take care of what we have better. it has gone down hill since we hired it out. full time custodial staff instead of a revolving part time situation It'd be nice if they had a lecture space and a lab space and a slightly bigger lab prep area for teachers.

get to the MS. That is also a safety concern. I would LOVE the opportunity to help with possible project planning for this, if there is bonding district. I hope to see this happen, and I want to help one in the rear, that can server our purpose just fine. As you can see, I've put a lot of thought into this. There is a LOT of potential in this capacity. It's not just about the band, choir and PAC; many people would benefit from this. We would lose the bus lane, but if we pave the and sharing with choir is a challenge. If we each had our own dedicated room between buildings, both MS and HS can come to the same for getting things into the building, and maybe even Central Office staff. The MS music room would be free to be converted into a large classroom, or event 2 smaller one. The HS music room would be available for theater storage, show choir rehearsing, or anything else where location. Furthermore, our HS students who mentor in the MS would no longer have to sign out and travel outside, in all sorts of weather, to the platforms would be helpful. I think I've given away who I am now, but having 2 sets of band equipment is going to be difficult to maintain, concession stand (that can be shared for events at the PAC), additional MS lockerrooms (and renovate current lockerrooms), a loading dock these things: MS/HS band room, MS/HS choir room, auditorium/Performing Arts Center, Ag shop, greenhouse, MS science lab, a real MS am very passionate about pushing for a building addition between the middle school and high school. This addition would be the home of

Gym Floor/appearance of gym walls/old and dated but that is a huge cost I'm sure.

Change location of the playground and upgrade

A general purpose room, (like the one that was lost to weight room, not a free-standing facility such as the multi-purpose building) - would provide MUCH needed functionality for all content areas, co-curricular classes, special needs students and extra-curricular groups.

There is very little storage room in my building.

academic facilities. maybe even an auditorium. Our athletic facilities (for specific sports) seem to have been the focus in the past, but we should shift focus to our It would be nice to one day add an addition between the MS and HS for teachers that are shared between buildings to have their own space,

would love to have our new steam table installed this year

a long time away from the time of submission. members, wether they will put it on here or not, have had tickets marked resolved without anything ever being done. If something is done, it is I just want to clarify a previous response. Custodial staff at the middle school is exceptional. The maintenance is severely lacking. Many staff

Love to see a performing arts center.

Music Rooms to accommodate both band and music

Appendix C)

ELEMENTARY				
1. Site	2. Building Exterior/Envelope	3. Building Interior	4. Educational Adequacy 5. Mechanical Systems	5. Mechanical Systems
#4 Playground- Equipment Repairs, Resurfacing, More secure	#2 Roof Repair	Continue Painting Project - Classrooms and Hallways	Larger Classrooms	#3 HVAC Systems- Temperature Control
Parking Lot Repair	Drop off canopy and entrance upgrade, Exterior door frames and roof edge trim need painting	Replace Ceiling Tiles	Redo Stage	Water Fountain in K-2 Cafeteria & 2nd Grade Hall
Parking Lot Painting	Skylight Repair	Clean up wire troughs in Hallways and Classrooms- Drop Ceiling		Classroom Sinks- Plumbing, Sink Traps
Circle Drive Repair	Sealing of Brick/Mortar	Floor Tile Repair		Refrigeration Units
Walkway Repair	Powerwashing outside walls	Foundation Repair		
Landscaping	West exterior wall below the brick line has sizable gouges	Wall Cracks Repair		
Bus Loading Area Water Retention Repair	Bus Loading Area Water West side (first grade hall) Retention Repair door water damage to the brick.			

ELEMENTARY				
6. Electrical Systems	7. Safety	8. Equipment	9. ADA	10. Other Long-Range Planning Considerations
#5 Classroom Electrical Capacity	#1 Upgrade Intercom System		Automatic Doors	On campus softball field.
Technology Infrastructure - New Instructional Technology	Upgrade Camera Systems		Day Plus Handicap Ramp	Perfoming Arts Center - Large Auditorium
Lighting Upgrades/Efficiency - LED, Automatic On/Off, Dimming	Investigate Door Locking Systems			Outdoor Classroom
	Fob More Doors			
	Outside Door Repair- Locking			
	Entrance Upgrades			

MIDDLE SCHOOL				
1. Site	2. Building Exterior/Envelope	3. Building Interior	4. Educational Adequacy 5. Mechanical Systems	5. Mechanical Systems
#9 Parking Lot Repairs/Painting	#6 Outdoor Tile Repair	STEAM Lab Flooring	Flexible classroom space	#2 Heating/Cooling - Temperature Conrol Systems
Outdoor Classroom Area Door Repairs- Weather stripping, Key fobs	Door Repairs- Weather stripping, Key fobs	Repair around windows	Science Lab Space	Hot Water Heater Upgrade
Front Landscaping	Leaks around roof drains- Ceiling tile replacement	#10 Gym floor refinished		
Paving Bus Drive & Back Lot	Foundation Repairs	Gym repainted		
Bus Loading Area Water Retention Repair	#8 Sidewalk Leveling	#4 Locker Room lockers refinished & reconfigure		
Sidewalk Leveling	#7 Brick Mortar Repairs	Painting- continue		A CONTRACT RESIDENCE PROPERTY CONTRACT OF SECURITY AND ADDRESS OF SECURITY ADD
Front Sign	Solar Lights	Restroom Sinks		
Storage on old Trash Receptical Area		Boys Locker Room Shower remodeled		
		Floor Tile Separation	The second section of the second section is a second section of the second section of the second section secti	
		Window in Steam Lab		
		Partial in Technology Storage		
		Folding Wall to hide recycle bins		
		Serving window in School Store		
	The second secon	Shelving in Art and Band		

MIDDLE SCHOOL		The second state of the second state of the second		
6. Electrical Systems	7. Safety	8. Equipment	9. ADA	10. Other Long-Range Planning Considerations
#3 Lighting Upgrades/Efficiency - LED, Automatic On/Off, Dimming	#1 New Middle School Entrance and Office Remodel	Flexible Seating	Automatic Doors	Additional Storage
Electrical Repairs and Upgrades in Kitchen and Commons	Upgrade Camera Systems	Hook up Middle School Kiln and ventilation	#5 Restroom for Resource Room	Addition betwen MS and HS - PLTW, Music, Performing Arts Cenfer
Technology Infrastructure - New Instructional Technology	Upgrade Intercom Systems	Kitchen for Resource Room & New Floor		
	Investigate Door Locking Systems			
	Eye wash stations in Science Rooms			
	Secure Windows			
			A STATE OF THE PROPERTY OF THE	mention of the control of the contro

нен ѕсноог				
1. Site	2. Building Exterior/Envelope	3. Building Interior	4. Educational Adequacy 5. Mechanical Systems	5. Mechanical Systems
#3b Repair Front Parking Lot	#1 Roof Repair	Old Restroom Renovations - Floor	#6 Remodel Science Room for Chemistry Lab	#2 HVAC Systems- Temperature Control
#3a Pave/Gravel Back Lot	Repair Cracks in Outer Wal	Replace Ceiling Tile	More of the bigger individual desks	Hot water in Science Rooms
Repair Bus Lane	Door Locks Repair	Paint Suspended Ceiling Grid in Lobby Area	#10 Mental Health Facility with secure outdoor entrance for families	Plumbing in Science Rooms
Outdoor Classroom	Retile #7 Foundation Repair on WI floors	Retile some classroom	offee shop to old ion stand area	AC Units in Technology Switch Rooms
#11 Water Retention Areas Fixed by Track/Football Field	Paint frar classroor More energy efficient windo windows	Paint frame around classroom entry windows		Restroom Plumbing Repair
Low Areas by Shot put and discus	Solar lighting	#4a Paint Gym	Reposition Mounted Projectors	Gas valves in science rooms
Parking Lot Lights	Sidewalk from White Mile to	#4b Redo Gym and Stage Floor	Redesign Performance Parkway Science Rooms	Ag Heating and Cooling
Prevent roof access in back of the high school	Drainage off White Mile	Continue Painting Project		Updated Water Fountains
To the later of th	#9 Remodel In Window Repair on White Mi Locker Rooms	#9 Remodel Indoor Locker Rooms		
	Removal of Effervescence 8 Ag/PLTW Area	Repair and Paint Ag/PLTW Area		
		Redo counter in office to accomodate counseling secretary sitting in front		
		#7 Hall of Fame Foundation	1	The second secon
		Tile on Exit Door on the east end of the White Mile, Blue Blvd, and Ag Entrance		
		Locker Removal in Tech Hallway		
		Refurbish/Replace Older Lockers		And the state of t
			and the second control of the second	The state of the s

нен эсноог				
6. Electrical Systems	7. Safety	8. Equipment	9. ADA	10. Other Long-Range Planning Considerations
#8 Lighting Upgrades/Efficiency - LED, Automatic On/Off, Dimming	#5 Entrance Updgrades - Secretary window, bullet resistant glass	Install already purchased dishwashers in Mail room and indoor concession stand	Automatic Doors	Addition betwen MS and HS - PLTW, Music, Performing Arts Center
Technology Infrastructure - New Instructional Technology	Upgrade Camera Systems	Additional Sink and Handwashing Station in FACS Room	Updated Water Fountains	Purchase land north of MS
Classroom Electrical	Upgrade Intercom Systems		Handicap Station in Science Room	More space for PLTW classes
Lightning Rods	Investigate Door Locking Systems		Handrails in more restroom stalls	General Pupose Room
Building Clock System	Make cafeteria more secure for safety - outside windows			On campus softball field
Update Electrical Panels for Sports Fields	Safety showers in science rooms on Performance Parkway			
Gym Lighting Control	Proper cabinets for chemical storage			
	Library Doors			
	Fob More Doors			
	Classroom Entry Glass			
	Library Window Lock			
	Number the outside of all windows and doors			
			167700 - 41300000 C 27	THE STREET STREET STREET STREET STREET, STREET STREET, STREET STREET,

4. Educational Adequacy 5. Mechanical Systems	ooms HVAC Systems- Temperature Control	Water Fountain in K-2 Cafeteria & 2nd Grade	Classroom Sinks- Plumbing, Sink Traps				To the second se	
4. Educationa	Larger Classrooms	Redo Stage	3003 1 0	,			11 **	
3. Building Interior	Continue Painting Project - Classrooms and Hallways	Replace Ceiling Tiles	Clean up wire troughs in Hallways and Classrooms	Floor Tile Repair Foundation Repair	Wall Cracks Repair			** ** *
2. Building Exterior/Envelope	Roof Repair	Drop off canopy and entrance upgrade	Skylight Repair			i i		
1. Site	Playground- Equipment Repairs, Resurfacing, More secure	Parking Lot Repair	Parking Lot Painting	Circle Drive Repair Walkway Repair	Landscaping Bus Loading Area Water Retention Repair			٧

Safety	Upgrade Camera Day Plus Handicap Perfoming Arts Center - Systems Large Auditorium	Investigate Door Locking Systems	Fob More Doors Outside Door Repair- Locking		
6. Electrical/Systems. Classroom Electrical	Technology Infrastructure - New Instructional Technology	Lighting Upgrades/Efficiency - LED, Automatic On/Off, Dimming			

.5. Mechanical Systems	It is ok.	·No concerns	: This seems to be good in my areas.	e e e e e e e e e e e e e e e e e e e	Working drinking fountains
4. Educationall Adequacy	Great in the elementary!	Good spaceIIII No concerns			Bigger classrooms
e: pullang interior	Looks great!	All of it Good spacel Carpeted classrooms need an upgrade, as do 'No concerns the paint colors in the Elementary hallways. Ceiling tiles need replaced in areas where the roof has leaked. Restrooms in the older areas of the Elementary building need renovated.	The older part of the building is very dreary in many of the classrooms because of the condition of paint. Also, the wires that hang out all over the place in the older part of the building is a bit ridiculous.	The elementary is very boring and bland inside. It would feel much cozier with warm colors on the walls. It would also be important to replace the ceilings in the old part of the building so that we can actually have up to date projectors. The rest of the building received new ones but since our ceilings have asbestos we get stuck with the crappy ones.	Bathrooms that work and classrooms that don't have leaks/bugs
	Everything is fine but it would be great to have key fabs on the remaining doors in our building.	Roofs There a several areas in the Elementary where the roof leaks.	The roof of the canopy at the parent drop off is unpainted. The patio was left with holes or unsightly crevices which is also a tripping chazard. In many parts of our building we have leaky ceilings, really leaky ceilings that leak it through the light fixtures.	า 1 เกียร์ การการแบบ with heavyrain	
		Playground parking lots The Elementary playground is in need of a serious upgrade, from equipment repairs, to resurfacing, to additional equipment needs like basketball goals and a kickball area. In addition, the landscaping that was put in at the entrance has not been maintained and does not look inviting to guests. The drop off circle drive and entrance could also use some attention.	Walkways are pretty run down near the older part of the elementary. The landscape of the older part of the building is not up to par. The circle drive has potholes, parking lot has potholes.	und needs to be converted to a soft er than woodchips. It would be safer tudents and better for the districts in the long run. Parking lots also need d and holes filled.	

5. Mechanicali Systems	Need to be able to control temperature of classrooms.		An updated HVAC system. In the first grade classrooms, when the AC comes on it blows extremely hard and blows things off our walls, and when it's off, it gets hot. It is always one extreme temperature or the other.			Our sinks in the 2nd grade rooms don't drain properly. This causes them to become coated in mold.
4. Educational Adequacy.		The classrooms are great, however in future planning, single desks would be more functional and aid in classroom management and planning.	The space in our rooms are excellent compared to other schools!			
3. Building Interior			Ceilings: We have a leak in the first grade hallway, we also had a safety problem in the second grade bathroom regarding chipping/leaks, which has been shut down for months. The floors are amazingly waxed, Thank you! Walls: A fresh coat of paint would be nice! Other appearances that need work: All the cords and wires from Technology is disappointing. They are visible and hanging	out everywhere.		The 2nd grade hallway leaks under the skylight. We also are concerned with the asbestos cellings.
-ZBuilding:Exterior/Envelope The state of the set of		The door by the 5th grade hallway does not lock unless it is slammed. This is a safety concern, as people have been able to walk in those doors. I would also suggest keypad/fob entries on every door as a safety feature.	Secure any roof building leaks.			
Playground: I would love to see a different I would love to see some color on the playground covering rather than the mulch, irather than all white, grass, and blacktop. Students would also like some new equipment.	Elementary playground is not in an ideal location, however, not sure where it could move to. Landscape fabric around tree has been a tripping hazard. Update painted lines on black top. n]]	With regard to the playground, balls constantly go over the fence, into the parking areas. Cars will go past, or even drive through the field when the kids are playing outside, and parents have come to the fence to talk with their kids. One suggestion would be to have a fall privacy fence on the parkinn lot have a fall privacy fence on the parkinn lot	# g	We need to move the playground. It is a safety issue.	The playground needs to be more kid friendly. I believe that the playground would benefit from a tall privacy fence to help keep the balls in and outside adults out. I also believe we need some way to separate the field due to cars driving in the field to get to their aparaments. We would really benefit from having basketballs or some activity on the court. The mulch also is a concern due to it is injuring students if they fall and is hard to manage.	

5: Mechanical Systems. The heating and cooling in my room has not worked properly on and off this year. The girls bathroom in the old part of the elementary has been out of order for several months. Unless you are in the classroom, you may not realize how this takes away from instructional time and causes behaviors to send students down to the new part of the building.	Work great!	÷ .	One of the sinks in the art room hasn't drained properly since March of 2017. Another has started having trouble this spring.		Plumbing seems to be a problem in the older part of the building in the student bathrooms.	
10es.	3-5 need bigger classrooms with the bigger kids and larger class sizes. The K-2 classrooms are larger and they have smaller kids, smaller class sizes.					
4. Educational Adequacy. Ceiling tiles honestly are bowed and look filthy Technology is great, however, there are and are water stained. The walls in my room unpresentable wires hanging in many place so unpresentable they must be covered with paper.	There are ceilings in the elementary classrooms and library that leak and have noticeable water stains.	There are areas of the building that the floors appear to be sinking and separating from the walls. This is also a problem when animals find their way into the building (snakes etc.)	Third grade decorates their hallways each year with their incredible, multi-disciplinary blome projects. It's a huge deal - something their students will remember forever. I think it would be amazing if we could paint the would be amazing if we could paint the backgrounds for their blomes (ocean, rain forest, arctic tundra, desert, etc.) as a permanent part of our building decor. It would be beautiful and welcoming AND a great teaching tool.	The foundation is shifting at the "new" end of the elementary. The art room counter tim is separating from the counter top as the floor shift downwards. It's not a big deal yet, but I know my former classroom (141) is having more serious issues.	Lots of places and classrooms need painting. The student bathrooms in the old part of the building are really gross and not pleasant to even peek your head into.	Leaks in ceiling causing mold issues for allergies
My classroom roof leaks and has for the past 2 years. Still leaks when it rains hard. Room 109	There are walls in the elementary that are cracked. You can see the classroom next door through the cracks.					
The elementary playground is a very sad representation of our district. Over 500 students use the facility daily. I understand equipment is expensive, but this area needs to be a priority. Mulch and loose rock are most always on the asphalt area and rumerous students are injured due to falls because of this. Much of the equipment is old. A few of the swings have sharp pieces on them. The matting under the mulch has been coming out for the past 3 years and no attempt has been made to improve this. There are areas that are not safe for students and I feel very passionate about this being resolved and would be willing to help in anyway.	It would be WONDERFUL to have a new playground!!		I often wonder if we could add a small playground just outside the E. Main Street doors (east of the building). Drainage is already an issue. It gets super muddy when it rains. If we need to fix that (and we're dreaming years ahead), let's put in a playground or something for kids to do if they finish lunch early.		Playground needs some TLC. The elementary landscaping is not attractive.	

5- Mechanical (Systems.	poob
4. Educational Adequacy ut to come down, space for program is adequate, om and in hall Buckets are en it rains. The e K-2 cafeteria 2 years. Student n or hot water to be a health issue	pood
3. Building Interior if Educational Adequacy girls Girls bathroom ceiling is about to come dwm, space for program is adequate. bad leaks in the girls bathroom and in hall next to girls bathroom leaks. Buckets are placed to catch the water when it rains. The students water fournain in the K-2 cafeteria has been non functioning for 2 years. Student bathrooms do not have warm or hot water to wash their hands, this would be a health issue	poofi
2. Building Exterior/Envelope. Ceiling in Elementary office leaks into the bathroom	pood
1. Site Parents have complained about circle drive pot holes. There is a gate on the north east end that hasn't worked in some time.	pood

key fob entrances. Such as the 1st and 5th grade doors. Louder intercom through the phone or put in an intercom system that we can hear

There is only one phone at one end of the	u			NW.Other.Long-Range Blanning Considerations
library. The library is a very large space. It is difficult to hear announcements made over the phone when having students at the opposite end of the library. It would also be difficult to hear intuder location updates from the library hiding place (RTI library room).				
Lots of electrical cords hanging from the ceiling	Double doors by the 2nd grade hallway do not lock properly. This has been a concern for a long time.			į
All Works Well.	It might be nice to have better placements for the cameras on the play ground. Sometimes we have serious issues, and no stories add up. It is hard to see what really happened because the cameras cannot see what is going on or they are too far away. I also know there are some spots in the elementary building where there are no cameras or the cameras cannot see all the way down the hall and what not.	All is good here.	I have never heard or have seen a problem with it.	It would be nice to move our playground, elementary. We have people who live in the apartments drive along the fence line in the grass, and on the field when our students are outside at recess.
The exposed cords for all of the various technologies are an eyesore. Some of them dangle while others are a huge mass on the floor. Many of the older parts of the buildings can't have more than one thing plugged in at a time or it blows a time.				There are some serious plumbing issues especially in the older part of the elementary particularly the 2nd grade classrooms.
Announcements are not heard in either of acceptable the cafeterias. This is a major safety issue when a grade is at lunch, and we go on lock-down.	f i acceptable	acceptable	acceptable	acceptable
I don't see issue with this category.	I am not sure what else we could do in this area.	I don't use any of this type of equipment.	I am not sure on this issue	
	Exterior doors do not always shut and latch on their own which is a safety concern	Water fountains and bathrooms frequently have issues		

6. Electrical Systems. Intercom system needs some work -	7. Safety	8. Equipment	9.ADA	10: Other Long-Range: Planning Considerations
respecially with cafeterias and gym. Can't hear announcements in those locations.	Many teachers prefer to use the door in	****		
	the first grade hallway. It does not have a key fob. It would be nice if it did.	h Ma	,	
	e mandama a			3
	keypad/fob entry on all doors would be an extra safety feature.	an The maker space in the elementary is amazing, and I know that it will be organized this summer. It would really benefit the students to be able to utilize this space as intended. In addition to teachers using the space, could this be added to the library/art curriculum? For instance, the 3-D printer?		
In my opinion, all is good here!	would like to request a key fob entry for the end of the first grade hallway.	·N/A	I think the elementary is handicapped accessible.	An updated playground would be nice!
		a 1		· · · · · · · · · · · · · · · · · · ·

6.: Electrical Systems	n too many items or we in the 2nd grade rooms. g in a few griddles for ended up having to go to		Worked great this year!	The technology seems to work well most of the time. However, this year Apple to has had lots of issues in my classroom. This makes it hard to teach when I was relaning to use apple to to connect my device for class.
7. Safety B. Equipment G. Safety	Sometimes the double doors lock in our wing and sometimes they don't.	Work orders and suggestions have been made regarding door locking and safety in the elementary building. We really must take a serious look at this. The recess that are sets the faces the ball field offen gets pea gravel in the threshold and keeps the doors from locking. PLEASE address this.	Work fine!	There is a cracked glass cover on a fire extinguisher outside the music room that an should be checked and possibly replaced.
10. Other Long-Range Planning Considerations		I am passionate about our playground and am willing to look for grant money, work with the foundation and PTO and anyone else who is willing to take on a project of that magnitude. Also, would it be an option to have our classroom floors waxed every other year. Packing kindergarten room each year is overwhelming and it would be nice to skip years. Maybe a rotational basis.		I feel that our school district really needs an auditorium for large meetings such as all staff professional development, graduation ceremonies, and music concerts.

Contracts		·	* ***			
			8	100	as er	ger
2				At the current time I have 7 middle school	children that attend day plus. As long as children get along with students younger than them i believe this would be an avenue to revue in adding 6th grade to our program. It would bring in more funds. however 6th grade students must be only to be a suit and the su	ue aule to riave patience with the younger children ok
ulug			,š	ddle	As lo ts yc be a grac more	the y
Jan			ž.	7 m	lus. /	
10. Other Long-Range Planning Considerations				have 7 middle sch	children that attend day plus. As long children get along with students your than them i believe this would be an avenue to revue in adding 6th grade our program. It would bring in more funds, however 6th grade students it to the children in the children	e)
Rau			•	e h	od day y with y with h ad ould ould ith g	atter
ong				Ę.	atter llong eliev rue ii rue ii rer 6	Ö.
arati				rreni	hat a yet a la l	18
10. Other Long Considerations				. n	ren tren (then then tren tren tren tren tren tren tren tr	en Le
Con Con			*		child child han aven aven our p	children ok
			٧.		e sie	
			ì	no	duite	
				ever i	<u>n</u>	×
				howe	<u> </u>	*
			,	A S	g 9	
				ssib	<u>.</u>	
			ä	acce	<u> </u>	
ADA			ē	ave	a J	11
N.				We have accessibility however our	inanticap ranip to thay Plus is quite steep	boog
7.35 - 1.35 - 1. 2.25 - 1.35 - 1.			U.S.F. or many			. <u>6</u> .
			1	ļ		
			1	is Is		
3.50				ļ.		
			,	1.		
						8
m ed				i.		
dn						
8. Equipment			1			poob
	X * 100		3 8 · · · · · · · · · · · · · · · · · ·		<u>a</u>	6
			,	had i	ame in	
				am e	ver to be	i.
				progr	owe sed	
				lus p	m, h	
				ay p	de it sroo re su	
			:	for d	t ma clas we	4
			r	tem	rd in f any f and	
afet				arm sys	inter place ors i are	;
S			i t	alarm system for day plus program had been needed for quite sometime	superintendent made it happen. a came was placed in classroom, however monitors if any were supposed to be in place, are not.	poob
7. Safety	#			alarm system fo	<u> </u>	
1.5			, he	Í.		
			ā st	in .		
			e ha			S
<u>ω</u>			ay ar	F .		
ifem.			allw	ż		
Sys			he h	j :		3
<u>8</u>			s in t	P.		1 1
llect			: EOO	200 20 20 20 20 20 20 20 20 20 20 20 20		
6. Electrical Systems			Intercoms in the hallway are hard to hear.	Ĭ.		¥.

1. Site	2. Building Exterior/Envelope	3. Building Interior	4. Educational/Adequac	4. Educational/Adequacy 5. Mechanical/Systems
Parking Lot Repairs/Painting	Outdoor Tile Repair	STEAM Lab Flooring	Flexible classroom	Heating Cooling - Temperature Conrol Systems
Outdoor Classroom Area Door Repairs- Weather stripping, Key fobs	Door Repairs- Weather stripping, Key fobs	Repair around windows	Science Lab Space	Hot Water Heater Upgrade
Front Landscaping	Leaks around roof drains- Ceiling tile replacement	Gym floor refinished	×	
Paving Bus Drive & Back Lot	Foundation Repairs	Gym repainted		
iter	: Sidewalk Leveling	Locker Room lockers refinished	*:	
Sidewalk Leveling	Brick Mortar Repairs	Painting- continue		
2 2 2		Restroom Sinks		#
A- 20 Te		Boys Locker Room		
		Snower remodeled	3 3 3 4 8	
		Floor Tile Separation		

(10. Other Long-Range Ranning Considerations s Additional Storage	Addition betwen MS and HS - PLTW, Music,		(1.2) (A. v.)	•			
9: ADA Automatic Doors	ē	4.8	8 f x;				(X)
8. Equipment Flexible Seating	Hook up Middle School Kiln and ventilation		, ,		i e	•	
7. Safety New Middle School Entrance and Office Remodel	Upgrade Camera Systems	Upgrade Intercom Systems	Investigate Door Locking Systems	Eye wash stations in Science Rooms			****
al Systems Efficiency - matic On/Off,	Dimming Electrical Repairs and Upgrades in Kitchen and Commons	Technology Infrastructure - New Instructional Technology					

special talents.	Remolding The playground surface needs to be Handicap accessible doors. The playground surface needs to be in the playground surface needs to be
------------------	---

3

(Responses)
Planning
Facility
Long-Range
R-II
Holden

1. Site	2. Building Exterior/Envelope	3. Building Interior	4. Educational Adequacy	5. Mechanical Systems
				The temperature control in the middle school needs some work. One day this winter it was 88 degrees Fahrenheit in my classroom, and just a few days ago it was 67 degrees while students were map festing. There seems to be no working vents in the SSC either and the room is
Outdoor educational area with more tables (currently only have two picnic tables)			e de la company	very cold in the winter. HVAC: My room is either freezing or really hot
N/A	N/A	N/A		Our rooms are either freezing or hot.
The only thing I have noticed being inadequate with the facilities that I come into contact with its the snow removal in the parking lot at the middle school. Our custodians did the best they could to keep the sidewalks free from ice, but sometimes the parking lot didn't even look like it had been touched.				
	There are leaks. There has been a bucket in middle of hallway by lunch area for quite a long time.			There is a WIDE variety of temperatures across classrooms. Some of them are SO cold that student computers are cold to the touch and fingers are frosty (e.g. SSC, Chambers). Other rooms can be stifling hot (e.g. Orton). It's very unpleasant for staff and students. The office area/rooms are usually adequate
		Lots of ceiling tiles are water stained. We could do some interior work to make our buildings look more modern/homey, and less industrial/prison-like with more open areas.	Special programs and space planning— more flexible space options for collaboration among larger groups. If teachers want to coteach a project, we don't really have the space to accommodate two classes of students.	
				The HVAC in the middle school seems unreliable/temperamental. All classrooms seem to run on a different temp and are at times way too hot/cold.
The middle school parking lot could use a little love.	Middle school still has some areas that leak.	The doors leading to the outside by the boy gym entrance needs weather stripping at the bottom to keep the cold air and bugs out.		
			State of the second	Section of the second control of the second

Responses)
Planning (R
Facility
Long-Range
₽-
Holden

	r. Sarety	8. Equipment	9. ADA	10. Other Long-Range Planning Considerations
I do not have any issues with the electrical systems.	There has never been a time where I felt unsafe at school.	I feel my computer lab at the middle school is very adequate. I have seen other computer labs at different schools and I feel my lab provides more opportunities for students.	I do feel our district should implement automatic doors at the entrances of each building for students with physical disabilities.	
Technology department is good			Needs improvement	
The apple TV continues to disconnect when No concern here. you connect from your computer. It would be really helpful if we could get this fixed. This for me is more important than the temperature.	No concern here.	No concern here.	No concern here.	No concern here.
	kitchen back door is very hard to open, might be a problem in case of emergency			would love to have our new steam table installed this year
Lighting Security needs updated Technology goes in and out. No fault of our I feel that there needs to an extra lock on tech team though. Internet is just not great in rural areas. Also, it seems MS students have problems moving from classrooms with their devices or keeping them safe in their lockers and at home. Maybe switch to where each class have a classroom set instead of individual ones.	Security needs updated I feel that there needs to an extra lock on the doors of the Data Room that are used for a safe room.	Love to have a poster maker in the library.	Mandicap accessible doors. (Push Button)	Love to see a performing arts center.

6. Electrical Systems	7. Safety	8. Equipment	9. ADA	10. Other Long-Range Planning Considerations
		The traps under the sinks in science classrooms are never cleaned.		There is very little storage room in my building.
Adjustable lighting would be nice in the classrooms and I need technology infrastructure to hook up a desktop computer for student use in my room.	Safety entryway for the middle school like the other buildings			
N/A	N/A	science sinks smell and eye sprayers do not work	'WA	N/A
	I'd like to see more security cameras and/or better quality as a way to better monitor students and to investigate reports of bullying, etc.			
With could always be improved to keep pace with our tech usage		I'm not sure if furniture fits into this category, but a vast majority of our desks/tables/chairs are dated and have to continually be repaired. More modern and flexible seating options that facilitate greater collaboration (for students and staff) would be ideal. Science labs could use updated areas and equipment to more closely reflect real-world labs. Middle School Klin plus a fume hood would be beneficial for the art room.	ter d d	It would be nice to one day add an addition between the MS and HS for teachers that are shared between buildings to have their own space, maybe even an auditorium. Our athletic facilities (for specific sports) seem to have been the focus in the past, but we should shift focus to our academic facilities.

	2building Exterior/Envelope we need roofs that don't leak!!! Every time it rains we are ruining district equipment, student work, etc.	3: Building:Interior.	4. Educational Adequacy	5. Wechanical Systems
Pot holes	Leaking roof	Public bathrooms need to be renovated.	Great	Ok
	Roof leaks everywhere			
If anything, I think the parking lot could use some work, but it isn't horrible.	Some leaks in the roof.			
Need rock behind high school, when it rains that parking lot becomes mud hole.				Boys bathroom in hall of fame hallway has had urinal issues most
Good.	Leaking roof.	Tiles missing from ceiling or damaged from leaks.	Fine.	HVAC is inconsistent in its operation.
I have to park in the back when it rains hard or snow the ground becomes very muddy-The doors outside of the middles school students are unable to walk out must walk around a large puddle to the buses.	fine	Ą	ok	ok
	roof at the school	retile some floors.	more rechargeable calculators, more of the bigger individual desks	if over the winter the temperature in the classrooms is going to kick down below 60 over night then have it kick back up before students and teachers get here. There are times where I would
		Ceilings still have water stain, lights has sitting water in them.		

5. Mechanical Systems Boys' bathroom floods often	We have had problems with the hvac since it was put in and continues	Hot water does not reach science rooms or does all sinks work in all science rooms AC units in switch rooms in the HS need to be looked at. Those rooms get warm. Some of the bathroom plumbing could be updated.
4. Educational Adequacy.		Hot water does not reach science rooms or does all sinks work in a science rooms If there were more science room, that were set up like lott's room, that'd be neat. The stationary work get warm. Some of the bathroom spaces in the other two, while nice plumbing could be updated. with all of the sinks and gas hook ups makes it hard to do more collaborative or flexible seating.
3. Building inferior Paint frame around windows in classroom doors; replacing ceiling tiles when they are removed		Fix ceiling tiles. Some of the bathrooms could be updated and the stalls painted over.
끈	Roof leaks in several classrooms at the high school "unacceptable". some areas of the roof still leak	Several leaks in roof causing issues inside classrooms The roofs need major fixing to fix the leaks.
cracks and water in parking lot; Cracks in wall to the outside wo snow removal in parking lot better, in classrooms; lack of insulated not creating mounds to walk walls; many ceiling leaks through	Parking lot should probably be sealed to make it last longer	Parking lot behind high school needs attention due to ruts It'd be nice if the lots behind the high school were paved over instead of gravel. While it's fun playing dodge the potholes in the elementary drop off/pick up drive, those need to be fixed. The high school student parking lot could be leveled. Track could be redone.

NA	I'm sure there are problems but they appear to try to keep them functioning, I assume a lot of that is dictated by age of equipment.	Update the urinals in the boys restroom by the gym, update both restrooms by the gym
NA NA	poop	Mental health facility within building, change location of coffee shop, move art room with kilns which will increase the space for PLTW
3. Building Interior The gym floor takes a beating though.	Our bathrooms are outdated and poorly maintained for extracurricular activities. Urinals repeated not sufficient to keep with flow. Some of that is just the age of the facility. Complete tearout/remodel needed i assume at great cost. Tap com holes in wall look poor in hallways through the hallways and bathrooms.	Repaint HS gym, many classrooms and bathrooms need to be repainted, remodel interior locker room and restrooms by gym and Ag room, floor in hall of fame is cracking in a major way
Z. Building Exterior/Envelope The roof is a major concern. Buckets all over the place when it rains.	exterior not bad, improvements have been made.	The security of the doors the magnetic strips are wearing and lock always locking properly, Fixing the roof properly until it can be replaced.
The main parking lot is deteriorating quickly, with pot holes, dips, waves, etc. And a large section of concrete was cut out in the bus lane and filled with gravel. Is that going to get fixed?	Roads around school are not great. Muddle/lack of gravel in back of high school.	The HS parking lot and bus lanes need to be repaved. The front of the high school has curbing falling apart. The drive in front of Day Plus is horrible.

5: Mechanical Systems More control over classroom temperature would be appreciated. I'm curious about the overall energy efficiency of the physical plant. Motion activated lights? Or some kind of mechanism (glow in the dark switch plates?) in dark conditions that indicate light switch locations.	More efficient windows in ag area classrooms
He Educational Adequacy Electrical outlets for ever- increasing technology needs are temperature would be appreciate temperature would be appreciate temperature would be appreciate temperature would be appreciate inadequate. I'm curious about the overall indequate. I'm curious about the overall indequate temperature would be appreciate independent to the physical independent to the physical placed at the proper distance from plant. Motion activated lights? Or some kind of mechanism (glow in the dark switch plates?) in dark conditions that indicate light switch locations.	no changes necessary
h Stained ceiling tiles make a terrible Electrical outlets for everimpression, they look awful - but increasing technology needs are the leaking roof stains whatever is inadequate. Ceiling mounted projectors are no cracks in walls and floors (even placed at the proper distance fron newer construction)	Floors look good. Rooms need colors other than white.
Roof leaks in MANY areas of high school.	
At least one street light in HS parking lot (east end) has been non-operational for quite some time. A more outdoor "classroom" friendly environment. Perhaps some kind of permanent seating and shaded area.	Gravel area behind High School is Some of the rooms need roof a muddy mess after a rain.

Fine. Fine. Had lights out for weeks without them being lok fixed- more outlets in some rooms. Or a more permanent power surge so it cannot be moved by students	No problems Fine.	Greatil Doors not handicapped accessible.	It would be neat if we could buy the land north of the MS.
Fine.	Fine.	Doors not handicapped accessible.	
Fine.		Doors not handicapped accessible.	
ing lok			
Difficult to hear announcements- sounds Bullet-proof glass in doors and windows; muffled; phones showing correct time and in viewing cameras in parking lot coordination with bells; students being able to record video on devices; extra charging devices			Teacher check out laptop cart for printing purposes
library in the H.S. needs new entry doors. there are dead zones for the cameras also	Drains in in 102 lab tables do not drain properly, gas lines and valves are not reliable to leave on. sinks in 126 have doors that wont fundock and fauctes that meet to be replaced the server room is doorned for finite to	Not acceptable.	
Concern with server room getting too hot as none Ro		none	none

Holden R-III Long-Range Facility Planning (Responses)

Possible put lightning rods on the roofs to help Upgrade security cameras for better picture. Science rooms in performance partway ne safety showers and proper cabinets to storm ingulate damage from lightning strikes. Don't let people prop open back doors. Safety showers and proper cabinets to storm more caustic chemicals such as various as an more caustic chemicals and proper cabinets to store croms down across from the bard half should be incomed and the fauces in the common caustic chemical such as various as an more caustic chemical such as various as an more caustic chemical particular properties. See the proper caustic chemical properties of the common caustic chemical particular properties. See the properties of the common caustic chemical particular properties. See the properties of the common caustic chemical particular properties of the common caustic chemical particular properties. See the common caustic chemical particular properties of the common caustic chemical particular properties. The common caustic chemical particular properties of the common caustic chemical part		i like our system	Install LED lighting, Correct the clocks—all Door access/locking system—the doors do not installation of dishwashers that are being always secure themselves and a real safety stored, Biology lab redesign, chemistry room concern, bullet proof glass in the front entry changes, physical science nom to have the mand cafeleria area install more cameras and capability of students performing labs
lg://DA ed ids. 1al. ak. Fine		Doog:	
May need to make more space for Project Lead the Way classes. Some of those rooms are not big enough. There needs to be enough space to store materials and supplies as well as have kids build and test their designs. Take another look at the layout of the science rooms. If the nice if they had a lecture space and a lab space and a slightly bigger lab prep area for teachers. I am very passionate about pushing for a building addition between the middle school and high school. This addition would he had not of these things.	Toom, auditorium/Performing Arts Center, Ag shop, greenhouse, MS science lab, a real MS concession stand (that can be shared for events at the PAC), additional MS lockernooms (and renovate current lockernooms), a loading dock for getting things into the building, and maybe even Central Office staff. The MS music room would be free to be converted into a large classroom, or event 2 smaller one. The HS music room would be available for the event 2 smaller one. The HS music room would be available for the eart stange, show choir rehearsing, or anything else where the platforms would be helpful. I think I've given away who I am now, that swould be helpful. I think I've given away who I am now, maintain, and sharing with choir is a challenge. If we each had our own dedicated room between buildings, both MS and HS can come to the same location. Furthermore, our HS students who mentor in the MS would no longer have to sign out and travel outside, in all sorts of weather, to get to the MS. That is also a safety concern. I would LOVE the opportunity to help with possible poutside, in all sorts of weather, to get to the MS. That is also a safety concern. I would LOVE the opportunity to help with possible about the band, choir and PAC; many people would benefit from this. We would lose the bus lane, but if we pave the one in the ear, that can server our purpose just fine. As you can see, I've put all of of thought into this. There is a LOT of potential in this	disfirct. I hope to see this happen, and I want to help. Gym Floor/appearance of gym walls/old and dated but that is a huge cost I'm sure.	Change location of the playground and upgrade

Appendix D)

Maintenance Repairs-Summer 2019 Elementary

	,	
Repair Items		Date Completed
Paint K-2 cooler-Nighthawk Blue		
Fix Eagles Nest benches		
Paint 2nd grade outdoor railing-Blue		
Paint Awning-White underneath, Blue border & window above new outdoor LED	w outdoor LED	
2nd, 1st, & nurse hallways-coconut white above		
2nd gr. Hall wiring cleaned up		
Change celing tile next to RR ramp		
Cove trim next to boy's RR		
Restroom sign replacement		
1st Gr. Awning-New light (Dusk to Dawn)-Paint to match 2nd gr, new blue metal roof	ew blue metal roof	
Eliminate handicap by circle drive		
Paint concrete barrier by circle drive		
Room signs with numbers-1st & 2nd gr.		
Room 14 carpet		
Light over sink in Room 10		
Hang handprint tiles		
K-2 cafeteria entrance conduit replacement/paint		
K-2 entrance trim paint-Nighthawk		
New benches for K-2 entrance (Ask Sarah)		
New lights w/ dusk to dawn on K-2 awning		
New No Parking signs in circle drive		
K-2 water fountain		
Replace exit sign from K-2 to Eagles Nest (all in K-2 cafeteria)		
Paint tray drop off window		
Paint serving line		
K-2 workroom RR floors		
K-2 workroom ceiling tile by server		
Portable AC vent in K-2 workroom		
Paint beam over Kind. Boys and girls RR entry		
Lights in east library display cases		
Replace faucets in Kind. Rooms		
Fix urinal in 3-5 restroom by cafeteria		

Maintenance Repairs-Summer 2019 Elementary

Stool replacement in girls 3-5 restroom by cafeteria	2
Playground entry light	
Roof drain over library	
Ceiling tile in office entry	
Powerwash Elem. west entry	
Remulch playground	August, 2019
Paint older playground equipment to match	
Landscaping by office	
Fill west foundation hole by Elem. gym	
Handicapped curbs for office entry	
Backboards for K-3 in gym	
Pads for walls	
Replace mirrors in RR by gym	
K-2 cafeteria entry awning by Eagles Nest	

June, 2019	Powerwash canopy underside
	New entry canopy lights
	Tile on front pillars
	Band room doors
	Ballast in girls locker room
	Remove towel racks in girls locker room
	Ceiling repair in boys locker room
	Paint boys & girls locker room office trim & outside door
	Boys locker room stool stall partition
	New locker room benches
Sept. 3, 2019	Repair sound system cables under bleachers
	Repair Scoreboard
	Fix art room drawers
	GFCI electric outlet on art room counter
	2 automatic flush in 7/8 Gr. Boys RR
	New eyewash stations in all science rooms
	Automatic flushers for 6-7 Gr. girls restroom
	Scrape, repair block & paint around all windows
August, 2019	Tile in Steam room & Room 100
August, 2019	Cove trim by Steam room
	Finish hallway (upper) painting
	Locker repairs
	New ceiling tiles in all RR
	Repair tray return roll down curtain
	Hot water heater for kitchen
	Bottle filling water fountain in commons
August, 2019	Paint above light troughs in commons
	RR sinks?
	Entry lights (ballast)
	Repaint entry-Coconut White
	Paint entry heater by front door
July, 2019	Paint all doors-Nighthawk
	Tile by front door
Date Completed	Repair Items

butdoor Classroom Landscaping Out Front

Maintenace Repairs-Summer 2019 M.S.

New rope on lights	August, 2019
Powerwash front of building	June. 2019
Blue slats on trash-move brown to storage fence	
Possibly paint electric transformer in back	
Light & powerwash back entry	
Paint practice field goal posts (South & East)	

Maintenance Repairs-Summer 2019

H.S.

Repair Items	Date Completed
Roof leaks on drain in indoor concession stand	
Science Rm.126 & 127Clean sink drains	
Science Rm.126 & 127Check faucets & gas outletstighten	
Science Room 128Seal double outside doors	
New double band room doors	
Paint back wall of band room	
Band Roomcarpet seams & corners need work	
Move washer & dryer to boiler roombuild catwalk to accommodate	
Window latches installed in library	
Redesign & redecorate library	
Install AC unit in PLTW room with heat	
Ouside shop doors need rubber seals	
Retractable roof motor on greenhouse	
Room 109Downspout outside	
Paint black rail around track	
Shower barrier to prevent water flow on football locker room	
Roof on Bright FuturesNew screws & rubber	
Tile in Bright Futures washing machine area	
Lettering for windows/doors on all buildings (reflective blue/white)	
Landscaping in front of multi-purpose room	
Hook up griddle in kitchen	
Paint or replace air return in kitchen	
Install wash-off station for fruit & vegetables	
Storage racks for outside consession stand (5 or 6)	
Fill & paint crack in east wall of outside concession stand	
Replace ceiling tiles in outside concession stand	
Paint top of wall in SW restrooms (B&Gwhite mile)	
Baby changing stations in both SW restrooms	
Ceiling tiles in training room	
Hall of Fame floor	
Paint floor on west gym entry	
Paint stage walls	
Replace tops bolts to wall on stage ladder	
Clean/paint gym vents on north wall	
Dana's desk extension	
AC in all tech areas	
Paint entry heaters	
Paint above lockers in Blue Blvd.	
Mirrors in Boy's Blue Blvd. RR	
Door handles in Boy's RR in Blue Blvd.	
Electrical panel in Blue Blvd. locking systems	
Locker trash cans opened up	
Redo window units in Ag Shop/Classroom	7
Plywood floor over shop office	
Replace sink in Ag classroom	
New floor in Ag classroom office	

Maintenance Repairs-Summer 2019

H.S.

New ceiling tile in Ag classroom	
Redo sink and eye wash station in Ag Shop	
Redo safety tape on shop floor	
Door handle on shopcustodial room	
New partitions & toilet seats in Ag restroom	,
New sinks in art room by shop	
New double outside doors in art room by shop	
Old spot lights in gym	
Replace some of gym floor for bad spots	
Paint lockers to cover lock scratches	

Maintenance Repairs-Summer 2019 C.O/Tennis Courts

te Completed
July, 2019
July, 2019
July, 2019
July, 2019
;
July, 2019

HOLDEN R-III FACILITIES PLANNING HOLDEN ELEMENTARY COMMITTEE

October 29, 2018 @ 4:00 p.m.

AGENDA

- 1. Celebrations
- 2. Introductions
- 3. Purpose of the Meeting
- 4. Bond Issue Review No Tax Increase
- 5. Tour of the Building Take Personal Notes
- 6. Review Facilities Survey Results and Personal Notes from Tour
- 7. Develop List of Needs
- 8. Prioritize Needs List
- 9. Questions
- 10.Common Message
- 11.Adjournment

HOLDEN R-III FACILITIES PLANNING HOLDEN MIDDLE SCHOOL COMMITTEE

October 18, 2018 @ 4:00 p.m.

AGENDA

1.	Celebrations
2.	Introductions
3.	Purpose of the Meeting
4.	Bond Issue Review – No Tax Increase
5.	Tour of the Building – Take Personal Notes
6.	Review Facilities Survey Results and Personal Notes from Tour
7.	Develop List of Needs
8.	Prioritize Needs List
9.	Questions

10.Common Message

11.Adjournment

HOLDEN R-III FACILITIES PLANNING HOLDEN HIGH SCHOOL COMMITTEE

November 1, 2018 @ 6:00 p.m.

AGENDA

1.	Celebrations
2.	Introductions
3.	Purpose of the Meeting
4.	Bond Issue Review – No Tax Increase
5.	Tour of the Building – Take Personal Notes
6.	Review Facilities Survey Results and Personal Notes from Tour
7.	Develop List of Needs
8	Prioritize Needs List

11.Adjournment

10.Common Message

9. Questions



SITE

Parking Lots-

A - Elementary Lot by Circle Drive

B - Elementary Circle Drive

C - Elementary Parking by Entrance

D - Middle School Front Lot

E - Middle School East Drive

F – Middle School West Drive/Bus Loading Will fix water retention issue

G – Middle School Morning Bus Lane and Back Lot Currently Gravel

H – High School Front Lot

J – High School Circle Drive and Staff Lot

K – High School Back Lot Currently Gravel

L - Bus Lane

Behind H.S. & Between H.S. and E.S.

N - Auxiliary Services Drive and Bus Lot

Elementary Playground
Update, Move, Secure

Sidewalk Leveling Front and Behind Middle School

Repair Water Retention Areas by Track/Football Field Entrance and by football bleachers ramp

Tennis Court Crack Repair

BUILDING EXTERIOR

Roof Repair-

A - Elementary (1957)

B - Elementary (2003)

C - High School (1995)

D – High School (1999) E – High School (2007)

Middle School Brick/Mortar Repairs & Sealing

Elementary School Brick/Mortar Repairs & Sealing

High School Brick/Mortar Repairs & Sealing

Energy Efficient Windows in Ag Shop & Project Lead the Way Building

High School White Mile (2007) Foundation Repair

BUILDING INTERIOR

Drop Ceiling in 1957 Section of Elementary School Hallways

Drop Ceiling in 1957 Section of Elementary School Classrooms

Foundation Repair in Southeast Corner of 2003 Elementary School Addition

Middle School Gym Floor Sanded and Lines Repainted

Middle School Gym Painted

Middle School Boys Locker Room Lockers

Middle School Boys Locker Room Showers (privacy)

High School Gym Floor Sanded and Lines Repainted

High School Gym Painted

Retile 2 Classroom Floors in High School

High School Hall of Fame Foundation and Floor Repair

High School Lobby Paint Older Suspended Ceiling Grid

High School Indoor Boys and Girls Locker Room Renovations - Epoxy Flooring, Update Plumbing, Shower Upgrades, New benches/lockers, Exhaust/HVAC

EDUCATIONAL ADEQUACY

Update and Upgrade H.S. Science Room 100 to become a functional Chemistry Classroom and Lab

Mental Health Facility Entrance at the end of the H.S. White Mile

Move Art Room in Ag Bldg. to Blue Boulevard in the High School (Kiln exhaust) - More room for Project Lead the Way Program

Move Coffee Shop to Old Concession Stand Area

MECHANICAL SYSTEMS

HVAC-

High School (1995) Roof Units

High School (1999) Roof Units

Middle School New Units and Rezoning
All Units except 2 that were replaced in 2012

Elementary (1957) Roof Units

Elementary (2003) Roof Units

Elementary (Kindergarten) Large Unit Rebuild

All New HVAC Units and Duct Work for Ag Building

ELECTRICAL SYSTEMS

Elementary School Lighting Upgrades for Efficiency

Middle School Lighting Upgrades for Efficiency

High School Lighting Upgrades for Efficiency

Elementary Lighting Upgrades for Efficiency

High School (Blue Boulevard) Classroom Electrical Capacity

Elementary (1957 – 1st and 2nd Grade Hallways) Classroom Electrical Capacity

Gym Lighting Control

Sports Fields Electrical Upgrades

Tennis Court Light Upgrades

SAFETY

Middle School Entrance Remodel for Safety

High School Entrance Upgrade for Safety

Elementary School Entrance Enlarge and Upgrade for Safety

New Elementary Office/Entrance at Circle Drive Safe Entrance and Canopy to match other buildings

Intercom System Upgrades (All buildings)

Camera System Upgrades (All buildings)

Automatic Door Locking Systems (All buildings)

Fob More Outside Doors

SITE

Dar	vin a	lote
rai	MILIE	Lots-

A – Elementary Lot by Circle Drive

B - Elementary Circle Drive

C – Elementary Parking by Entrance

D - Middle School Front Lot 13/14

E - Middle School East Drive

F - Middle School West Drive/Bus Loading Will fix water retention issue

G - Middle School Morning Bus Lane and Back Lot Currently Gravel

H - High School Front Lot 15/15/15

J – High School Circle Drive and Staff Lot

K - High School Back Lot 12 Currently Gravel

L - Bus Lane

Behind H.S. & Between H.S. and E.S.

N - Auxiliary Services Drive and Bus Lot

Elementary Playground 7/8/6/2/10/10/12/13 Update, Move, Secure

Sidewalk Leveling Front and Behind Middle School 14/14

Repair Water Retention Areas by Track/Football Field Entrance and by football bleachers ramp

Tennis Court Crack Repair

BUILDING EXTERIOR

Roof Repair-

Roof RepairA – Elementary (1957) 1/4/7/1/5/4/4/5/5/2B – Elementary (2003) 13/14/6/7/6C – High School (1995) 1/4/5/13/3/12/8/7/7D – High School (1999) 12/6/8/8/14/4/13/6E – High School (2007) 14/5/15/5/9

Elementary School Brick/Mortar Repairs & Sealing

Middle School Brick/Mortar Repairs & Sealing 3

High School Brick/Mortar Repairs & Sealing

Energy Efficient Windows in Ag Shop & Project Lead the Way Building

High School White Mile (2007) Foundation Repair 12/11/15/10/2/12

BUILDING INTERIOR

Drop Ceiling in 1957 Section of Elementary School 1.5/12
Drop Ceiling in 1957 Section of Elementary School Classrooms
Foundation Repair in Southeast Corner of 2003 $11/7/15$ Elementary School Addition
Middle School Gym Floor Sanded and Lines Repainted
Middle School Gym Painted 7
Middle School Boys Locker Room Lockers
Middle School Boys Locker Room Showers (privacy)
High School Gym Floor Sanded and Lines Repainted
High School Gym Painted
Retile 2 Classroom Floors in High School
High School Hall of Fame Foundation and Floor Repair $10/8/9/13/11$
High School Lobby Paint Older Suspended Ceiling Grid
High School Indoor Boys and Girls Locker Room $14/13/12/13$ Renovations - Epoxy Flooring, Update Plumbing, Shower Upgrades, New benches/lockers, Exhaust/HVAC

EDUCATIONAL ADEQUACY

Update and Upgrade H.S. Science Room 100 to become a functional Chemistry Classroom and Lab

Mental Health Facility Entrance at the end of the H.S. $\sqrt[8]{7/9/11/5/15}$ White Mile

Move Art Room in Ag Bldg. to Blue Boulevard in the High School (Kiln exhaust) - More room for Project Lead the Way Program

Move Coffee Shop to Old Concession Stand Area

MECHANICAL SYSTEMS

HVAC- High School (1995) Roof Units $10/13$
High School (1999) Roof Units
Middle School New Units and Rezoning All Units except 2 that were replaced in 2012
Elementary (1957) Roof Units $11/9/19/13/15/3/6/9$
Elementary (2003) Roof Units
Elementary (Kindergarten) Large Unit Rebuild $4/9/1/5/12/10/12/14$
All New HVAC Units and Duct Work for Ag Building
ELECTRICAL CYCTERAC
ELECTRICAL SYSTEMS
Elementary School Lighting Upgrades for Efficiency $10/10/11$
Middle School Lighting Upgrades for Efficiency 8
High School Lighting Upgrades for Efficiency 14/9
Elementary-Lighting-Upgrades-for-Efficiency
High School (Blue Boulevard) Classroom Electrical Capacity 14
Elementary (1957 – 1 st and 2 nd Grade Hallways) Classroom Electrical Capacity $12/15/11/5$
Gym Lighting Control
Sports Fields Electrical Upgrades $12/6/8/5/10$
Tennis Court Light Upgrades

SAFETY

Middle School Entrance Remodel for Safety 1/1/3/1/5/1/1/1/2/1/1/3/13High School Entrance Upgrade for Safety 3/3/1/3/15/3/3/3/8/10Elementary School Entrance Enlarge and Upgrade for Safety 2/4/2/2/2/2New Elementary Office/Entrance at Circle Drive Safe Entrance and Canopy to match other buildings 2/11Intercom System Upgrades (All buildings) 4/6/14/4/9/8/6/6/3/4/14/6/8/7Camera System Upgrades (All buildings) 10/7/i0/15/2/5/5/7/7/4/9/8Automatic Door Locking Systems (All buildings) 4/11/6/7/6Fob More Outside Doors 8/9/15/13/12

Appendix G)

d for inflat	BUDGET ESTIMATE
*Not adjuste	
IORITES	

ITEM SCHOOL	SCOPE	NOTES	1-2 YEARS	5-6 YEARS	10-12 YEARS
1 DISTRICT-WIDE	ROOFING REPLACEMENT				
	- ELEWENTARY TAR ROOF REPLACEMENT WITH NEW EPDM ROOF	1 \$	345,000.00		
	- INTERMEDIATE EPDM REPLACEMENT WITH WET INSULATION REPLACED				\$ 429,600.00
	- HIGH SCHOOL GRAVEL ROOF REPLACEMENT	\$	00.000,99		
	- HIGH SCHOOL EPDM REPLACEMENT WITH WET INSULATION REPLACED - OLDER ROOF (EXCLUDES GYM)	S	295,064.00		
	- HIGH SCHOOL EPDM REPLACEMENT WITH WET INSULATION REPLACED - 2007 ROOF (EXCLUDES GYM)	1			\$ 290,736.00
	- HIGH SCHOOL METAL ROOF OPTION	\$	3,164,000.00		
		\$	3,870,064.00	\$	\$ 720,336.00
2 DISTRICT-WIDE	ASPHALT REPLACEMENT				
	- ELEMENTARY/INTERMEDIATE SCHOOL	2			
	- AREA A			\$ 68,000.00	
	- AREA B			\$ 45,200.00	
	- AREA C				
	- MIDDLE SCHOOL	2			
	- AREA D			\$ 159.400.00	
	- AREA E				
	AREAF				
	- AREA G			\$ 98,000.00	
	- HIGH SCHOOL	2			
	- AREA H			\$ 391,200.00	
	- AREA J			\$ 114,600.00	
	- AREA K			111,200,00	
	- AREA L			\$ 165,100,00	
	- AREA M				
	- BUS BARN	2			
	- AREA N			\$ 264,000.00	
		\$		\$ 1,649,100.00	\$
3 DISTRICT-WIDE	HVAC MODERNIZATION (WITH CONTROLS)				
	- ELEMENTARY/INTERMEDIATE SCHOOL ROOFTOP HVAC REPLACEMENT	3	0,	\$ 927,875.00	
	- AG BLDG HVAC		0,	330,000.00	
	- MIDDLE SCHOOL ROOFTOP HVAC REPLACEMENT			\$ 325,000.00	
	- EXHAUST FAN REPLACEMENT (ELEMENTARY AND HIGH SCHOOL)		0,	\$ 125,000.00	
	- HIGH SCHOOL ROOFTOP HVAC REPLACEMENT WITH CONDENSATE DRAIN SYSTEM			\$ 585,000.00	
		\$		\$ 2,292,875.00	\$
4 DISTRICT-WIDE	LED LIGHTING RETROFIT				
	- ELEMENTARY/INTERMEDIATE LED FIXTURE REPLACEMENT	4 \$			
	- MIDDLE SCHOOL LED FIXTURE REPLACEMENT	4 \$	155,520.00		
1000	- HIGH SCHOOL LED FIXTURE REPLACMENT	4 \$			
	- DIMMING FOR ELEMENTARY, MIDDLE, AND HIGH SCHOOL	45			
		\$	690,175.00	. \$	\$
5 DISTRICT-WIDE	SECURITY ENTRANCE MODIFICATIONS				
	- ELEMENTARY/INTERMEDIATE SCHOOL (RELOCATE STOREFRONT, ADD BULLETPROOF PASS THROUGH WINDOW, MODIFY ELOORING)	V	00 000 00		
	- MIDDLE SCHOOL (REWORK MASONRY WALLS, ADD BULLET RESISTANT WINDOW, ADD VISION GLASS INTO COMMONS, EXCLUDES MOVING INTERCOM PARELY				
	- HIGH SCHOOL (REPLACE STOREFRONT WITH LAMINATED GLASS, ADD BULLETPROOF PASS THROUGH WINDOW)	\$			
				-	

	THE COURT WELL CONTROL OF THE PRINCIPLE	00:000:00
7 ELEMENTARY/INTERMEDIATE	FLOOR SLAB REPAIR - SOUTHEAST CORNER OF BUILDING (POLYFILL, PATCH DAMAGED FLOORING)	\$ 15,000.00
8 ELEMENTARY/INTERMEDIATE	NEW LAY-IN CEILING IN ELEMENTARY CORRIDOR (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS, EXCLUDES SKYLIGHT REPAIRS)	\$ 42,000.00
9 ELEMENTARY/INTERMEDIATE	NEW LAY-IN CEILING IN ELEMENTARY CLASSROOMS (INCLUDES NEW LIGHTING, REVISED HVAC, ELECTRICAL REVISIONS)	\$ 168,000.00
10 ELEMENTARY/INTERMEDIATE	ADD ELECTRICAL OUTLETS TO 1ST AND SECOND GRADE HALLWAYS	\$ 80,000.00
11 ELEMENTARY/INTERMEDIATE	REMOVE STAGE WALL	\$ 3,000.00
12 ELEMENTARY/INTERMEDIATE	NEW ENTRY BLDG ADDITION AT CIRCLE DRIVE	5 \$ 800,000.00
13 MIDDLE SCHOOL	ELECTRICAL UPGRADES - NEED ADDITIONAL BREAKERS FOR NEW PANELS	\$ 25,000.00
14 MIDDLE SCHOOL	GYM FLOOR SANDING AND REPAIR	\$ 31,950.00
15 MIDDLE SCHOOL	BUS LOADING AREA - WATER DETENTION REPAIR◆	- \$ 12
16 MIDDLE SCHOOL	SIDEWALK LEVELING AT 2 LOCATIONS	\$ 5,000.00
17 MIDDLE SCHOOL	ADD ROOF AND GARAGE DOOR TO TRASH RECEPTACLE AREA*	
18 MIDDLE SCHOOL	OUTDOOR TILE REPAIR	\$ 2,000.00
19 MIDDLE SCHOOL	REPAINT GYM WALLS (NOT INCLUDING CEILING)	\$ 15,000.00
20 MIDDLE SCHOOL	RECONFIGURE LOCKERS IN LOCKER ROOM INCLUDING REFURBISHING MOST OF EXISTING	\$ 15,000.00
21 MIDDLE SCHOOL	ADD PARTITIONS TO LOCKER ROOM SHOWERS IN BOYS LOCKER ROOM	\$ 5,000.00
22 MIDDLE SCHOOL	ADD RESTROOM TO RESOURCE ROOM	
23 HIGH SCHOOL	FIX WATER RETENTION AREAS AT TRACK/FOOTBALL FIELD	\$ 7,000.00
24 HIGH SCHOOL	REPLACE AG/PLTW WINDOWS	\$ 11,475.00
25 HIGH SCHOOL	SIDEWALK AT WHITE MILE PARKING LOT	\$ 15,000.00
26 HIGH SCHOOL		\$ 14,000.00
27 HIGH SCHOOL	PAINT GYM WALLS (NOT INCLUDING CEILING)	\$ 15,000.00
28 HIGH SCHOOL	REFURBISH / REPLACE OLD LOCKERS DOWN BLUE BLVD (NEED # OF LOCKERS)	10 \$ 45,000.00
29 HIGH SCHOOL	REMODEL SCIENCE ROOM TO BE CHEMISTRY CLASSROOM (2 NEW HOODS, CABINTRY, ETC.)	9 \$ 200,000.00
30 HIGH SCHOOL	SECURE ENTRANCE AT MENTAL HEALTH FACILITY (ADD STOREFRONT OUTSIDE OF ROOM 151 AND ADD DOOR INTO 151)	\$ 8,000.00
31 HIGH SCHOOL	MOVE COFFEE SHOP TO OLD CONCESSION AREA (REMOVE BRICK WALL WHERE PRESENTLY IN COFFEE SHOP)	\$ 7,000.00
32 HIGH SCHOOL	MOVE ART ROOM TO MAIN HALLWAY (RELOCATE KILNS/EXHAUST, ADD EXHAUST FOR NEW PLTW ROOM)	\$ 15,000.00
33 HIGH SCHOOL	ADD ELECTRICAL RECEPTACLES / NEW PANELS FOR CLASSROOMS DOWN BLUE BLVD	\$ 80,000.00
34 HIGH SCHOOL	ADD LIGHT SWITCHES FOR GYM AND STAGE LIGHTING . '	\$ 3,500.00
35 HIGH SCHOOL	ADD WINDOW REFLECTIVE TINT TO CAFETERIA WINDOWS	\$ 3,000.00
36 HIGH SCHOOL	GYM FLOOR SANDING AND REPAIR (INCLUDES STAGE)	\$ 64,250.00
37 HIGH SCHOOL	FLOOR/TILE CRACKING AND FOUNDATION ISSUES DOWN HALL OF FAME (POLYFILL, PATCH DAMAGED FLOORING)	\$ 15,000.00
	180'S AND GIRIS LOCKER ROOM RENOVATIONS (NEW EPOCXT FLOORING, PLUMBING FIXTURES, INDIVIDUAL SHOWER CONTROL, BENCHES,	
38 nigh 3chool		\$ 150,000.00
39 HIGH SCHOOL	BOYS RESTROOM RENOVATIONS (NEW EPOXY FLOORING, PLUMBING FIXTURES, PARTITIONS)	
40 HIGH SCHOOL	WHITE MILE FOUNDATION AND CRACKING ISSUES (NEW HELLCAL PIERS)	\$ 100,000.00
41 HIGH SCHOOL	EXISTING 1200A SWITCHGEAR REPLACEMENT	40.000.00

3,941,975.00 \$

\$ 6,906,914.00 \$ \$ 11,569,225.00

1 CONTAINS SOLAR PANELS
2 SEE SEPARATE SHEETS FOR AREA BREAKDOWN, ADDED SURFACE THICKNESS FOR HEAV? BUS TRAFFIC NOT INCLUDED IN THIS BUDGET PRICE
3 133.5 TONS FOR ELEMENTARY, 182 TONS FOR INTERMEDIATE. TO BE REFINED WITH MARK'S INFO
4 COST INCLUDES OCCUPANCY STRONGRS, ESTRONGRS, ESTRONGRS, STRONGRS, SUBDRANINS, CURBS, AND LABOR TO RELOCATE
HALF OF EXISTING EQUIPMENT, NEW EQUIPMENT NOT INCLUDED.
7 REPAIRS INCLUDED IN AGPHALT, STRE WORK
8 NOT FEASIBLE DUE TO EXISTING WATER DAMAGE
9 INCLUDES REPLACE FLOORING, CEILINGS, WOOD CASEWORK, ELECTRICAL, PLUMBING, 3 LAB HOODS, VISUAL DISPLAY AND PAINTING. THE HVAC COST FOR SCIENCE EMALLYS FOR THE LAB HOODS IS \$50,000 OF THE OVERALL BUDGET.
10 THE BUDGET INCLUDES REPLACING 150 LOCKERS, WE'VE ASSUUMED A BUDGET OF \$300/LOCKER. THIS BUDGET CAN BE MODIFIED BASED ON ACTUAL NEEDS.