

Lead in Water Testing Results
South Washington County Schools
Liberty Ridge Elementary

On December 30th, 2022 Liberty Ridge Elementary School's drinking water was tested for concentration of lead.

**All water sources tested less than our current action level of 20 parts-per-billion.
No action was taken at this time.**

LOCATION	SOURCE	RESULTS (in ug/L)
Nurse's Office	SINK	.58
Nurse's Office (bathroom)	SINK	.47
Staff Dining	SINK	.11
Kitchen (left)	SINK	2.1
Kitchen (right)	SINK	3.2
Kitchen	SPRAYER	1.9
Hallway (gym, left)	FOUNTAIN	ND
Hallway (gym, right)	FOUNTAIN	ND
Hallway (gym)	BOTTLE FILLER	ND
Gym A	FOUNTAIN	.23
Gym B	FOUNTAIN	.20
Gym C	FOUNTAIN	ND
Hallway (by A103, left)	FOUNTAIN	ND
Hallway (by A103, right)	FOUNTAIN	1.4
Hallway (by A103)	BOTTLE FILLER	ND
Room A003	SINK	1.1
Room A004	SINK	.9

Room A008	SINK	.66
Room A010	SINK	.84
Room A011	SINK	.73
Room A014	SINK	.78
Room A018	SINK	.52
Hallway (NE, left)	FOUNTAIN	.34
Hallway (NE, right)	FOUNTAIN	ND
Hallway (NE)	BOTTLE FILLER	ND
Room E101	SINK	1.1
Room E116	SINK	2.1
Hallway (outside E115)	SINK	2.2
Room E115	SINK	1.3
Room E114	SINK	.91
Room E112	SINK	1.0
Room E119	SINK	1.3
Room E118	SINK	.96
Room E103	SINK	6.3
Room E104	SINK	2.4
Room E111	SINK	2.8
Room E109	SINK	2.7
Room E 108	SINK	3.0
Hallway (outside E108)	SINK	2.7
Room E107	SINK	2.0
Room E106	SINK	2.5
Hallway (SE)	FOUNTAIN	.28

Room D116	SINK	1.1
Room D108	SINK	2.5
Room D103	SINK	2.7
Hallway (outside SW)	FOUNTAIN	.24
Room C106	SINK	.7
Room C107	SINK	3.6
Hallway (outside C108)	SINK	2.4
Room C108	SINK	1.8
Room C109	SINK	1.3
Room C111	SINK	.88
Room C118	SINK	.62
Room C119	SINK	1.8
Room C104	SINK	1.9
Room C112	SINK	.71
Room C114	SINK	4.5
Room C115	SINK	6.2
Hallway (outside C115)	FOUNTAIN	1.5
Room C116	SINK	3.0
Room C101	SINK	3.8
Media Center WR	SINK	.65
Hallway (NW)	FOUNTAIN	ND
Hallway (NW)	BOTTLE FILLER	ND