

Lead in Water Testing Results
South Washington County Schools
Woodbury High School

On December 30th, 2022 Woodbury High School's drinking water was tested for concentration of lead.

The following water sources tested less than our current action level of 20 parts-per-billion. No action was taken on these sources at this time.

| LOCATION | SOURCE | RESULTS (in ug/L) |
|------------------------------|---------------|--------------------------|
| Office Work Room | SINK | 1.9 |
| Nurse Office | SINK | 7.9 |
| Hallway (outside 101) | FOUNTAIN | 4.0 |
| Hallway (outside 160, left) | FOUNTAIN | ND |
| Hallway (outside 160, right) | FOUNTAIN | .77 |
| Hallway (outside 160) | BOTTLE FILLER | ND |
| Testing Room | SINK | .77 |
| Hallway (outside 170, right) | FOUNTAIN | .91 |
| Hallway (outside 170, other) | FOUNTAIN | 1.2 |
| Room 115 (kitchen area) | SINK | 1.6 |
| Room 115 (bath area) | SINK | 8.2 |
| Room 115 (laundry) | SINK | 16.7 |
| Room 112 (1) | SINK | 1.9 |
| Room 112 (2) | SINK | 5.2 |
| Room 112 (3) | SINK | 3.1 |
| Room 112 (4) | SINK | 3.9 |
| Room 112 (5) | SINK | 3.8 |
| Room 112 (6) | SINK | 4.9 |

| | | |
|-------------------------|---------------|------|
| Room 116 (right) | SINK | 13.4 |
| Hallway (outside 120) | FOUNTAIN | 1.7 |
| Hallway (AC, left) | FOUNTAIN | ND |
| Hallway (AC, right) | FOUNTAIN | .13 |
| Hallways (AC) | BOTTLE FILLER | ND |
| Cafeteria (left) | FOUNTAIN | ND |
| Cafeteria (left) | BOTTLE FILLER | ND |
| Cafeteria (right) | FOUNTAIN | ND |
| Cafeteria (right) | BOTTLE FILLER | ND |
| Kitchen | SINK | 2.9 |
| Kitchen | SPRAYER | 8.6 |
| Hallway (by 218) | FOUNTAIN | ND |
| Hallway (by 218) | BOTTLE FILLER | ND |
| Room 204 | SINK | 3.5 |
| Hallway (by 211) | FOUNTAIN | .24 |
| Hallway (by 211) | BOTTLE FILLER | .23 |
| Hallways (by 273, left) | FOUNTAIN | 2.2 |
| Hallway (by 273, right) | FOUNTAIN | .9 |
| Hallway (by 279) | FOUNTAIN | 2.0 |
| Hallway (by 260, left) | FOUNTAIN | 1.2 |
| Hallway (by 260, right) | FOUNTAIN | .96 |
| Hallway (by 231) | FOUNTAIN | 7.1 |
| Room 255 | BOTTLE FILLER | ND |
| Room 256 | FOUNTAIN | ND |
| Room 256 | BOTTLE FILLER | ND |

The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources were shut down and will no longer be used until they are replaced and re-tested.

| LOCATION | SOURCE | INITIAL RESULTS (in ug/L) |
|----------------------------|---------------|----------------------------------|
| Hallway (outside 126) | FOUNTAIN | 38.7 |
| Hallway (outside 126, gym) | FOUNTAIN | 65.3 |