

Radon Testing Results - Springfield School District

The EPS's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting

Six spike tests were conducted to ensure the integrity of the testing process and all spike test passed satisfactorily.

Site Name	Room Description (per floor plan)	Kit serial #	Date sampled	Type of test	Results (pCi/L)
Mohawk Elementary	Room 1	RK108187	3/3/2022	Detector Kit	DNR
Mohawk Elementary	Room 2	RK108156	3/3/2022	Detector Kit	1.2 ± 0.4
Mohawk Elementary	Room 3	RK108215	3/3/2022	Detector Kit	1.0 ± 0.4
Mohawk Elementary	Workroom	RK108235	3/3/2022	Detector Kit	0.7 ± 0.3
Mohawk Elementary	Workroom	RK108246	3/3/2022	Duplicate	0.7 ± 0.3
Mohawk Elementary	Staff Room	RK108852	3/3/2022	Detector Kit	0.8 ± 0.4
Mohawk Elementary	Office near Staff Room	RK108836	3/3/2022	Detector Kit	< 0.4
Mohawk Elementary	Principal Office	RK108845	3/3/2022	Detector Kit	0.8 ± 0.5
Mohawk Elementary	Main Office	RK108245	3/3/2022	Detector Kit	< 0.4
Mohawk Elementary	Main Office	RK108249	3/3/2022	Duplicate	< 0.8
Mohawk Elementary	Library	RK108857	3/3/2022	Detector Kit	1.1 ± 0.3
Mohawk Elementary	Library Office	RK108838	3/3/2022	Detector Kit	0.9 ± 0.3
Mohawk Elementary	Music Storage Room	RK108830	3/3/2022	Detector Kit	0.9 ± 0.3
Mohawk Elementary	Room 4	RK108848	3/3/2022	Detector Kit	1.1 ± 0.4
Mohawk Elementary	Room 7	RK108160	3/3/2022	Detector Kit	1.7 ± 0.4
Mohawk Elementary	Workroom	RK108154	3/3/2022	Detector Kit	< 0.7
Mohawk Elementary	Room 5	RK108844	3/3/2022	Detector Kit	0.8 ± 0.4
Mohawk Elementary	Room 6	RK108153	3/3/2022	Detector Kit	2.3 ± 0.6
Mohawk Elementary	Gym	RK104636	3/3/2022	Detector Kit	0.6 ± 0.4
Mohawk Elementary	Gym	RK108072	3/3/2022	Detector Kit	1.3 ± 0.4
Mohawk Elementary	PE Teacher Office	RK108243	3/3/2022	Detector Kit	1.5 ± 0.5