


INSPECTION CERTIFICATION for Saint Paul Public Schools -- Johnson Senior High School

STATEMENT OF BUILDING ACCESS

On behalf of Saint Paul Public Schools for Johnson Senior High School, I certify that I have provided access to all areas within the building to IEA's inspector identified below for the purpose of inspecting for asbestos-containing building materials (ACBM) as mandated by 40 CFR 763.85, "Inspections and Reinspections."

Additionally, I have discussed any concerns I have regarding identified or non-identified ACBM within this building.



Signature

8/11/21

Date of Inspection

INSPECTOR

As mandated by 40 CFR 763.85, "Inspections and Reinspections," I certify that I have inspected all accessible areas in Johnson Senior High School for the purpose of identifying and assessing asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Inspector. A copy of my certification/accreditation is attached.



Signature
Spencer West

Print Name

8/11/21

Date of Inspection
14511

State Certification/Accreditation Number

MANAGEMENT PLANNER

I certify that I have reviewed all of the inspection data for Johnson Senior High School and have appropriately provided assessments and response actions for identified asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Management Planner. A copy of my certification/accreditation is attached.



Signature
M. Lindberg

Print Name

9/3/2021

Date of Review
A23896

State Certification/Accreditation Number

Inspector State Certification/Accreditation



m ASBESTOS
DEPARTMENT OF HEALTH INSPECTOR
Certified by:
State of Minnesota
Department of Health
Expires: 09/02/2021
Spencer D. West
4227 Penn Ave N
Minneapolis, MN 55412

Spencer D. West
Director, Env. Health Div.

No. A14511 Issued: 09/22/2020

Management Planner State Certification/Accreditation



m ASBESTOS
DEPARTMENT OF HEALTH MANAGEMENT
Certified by: **PLANNER**
State of Minnesota
Department of Health
Expires: 08/06/2022
Matthew A Lindberg
11816 Ghia St NE
Blaine, MN 55449

Matthew A Lindberg
Director, Env. Health Div.

No. AM3896 Issued: 08/24/2021

Inspector State Certification/Accreditation



m ASBESTOS
DEPARTMENT
OF HEALTH
INSPECTOR

Certified by:
State of Minnesota
Department of Health
Expires: 08/06/2022

Matthew A Lindberg
11816 Chia St NE
Blaine, MN 55449

Director, Env. Health Div. No. AI3896 Issued: 08/24/2021

Inspector State Certification/Accreditation



m ASBESTOS
DEPARTMENT
OF HEALTH
INSPECTOR

Certified by:
State of Minnesota
Department of Health
Expires: 10/02/2021

Chad M. Whaylen
6605 Yucca Ln N
Maple Grove, MN 55369

Director, Env. Health Div. No. AI12966 Issued: 10/13/2020

Chart A - Immediate Response Situations

The following is a list of those events that contain damaged asbestos material and should be considered to be potential hazards. It is imperative that the following immediate response situations are corrected as soon as possible but no later than six months from the date of this inspection to avoid increased risk of exposure to airborne asbestos fibers. The district should take extra precaution to ensure that properly trained personnel use appropriate techniques to implement these responses.

Following is an explanation of the immediate Response Action codes identified in this report.

EPA ASSESSMENT CATEGORY	RESPONSE ACTION
1 = Damaged or significantly damaged TSI ACM.	A = Cleanup ACM debris.
2 = Damaged friable surfacing ACM.	B = Encapsulate slight damage on TSI.
3 = Significantly damaged friable surfacing ACM.	C = Patch TSI and/or repair ACM cover.
4 = Damaged or significantly damaged friable miscellaneous ACM.	D = Enclose or protect accessible sections with protective barrier.
5 = ACBM with potential for damage.	E = Remove section of damaged ACM.
6 = ACBM with potential for significant damage.	F = Remove ACM and replace with non-ACM.
7 = Remaining friable ACBM or friable suspected ACBM.	G = Isolate area until repaired/removed.
	H = Encapsulate slight damage.
	I = Remove and replace damaged or loose tile section.
	J = Monitor condition of material(s).

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Amount of Damage	EPA Assess.	Immediate Response Action	Comments
87 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 0208 (WOOD SHOP) OFFICE 0208C	90 Sq Ft	1 Sq Ft	5	D	WEAR THROUGHOUT. RECOMMEND SEALING WITH WAX AND COVER WITH CHAIR MAT.
126 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1213	750 Sq Ft	1 Sq Ft	5	D	TILE STARTING TO WEAR & CRACK BY TEACHER'S DESK. RECOMMEND CHAIR MAT.
142 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1214	420 Sq Ft	1 Sq Ft	5	D	TILE WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT.
144 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1219	1350 Sq Ft	1 Sq Ft	5	D	INCLUDES MATERIAL UNDER 12" TILES, TABLES & CHAIRS SCRATCHING FLOOR TILE. RECOMMEND CHAIR MAT.
149 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1218	750 Sq Ft	1 Sq Ft	5	D	TILE WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT.
152 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1221	750 Sq Ft	1 Sq Ft	5	D	TILE WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT.
236 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1101	750 Sq Ft	1 Sq Ft	5	D	WEARING & SCRATCHING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT.
246 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1105/1103A	420 Sq Ft	1 Sq Ft	5	D	TWO (2) ROOMS. WEARING UNDER CHAIRS. RECOMMEND CHAIR MAT.
255 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1113	750 Sq Ft	1 Sq Ft	5	D	WEARING UNDER DESKS & CHAIRS. RECOMMEND CHAIR MAT.

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Amount of Damage	EPA Assess.	Immediate Response Action	Comments
284 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 2208	750 Sq Ft	1 Sq Ft	5	D	TILE WEAR UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT.
298 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 2209	750 Sq Ft	1 Sq Ft	5	D	WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT. CHIP IN TILE 6' FROM DOOR
307 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 2218	750 Sq Ft	1 Sq Ft	5	D	WEARING UNDER COMPUTER CHAIRS. RECOMMEND CHAIR MAT.
312 CAD #:	U0A	Light Pad Insulation Small, Round Light Fixture	ROOM 2220	1 Sq Ft	1 Sq Ft	4	E	GLOBE MISSING. BY RESTROOM. STARTING TO FALL APART. RECOMMEND REMOVAL AND REPLACEMENT.
382 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 2110	1200 Sq Ft	1 Sq Ft	5	D	TILE WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT.