

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
8 CAD #:	X1P	Miscellaneous Material 1" X 1" Brown Ceramic Floor Tile System	THROUGHOUT 1952 ORIGINAL BUILDING RESTROOMS	2400 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
11 CAD #:	D2A	Interior Boiler Insulation Floor	BOILER ROOM	60 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
12 CAD #:	P0A	Fire Doors Composite - No Rating (Weldwood)	BOILER ROOM	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
14 CAD #:	B1A	Air Cell Pipe Insulation 1952 Original Building	ROOM 1104A (ELECTRICAL)	5 Lin Ft	N	ASSUMED	5
Comments: ABOVE PLASTER CEILING. ACCESS THROUGH CEILING HATCH. INACCESSIBLE FOR REMOVAL. RECOMMEND KEEPING AREA ISOLATED UNTIL REMOVED OR DAMAGED IS FIXED.					Sample #:		
15 CAD #:	A1A	Mudded Pipe Joints on Air Cell Insulation 1952 Original Building	ROOM 1104A (ELECTRICAL)	3 Joints	Y	ASSUMED	1
Comments: ABOVE PLASTER CEILING. ACCESS THROUGH CEILING HATCH. EXPOSED FITTING. INACCESSIBLE FOR REPAIR/REMOVAL. INACCESSIBLE FOR REMOVAL. RECOMMEND KEEPING AREA ISOLATED UNTIL REMOVED OR DAMAGED IS FIXED.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
34 CAD #:	X1T	Miscellaneous Material 4" X 4" Beige Ceramic Wall Tile System	ROOM 1004B (NURSE RESTROOM)	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
39 CAD #:	W1D	1' x 1' Ceiling Tile Adhesive Associated w/I1D	ROOM 1106 (GYMNASIUM)	500 Sq Ft	N	ASSUMED	5
Comments: ARRANGE LIFT IF YOU CAN SAMPLE W/O DAMAGE.					Sample #:		
42 CAD #:	S0A	Wood Floor Felt / Vapor Barrier Elevated (1952)	ROOM 1108 (STAGE)	450 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
43 CAD #:	T0A	Light Cord Insulation White	ROOM 1108 (STAGE)	48 Lin Ft	N	ASSUMED	5
Comments: FOUR (4) LIGHTS WITH TWO (2), SIX-FOOT (6') CORDS EACH.					Sample #:		
48 CAD #:	X0D	Miscellaneous Material Wired Window Glaze	1ST FLOOR SOUTHWEST STAIRWELL 1199A	2 Sq Ft	N	3 CH	5
Comments:					Sample #: 112508MV-20		
50 CAD #:	X1V	Miscellaneous Material 4" X 4" Blue Ceramic Wall Tile System	BOYS' RESTROOM 1208	70 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
51 CAD #:	X1U	Miscellaneous Material 4" X 4" White Ceramic Wall Tile System	DRINKING FOUNTAINS ACCROSS FROM BOYS' RESTROOM 1208	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
56 CAD #:	X1U	Miscellaneous Material 4" X 4" White Ceramic Wall Tile System	RESTROOM 1209A BY ROOM 1211	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
57 CAD #:	X1V	Miscellaneous Material 4" X 4" Blue Ceramic Wall Tile System	RESTROOM 1209B BY ROOM 1211	70 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
59 CAD #:	X0U	Miscellaneous Material Kiln Gloves	ROOMS 1210 (STORAGE) & 1210A	2 Sq Ft	Y	ASSUMED	4
Comments:					Sample #:		
61 CAD #:	X1E	Miscellaneous Material Metal Frame Chalkboard Adhesive (1952)	ROOM 1211	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
62 CAD #:	X1F	Miscellaneous Material Metal Frame Corkboard Adhesive (1952)	ROOM 1211	100 Sq Ft	N	ASSUMED	5
Comments: ON CONCRETE BLOCK WALL.					Sample #:		
68 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 1212	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
75 CAD #:	K0I	9" x 9" Vinyl Floor Tile & Mastic White w/Black Streaks	ROOM 1214	750 Sq Ft	N	10 CH (TILE ONLY)	5
Comments: ASSUMED UNDER WOOD FLOOR.					Sample #: 527-JJT-53		
78 CAD #:	X0N	Miscellaneous Material Mirror Adhesive	ROOM 1214	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
79 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 1214	16 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
80 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Renovation	ROOM 1214	750 Sq Ft	N	ASSUMED	5
Comments: MAY HAVE BEEN INSTALLED OVER FLOOR TILE AND/OR MASTIC.					Sample #:		
83 CAD #:	X1E	Miscellaneous Material Metal Frame Chalkboard Adhesive (1952)	ROOM 1215	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
84 CAD #:	X1F	Miscellaneous Material Metal Frame Corkboard Adhesive (1952)	ROOM 1215	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
89 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 1216	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
97 CAD #:	X1B	Miscellaneous Material Metal Frame Chalkboard Adhesive (1962)	ROOM 1219	40 Sq Ft	N	ASSUMED	5
Comments: SOME COVERED WITH WHITEBOARDS.					Sample #:		
98 CAD #:	X1H	Miscellaneous Material Metal Frame Corkboard Adhesive (1962)	ROOM 1219	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
101 CAD #:	X1H	Miscellaneous Material Metal Frame Corkboard Adhesive (1962)	ROOM 1218	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
102 CAD #:	X1B	Miscellaneous Material Metal Frame Chalkboard Adhesive (1962)	ROOM 1218	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
105 CAD #:	X1B	Miscellaneous Material Metal Frame Chalkboard Adhesive (1962)	ROOM 1220	20 Sq Ft	N	ASSUMED	5
Comments: SOME COVERED WITH WHITEBOARDS.					Sample #:		
106 CAD #:	X1H	Miscellaneous Material Metal Frame Corkboard Adhesive (1962)	ROOM 1220	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
109 CAD #:	X1B	Miscellaneous Material Metal Frame Chalkboard Adhesive (1962)	ROOM 1221	40 Sq Ft	N	ASSUMED	5
Comments: SOME COVERED WITH WHITEBOARDS.					Sample #:		
110 CAD #:	X1H	Miscellaneous Material Metal Frame Corkboard Adhesive (1962)	ROOM 1221	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
113 CAD #:	X0D	Miscellaneous Material Wired Window Glaze	STAIRWELL NEAR ROOM 1222	2 Sq Ft	N	3 CH	5
Comments:					Sample #:		
120 CAD #:	X1N	Miscellaneous Material Multi-Size Ceramic Floor Tile System	RESTROOM BY ROOM 1223	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
121 CAD #:	X1O	Miscellaneous Material 1" X 1" Blue Ceramic Wall Tile System	RESTROOM BY ROOM 1223	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
122 CAD #:	X1V	Miscellaneous Material 4" X 4" Blue Ceramic Wall Tile System	RESTROOM BY ROOM 1223	160 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
124 CAD #:	X1W	Miscellaneous Material 1" X 1" Salmon Ceramic Wall Tile System	CUSTODIAL CLOSET 1228	35 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
127 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive (1966)	ROOM 1225	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
128 CAD #:	X1I	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 1225	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
131 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive (1966)	ROOM 1230	40 Sq Ft	N	ASSUMED	5
Comments: SOME COVERED WITH WHITEBOARDS.					Sample #:		
132 CAD #:	X1I	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 1230	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
143 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive (1966)	ROOM 2228	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
144 CAD #:	X1I	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 2228	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
146 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive (1966)	ROOM 2225	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
147 CAD #:	X1I	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 2225	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
152 CAD #:	X1I	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 2223	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
156 CAD #:	X1Q	Miscellaneous Material Multi Sized Blue Ceramic Floor Tile System	1966 ADDITION 2ND FLOOR STAFF RESTROOM 2224A	250 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
157 CAD #:	X1R	Miscellaneous Material Multi Sized Beige Ceramic Wall Tile System	1966 ADDITION 2ND FLOOR STAFF RESTROOM 2224A	750 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
159 CAD #:	X1C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1962)	ROOM 2222	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
160 CAD #:	X1J	Miscellaneous Material Wood Frame Corkboard Adhesive (1962)	ROOM 2222	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
163 CAD #:	X1B	Miscellaneous Material Metal Frame Chalkboard Adhesive (1962)	ROOM 2221	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
164 CAD #:	X1H	Miscellaneous Material Metal Frame Corkboard Adhesive (1962)	ROOM 2221	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
168 CAD #:	X1B	Miscellaneous Material Metal Frame Chalkboard Adhesive (1962)	ROOM 2220	40 Sq Ft	N	ASSUMED	5
Comments: SOME COVERED WITH WHITEBOARDS.					Sample #:		
169 CAD #:	X1H	Miscellaneous Material Metal Frame Corkboard Adhesive (1962)	ROOM 2220	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
173 CAD #:	X1B	Miscellaneous Material Metal Frame Chalkboard Adhesive (1962)	ROOM 2219	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
174 CAD #:	X1H	Miscellaneous Material Metal Frame Corkboard Adhesive (1962)	ROOM 2219	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
180 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 2218	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
185 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 2217	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
189 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 2216	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
194 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 2215	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
199 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 2214	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
204 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 2213	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
209 CAD #:	X1G	Miscellaneous Material Wood Frame Corkboard Adhesive (1952)	ROOM 2212	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
211 CAD #:	X1E	Miscellaneous Material Metal Frame Chalkboard Adhesive (1952)	ROOM 2212	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
213 CAD #:	X1E	Miscellaneous Material Metal Frame Chalkboard Adhesive (1952)	ROOM 2211	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
214 CAD #:	X1F	Miscellaneous Material Metal Frame Corkboard Adhesive (1952)	ROOM 2211	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
218 CAD #:	X1U	Miscellaneous Material 4" X 4" White Ceramic Wall Tile System	STAFF RESTROOM 2210	45 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
225 CAD #:	X1V	Miscellaneous Material 4" X 4" Blue Ceramic Wall Tile System	1952 ORIGINAL BUILDING 2ND FLOOR BOYS' RESTROOM 2203	225 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
226 CAD #:	X0D	Miscellaneous Material Wired Window Glaze	1952 ADDITION 2ND FLOOR SOUTHWEST STAIRWELL 2299A	2 Sq Ft	N	3 CH	5
Comments:					Sample #:		
232 CAD #:	X0B	Miscellaneous Material Damp Proofing	WALL CHASE BY MULTI-PURPOSE 1110	1000 Sq Ft	N	5 CH	5
Comments: EXTERIOR OF ORIGINAL BUILDING. ONLY 20 SQ FT VISIBLE IN HATCH.					Sample #: 112508MV-17		
246 CAD #:	P0B	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	ROOM 1114	20 Sq Ft	Y	ASSUMED	4
Comments: ONE (1) DOOR. FRONT PLATE DAMAGED, CORE EXPOSED UNDER INSIDE HANDLE. ALSO, DAMAGED ON HINGE SIDE NEAR BOTTOM HINGE. CORE EXPOSED. DRILLED BOLTS THROUGH DOOR TO MOVE HINGES.					Sample #:		