

Summer Activities:

- We started the Summer off serving 286 lunches to learners at the Enrichment Camp.



- The Traffic Study to look at the feasibility of reinstalling flashing school zone lights on 772 was concluded. We are waiting on input from State Police before submitting it to Leacock Twp. who then needs to apply to Penn Dot. We will not have a decision for a few more months.
- The District was reimbursed \$9,773 from the NRG Energy Reduction Program that we are enrolled in. On high energy demand days the District cuts back on lighting and HVAC. This does not make everyone happy, especially those using the Fitness Center, but being in the program is a big advantage for the District. We only had four days last year where energy had to cut back while people were in the buildings.
- We evaluated the softball field with Hummer Turfgrass. Significant maintenance will happen to the field this Fall. Four truckloads of diamondtex will be added to the infield. 4' of the infield sod will be replaced. The whole field will be edged, and a truckload of warning track material will be added. In addition the home place circle will be expanded to accommodate the new batting box regulations.
 - Protective fencing was added above the pitcher/catcher warmup area to protect athletes from foul balls.
- A carved Indian was donated to the District. We placed it above the Fitness Center entrance.



- We cleaned and mulched the Salisbury courtyard



- The Capital Reserve project to coat all of the flat roofs at Salisbury El. was completed.



- The Capital Reserve project to replace the VAV units at Salisbury has started. 22 skids of parts were delivered the past two weeks. This project is behind schedule. We are going to get as many units replaced as possible before the beginning of school, but this project will extend into the school year.
- The playground at Salisbury continues to be an issue and the equipment ages and degrades. See the included inspection report.
- We hot striped and lined Paradise El's parking lot. The whole lot will need to be recoated in approximately five years.

