



RainCrow

Environmental

***Triennial Asbestos
Re-inspection
Report***

**Tuscumbia City BOE
303 North Commons St. East
Tuscumbia, AL 35674**

August 25th, 2022

Stan Eller, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

LEA: Tuscumbia City Schools
General Administrative and Support Facilities
303 N. Commons St. East
Tuscumbia, Alabama 35674

REINSPECTION DATE: 8/25/22

INSPECTOR: Stan Eller

ACCREDITATION NO.: AIN0622257655


SIGNATURE: 

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Fourteen-hour training for maintenance personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – General Administrative and Support Facilities		School # 000	
Building Name - Bus Shop		Building # 003	
Address: 303 N. Commons St. East Tuscumbia, Alabama 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Roof Coating Material (Under-side of Corrugated Roof) – 3,025 sf		“Peerless” Gas Ceiling Heater/ Lining (Shop Area)		Sheetrock Walls & Ceiling (Office Area)											
			No.	01-01	02-01	03-02	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
			Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI			X														
	Surfacing																	
	Miscellaneous		X				X											
	Assumed ACBM			X	X													
	Sampled/Tested		X															
	Non ACBM		X				X											
	ACBM																	
	Nonfriable		X				X											
Friable				X	X													
Assessment/Reassessment																		
Change in Condition? (Y/N)			N	N		N												
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
40 Hours/Week																		
Check All That Apply	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
Assessment Category			5		7													

Non-ACBM From Recent Renovation.

Stan Eller, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

LEA: Tuscumbia City Schools
Deshler Vocational/ High
200 N. Commons
Tuscumbia, Alabama 35674

REINSPECTION DATE: 8/25/22

INSPECTOR: Stan Eller

ACCREDITATION NO.: AIN0622257655

SIGNATURE: 

COMMENTS AND INSTRUCTIONS:

Since the last inspection, the 8" light fixture heat shield located at the janitor closet of the *Main* building (001), has been removed as well as the two sinks located at the art room. The old laboratory counter tops and the laboratory ovens have been removed from the *Main* building.

And since the last inspection, the old laboratory counter tops have been removed from the *Jr. High* building (002).

Since the last inspection, the ceiling heaters with vibration dampers have been removed from the *Gym* building (003).

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:


- An asbestos caution sign should be posted near the gym boiler because of the presence of suspect asbestos boiler insulation.
- Two-hour training for custodial personnel should be accomplished as needed.
- Fourteen-hour training for maintenance personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.

Stan Eller, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022


Cell Phone: 334-315-2892

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
 AHERA Reinspection Form**


Date of Previous Inspection – 6-20-19						Date Of Reinspection – 8-25-22																
LEA Name - Tusculmbia City Board Of Education						LEA # 201																
School Name – Deshler Vocational/High						School # 010																
Building Name - High School						Building # 001																
Address: 200 N. Commons Tuscumbia, AL 35674						Inspector's Name – Stan Eller																
						Signature - 																
						Alabama Accreditation No. – AIN0622257655																
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Principal's Office) off white		Black Floor Tile (Threshold Steps)		9" Vinyl Floor Tile (Counselor Office) gray		12" Vinyl Floor Tile – beige speck		Oven Liner In Chemistry Laboratory		Oven Liner In Chemistry Laboratory		Oven Liner In Chemistry Laboratory		White Floor Tile Replacements In Room 210		Dark Brown Floor Tile @ Classroom Entry		Light Brown Streak Floor Tile @ Classrooms	
			No.	01	06	07	11	14	15	16	18	20	21									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI								X	X	X											
	Surfacing																					
	Miscellaneous		X		X		X		X					X	X			X		X		
	Assumed ACBM		X						X	X												
	Sampled/Tested				X		X				X		X			X		X		X		
	Non ACBM																					
	ACBM				X	X	X				X		X			X	X	X	X	X	X	
	Nonfriable		X		X	X	X		X	X	X		X		X	X	X	X	X	X	X	
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			Y		N		Y		N		Y		Y		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration		Covered W/ Carpet Prior To 1998 Re-inspection. Removed																			
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility		Covered W/ New Floor Tile Prior To 2004 Re-inspection.																			
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	Maintenance		Covered W/ Carpet Prior To 1995 Re-inspection. Removed																			
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category			Covered W/ New Floor Tile Prior To 2004 Re-inspection.																			
Maintenance																						
Custodial																						
Faculty/Students																						
Assessment Category			Covered W/ New Floor Tile Prior To 2004 Re-inspection.																			
Maintenance																						
Custodial																						
Faculty/Students																						
Assessment Category			Covered W/ New Floor Tile Prior To 2004 Re-inspection.																			
Maintenance																						
Custodial																						
Faculty/Students																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22
LEA Name - Tusculmbia City Board Of Education		LEA # 201
School Name – Deshler Vocational/High		School # 010
Building Name - High School		Building # 001
Address: 200 N. Commons Tuscumbia, AL 35674		Inspector's Name – Stan Eller
		Signature - 
Alabama Accreditation No. – AIN0622257655		


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Red/White Streak Floor Tile In Classroom		White /Red Floor Tile In Classroom		Boiler Jacket Insulation		Boiler Door Material		8" Light Fixture Heat Shield (Janitor Closet)		2 - Sinks W/ White Spray-on (Art Room)		Lab Counter Tops (Science Lab)								
			No.	22	23	27	28	76	77	121													
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI						X		X														
	Surfacing											X											
	Miscellaneous			X		X					X				X								
	Assumed ACBM					X	X				X		X		X								
	Sampled/Tested			X				X		X													
	Non ACBM																						
	ACBM			X	X			X		X													
	Nonfriable			X	X	X	X	X		X		X		X		X							
Friable																							
Assessment/Reassessment																							
Change in Condition? (Y/N)			N		N		N		N		Y		Y		Y								
Rate 1 To 5 5 is Worst	Deterioration																						
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility																						
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
Check All That Apply	40 Hours/Week																						
	Maintenance																						
	Custodial																						
	Faculty/Students																						
Public																							
Assessment Category			Covered W/ New Floor Tile Prior To 2004 Re-inspection.			Covered W/ New Floor Tile Prior To 2004 Re-inspection.			Removed Prior To 1998 Re-inspection.			Removed Prior To 1998 Re-inspection.			Not Listed In The Original Management Plan. Removed			Not Listed In The Original Management Plan. Removed			Not Listed In The Original Management Plan. Removed in 2019		

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22
LEA Name - Tusculmbia City Board Of Education		LEA # 201
School Name – Deshler Vocational/High		School # 010
Building Name - Jr. High School		Building # 002
Address: 200 N. Commons Tuscumbia, AL 35674		Inspector's Name – Stan Eller
		Signature - 
Alabama Accreditation No. – AIN0622257655		


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Pipe Insulation In Boiler Room & Above Classrooms		Heater Insulation Inside Heater (Wall Units @ Annex)		Rope Insulation Inside Boiler		9" VFT (2- CR' s Hall & Nurses Sta.) gray w/ white & black marbled		4 -Laboratory Counter Tops (ScienceLab) – 60 sf										
			No.	35	36	47	78	79													
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI		X		X		X														
	Surfacing																				
	Miscellaneous								X	X											
	Assumed ACBM										X										
	Sampled/Tested		X		X		X		X	X											
	Non ACBM								X	X											
	ACBM		X		X		X	X													
	Nonfriable								X	X	X										
Friable		X		X		X	X														
Assessment/Reassessment																					
Change in Condition? (Y/N)			N		N		N		N	Y											
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
Public																					
Assessment Category			Not In Boiler Room In 2004 & 2007 Re-inspections.		Units Removed Prior To 2004 Re-inspection.				Not Listed In The Original Management Plan. Removed From Hall In Approx. 2012.		Not Listed In The Original Management Plan. Removed										

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – Deshler Vocational/High		School # 010	
Building Name - Library		Building # 004	
Address: 200 N. Commons Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Green/White Floor Tile		2 – Sinks W/ White Spray-on (Workroom Area)		2- White Canvas Vibration Dampers (Back HVAC Closet)														
			No.	24	84	122															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																				
	Surfacing				X																
	Miscellaneous			X			X														
	Assumed ACBM		X	X	X	X	X	X													
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable		X	X	X	X	X	X													
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			N		Y		N														
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category			Covered In 2005.		Not Listed In The Original Management Plan. One Removed		Not Listed In The Original Management Plan.														

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – Deshler Vocational/High		School # 010	
Building Name - Cafeteria		Building # 005	
Address: 200 N. Commons Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" Yellow Floor Tile		9" Light Gray Floor Tile		Black Floor Tile (Threshold Strip)		Off White Floor Tile (Patches & Entry)		Plaster Ceiling (In Kitchen & Storage)		White Floor Tile (Kitchen)								
			No.	113	114	115	116	117	120												
			Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.
Check one	TSI																				
	Surfacing										X										
	Miscellaneous		X		X		X		X				X								
	Assumed ACBM								X		X		X								
	Sampled/Tested		X		X		X			X		X		X							
	Non ACBM									X		X		X							
	ACBM		X	X	X	X	X	X													
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X						
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			N		N		N		Y		Y		Y								
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
Public																					
Assessment Category			Covered W/ Light Gray Floor Tile W/ Dark Gray & Cream Flakes Prior To 1998 Re-inspection.		Covered W/ Light Gray Floor Tile W/ Dark Gray & Cream Flakes Prior To 1998 Re-inspection.		Covered W/ Light Gray Floor Tile W/ Dark Gray & Cream Flakes Prior To 1998 Re-inspection.		Covered W/ Light Gray Floor Tile W/ Dark Gray & Cream Flakes Prior To 1998 Re-inspection.				Covered W/ Light Gray Floor Tile W/ Dark Gray & Cream Flakes Prior To 1998 Re-inspection.								

**Alabama Asbestos Management Program
AHERA Reinspection Form**


Date of Previous Inspection – 6-20-19						Date Of Reinspection – 8-25-22																	
LEA Name - Tusculmbia City Board Of Education						LEA # 201																	
School Name – Deshler Vocational/High						School # 010																	
Building Name - Auditorium						Building # 006																	
Address: 200 N. Commons Tuscumbia, AL 35674						Inspector's Name – Stan Eller																	
						Signature - 																	
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.						Alabama Accreditation No. – AIN0622257655																	
Homogeneous Area	Description	9" Red Floor Tile (Auditorium)		9" Tan Floor Tile		Red/White Streak Floor Tile (In Lobby)		Red Roll Tile (PIT)		Rope Boiler Gasket (In Basement)		Boiler Insulation Inside Boiler		Boiler Door Insulation		Fire Clay Boiler Door		Blue Floor Tile (Office)		9" Dark Brown Floor Tile (Chorus Room)			
		No.	48	49	51	52	55	56	57	58	59	60											
Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI									X	X	X	X										
	Surfacing																						
	Miscellaneous	X		X		X		X										X		X			
	Assumed ACBM																	X	X				
	Sampled/Tested	X		X		X		X		X		X		X		X					X		
	Non ACBM																						
	ACBM	X	X	X	X	X	X	X	X						X						X		
	Nonfriable	X	X	X	X	X	X	X	X						X		X	X	X	X			
Friable										X	X	X											
Assessment/Reassessment																							
Change in Condition? (Y/N)		Y		Y		Y		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration	Covered W/ Carpet Prior To 1998 Re-inspection. Covered w/ new red/gray patterned carpet in 2021.																					
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility	Covered W/ Carpet Prior To 1998 Re-inspection. Covered w/ new red/gray patterned carpet in 2021.																					
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
Check All That Apply	Maintenance	Covered W/ Carpet Prior To 1998 Re-inspection. Covered w/ new red/gray patterned carpet in 2021.																					
	Custodial																						
	Faculty/Students																						
	Public																						
Assessment Category		Covered Prior To 2001 Re-inspection.																					
		Covered Prior To 2001 Re-inspection. Removed.																					

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – Deshler Vocational/High		School # 010	
Building Name - Vo-Tech Center		Building # 007	
Address: 200 N. Commons Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature -	
Alabama Accreditation No. – AIN0622257655			

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" VFT (Drafting & HVAC Off.) light green		12" VFT (HVAC-Now Wrestling Room) tan		Transite Walls In Welding(Now Wood Shop)		Vibration Damper @ Gas Heater (Shop) White		5' x 3' Roof Deck Panels – 5,600 sf											
			No.		40		41		43		44		75									
			Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI						X		X													
	Surfacing																					
	Miscellaneous			X		X						X										
	Assumed ACBM		X	X	X							X	X									
	Sampled/Tested							X		X												
	Non ACBM																					
	ACBM							X		X	X											
	Nonfriable		X	X	X			X		X	X	X	X									
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		Y		N		N											
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
	Assessment Category																					
			Removed From Special Ed. Restroom/Approx. 2012.				Covered Prior To 2001 Re-inspection. Removed Prior To 2016.				All Removed Except By Storage Cab Prior To 2004 Re-inspection.. All Removed.											

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19				Date Of Reinspection – 8-25-22			
LEA Name - Tusculmbia City Board Of Education				LEA # 201			
School Name – Deshler Vocational/High				School # 010			
Building Name - Old Armory/ Gym				Building # 010			
Address: 200 N. Commons Tuscumbia, AL 35674				Inspector's Name – Stan Eller			
				Signature - 			
Alabama Accreditation No. – AIN0622257655							

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" VFT (Storage Rm @ Back Corner) drk brown – 224 sf																		
			No.	01-01																	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																				
	Surfacing																				
	Miscellaneous				X																
	Assumed ACBM			X	X																
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable			X	X																
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)				N																	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
	40 Hours/Week																				
Check All That Apply	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category																					

Stan Eller, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

LEA: Tuscumbia City Schools
Deshler Middle (Old Northside Middle)
600 N. High Street
Tuscumbia, Alabama 35674

REINSPECTION DATE: 6/20/19

INSPECTOR: Stan Eller

ACCREDITATION NO.: AIN0619257655


SIGNATURE: 

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:


- Two-hour training for custodial personnel should be accomplished as needed.
- Fourteen-hour training for maintenance personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tuscumbia City Board Of Education		LEA # 201	
School Name – Northside Middle – Now Deshler Middle		School # 020	
Building Name - Main		Building # 001	
Address: 600 N. High Street Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" Buff Floor Tile (Throughout)		9" Tan Repair Floor Tile (Throughout)		9" Blue Repair Floor Tile (Throughout)		9" Blue Floor Tile		9" Light Green Floor Tile (Mechanical Rm. @ Storage)		Brown Stair Nosing (In Auditorium)		Sinks W/ White Spray-on (Classrooms)		Sinks W/ Black Spray-on (Old Home-Ec CR & Nurse's Station)		Sinks W/ Gray Spray-on (Library Workroom & Office Kitchen)		Transite Panels (@ Base of Each Classroom Window)	
			No.	04	05	07	08	09	11	15	16	17	18									
			Inspection/Reinspection	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																					
	Surfacing																					
	Miscellaneous																					
	Assumed ACBM																					
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable																					
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)																						
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category																						
Covered In 2005. Remains Under Stage.																						
Covered In 2005 – Remains In Conference Room/Lounge, Teachers Storage Rooms																						
Covered In 2005																						
Covered In 2005																						
1/3 Missing @ Janitor Closet Adjacent Kitchen.																						
Covered W/ Carpet Prior To 2001 Re-inspection. Now Removed.																						
Not Listed In The Original Management Plan.																						
Not Listed In The Original Management Plan.																						
Not Listed In The Original Management Plan.																						
Not Listed In The Original Management Plan.																						

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22
LEA Name - Tusculmbia City Board Of Education		LEA # 201
School Name – Northside Middle – Now Deshler Middle		School # 020
Building Name - Main		Building # 001
Address: 600 N. High Street Tuscumbia, AL 35674		Inspector's Name – Stan Eller
		Signature - 
Alabama Accreditation No. – AIN0622257655		

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	18- Dampers on Air Handling Unit (Closets & Above Ceiling)		Fire-doors (All Classroom)		Gypsum Ceiling (Upstairs Mechanical Room)														
			No.	13	19	20															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																				
	Surfacing																				
	Miscellaneous			X	X	X															
	Assumed ACBM		X	X	X	X															
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable		X	X	X	X															
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			N		Y		Y														
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
Public																					
Assessment Category																					
			Not Listed In The Original Management Plan.				Not Listed In The Original Management Plan.														

Stan Eller, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

LEA: Tuscumbia City Schools
R. E. Thompson Elementary
Frankford Road
Tuscumbia, Alabama 35674

REINSPECTION DATE: 8/25/22

INSPECTOR: Stan Eller

ACCREDITATION NO.: AIN0622257655


SIGNATURE: 

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:


- Two-hour training for custodial personnel should be accomplished as needed.
- Fourteen-hour training for maintenance personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – R. E. Thompson Elementary		School # 030	
Building Name - Main		Building # 001	
Address: Frankford Road Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Hall) Tan		Threshold Strip (Throughout)		9" Vinyl Floor Tile (Throughout) White / Brown		9" Vinyl Floor Tile (Health Room) Brown / Brown Speck		Light Gasket (Janitor's Closet)		9" Vinyl Floor Tile (Classroom) Brown		Gas Heaters In Classroom		9" Vinyl Floor Tile (Classroom #2) Black / White		9" Vinyl Floor Tile (Classroom #3) Black / White		9" Vinyl Floor Tile (Classroom #3) White Speck	
			No.	01	02	03	04	10	15	16	17	18	19									
			Inspection/Reinspection	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now			
Check one	TSI																					
	Surfacing								X			X										
	Miscellaneous		X		X		X		X			X			X			X		X		X
	Assumed ACBM		X	X	X	X		X	X			X	X		X	X		X	X	X	X	X
	Sampled/Tested					X				X				X								
	Non ACBM					X																
	ACBM								X			X										
	Nonfriable		X	X	X	X	X		X	X	X		X	X	X		X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			Y		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category			Covered. Approx. 25 sf are broken.																			
			Removed In 1997.																			
			Some Classes Removed Rm's 4, 7 & 10 (August 1999)																			
			Units Were Replaced In Early 1990's																			
			Covered With 12" Cream Floor Tile With Gray Flakes Prior To 1998 Re-inspection.																			

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – R. E. Thompson Elementary		School # 030	
Building Name - Main		Building # 001	
Address: Frankford Road Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area		Description		9" Vinyl Floor Tile (Classroom #8) Gray / White		8 – Sink W/ Gray Spray-on (Classrooms 11 - 18)		1 – Sink W/ White Spray-on (Nurses Station)		9" Vinyl Floor Tile (Throughout) White / Brown		4 - Firedoors (Through-out Hallways)		Cement Panels (Hall Windows)		2-“ Janitrol” Gas Ceiling Heaters/ Lining (Each End / Stage)		10 – Sinks W/ Black Spray-on		Sheetrock walls (Office Area)		
	No.	20	26-01	26-02	05	29	30	14-15	32	31-01	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																						
	Surfacing																						
	Miscellaneous		X	X	X	X	X	X															
	Assumed ACBM		X	X	X	X	X	X			X	X	X					X	X	X	X		
	Sampled/Tested									X								X					
	Non ACBM									X								X					
	ACBM																						
	Friable		X	X	X	X	X	X	X	X	X	X	X					X		X	X	X	X
Assessment/Reassessment																							
Change in Condition? (Y/N)		N	N	N	N	N	N	N	N	Y	N	N	N	N	N	N	N	N	N	N	N	N	
Rate 1 To 5 5 is Worst	Deterioration																						
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility																						
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
Check All That Apply	40 Hours/Week																						
	Maintenance																						
	Custodial																						
Faculty/Students																							
Public																							
Assessment Category		Covered With 12" Cream Floor Tile With Gray Flakes Prior To 1998 Re-inspection.																					
		Hall Covered With 12" Tan Floor Tile With Brown Spots Prior To 1998 Re-inspection.																					
		Not Listed In The Original Management Plan.																					
		Not Listed In The Original Management Plan. Determined to be <i>Masonite</i> fiber board.																					
		Not Listed In The Original Management Plan.																					
		Not Listed In The Original Management Plan.																					

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – R. E. Thompson Elementary		School # 030	
Building Name - Valdosta Community Center		Building # 002	
Address: Frankford Road Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Brown Cove Base In Gym		12" Mottled Floor Tile (Gym Area)		2 x 4 Transite Ceiling Tile (Canopy) – 40 sf														
			No.	22	24	28	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																				
	Surfacing																				
	Miscellaneous			X		X		X													
	Assumed ACBM			X		X		X	X												
	Sampled/Tested						X														
	Non ACBM																				
	ACBM																				
	Nonfriable			X		X	X	X	X												
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			N		N		N														
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category			Removed By City Prior To Deed Transfer Prior To 2004 Re-inspection.			Covered With New Floor Tile Prior To 2004 Re-inspection. Only the Black Mastic Determined to be Positive.			2 – Tile Replaced With New 2x4 Ceiling Tile.												

Stan Eller, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

LEA: Tuscumbia City Schools
G. W. Trenholm Primary (Old Southside Elementary)
1408 Joe Wheeler Parkway
Tuscumbia, Alabama 35674

REINSPECTION DATE: 8/25/22

INSPECTOR: Stan Eller

ACCREDITATION NO.: AIN0622257655

SIGNATURE: 


COMMENTS AND INSTRUCTIONS:

Since the last inspection, one material type was identified at the *Main Building* (001) that was not previously listed as suspect ACBM. The item identified included sheetrock mud joints located at the stage area classrooms. Also, the 12" vinyl floor tiles were tested for asbestos content at the 1982 classroom wing. Only the mastic was positive for asbestos.

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:


- Two-hour training for custodial personnel should be accomplished as needed.
- Fourteen-hour training for maintenance personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – Southside (G.W. Trenholm Primary School)		School # 040	
Building Name - Main		Building # 001	
Address: 1408 Joe Wheeler Parkway Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area		Description		9" VFT (FIT In Auditor., Café, Jan. Strge & Teacher Lounge Kitch) brn/ wht		Insulation (Inside "Peer-less" Gas Furnace In Penthouse)		9" Vinyl Floor Tile (Throughout) green/white		Tan Trim On Floor Tile Throughout		Brown Roll Flooring (Library)		Brown Marble Roll Flooring (Lounge)		Wall Panels (Library Office & Hall)		12" Vinyl Floor Tile (Classroom & Hall) cream mottled		12" Vinyl Floor Tile (Classroom) tan mottled		Roof Material			
	No.		01	06	09	10	14	16	18	19	20	03														
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
			Check one	TSI				X																		
Surfacing																										
Miscellaneous				X			X		X		X		X		X		X		X		X				X	
Assumed ACBM		X		X			X	X	X	X	X		X		X	X	X	X	X	X	X					
Sampled/Tested					X																			X		
Non ACBM																										
ACBM					X																			X	X	
Nonfriable		X		X			X	X	X	X	X		X		X	X	X	X	X	X	X	X	X	X	X	
Friable				X																						
Assessment/Reassessment																										
Change in Condition? (Y/N)			N		N		N		N		Y		N		N		N		N		N		N			
Check All That Apply	Rate 1 To 5 5 is Worst	Deterioration	Carpet Over Or Covered W/ White Rock Patterned Tile Prior To 1995 Re-inspection. Removed Boiler In 2005. Covered In 2005 Except For Library Work Room. & Janitor Closet Covered In 2005. Carpet Over Tile Prior To 1995 Re-inspection. Determined To Have Been Removed. Carpet Over Floor Tile Prior To 1995 Re-inspection. Appears To Be Removed. Covered In 2005. Covered In 2005. Possibly The Plaster.																							
		Physical Damage																								
Length of Exposure		Water Damage																								
		Activity/Vibration																								
		Exposure																								
		Accessibility																								
		1 Hour/Week																								
Public		5 Hours/Week																								
		10 Hours/Week																								
		20 Hours/Week																								
		40 Hours/Week																								
Assessment Category																										

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22
LEA Name - Tusculmbia City Board Of Education		LEA # 201
School Name – Southside (G.W. Trenholm Primary School)		School # 040
Building Name - Main		Building # 001
Address: 1408 Joe Wheeler Parkway Tuscumbia, AL 35674		Inspector's Name – Stan Eller
		Signature - 
Alabama Accreditation No. – AIN0622257655		

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Roof Material		13 - Firedoors (Office Storage & 12 Class-rooms)		1 - Sink W/ Gray Spray-on (Library Work Room)		12 - Sink W/ Gray Spray-on (Classrooms)		8 - Sink W/ White Spray-on (1982 Class-room Addition)		2x4 Ceiling Tile (1982 CR Addition)		12" Vinyl Floor Tile (CR # 15 & Hall @ 1982 Wing) tan /gray marbled		12" Vinyl Floor Tile (CR' s @ 1982 Wing) tan marbled		Quarry Tile Flooring/ Grout (RR' s @ Old Section)		Quarry Tile Flooring/ Mastic (RR' s @ Old Section)			
			No.	05	22	23-01	23-02	24-01	25-01	31-01	32-01	33-01	34-01											
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																							
	Surfacing																							
	Miscellaneous			X		X						X		X		X		X		X		X		
	Assumed ACBM					X X		X X		X X		X X				X X								
	Sampled/Tested			X										X				X		X		X		
	Non ACBM													X				X		X		X		
	ACBM			X X												X X		X X						
	Nonfriable			X X		X X		X X		X X		X X		X X		X X		X X		X X		X X		
Friable																								
Assessment/Reassessment																								
Change in Condition? (Y/N)			N		N		N		N		N		N		N		Y		N		N			
Rate 1 To 5 5 is Worst	Deterioration																							
	Physical Damage																							
	Water Damage																							
	Activity/Vibration																							
	Exposure																							
Length of Exposure	Accessibility																							
	1 Hour/Week																							
	5 Hours/Week																							
	10 Hours/Week																							
	20 Hours/Week																							
Check All That Apply	40 Hours/Week																							
	Maintenance																							
	Custodial																							
	Faculty/Students																							
Public																								
Assessment Category			Possibly The Plaster.																					
			Not Listed In The Original Management Plan.																					
			Not Listed In The Original Management Plan.																					
			Not Listed In The Original Management Plan.																					
			Not Listed In The Original Management Plan.																					
			Not Listed In The Original Management Plan.																					
			Only Mastic Is Hot.																					

**Alabama Asbestos Management Program
 AHERA Reinspection Form**

Date of Previous Inspection – 6-20-19		Date Of Reinspection – 8-25-22	
LEA Name - Tusculmbia City Board Of Education		LEA # 201	
School Name – Southside (G.W. Trenholm Primary School)		School # 040	
Building Name - Main		Building # 001	
Address: 1408 Joe Wheeler Parkway Tuscumbia, AL 35674		Inspector's Name – Stan Eller	
		Signature - 	
Alabama Accreditation No. – AIN0622257655			

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Sheetrock Mud Joints (Classroom Divider Walls) – 3,600 sf		Sheetrock Mud Joints (Café Stage Rooms) – 1,350 sf																
			No.	35-01	36-01																
			Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.
Check one	TSI																				
	Surfacing																				
	Miscellaneous			X		X															
	Assumed ACBM				X		X														
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable			X		X															
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			Y		Y																
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
40 Hours/Week																					
Check All That Apply	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category																					