

Columbine High School		Sampled 4/27/2022	Status
CustomerSampleNumber	Description	Lead Results (ppb)	
73500-UH1H-WBFS	Water Bottle Filling Station near Classroom MA11	<0.1*	
73500-UH1H-DF	Drinking Fountain near Classroom MA11	<0.1*	
73500-UA1H-DF	Hallway Drinking Fountain outside of SCI-9	<0.1*	
73500-2022-UA1H-WBFS	Water Bottle Filling Station outside of SCI-9	0.1	
73500-LB2-S2	Food Service Sink-Food Prep	1.7	
73500-LB3-S	Sink in Teacher's Lounge	6.7	Repairs pending
73500-LA2H-WBFS	Hallway Water Bottle Filling Station outside of Cafeteria	<0.1*	
73500-LA2H-DF	Drinking Fountain outside of Cafeteria	<0.1*	
73500-UE9H-DF	Hallway Drinking Fountain in the Lobby	<0.1*	
73500-2022-UE9H-WBFS	Water Bottle Filling Station in the lobby	<0.1*	
73500-53-S	Sink in Training Room	0.2	
73500-UC4-DF	Drinking Fountain in Small Gym	<0.1*	
73500-2022-UC7-DFL	Drinking Fountain in Girl's Locker Room/Left	<0.1*	
73500-2022-UC7-DFR	Drinking Fountain in Girl's Locker Room/Right	<0.1*	
73500-2022-UC7-WBFS	Water Bottle Filling Station in Girl's Locker Room	<0.1*	
73500-2022-UC31-DFL	Drinking Fountain in Girl's Athletic Locker Room/Left	<0.1*	
73500-2022-UC31-DFR	Drinking Fountain in Girl's Athletic Locker Room/Right	<0.1*	
73500-2022-UC31-WBFS	Water Bottle Filling Station in Girl's Athletic Locker Room	<0.1*	
73500-UB23AXH-DF	Hallway Drinking Fountain outside of Activity Room UB-21	0.2	
73500-113-DFL	Drinking Fountain in Library Lobby/Left	0.3	
73500-113-DFR	Drinking Fountain in Library Lobby/Right	0.4	
73500-CL1-DF	Drinking Fountain in Computer Lab 1	0.9	
73500-LM2-S	Sink in Consumer Science Room LM-2	0.1	
73500-UD23-S1	Sink in Kitchen Classroom UD-23	0.2	
73500-UD23-S2	Sink in Kitchen Classroom UD-23	<0.1*	
73500-UD23-S3	Sink in Kitchen Classroom UD-23	<0.1*	
73500-UD23-S4	Sink in Kitchen Classroom UD-23	<0.1*	
73500-UD23-S5	Sink in Kitchen Classroom UD-23	0.1	
73500-UD23-S6	Sink in Kitchen Classroom UD-23	0.1	
73500-UD23-S7	Sink in Kitchen Classroom UD-23	0.2	
73500-UD1H-DF	Hallway Drinking Fountain across from Office UD1H	0.1	
73500-UD36-S	Sink in Instrument/Band Office	1.1	

73500-UD36-DF	Drinking Fountain in Instrument/Band Office	10.2	Repairs pending
73500-UE36-S	Sink in Clinic	4.3	
73500-UE27-WC	Water Cooler in Planning Room UE-27	<0.1*	
73500-YC53-IM	Ice Machine in Training Room UC-53	<0.1*	
73500-2022-AUXGYMLOBBY-DFL	Drinking Fountain in Auxilary Gym Lobby/Left	<0.1*	
73500-2022-AUXGYMLOBBY-DFR	Drinking Fountain in Auxilary Gym Lobby/Right	<0.1*	
73500-2022-AUXGYMLOBBY-WBFS	Water Bottle Filling Station in Auxilary Gym Lobby	<0.1*	
73500-2022-UC2H-DFL	Hallway Drinking Fountain/Left	<0.1*	
73500-2022-UC2H-DFR	Hallway Drinking Fountain/Right	<0.1*	
73500-2022-UC2H-WBFS	Hallway Water Bottle Filling Station	<0.1*	

* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.